

Card No.: F/n-1

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** N. C. Nariealvala Fire

Temple



		- r				
1.0	Denomination					
1.1	Name of Premises	N. C. Nariealvala F	ire Temple			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Mumbai Marathi Gr No. 26)	anth Sangrahalay	Marg (N	laigaon Cross Ro	oad
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust owned				
4.0	Use					
4.1	Present	Religious, place of Worship				
4.2	Past	Religious, place of Worship				
4.3	Usage	Religious use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located next to Par Granth Sangrahala Station.				
5.2	Architectural Description	Belongs to the typology of Parsi fire temples in the city. The façade is governed by a verandah running throughout the structure. Features like circular columns, furoher, motifs, carved C.I. grill, gate along with interesting sloping roof profile with ventricular etc. adorn the façade. Two Lion statue on either side enhances entrance.				
5.3	Intrinsic	The Zoroastrian (Pacolonies / precincts community located colony is one of the Zoroastrian Communit also has an Agiar	specially built for a at various places i biggest communit unity in India. Just	all the se n the isla y settler like any	ections of the and city. Dadar F ments of the	Parsi
5.4	Value Classification	A(arc), A(cul), E		Recom	mended Grade	II A
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Basalt dressed stor	ne coursed plinth			
7.2	Walls	Load bearing brick	walls			
						_

7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh 8.2 Vent 8.3 Elect 8.4 Wate 8.5 Drai 8.6 Fire 8.7 Other Syst  9.0 Con 9.1 Plint 9.2 Wall 9.3 Floor 9.4 Stain 9.5 Ope 9.6 Roor 9.7 Articl 9.8 Serv 9.9 Outt 9.10 Ove 10.0 Tran 10.1 Form 10.2 Strue 10.3 Articl	enings  fing  culation & Finishes  vices  buildings  erall condition  nsformation	Good (Wooden members in sound state)  Good (Mangalore tiles, fascia and external m Good  Access denied  Good (Partly landscaped and maintained clea Good Maintenance level  Plastic sheets roof added in front.  No transformation  None			
7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh 8.2 Vent 8.3 Elect 8.4 Wate 8.5 Drai 8.6 Fire 8.7 Other Syst  9.0 Con 9.1 Plint 9.2 Wall 9.3 Floor 9.4 Stain 9.5 Ope 9.6 Roor 9.7 Articl 9.8 Serv 9.9 Outt 9.10 Ove 10.0 Tran 10.1 Form 10.2 Struit	enings  fing  culation & Finishes  vices  buildings  rall condition  nsformation  m	Good (Mangalore tiles, fascia and external m Good Access denied Good (Partly landscaped and maintained clea Good Maintenance level  Plastic sheets roof added in front. No transformation	an)		
7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh 8.2 Vent 8.3 Elect 8.4 Wate 8.5 Drai 8.6 Fire 8.7 Othe Syst 9.0 Con 9.1 Plint 9.2 Wall 9.3 Floo 9.4 Stain 9.5 Ope 9.6 Roo 9.7 Artic 9.8 Serv 9.9 Outt 9.10 Ove 10.0 Trar 10.1 Form	enings  fing  culation & Finishes  vices  buildings  erall condition  nsformation	Good (Mangalore tiles, fascia and external m Good Access denied Good (Partly landscaped and maintained clea Good Maintenance level  Plastic sheets roof added in front.	an)		
7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh 8.2 Vent 8.3 Elect 8.4 Wate 8.5 Drai 8.6 Fire 8.7 Other Syst  9.0 Con 9.1 Plint 9.2 Wall 9.3 Floor 9.4 Stain 9.5 Ope 9.6 Roor 9.7 Articl 9.8 Serv 9.9 Outh 9.10 Ove 10.0 Tran	enings  fing  culation & Finishes  vices  buildings  erall condition  nsformation	Good (Mangalore tiles, fascia and external m Good Access denied Good (Partly landscaped and maintained clear Good Maintenance level	an)		
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other  Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floor  9.4 Stain  9.5 Ope  9.6 Roor  9.7 Articl  9.8 Serv  9.9 Outh  9.10 Ove	enings  fing  culation & Finishes  vices  buildings  crall condition	Good (Mangalore tiles, fascia and external m Good Access denied Good (Partly landscaped and maintained clea	an)		
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other  Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floor  9.4 Stain  9.5 Ope  9.6 Roor  9.7 Articl  9.8 Serv  9.9 Outb	enings  fing  culation & Finishes  vices  buildings	Good (Mangalore tiles, fascia and external m Good Access denied Good (Partly landscaped and maintained clea	an)		
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other  Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floor  9.4 Stain  9.5 Ope  9.6 Roor  9.7 Article  9.8 Serv	enings  fing  culation & Finishes  vices	Good (Mangalore tiles, fascia and external m Good Access denied			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Watt  8.5 Drai  8.6 Fire  8.7 Othe Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floo  9.4 Stain  9.5 Ope  9.6 Roo  9.7 Artice	enings  fing  culation & Finishes	Good (Mangalore tiles, fascia and external m	embers in sound state)		
7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh 8.2 Vent 8.3 Elect 8.4 Wate 8.5 Drai 8.6 Fire 8.7 Othe Syst 9.0 Con 9.1 Plint 9.2 Wall 9.3 Floo 9.4 Stain 9.5 Ope 9.6 Roo	enings	Good (Mangalore tiles, fascia and external m	embers in sound state)		
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floo  9.4 Stain  9.5 Ope	enings		embers in sound state)		
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Flood  9.4 Stain		Good (Wooden members in sound state)			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other Syst  9.0 Con  9.1 Plint  9.2 Wall  9.3 Floo	rs				
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other Syst  9.0 Con  9.1 Plint  9.2 Wall		Access denied			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other  Syst  9.0 Con  9.1 Plint	or	Access denied			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Othe Syst  9.0 Con	ls	Good (No dampness or cracks observed)			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other Systems	th	Good (No settlement or cracks observed)			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai  8.6 Fire  8.7 Other	dition				
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate  8.5 Drai	er (HVAC / BMS / Security tems)	Not provided			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elect  8.4 Wate	precaution	Not provided			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent  8.3 Elec	inage (Plumbing and Sanitation)	MCGM			
7.10 Com  7.11 Curt Build  8.0 Serv  8.1 Ligh  8.2 Vent	er Supply	MCGM			
7.10 Com 7.11 Curt Build 8.0 Serv 8.1 Ligh	etricity	BEST			
7.10 Com 7.11 Curt Build 8.0 Serv	tilation	Natural and artificial, good natural ventilation			
7.10 Com 7.11 Curt Build		Natural and artificial, good natural lighting			
7.10 Com	dings / Landscape	and trees			
	tilage / Unbuilt Space / Out	decorative gate with pillars  Side and front open space concreted, area landscaped with shrubs			
70 Intor	riors (Movable & Immovable)  npound / Fence / Gate	Plastered brick wall with ornamental C.I. railings with C.I.			
7.0 Fins		Access denied	a painted		
	culation	Decorative arches, sarosh bergis at entrance ball motifs  Internally and externally cement plastered an			
7.6 Roo		Partly flat roof with terrace and partly sloping			
	-	shutters			
<ul><li>7.4 Stair</li><li>7.5 Ope</li></ul>	enings	Access denied  Rectangular and arched openings with woode	on frames and glazed		
7.3 Floo	rs	Access denied			

## N. C. Nariealvala Fire Temple



Main entrance pillar with cast iron gate for Nariyalwala Agiary from Mumbai Granth Sangrahalay Road.




Entrance steps to building with lion statue located at the end of the steps.



Front façade of the structure with landscaped front open space.



Arches resting on Corinthian columns, opening enclosed with glazed pannel.



Arched opening and concrete parapet wall, roof levels with louvers.



Archival photograph of Nariyalwala Agiary from Parsi colony book.

#### **Dastoor Wadi Precinct**

Dastoor Wadi is one of the community settlements of the Zoroastrian Community in Mumbai. Just like any other Parsi precinct, it also has an Agiary located outside next to wadi. The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city.

As the part of early suburbanization, this wadi planned in different way, with lots of open space in between structures. The Zoroastrian (Parsi) community of Bombay, mostly resided in colonies / precincts specially built for all the sections of the community, by the Parsi Trusts or Parsi Panchayat. They were located at various places in the island city. The 'Baugs' are sprawling colonies built around large open spaces mainly occupied by upper

The precinct has peculiar Parsi style structures with minimal ornamentation. The facades have features like projecting bands, decorative balcony railings etc. All the buildings are of same scale and proportions and follow the lane in T shape. The buildings of the precincts maintain the skyline and still differ in their styles. Wooden single flight staircase on front façade is highlighted feature. Mangalore tiled sloping roof to all structures. Owners house is segregated from other blocks, located near main entry to plot from Mumbai Marathi Granth Sangrahalay Road near Dadar Central Railway Station.

## Buildings in the Precincts:

- **Dastoor House**
- Block A b.
- Block B c.
- Block C d.
- Block D e.
- Block E f.
- Block F g. Block G
- Block H
- i.
- Block I Block J



Card No.: F/n-2

Ward (Part): F north-VI

CS No.: Not applicable

Plot Area: Not applicable

**B U Area:** Not applicable

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Dastoor Wadi Precinct



1.0	Denomination					
1.1	Name of Premises	Dastoor Wadi Preci	inct			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Mumbai Marathi Gr No. 26)	anth Sangrahalay	Marg (N	laigaon Cross Ro	oad
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Private, Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	This linear precinct important roads is least which faces D	ocated close to the			Dadar
5.2	Architectural Description	The buildings of the precinct in the typology of 'wadis, are of similar scale and proportions, low-rise Vernacular with sloping roofs and with minimal ornamentation on the facade. The buildings are closely spaced with services in between in a very poor condition. One structure consists of two symmetrical blocks with open space around.			and on.	
5.3	Intrinsic	The 'wadi's located in the older parts of the city belong to the typology of community housing. 2 to 4 storey Vernacular buildings informally planned around the shared open space invariably dotted with trees are seen in Dadar, Girgaon and Girangaon mostly resided by Marathis, Gujratis and Parsis. Dastoor wadi is a private owned premises resided by Zoroastrians.				
5.4	Value Classification	A(arc), G(grp), J		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				

		<del>-</del>		
7.3	Floor	Not applicable		
7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	The two buildings have lots of open space in between planted wishrubs and trees. Pathways concreted.		
8.0	Services & Utilities			
8.1	Lighting	Not applicable		
8.2	Ventilation	Not applicable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Not applicable Maintenance level Not applicable		
10.0	Transformation			
10.1	Form	Not applicable		
10.2	Structure	Not applicable		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: Prevailing in England at that time, thus the colony was planned with open spaces. Services of toilets are clubbed together which are in extremely poor and unhygienic condition.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

# Dastoor wadi precinct



Front façade of Block A with wooden staircase.



Side elevation of Block B with wooden staircase.



Front façade of Block B with wooden staircase.



Block B with wooden staircase detail.



Block C with symmetrical facade.



Block D with symmetrical facade.



Block E from north side with lots of open space in front.



Block D from north side with lots of open space in front.



Card No.: F/n-2a

Ward (Part): F north-VI

**CS No.:** 1/3

Plot Area: 913.88 sq.m.

**B U Area:** 1560.9 sq.m.

**Date:** May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: Dastoor House



1.0	Denomination					
1.1	Name of Premises	Dastoor House				
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (i	if any)	Not applicable	
2.0	Access					
2.1	Main	Mumbai Marathi Gr No. 26)	anth Sangralaya N	/larg (Na	aigaon Cross Roa	ad
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Bai Najabai Dinsha	Bai Najabai Dinshaw Dastoor			
3.2	Past	Bai Najabai Dinsha	Bai Najabai Dinshaw Dastoor			
3.3	Status	Privately owned				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Part of the large Da B.R. Ambedkar Ro		ct near t	he Fire Brigade o	on Dr
5.2	Architectural Description	Ornamentation in Vernacular style is best seen in this bungalow. The most prominent feature of this building the external wooden straight flight staircase reaching second floor. The structure is characterized by Mangalore tiled sloping roofs with carved fascia in interesting profile at different levels. Features like wooden posts supporting the balcony, motifs, carved C.I. jali to balconies etc. adorn the façade.				en cia in ts
5.3	Intrinsic	Small Vernacular Parsi settlement called Dastoor Wadi was constructed in Dadar during the early 20 <sup>th</sup> century. Dastoor House is the owner's bungalow and the most prominent structure in Dastoor Wadi.				
5.4	Value Classification	A(arc), B(des), C(se	eh)	Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Random rubble, pla	stered Black Basa	alt stone	plinth	
7.2	Walls	Brick load bearing	walls			
7.3	Floor	Wooden flooring wi	th wooden joists a	nd batte	ns	

0	Documents Available	Notes: Different vernacular styled Parsi structure in old Dastoor Wadi Precinct.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		
12.0	Additional Notes / References /			
11.0	DP Remarks / Perceived Threats	None		
10.2	Articulation & Finishes	No transformation  No transformation		
10.1	Structure	No transformation		
10.1	Form	No transformation		
10.0	Transformation			
9.10	Overall condition	Fair Maintenance level Fair		
9.9	Outbuildings	Good		
9.8	Services	Fair (Recently replastered)		
9.7	Articulation & Finishes	Fair (Plaster chapped off at some places )		
9.6	Roofing	Fair (Mangalore tiles and fascia need repairs)		
9.5	Openings	Fair (Wooden members need maintenance)		
9.3 9.4	Stairs	Good (Well maintained)		
9.2 9.3	Floor	Fair (Sagging observed at some places)		
9.1 9.2	Walls	Good (No settlement or cracks observed)  Good (No dampness or cracks observed)		
	<b>Condition</b> Plinth	Good (No sattlement or cracks observed)		
9.0	Systems)			
8.7	Other (HVAC / BMS / Security	Window air-conditioning units at some places		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
3.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.1	Lighting	Natural and artificial, fair natural lighting		
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Few trees around, unbuilt space not paved		
7.10	Compound / Fence / Gate	Not provided		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.8	Finishes	Internally and externally plastered and painted		
7.7	Articulation	Prominent cornice bands, cast iron railing, decorative wooden fascia, wooden railing.		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
	Openings	Rectangular with wooden frames and glazed shutters		

#### **Dastoor House**



East elevation showing single flight wooden staircase of house from Mumbai Marathi Granth Sangrahalay road.



Front façade of house showing the hierarchy of blocks.



Front façade of house showing the hierarchy of blocks.



Front façade of house showing the hierarchy of blocks.



East elevation showing single flight wooden staircase of house from Mumbai Marathi Granth Sangrahalay road



East elevation showing single flight wooden staircase of house from Mumbai Marathi Granth Sangrahalay road.



Front façade of house showing the hierarchy of blocks.

#### **Madhav Wadi Precinct**

The precinct is in typology of a Wadi, located in busy area near Dadar Central Railway Station. It is the complex of Vernacular longitudinal structures constructed in stone, brick masonry around the courtyard. It got typical entrance gate trough two buildings. One of the G + 1 building has decorative wooden brackets, columns, Mangalore tiled sloping roof. Wadi has introvert planning, all buildings on periphery inside big open space. One of the buildings inside has façade on lower floor have Neo-classical features like pilasters, semi circular arches with prominent key stone and punctured balusters.

The Wadi is a typology in which a group of Chawls abutting the road enclosed an open space invariably dotted with large to be used as community area for multi purpose usage. The entry is through an arch way from road in a busy area. The Madhav wadi is located very closed to the Dadar station. The façade on the main road are invariably highlighted by Neo-classical features to impact a quality of grandeur in spite of the modest facilities provided for the resident like toilet.

#### Buildings in the Precincts:

- a) Main entrance gate Black Basalt stone
- b) Block B
- c) Block A
- d) Block C



Card No.: F/n-3

Ward (Part): F north-VI

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: February, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Madhav Wadi Precinct



	Itel	Wadnay Wadi i recinct		
1.0	Denomination			
1.1	Name of Premises	Madhav Wadi Precinct		
1.2	Earlier Name	Not applicable		
1.3	Built in	Early 20 <sup>th</sup> century Extension Date (if any) Not applicable		
2.0	Access			
2.1	Main	Mumbai Marathi Granth Sangrahalay Marg (Naigaon Cross Road No. 26)		
2.2	Subsidiary	Not applicable		
3.0	Ownership Pattern			
3.1	Present	Not available		
3.2	Past	Not available		
3.3	Status	Tenanted		
4.0	Use			
4.1	Present	Residential, Health care, Commercial		
4.2	Past	Residential, Commercial		
4.3	Usage	Regular residential, health care and commercial use		
5.0	Significance & Value Classificat	ion		
5.1	Townscape (Natural / Manmade)	The Madhav Wadi is located very closed to the Dadar station. An archway from the busy road highlights its entry.		
5.2	Architectural Description	The typology of wadi is characterized by a group of chawls around an open space to be used as community area. The complex is abutting the road, and the façade on the main road highlighted by Neo-classical features to express a quality of grandeur although the infrastructure inside is quite modest. The buildings in this precinct are G + 5 and have a strong vernacular style with ornamentation on the facade. Block B is G + 1 structure with Mangalore tiled sloping roof. Decorative wooden brackets, posts, trellis work, cast iron larges are the main characteristics. Buildings are of similar scale and proportion.		
5.3	Intrinsic	Earlier occupied by working class employed in the nearby mills, is now predominately occupied by a middle class.		
5.4	Value Classification	A(arc), G(grp) Recommended Grade		
6.0	Topography	·		
6.1	Floors	Not applicable		
7.0	Construction			
7.1	Plinth	Not applicable		
7.2	Walls	Not applicable		
7.3	Floor	Not applicable		

7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Buildings are on perip partly concreted.	hery of wadi and have	open space in between
8.0	Services & Utilities			
8.1	Lighting	Not applicable		
8.2	Ventilation	Not applicable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Not applicable		_
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	Not applicable		
10.2	Structure	Not applicable		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: Occupied earlier by working class people (working in Mills around it), now it is predominately a middle class people. The Wadi is a typology in which a group of chawls abutting the road enclosed an open space to be used as community area for multi purpose usage.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

## **Madhav Wadi Precinct**



Corner detail of block B showing decorative facia, cast iron railing and wooden post.



Main entrance gate to Madhav wadi through two buildings.




Detail of balcony in block A supported with decorative concrete bracket.



Detail of concrete railing with pillar.



Side elevation of block A.



Decorative front façade of block A.



Block B, chawl like structure with decorative common passage on first floor.



Corner of Block B showing bressed wooden post supporting sloping roof.

## **Madhav Wadi Precinct**



Corner of Block A highlighted in coarsed black basalt masonary.



Window with decorative pediment around it and ornamented concrete railing.



Gargoyles at the corner of cornice band on first floor.



Decorative concrete bracket supporting the first floor balcony.



Corinthian column supporting arched window opening. Pediments with keystone in stucco work.



View of block B showing single flight staircase.

## Dr. Babasaheb Ambedkar Road front

This street front starts at the junction of Mumbai Marathi Granth Sangrahalay and Dr. Babasaheb Ambedkar Road (major north south road in Mumbai). The construction started in 1930's and completed around 1940's. Street front has a vernacular style with decorative motifs, semi circular arched openings, part sloping roof, decorative concrete large, brackets and posts. Street front starts with ornamented Sai Kunj building in Black basalt stone. The building manly used for commercial purpose cause located on main road on south of Khodadad Circle, all buildings are of similar scale and proportions.

The buildings included in this Road front:

- 1. Irani Building
- 2. Suleman Building
- 3. Kavarana Building
- 4. Sai Kunj



Card No.: F/n-4

Ward (Part): F north-VI

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: January 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Dr. Babasaheb

Ambedkar Road front



1.0	Denomination					
1.1	Name of Premises	Dr. Babasaheb Am Dadar)	nbedkar Road front	(Opposi	te Asiad bus der	oot,
1.2	Earlier Name	Not applicable				
1.3	Built in	Late 1930s and early 1940s	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Dr. Babasaheb Am	nbedkar Road			
2.2	Subsidiary	Not applicable	Not applicable			
3.0	Ownership Pattern					
3.1	Present	Not applicable	Not applicable			
3.2	Past	Not applicable	Not applicable			
3.3	Status	Not applicable	Not applicable			
4.0	Use					
4.1	Present	Not applicable				
4.2	Past	Not applicable				
4.3	Usage	Not applicable				
5.0	Significance & Value Classificatio	n				
5.1	Townscape (Natural / Manmade)	Cape (Natural / Manmade)  The row of buildings with similar scale and proportions, starting at the junction of Mumbai Marathi Granth Sangrahalay and Dr.  Babasaheb Ambedkar Road on the west side, south of Khodadad circle ( Dadar T T Circle) .			•	
5.2	Architectural Description	features. The corn- curved balconies a street front has a v circular arched ope	The buildings in this front designed in similar way with varying features. The corner buildings have special accents in the form of curved balconies and rounded corner pavilions on the terrace; The street front has a vernacular style with decorative motifs, semi circular arched openings, part sloping roof, decorative concrete large, brackets, posts. It starts with ornamental Sai Kunj building in			
5.3	Intrinsic	for commercial pur	Although earlier used for residential purpose, are now mainly used for commercial purpose since it is close to the commercially thriving Khodad circle.			used
5.4	Value Classification	A(arc), E, I(sce)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction	-				
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
Adarka	r Associates, Architects	17			Ward	f F north

7.3	Floor	Not applicable		
7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable		
8.0	Services & Utilities			
8.1	Lighting	Not applicable		
8.2	Ventilation	Not applicable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	Not applicable		
10.2	Structure	Not applicable		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Affected by shopline or	n proposed Developm	ent Plan. (D.P.)
12.0	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eiche	er City Maps – Mumbai.

# Dr. Babasaheb Ambedkar Road front ( Opposite Asiad bus depot, Dadar )



Street front including Kavrana Building, Irani Building, Suleman Building.



Arched opening to common passage on first floor on Suleman Building.



Detail of concrete jali in Irani Building.



Detail of decorative balcony in Kavrana Building.



Card No.: F/n-4a

Ward (Part): F north-VI

**CS No.:** 795 / 10

Plot Area: 615.39 sq.m.

**B U Area:** 1500 sq.m.

**Date:** May, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: Sai Kunj



1.0	Denomination					
1.1	Name of Premises	Sai Kunj				
1.2	Earlier Name	Not applicable				
1.3	Built in	Late 1930-35	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Dr. Babasaheb Am	bedkar Road, Dada	ır		
2.2	Subsidiary	Mumbai Marathi Gr No. 26)	ranth Sangralaya M	arg (Na	aigaon Cross Roa	ad
3.0	Ownership Pattern					
3.1	Present	Not available	Not available			
3.2	Past	Not available	Not available			
3.3	Status	Tenanted	Tenanted			
4.0	Use					
4.1	Present	Residential, Comm	ercial			
4.2	Past	Residential, Comm	ercial			
4.3	Usage	Regular residential	and commercial us	е		
5.0	Significance & Value Classificatio	n				
5.1	Townscape (Natural / Manmade)		Located on a busy corner plot on Dr. Babasaheb Ambedkar Road, North-South arterial road and Mumbai Marathi Granth Sangralaya			
5.2	Architectural Description	junction. The façad second floors, part semicircular archec openings on the se openings. Features	Corner building following the road profile along the curve of the junction. The façade exhibits a continuous corridor on first and second floors, part of it now enclosed. The corridor is treated with semicircular arched openings on first floor and rectangular openings on the second floor, both divided in group of three openings. Features like husks below some windows, continuous band around the arched openings, cornices, etc. give character to otherwise plain facade.			
5.3	Intrinsic	One of the many buildings with ground floor commercial and upper floors with residential user. One of the buildings in street front on Dr. Babasaheb Ambedkar Road.				
5.4	Value Classification	A(arc), G(grp)		Recom	nmended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered Basalt sto	one coursed mason	ry plint	h	
7.2	Walls	Brick load bearing I	brick walls			
7.3	Floor	Wooden flooring wi	th wooden joists an	d batte	ns	
	i .					

7.4	Stairs	Wooden single flight staircase		
7.5	Openings	Rectangular with wooden frames and glazed shutter		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Prominent cornice bands and wooden brackets		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, poor natural lighting		
8.2	Ventilation	Natural and artificial, poor natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Fair (Cracks observed at some places)		
9.2	Walls	Fair (dampness and cracks observed at some places)		
9.3	Floor	Fair (Sagging observed at some places)		
9.4	Stairs	Fair (Wooden members need maintenance)		
9.5	Openings	Fair (Broken window panes need replacement, some windows replaced by aluminium windows)		
9.6	Roofing	Fair (Leakage to be repaired)		
9.7	Articulation & Finishes	Fair (Recently replastered)		
9.8	Services	Poor		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation	<u> </u>		
10.1	Form	Box grills & sliding windows added at many places.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot affected by shopline on proposed Development Plan. (D.P.)		
12.0	Additional Notes / References / Documents Available	Notes: Corner building which is also the starting building of street front.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



View of Sai Kunj from junction of Dr. Babasaheb Ambedkar road and Marathi Sahitya Sangrahalay road.



Front façade of Sai Kunj from Dr. Babasaheb Aambedkar road.



Detail of arched window from front façade.



Detail of motif below window.



Card No.: F/n-5

Ward (Part): F north-IV

**CS No.:** 99 / 10

Plot Area: 408.86 sq.m.

**B U Area:** 1146.9 sq.m.

Date: April, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 541, Gajjar Niwas



1.0	Denomination							
1.1	Name of Premises	541, Gajjar Niwas	541, Gajjar Niwas					
1.2	Earlier Name	Not applicable						
1.3	Built in	1930's	Extension Date (if	fany)	Not applicable			
2.0	Access							
2.1	Main	Dr. Babasaheb Am	bedkar Road					
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Trustees for Improv	rement of City of Bo	ombay,	Private			
3.2	Past	Trustees for Improv	ement of City of Bo	ombay,	Private			
3.3	Status	Tenanted						
4.0	Use							
4.1	Present	Residential						
4.2	Past	Residential						
4.3	Usage	Regular residential	use					
5.0	Significance & Value Classification	1						
5.1	Townscape (Natural / Manmade)	Rectangular plot facing Dr. Babasaheb Ambedkar Road, near the Maheshwari Udyan node.						
5.2	Architectural Description	G + 2 modest building, load bearing walls and R.C.C floor. Balconies supported on wooden and concrete brackets and its roof is supported on wooden posts. The geometrical pattern of the wooden railing along with the balconies gives the building its Vernacular architectural characteristic. It forms symmetrical façade with decorative pediments on the terrace parapet.						
5.3	Intrinsic	This is a modest tell Improvement of City phase of the city.						
5.4	Value Classification	B(per)		Recom	mended Grade	III		
6.0	Topography							
6.1	Floors	G + 2						
7.0	Construction							
7.1	Plinth	Coursed Black Bas	alt stone plinth					
7.2	Walls	Load bearing brick	walls					
7.3	Floor	R.C.C. slab flooring	J					
7.4	Stairs	Wooden dog legged	d staircase with hig	hly deco	prative newel po	st		
7.5	Openings	Rectangular openin	ngs with wooden fra	ames an	d glazed shutter	r		

7.6	Roofing	Flat roof with partly sloping roof on balconies				
7.7	Articulation	Highly decorative with wooden railing, ornamental posts in wood. Pediments below windows. Cornice bands running at floor level.				
7.8	Finishes	Internally and externally cement plastered and painted				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.10	Compound / Fence / Gate	Plastered brick wall with cast iron gate in front of structure				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Trees within the compound. Low height compound wall in front, front open space paved with coursed Black Basalt stone.				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural lighting				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging observed)				
9.4	Stairs	Good (Well maintained)				
9.5	Openings	Good (Wooden members in sound state)				
9.6	Roofing	Good (No sagging or leakage observed)				
9.7	Articulation & Finishes	Good (Need to be re-paint, cracks in brackets )				
9.8	Services	Fair				
9.9	Outbuildings	Good				
9.10	Overall condition	Good Maintenance level Good				
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	None				
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				



Front façade from Dr. Babasaheb Ambedkar road.



Details of balconies showing wooden railing.



Card No.: F/n-6

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\ B. Ref.: N. Maheshwari Udyan



1.0	Denomination							
1.1	Name of Premises	B. N. Maheshwari	Udyan					
1.2	Earlier Name	Not applicable						
1.3	Built in	Mid 20 <sup>th</sup> century	Mid 20 <sup>th</sup> century Extension Date (if any) Not applicable					
2.0	Access							
2.1	Main	Dr. Babasaheb Am	bedkar Road					
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Not available						
3.2	Past	Not available						
3.3	Status	Not available						
4.0	Use							
4.1	Present	Recreational, Publi	ic					
4.2	Past	Recreational, Publi	ic					
4.3	Usage	Regular public use						
5.0	Significance & Value Classification	on						
5.1	Townscape (Natural / Manmade)	seven roads. Dr. B	A landmark traffic island on a strategic node of circular junction of seven roads. Dr. Babasaheb Ambedkar Road, Bhandarkar Road, Bhau Daji Road and H Adenwala Road are some of the prominent roads.					
5.2	Architectural Description	Open garden locate intersection. It is we Pathways paved in divisions covered v	ooded with some la	arge tree	s and shrubs.	r of		
5.3	Intrinsic	Part of the develop during the suburba "King's Circle"						
5.4	Value Classification	C(seh), I(sce), J		Recom	mended Grade	II A		
6.0	Topography							
6.1	Floors	Not applicable						
7.0	Construction							
7.1	Plinth	Not applicable						
7.2	Walls	Not applicable						
7.2 7.3	Walls Floor	Not applicable  Not applicable						

7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Low height peripheral	concrete wall with mile	steel fencing
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Ground covered with trees.	lawn and different kinds	s of shrubs and large
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, o	good natural lighting	
8.2	Ventilation	Natural and artificial,	excellent natural ventila	ation
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	мсөм		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Good
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Plot demarcated as re Plan (D.P).	ecreational ground on p	roposed Development
12.0	Additional Notes / References / Documents Available	Documents: C.S. She	ets, D.P. Sheets, Eiche	er City Maps-Mumbai

# Maheshwari Udyan



View of Maheshwari Udyan from Bhau Daji Road.



Main entrance for Maheshwari Udyan from Dr. Babasaheb Ambedkar Road



View of Maheshwari Udyan from Bhandarkar Road.



Card No.: F/n-7

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Sharada Sadan



1.0	Denomination						
1.1	Name of Premises	Sharada Sadan					
1.2	Earlier Name	Not applicable					
1.3	Built in	1925-35	Extension Date (if	f any)	1960s		
2.0	Access						
2.1	Main	Gyanjivandas Road	t				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Not available					
3.2	Past	Not available					
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential	use				
5.0	Significance & Value Classification	า					
5.1	Townscape (Natural / Manmade)	Overlooking Gyanjivandas Road leading to Dadar Station., near the Khodadad circle, it is surrounded by buildings of similar scale.					
5.2	Architectural Description	An exquisitely ornamented well composed building in Neo Classical style with a judicious blending of vernacular balconies. Well-composed front façade. Ground and first floor have decorative arched opening supported on Corinthian columns. Balconies with wooden railing on both side of facade maintain the symmetry.					
5.3	Intrinsic	Built on the plot wh west of Dr. Babasa started in1920's.					
5.4	Value Classification	A(arc), B(des), C(se	eh), G(grp)	Recom	nmended Grade	Ш	
6.0	Topography	•					
6.1	Floors	G + 3 (Top floor ad	ded later)				
7.0	Construction						
7.1	Plinth	Malad stone course	ed masonry				
7.2	Walls	Load bearing brick	walls				
7.3	Floor	R.C.C floor					
7.4	Stairs	Open well staircase	e with winders				
7.5	Openings	Semicircular archeo		pening	with wooden fra	mes	

7.6	Roofing	Flat roof terrace				
7.7	Articulation	Decorative terrace parapet wall with RCC balustrades, pediment on corner façade with date of construction encrypted. Decorative husk on corner façade. Pilaster columns on corner and architraves cornice band on each floor.				
7.8	Finishes	Internally and externally cement plastered and painted				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.10	Compound / Fence / Gate	Brick compound wall with cast iron fence and gate				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unbuilt space paved with Shahabad tiles and few trees around the building out building include garage				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, fair natural lighting				
8.2	Ventilation	Natural and artificial, fair natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Windows air-conditioning units provided some places				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging observed)				
9.4	Stairs	Good (Well maintained)				
9.5	Openings	Good (wooden members in sound state)				
9.6	Roofing	Good (No sagging or leakage observed)				
9.7	Articulation & Finishes	Good (Well maintained)				
9.8	Services	Fair (Some pipes need repairs)				
9.9	Outbuildings	Good				
9.10	Overall condition	Fair Maintenance level Fair				
10.0	Transformation					
10.1	Form	Sliding windows added later.				
10.2	Structure	Top floor added in 1960s				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	None				
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai. Needs to be conserved good façade value.				



Front façade of Sharada Sadan from Gyanjivandas road.



Detail of front façade showing semicircular arches resting on circular columns, stucco work at ends and stained glass panel.



Detail of balcony showing cast iron railing fixed in between wooden posts.



Detail of semicircular arched window opening.



Card No.: F/n-8

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\Ref.: 41, Krishna Niwas



		,						
1.0	Denomination							
1.1	Name of Premises	41, Krishna Niwas						
1.2	Earlier Name	Not applicable						
1.3	Built in	1925-35	Extension Date (i	f any)	Not applicable			
2.0	Access							
2.1	Main	Sir Bhalchandra M	arg					
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Not available						
3.2	Past	Not available						
3.3	Status	Tenanted						
4.0	Use							
4.1	Present	Residential						
4.2	Past	Residential						
4.3	Usage	Regular residential	use					
5.0	Significance & Value Classification	on						
5.1	Townscape (Natural / Manmade)	A small plot on Sir colony.	A small plot on Sir Bhalchandra Marg, the major road of Hindu colony.					
5.2	Architectural Description	A Vernacular style façade. The project CI railings and the Chajjas above the brackets.	ting floor bands ha stained glass venti	ving mo lators ar	ldings, balconies e the highlights.	s with		
5.3	Intrinsic	The Hindu Commu west of Dr. Babasa Hindu population s	heb Ambedkar Ro	ad. Thus	s the area consis	sts of		
5.4	Value Classification	A(arc), C(seh), G(g	Jub)	Recom	nmended Grade	Ш		
6.0	Topography							
6.1	Floors	G + 2						
7.0	Construction							
7.1	Plinth	Dressed stone plin	th					
7.2	Walls	Load bearing brick	walls					
7.3	Floor	R.C.C. slab flooring	9					
7.4	Stairs	Wooden dog legge	d staircase with sir	nple bal	usters			
7.5	Openings	Rectangular woode						

ofing	Partly flat roof and part wooden trusses	tly sloping roof with Ma	ngalore tiles and		
iculation	Floor band projecting v stainglass ventilators	Floor band projecting with moldings. Projecting balconies with stainglass ventilators			
ishes	Internally and external	ly plastered and painte	d		
eriors (Movable & Immovable)	Interiors, not of heritag	e value.			
mpound / Fence / Gate	Stone and brick compo	ound wall			
rtilage / Unbuilt Space / Out ildings / Landscape	Central open space be	etween two buildings			
rvices & Utilities					
hting	Natural and artificial, g	ood natural light			
ntilation	Natural and artificial, g	ood natural ventilation			
ectricity	BEST				
ater Supply	MCGM				
ainage (Plumbing and Sanitation)	MCGM				
e precaution	Not provided				
ner (HVAC / BMS / Security stems)	Not provided				
ndition					
nth	Fair (Cracks observed at some places)				
alls	Fair (Dampness obser	ved at few places)			
or	Fair (Sagging observe	d at some places)			
airs	Fair (Wooden member	s need maintenance)			
enings	Fair (Window panes ne	eed repairs)			
ofing	Fair (Leakage observe	d at some places)			
iculation & Finishes	Fair (Plastered attack I	by moss near toilet)			
rvices	Fair (Leakage of some	toilet pipes)			
tbuildings	Fair				
erall condition	Fair	Maintenance level	Fair		
ansformation					
rm	No transformation				
ucture	No transformation				
iculation & Finishes	No transformation				
Remarks / Perceived Threats	None				
ditional Notes / References / cuments Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				
		wide Kingsway (Now E principal access lit by 6 1926. Documents: C.S. Shee	wide Kingsway (Now Dr. Babasaheb Ambedk principal access lit by electric lamps. The plot 1926.		



Front façade of Krishna Niwas from Sir Bhalchandra road behind dense vegetation.



Detail of balconies on first and second floor forming symmetrical façade.



Detail of small balcony on south corner of the structure.



Front balcony supported with decorative bracket with cast iron railing fixed in wooden post supporting stained glass pannel.



Entrance gate pillar with marble plaque showing date of construction.



Slopping roof of staircase block.



Card No.: F/n-9

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.:

Mumbai LohMarg Police Karmachari Sahakari Patpedhi Ltd.



1.0	Denomination							
1.1	Name of Premises	Mumbai Lohmarg Police Karmachari Sahakari Patpedhi Ltd.						
1.2	Earlier Name	Not applicable						
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable			
2.0	Access							
2.1	Main	Sir Bhalchandra Ma	arg					
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Government						
3.2	Past	Government						
3.3	Status	Government owned	d					
4.0	Use							
4.1	Present	Residential quarters	s					
4.2	Past	Residential quarters	S					
4.3	Usage	Regular residential	use					
5.0	Significance & Value Classification	1						
5.1	Townscape (Natural / Manmade)	Located on a large Marg, a major road						
5.2	Architectural Description	Simple low-rise ver bays with sloping re central playground. the buildings are of Bhalchandra Marg	oofs. located at the The quarters are n similar scale, exce	edge of neant fo pt for th	f the plot with a land for the police staff for a structure facin	arge . All		
5.3	Intrinsic	In the Hindu colony other buildings belo				ny		
5.4	Value Classification	A(arc), C(seh)		Recom	mended Grade	IIΒ		
6.0	Topography							
6.1	Floors	G + 1						
7.0	Construction							
7.1	Plinth	Plastered and paint	ed masonry plinth					
7.2	Walls	Load bearing brick	walls					
7.3	Floor	R.C.C. slab flooring	]					
7.4	Stairs	R.C.C. dog legged	staircase					
7.5	Openings	Rectangular with w	ooden frames and	glazed	shutters			

		1926. Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in				
11.0	DP Remarks / Perceived Threats	None				
10.3	Articulation & Finishes	No transformation				
10.2	Structure	No transformation				
10.1	Form	M.S. chajjas added at some places.				
10.0	Transformation					
9.10	Overall condition	Fair Maintenance level Fair				
9.9	Outbuildings	Fair				
9.8	Services	Fair				
9.7	Articulation & Finishes	Good (Some pipes need repairs)				
9.6	Roofing	Fair (Mangalore tiles and fascia need repairs)				
9.5	Openings	Fair (Some windows panes broken)				
9.4	Stairs	Good (Well maintained)				
9.3	Floor	Fair (Sagging observed at some places)				
9.1	Walls	Fair (Cracks observed at some places)				
9.1	Plinth	Good (No settlement or cracks observed)				
9.0	Condition					
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units provided at some places				
8.6	Fire precaution	Not provided				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.4	Water Supply	MCGM				
8.3	Electricity	BEST				
8.2	Ventilation	Natural and artificial, fair natural ventilation				
8.1	Lighting	Natural and artificial, fair natural lighting				
8.0	Services & Utilities					
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Open space paved with Shahabad tiles				
7.10	Compound / Fence / Gate	Stone compound wall				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.8	Finishes	Internally and externally plastered and painted				
7.7	Articulation	Not much articulation on facade				
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses	3			

# Mumbai Lohamarg Police Karmachari Sahakari Patpedhi



Front view of building from Sir Bhalchandra road.



View of south side of building along with main entrance.



Detail of recessed balcony on first floor with wooden railing.



Card No.: F/n-10

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

**B U Area:** Not available

Date: April, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Police Ground and

Quarters, Sir Bhalchandra Marg



1.0	Denomination					
1.1	Name of Premises	Police Ground and Q	Police Ground and Quarters, Sir Bhalchandra Marg			
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (if	any) Not applicable	)	
2.0	Access					
2.1	Main	Sir Bhalchandra Mar	g			
2.2	Subsidiary	Tilak Bridge				
3.0	Ownership Pattern					
3.1	Present	Government				
3.2	Past	Government				
3.3	Status	Government owned				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Police Camp for train	ees			
4.3	Usage	Regular residential u	se			
5.0	Significance & Value Classification	on				
5.1	Townscape (Natural / Manmade)	Located on the corne colony.	er plot of Sir Bhalc	handra Marg in the hid	lu	
5.2	Architectural Description	identically planned w	ith an open space	of around ten building: . The buildings have n s with plain timber raili	nodest	
5.3	Intrinsic	The main characteris		x is the open space us department	ed for	
5.4	Value Classification	J		Recommended Grade	III	
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered stone plinth	า			
7.2	Walls	Load bearing brick w	alls			
7.3	Floor	RCC slab flooring	RCC slab flooring			
7.4	Stairs	RCC staircase with w	RCC staircase with wooden cladding			
7.5	Openings	Rectangular windows	s with wooden fran	mes and glazed shutte	rs	
7.6	Roofing	Flat roof terrace				

7.7	Articulation	Projecting floor bands and window sills				
7.8	Finishes	, ,	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Not applicable	ny comoni piaotorea an	ia paintou		
7.10	Compound / Fence / Gate	Brick and stone comp	ound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	· ·	training and parade gro	ound		
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, g	good natural lighting			
8.2	Ventilation	Natural and artificial, o	good natural ventilation			
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places				
9.0	Condition					
9.1	Plinth	Good (No settlement	or cracks observed)			
9.2	Walls	Good (No dampness	or cracks observed)			
9.3	Floor	Good (No sagging ob	served)			
9.4	Stairs	Good (No sagging ob	served)			
9.5	Openings	Good (Well maintaine	d)			
9.6	Roofing	Good (No deflection o	r leakage observed)			
9.7	Articulation & Finishes	Fair (Re-plastering red	quired at some places)			
9.8	Services	Fair (Some pipes nee	d repairs)			
9.9	Outbuildings	Good				
9.10	Overall condition	Good	Maintenance level	Good		
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	Open ground in plot demarcated for recreational ground on proposed Development Plan (D.P).				
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				

## Police Ground and Quarters, Sir Bhalchandra Marg



Open parade ground with low height compound wall.



Rare side of Police Quarters block from Lakhamji Nappu road.



Front open space of Police Quarters Block.



Unused open space between Tilak road and Police Quarters block.



Cluster of Police Quarters block with lot of open spaces.

As part as early suburbanization, 22 acres of land on west of Vincent Road (now Dr. B. Ambedkar Road, a major North-South artery), was allotted by BIT around 1920 to the people from Hindu community specially Marathi speaking middle class. The development commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.

After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.

The precinct is a complex of Vernacular style structures often blended with Indo Sarscenic and Haveli style features. The facades are characterized with interesting balconies with wooden railings and often covered with sloping roofs. All the buildings are of similar scale and proportions and follow the lane in T shape. The buildings of the precincts maintain the skyline and yet differ in their appearance.

The development is in grid iron pattern around plane open spaces. Each building is independently located on the plots, the plots as well dividing internal roads are lined with trees.

The buildings of the precinct are low-rise (G + 2). Each building is located on individual plot with trees around it. All roads have trees on both sides. Open space, grounds and gardens inside precinct. Vaidya garden, Dadakar garden and IES School are part of it.

Many buildings are of same scale and proportions and follow the lane in rectangular plot. However some private plots are developed haphazardly as G+ 6 buildings using thy TDR. This has ruined the scale of the colony .Yet plenty of open spaces, gardens, planned roads lined with trees characterize the colony.

#### Buildings in the Precincts:

- 1. 171, Sunoo Lodge
- 2. 55-57, Neelam Building
- 3. 58, Govind Sadan
- 4. 70, Ramchandra Bhuvan
- 5. 67, Radhakrishna Niwas
- 6. 92, Tulsi Bhavan
- 7. 103, Shankar Niketan
- 8. 111, Laxmi Niketan
- 9. 110, Govind Sadan
- 10. 122, Bang Bhavan
- 11. 119, Abhyankar Niwas
- 12. 100, Vishnu Sadan
- 13. 129, Raj Griha
- 14. 133, Gujrathi Bal Mandir and Primary School



Card No.: F/n-11

Ward (Part): F north-IV & VI

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Hindu Colony Precinct



1.0	Denomination						
1.1	Name of Premises	Hindu Colony Pred	Hindu Colony Precinct				
1.2	Earlier Name	Not applicable	Not applicable				
1.3	Built in	1920's	Extension Date (if	f any)	Not applicable		
2.0	Access						
2.1	Main		Dr. Babasaheb Amb Nappu Marg, Tilak		oad, Sir Bhalcha	andra	
2.2	Subsidiary	Hindu colony Road	d no 1 to 6				
3.0	Ownership Pattern						
3.1	Present	Trustees for Impro	vement City of Bom	nbay, Pr	ivate, Tenanted		
3.2	Past	Trustees for Impro	vement City of Bom	nbay, Pri	vate, Tenanted		
3.3	Status	Trust, Private, Ten	anted				
4.0	Use						
4.1	Present	Residential, Comm	nercial, Educational	, Religio	us		
4.2	Past	Residential, Comm	nercial, Educational	, Religio	us		
4.3	Usage	Regular residentia	l, commercial, educ	ational a	and religious		
5.0	Significance & Value Classification	n					
5.1	Townscape (Natural / Manmade)		n pattern, the building of open spaces, garize the colony.				
5.2	Architectural Description	modest ornamenta interesting balconic sloping roofs. Each	The buildings of the precinct are low rise (G + 2/3) Vernacular with modest ornamentation. The facades are characterized with interesting balconies with wooden railings and often covered with sloping roofs. Each building is located on individual plot with trees around it. Vaidya Garden, Dadkar garden and IES School provide the infrastructure				
5.3	Intrinsic	As part as early suburbanization, 22 acres of land on west of Vincent Road (now Dr. B. Ambedkar Road, a major North-South artery), was allotted by BIT around 1920 to the people from Hindu community specially Marathi speaking middle class. The development commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.					
5.4	Value Classification	A(arc), G(grp)		Recom	mended Grade	Ш	
6.0	Topography						
6.1	Floors	Not applicable					
7.0	Construction						
7.1	Plinth	Not applicable					
7.2	Walls	Not applicable					

7.3	Floor	Not applicable			
7.4	Stairs	Not applicable			
7.5	Openings	Not applicable			
7.6	Roofing	Not applicable			
7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Not applicable			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	concreted. Little shrub	orm open space around s or big trees around b use for servant behind i	uildings. Some	
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Not applicable			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Not applicable	Maintenance level	Not applicable	
10.0	Transformation				
10.1	Form	Not applicable			
10.2	Structure	Not applicable			
10.3	Articulation & Finishes	Not applicable			
11.0	DP Remarks / Perceived Threats	Plots fall under a Residential Zone on proposed Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

### **Hindu Colony**



Ornamented front façade of Vartak Gruh



Ornamented front façade of Sathe Building



View of Vasant Bhuvan from Lakhamshi Nappu Road




Corner view of Mahalakshmi Building



Façade of Foencia Building



Ornamented façade of Shradha Niwas



Ornamented façade of Sitaram Bhuvan



Ornamented façade of Sharada niwas



Ornamented façade of Laxmi Niketan



Ornamented façade Savitri Niwas



Detail of motifs on top of staircase block





Detail of cast iron railing to balcony



Detail of stain glass panel in Sitaram Bhuvan



Detail of balcony of Dharm Sadan



Detail of balconies of Dharm Sadan and stained glass panels



Detail of entrance to Krishna Bhuvan



Detail of wooden staircase with decorative navel post



Detail of curved balconies Shikant Lodge.



Card No.: F/n-11a

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 171, Sunoo Lodge



1.0	Denomination				
1.1	Name of Premises	171, Sunoo Lodge			
1.2	Earlier Name	Not applicable			
1.3	Built in	1925-35	Extension Date (if	f any)	Not applicable
2.0	Access				
2.1	Main	Tilak Road			
2.2	Subsidiary	Sir Bhalchandra Ma	arg		
3.0	Ownership Pattern				
3.1	Present	Not available			
3.2	Past	Not available			
3.3	Status	Tenanted			
4.0	Use				
4.1	Present	Residential, Commercial			
4.2	Past	Residential, Commercial			
4.3	Usage	Regular residential	and commercial us	se	
5.0	Significance & Value Classification	l			
5.1	Townscape (Natural / Manmade)	Part of the Hindu Colony precinct, this building faces the junction of Lokmanya Tilak Road and Sir Bhalchandra Marg, two major roads of Hindu colony.			
5.2	Architectural Description	An interesting blend of styles, The corner of building as hexagonal tower displays Indo Sarascenic where as the decorative arched openings are supported on Corinthian columns. Vernacular style balconies with wooden railing on both sides of facade maintain the symmetry. Decorative cornice band at second floor level.			
5.3	Intrinsic	As part as early suburbanization, 22 acres of land on west of Vincent Road (now Dr. B. Ambedkar Road, a major North-South arterial), was allotted by BIT around 1920 to the people from Hindu community specially Marathi speaking middle class. The development commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.			
5.4	Value Classification	A(arc), C(seh), G(g	rp)	Recom	mended Grade III
6.0	Topography				•
6.1	Floors	G + 2			
7.0	Construction				
7.1	Plinth	Dressed Black Basalt stone coursed masonry			
7.2	Walls	Load bearing brick	walls		
7.3	Floor	R.C.C. slab flooring	J		
	-				

7.4	Stairs	Dog legged R.C.C. staircase				
7.5	Openings	Rectangular opening with wooden frames and glazed shutters				
7.6	Roofing	Flat roof terrace				
7.7	Articulation	Cornice band at each floor level, architraves, Moorish arch, cast iron large to balcony				
7.8	Finishes	Internally and externally cement plastered and painted				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.10	Compound / Fence / Gate	Not provided				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not provided				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural light				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging observed)				
9.4	Stairs	Good (Well maintained)				
9.5	Openings	Good (Wooden panes wooden members in sound state)				
9.6	Roofing	Fair (No leakage or deflection observed)				
9.7	Articulation & Finishes	Fair (Plastered chipped off at some places)				
9.8	Services	Fair (Some pipes need repairs)				
9.9	Outbuildings	Fair				
9.10	Overall condition	Fair Maintenance level Fair				
10.0	Transformation					
10.1	Form	Sliding windows added, hoardings added on ground floor.				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	None				
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				

#### 171, Sunoo Lodge



Wes side elevation of Sunoo Lodge from Sir Bhalchandra road.



View of Sunoo Lodge from junction of sir Bhalchandra road and Tilak road.



Octagonal block on top at corner of building with decorative features.



South side elevation showing balconies of Sunoo Lodge from Tilak road



South east corner of building in octagonal shape highlighted with decorative bands



Detail of balcony on south side showing decorative railing, posts supporting sloping roof



Card No.: F/n-11b

Ward (Part): F north-IV

**CS No.:** 99/10

Plot Area: 408.86 sq.m.

**B U Area:** 1146.9 sq.m.

Date: April 25, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 55-57, Neelam Building



1.0	Denomination					
1.1	Name of Premises	55-57, Neelam Buil	55-57, Neelam Building			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1930's	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Hindu Colony Road	no. 1			
2.2	Subsidiary	Lakhamshi Napoo I	Road			
3.0	Ownership Pattern					
3.1	Present	Trustees for improv	ement of city of Bo	mbay, F	Private	
3.2	Past	Trustees for improv	ement of city of Bo	mbay, F	Private	
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Rectangular plot fac Colony Precinct.	cing Hindu Colony	Road no	o. 1. Part of Hind	lu
5.2	Architectural Description	G + 2 structure with wooden work and s facade.				ative
5.3	Intrinsic	The Hindu Colony of trusts or private own Island City.				ent
5.4	Value Classification	A(arc), B(des), E		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G+2				
7.0	Construction					
7.1	Plinth	Coursed Black Basalt stone plinth				
7.2	Walls	Load bearing brick walls				
7.3	Floor	R.C.C. slab flooring				
7.4	Stairs	Wooden dog legged staircase with highly decorative newel post				st
7.5	Openings	Rectangular openin	gs with wooden fra	ame and	d glazed shutter	
7.6	Roofing	Flat roof with partly	sloping roof on bal	Iconies		

7.7	1				
7.7	Articulation	Highly decorative with wooden railing, ornamental posts and Moorish arches in wood. Stained glass panels on balcony.			
7.8	Finishes	Internally and externa	lly cement plastered an	d painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage	ge value		
7.10	Compound / Fence / Gate	Plastered brick wall w	ith cast iron gate on sid	e of structure	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape		oound. No compound w rsed Black Basalt stone		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial,	good natural lighting		
8.2	Ventilation	Natural and artificial,	good natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	мсөм			
8.5	Drainage (Plumbing and Sanitation)	мсөм			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement	or cracks observed)		
9.2	Walls	Good (No dampness	or cracks observed)		
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good (Well maintaine	d)		
9.5	Openings	Good (Wooden panes	s wooden members in s	ound state)	
9.6	Roofing	Fair (No leakage or de	eflection observed)		
9.7	Articulation & Finishes	Fair (Plastered chippe	ed off at some places)		
9.8	Services	Fair (Some pipes nee	d repairs)		
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### **Neelam Building**



View of Neelam Building from V. P. Pradhan building.



View of Neelam Building from Lakhamshi Nappu road.



Decorative balcony on first & second floor supported with brackets, stained glass pannels on first floor.



Detail of wooden railing pitched between wooden post supporting slopping roof.



Card No.: F/n-11c

Ward (Part): F north-IV

**CS No.:** 109/10

Plot Area: 575.25 sq.m.

**B U Area:** 900 sq.m.

Date: April, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\Ref.: 58, Govind Sadan



1.0	Denomination						
1.1	Name of Premises	58, Govind Sadan	58, Govind Sadan				
1.2	Earlier Name	Not applicable	Not applicable				
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable		
2.0	Access	·					
2.1	Main	Hindu Colony Cros	s Road no. 1				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Trustees for improve Bhide	vement of city of Bo	mbay, l	Mahadeo Govino	t	
3.2	Past	Waman Govind Bh Bhide, Ganesh Gov	ide, Jaikurerbai Jetl vind Bhide	halal G	andhi, Vishnu Go	ovind	
3.3	Status	Private					
4.0	Use						
4.1	Present	Residential, Comm	ercial				
4.2	Past	Residential, Comm	ercial				
4.3	Usage	Regular residential	and commercial us	se			
5.0	Significance & Value Classificatio	n					
5.1	Townscape (Natural / Manmade)		Located on a plot facing Cross Road no. 1, one of the minor roads in Hindu colony. Part of Hindu Colony Precinct.				
5.2	Architectural Description	Vernacular style me the precinct. The st composed projectir	tructure has an orna	amente	d façade with we		
5.3	Intrinsic		The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.				
5.4	Value Classification	A(arc), E, G(grp)		Recom	nmended Grade	Ш	
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth	Dressed Basalt stone plinth 0.6 high					
7.2	Walls	Load bearing brick walls					
7.3	Floor	R.C.C slab flooring	R.C.C slab flooring				
7.4	Stairs	Wooden dog legge	d staircase				
7.5	Openings	Rectangular and ar shutter	ched openings with	woode	en frames and gla	azed	


7.6	Roofing	Flat roof with façade			
7.7	Articulation	Decorative balconies and cornice bands. Stain glass is used at places.			
7.8	Finishes	Externally sand plastered and internally painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Not provided			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly paved with Black Basalt stone, open space with some trees in compound			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fair natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good (Wooden members in sound state)			
9.5	Openings	Good (Well maintained)			
9.6	Roofing	Good			
9.7	Articulation & Finishes	Poor (Chajjas corroded and plaster chipped off at some places)			
9.8	Services	Fair (Some pipes show leakage)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Fair			
10.0	Transformation				
10.1	Form	Ground floor façade partly hidden behind shop signboards.			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



View of Govind Sadan from Hindu colony road no.1 showing front and east side.



Detail of balcony with decorative brackets supporting it having decorative concrete jali. Columns with decorative arches supporting the balcony above.



Card No.: F/n-11d

Ward (Part): F north-IV

**CS No.:** 99/10

Plot Area: 408.86 sq.m.

**B U Area:** 1146.9 sq.m.

Date: April 25, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 70, Ramchandra


Bhuvan



1.0	Denomination					
1.1	Name of Premises	70, Ramchandra Bhu	70, Ramchandra Bhuvan			
1.2	Earlier Name	Not available				
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lakhamshi Nappu R	oad			
2.2	Subsidiary	Cross Road no. 1				
3.0	Ownership Pattern					
3.1	Present	Trustees for improve	ement of city of Bo	mbay		
3.2	Past	Not available				
3.3	Status	Private owned				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential u	ıse			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Corner plot at junctic colony road no. 4 fact Colony Precinct.				
5.2	Architectural Description	The Vernacular style façade with balconies supported on wooden and concrete brackets and its roof supported on wooden posts. Wooden railing .Top floor has a full-length balcony. Stained glass panels are fixed in top part of window opening. It represents the Hindu colony character,				
5.3	Intrinsic	The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.				
5.4	Value Classification	A(arc), E, G(grp) Recommended Grade				
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Dressed basalt stone plinth 0.3 m. high				
7.2	Walls	Load bearing brick walls				
7.3	Floor	R.C.C. slab flooring				
7.4	Stairs	Wooden dog legged	staircase with hig	hly dec	orative newel pos	st

7.5	Openings	Rectangular and arched openings with wooden frames and glazed (stained glass) shutter			
7.6	Roofing	Flat roof with partly sloping roof			
7.7	Articulation	Highly decorative with wooden railing, ornamental columns and Moorish arches			
7.8	Finishes	Internally and externall	ly cement plastered ar	nd painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	e value		
7.10	Compound / Fence / Gate	Plastered brick wall wit	th cast iron railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Lots of trees within the	compound		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	ood natural lighting		
8.2	Ventilation	Natural and artificial, g	ood natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement o	r cracks observed)		
9.2	Walls	Good (No dampness o	r cracks observed)		
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good (Wooden member	ers in sound state)		
9.5	Openings	Good (Well maintained	1)		
9.6	Roofing	Good (No leakage or b	reaking of Mangalore	tiles observed)	
9.7	Articulation & Finishes	Good (Needs to be pai	inted)		
9.8	Services	Fair			
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### 70, Ramchandra Bhuvan



View of building from junction of L.N.Road & V.P.Pradhan road.




South side façade of building from V.P.Pradhan road.



Decorative balconies forming symmetrical elevation.



Corner of building with hexagonal block stand out in elevation. Decorative stained glass pannels above window opening.



Card No.: F/n-11e

Ward (Part): F north-IV

**CS No.:** 74/10

Plot Area: 314.38 sq.m.

**B U Area:** 823.17 sq.m.

Date: April, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above


Photo T-III-Fn:\Ward F north\Ref.: 76, Radha Krishna Niwas



1.0	Denomination				
1.1	Name of Premises	76, Radha Krishna Niwas			
1.2	Earlier Name	Not applicable	Not applicable		
1.3	Built in	1934	Extension Date (if a	any) Not applicable	
2.0	Access				
2.1	Main	Hindu colony Roa	d no. 2		
2.2	Subsidiary	Not applicable			
3.0	Ownership Pattern				
3.1	Present	Trustees for Impre	Trustees for Improvement of City of Bombay, Indirabai Babubai Boy		
3.2	Past	Trustees for Impre	Trustees for Improvement of City of Bombay, Indirabai Babubai Boy		
3.3	Status	Tenanted			
4.0	Use				
4.1	Present	Residential	Residential		
4.2	Past	Residential	Residential		
4.3	Usage	Regular residentia	Regular residential use		
5.0	Significance & Value Classification				
5.1	Townscape (Natural / Manmade)	Located on a small plot of Hindu Colony Road no. 2, a minor road of Hindu colony. Part of Hindu Colony Precinct.			
5.2	Architectural Description	A well articulated building with a symmetrical character governed by the composition of balconies with intricate concrete jalis. The staircase bay has semi-circular arched ventilators with simple architraves.			
5.3	Intrinsic	The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.			
5.4	Value Classification	A(arc), E, G(grp)	F	Recommended Grade	III
6.0	Topography		•		
6.1	Floors	G + 2			
7.0	Construction				
7.1	Plinth	Sand faced cement plaster finished masonry plinth			
7.2	Walls	Composite brick masonry walls			
7.3	Floor	R.C.C. slab flooring			
7.4	Stairs	R.C.C. staircase with wooden cladded members			
7.5	Openings	Rectangular with wooden frames and glazed shutters			

Roofing Articulation Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape		•		
Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out	Interiors, not of heritage	/ plastered and painte	d	
Compound / Fence / Gate Curtilage / Unbuilt Space / Out			u	
Curtilage / Unbuilt Space / Out	5	Interiors, not of heritage value		
	Plastered brick compou	ınd wall		
zananigo / Landodapo	Not provided			
Services & Utilities				
Lighting	Natural and artificial, fai	ir natural lighting		
Ventilation	Natural and artificial, fai	ir natural ventilation		
Electricity	BEST			
Water Supply	MCGM			
Drainage (Plumbing and Sanitation)	MCGM			
Fire precaution	Not provided			
Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
Condition				
Plinth	Good (No settlement or cracks observed)			
Walls	Fair (Dampness observed in passage near staircase)			
Floor	Good (No sagging observed)			
Stairs	Fair (No deflection observed)			
Openings	Fair (Wooden members need maintenance)			
Roofing	Fair (No dampness or leakage observed)			
Articulation & Finishes	Fair (Re-plastering and repainting required)			
Services	Fair (Tree growth near toilet pipes)			
Outbuildings	Fair			
Overall condition	Fair I	Maintenance level	Fair	
Transformation				
Form	No transformation			
Structure	No transformation			
Articulation & Finishes	No transformation			
DP Remarks / Perceived Threats	None			
Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			
	Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition  Transformation Form Structure Articulation & Finishes  DP Remarks / Perceived Threats  Additional Notes / References /	Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Good (No settlement or Good (No sagging observable) Fair (Dampness observable) Fair (No deflection observable) Stairs Fair (No deflection observable) Fair (No dampness or least (Wooden members) Fair (No dampness or least (Wooden members) Fair (Re-plastering and Services Fair (Tree growth near observable) Coverall condition Fair  Transformation Form No transformation Structure Articulation & Finishes No transformation  Por Remarks / Perceived Threats Additional Notes / References / Documents Available  Articulation & Finishes Notes: After the decision provide the accommod Wadala areas, 440 acres Scheme. The biggest p wide Kingsway (Now D principal access lit by e 1926.	Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems) Window air-conditioning units at some places Systems)  Condition Plinth Good (No settlement or cracks observed) Walls Fair (Dampness observed in passage near st Floor Good (No sagging observed) Stairs Fair (No deflection observed) Openings Fair (Wooden members need maintenance) Roofing Fair (No dampness or leakage observed) Articulation & Finishes Fair (Re-plastering and repainting required) Services Fair (Tree growth near toilet pipes) Outbuildings Fair Overall condition Fair Maintenance level  Transformation  Form No transformation Structure No transformation Notes: After the decision of Bombay Improve provide the accommodation facilities in Dada Wadala areas, 440 acres of land was acquire Scheme. The biggest plus point at that time wide Kingsway (Now Dr. Babasaheb Ambed principal access lit by electric lamps. The plot	

### 76, Radhakrishna Niwas



Front façade of Radhakrishna Niwas from Hindu colony road no.2.



Deail of balcony with decorative concrete large supported with ornamented concrete brackets.

	Com	nmon Ref. No.:
	Card	No.: F/n-11f
W. C.	Ware	d (Part): F north-IV
	CSN	No.: 91/10
	Plot	Area: 381.27 sq.m.
	ви	Area: 1097.4 sq.m.
000	Date	e: April, 2005
	Reco	ord by: Keshav S, Gauri J
	Revi	iew by: Arun Kale
	Inter	rnal: As above
	Exte	ernal: As above
	Phot Ref.	to T-III-Fn:\Ward F north\ : 92, Tulsi Bhavan
1.0 Denomina	tion	
1.1 Name of P	remises	92, Tulsi Bhavan
1.2 Earlier Nar	me	Not applicable
1.3 Built in		1925-35 Extension Date (if any) Not applicable
2.0 Access		
2.1 Main		Hindu Colony Road no. 3
2.2 Subsidiary		Not applicable
3.0 Ownership	o Pattern	
3.1 Present		Trustees for City pf Improvement of Bombay, Tulsidas Bhanji
3.2 Past		Trustees for City pf Improvement of Bombay, Tulsidas Bhanji
3.3 Status		Tenanted
4.0 Use		
4.1 Present		Residential
4.2 Past		Residential
4.3 Usage		Regular residential use
5.0 Significan	ce & Value Classificati	ion
5.1 Townscape	e (Natural / Manmade)	Located on Hindu Colony Road no. 3, a road parallel to Tilak Bridge off Sir Bhalchandra Marg. Part of Hindu Colony Precinct.
5.2 Architectur	al Description	An ornate but well composed front façade. Balconies on both sides have decorative cast iron railing on first floor supported by decorative brackets in concrete. Decorative wooden door to entrance to building. The flat pointed arches in the balconies resemble Haveli style. Second floor balcony and staircase block has sloping roof in Mangalore tiles.
5.3 Intrinsic		The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.
5.4 Value Clas	sification	A(arc), E, G(grp) Recommended Grade
6.0 Topograph	hy	
6.1 Floors		G + 2
7.0 Construct	ion	
7.1 Plinth		Basalt stone coursed masonry 0.6 m. high plinth
7.2 Walls		Load bearing brick walls
7.3 Floor		RCC slab flooring
7.4 Stairs		Wooden dog-legged staircase


	T			
7.5	Openings	Rectangular and arched openings with wooden frames and glazed shutter		
7.6	Roofing	Flat roof and partly sloping roof		
7.7	Articulation	Cornice bands at floor levels. Cast iron railings to balconies. Wooden posts supporting balcony.		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall with cast iron railing and gate		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Concreted open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (Cracks observe on first floor )		
9.3	Floor	Fair (Sagging observed at few places)		
9.4	Stairs	Fair (Wooden members need maintenance)		
9.5	Openings	Good (Window panes and wooden members in sound state)		
9.6	Roofing	Fair (Sloping roof needs maintenance)		
9.7	Articulation & Finishes	Fair (Needs to be painted)		
9.8	Services	Fair (Leakage observed in some pipes)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Symmetrical Front façade of Tulsi Bhavan from Hindu colony road no 3



Detail of balcony having decorative cast iron railing, Moorish arch and staircase block with sloping roof.



7.5	Openings	Rectangular and arched openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof with partly sloping roof	
7.7	Articulation	Highly decorative with wooden railing, ornamental columns and Moorish arches	
7.8	Finishes	Internally and externally cement plastered and painted.	
7.9	Interiors (Movable & Immovable)	No interiors of Heritage value.	
7.10	Compound / Fence / Gate	Plastered brick wall	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Garage is paved with concrete	
8.0	Services & Utilities		
8.1	Lighting	Natural and artificial, Good natural lighting	
8.2	Ventilation	Natural and artificial, Good natural ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and Sanitation)	MCGM	
8.6	Fire precaution	Not provided	
8.7	Other (HVAC / BMS / Security Systems)	Not provided	
9.0	Condition		
9.1	Plinth	Good (No settlement or cracks observed)	
9.2	Walls	Good ( cracks observe on 1 <sup>st</sup> floor )	
9.3	Floor	Fair (Sagging observed at few places)	
9.4	Stairs	Fair (Wooden members need maintenance)	
9.5	Openings	Good (Window panes and wooden members in sound state)	
9.6	Roofing	Fair (Sloping roof needs maintenance)	
9.7	Articulation & Finishes	Fair (needs to be painted)	
9.8	Services	Fair (Leakage observed in some pipes)	
9.9	Outbuildings	Fair	
9.10	Overall condition	Fair Maintenance level Fair	
10.0	Transformation		
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No transformation	
11.0	DP Remarks / Perceived Threats	None.	
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai	



Front view of Shankar Niketan from road no. 4.



Detail of balconies having decorative ornamented concrete jali fixed in between posts supporting sloping roof above.



Detail of balconies on first floor along with ornamented staircase block.




		1926. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in		
11.0	DP Remarks / Perceived Threats	None.		
10.3	Articulation & Finishes	No transformation		
10.2	Structure	No transformation		
10.1	Form	No transformation		
10.0	Transformation			•
9.10	Overall condition	Fair	Maintenance level	Fair
9.9	Outbuildings	Fair		
9.8	Services	Fair (Leakage observed in some pipes)		
9.7	Articulation & Finishes	Fair (needs to be painted)		
9.6	Roofing	Fair (Leakage observed in some part)		
9.5	Openings	Good (Window panes and wooden members in sound state)		
9.4	Stairs	Fair (Wooden members need maintenance)		
9.3	Floor	Fair (Sagging observed at few places)		
9.2	Walls	Good ( cracks observe on 1 <sup>st</sup> floor )		
9.1	Plinth	Good (No settlement or cracks observed)		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, (	Good natural ventilation	1
8.1	Lighting	Natural and artificial, 0	Good natural lighting	
8.0	Services & Utilities	<u>I</u>		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Garage and open spa	ce is concreted	
7.10	Compound / Fence / Gate	Plastered brick wall and concrete jali with cast iron gate		
7.9	Interiors (Movable & Immovable)	No interiors of Heritage value.		
7.8	Finishes	Externally sand plastered and internally painted		
7.7	Articulation	Decorative balconies a	and cornice bands	



Front façade of Lakshmi Niketan showing decorative arches and concrete jali.



Porch supported with Corinthian column forms beautiful entrance to building.Compound wall with cast iron railing.



7.6	Roofing	Flat roof		
7.7	Articulation	Decorative balconies and cornice bands. Stain glass is used.		
7.8	Finishes	Externally sand plastered and internally painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Garage is cemented and compound has few trees		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition	dition		
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Fair (Dampness observed in passage near staircase)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Fair (No deflection observed)		
9.5	Openings	Fair (Wooden members need maintenance)		
9.6	Roofing	Fair (No dampness or leakage observed)		
9.7	Articulation & Finishes	Fair (Re-plastering and repainting required)		
9.8	Services	Fair (Tree growth near toilet pipes)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None.		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

### 110, Govind Sadan



Detail of balcony on first and second floor.



Concrete bracket supporting balcony on first floor having decorative jali and post.



Symmetrical front façade of Govind sadan building from Hindu Colony road no.4.



Card No.: F/n-11j

Ward (Part): F north-IV

**CS No.:** 121 / 10

Plot Area: 650 sq.m.

**B U Area:** 720 sq.m.

Date: April, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale.

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 122, Bang Bhavan



1.0	Denomination					
1.1	Name of Premises	122, Bang Bhavan				
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (if a	any)	Not available	
2.0	Access					
2.1	Main	Sir Bhalchandra Ma	arg			
2.2	Subsidiary	Hindu colony Cross	Road no. 5			
3.0	Ownership Pattern					
3.1	Present	Trustees for Improv	vement of City of Bor	nbay		
3.2	Past	Trustees for Improv	ement of City of Bor	nbay		
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Corner plot on junction of Sir Bhalchandra Marg and Cross Road no. 5, on a major road junction. Part of Hindu Colony Precinct.				
5.2	Architectural Description	character. The faça the balcony bay loo White painted band below second floor railing along with the	cladded massive build ade follows the build in cated between the two distribution in concrete highlig windows, sloping character is all on the architectural value.	ng typo o side ht the f ajjas, v	ology in the vicin projecting bays. floors, concrete wooden balcony	ity by jalis
5.3	Intrinsic		of Hindu Colony commers, who shifted fro			
5.4	Value Classification	A(arc), B(des), C(se	eh), G(grp)	Recomi	mended Grade	Ш
6.0	Topography					
6.1	Floors	G +3 (Top floor add	ded)			
7.0	Construction					
7.1	Plinth	Black Basalt stone	coursed masonry pli	nth		
7.2	Walls	Load bearing brick stone, Ashlar maso	walls, external walls onry	cladde	ed in Black Basa	lt
7.3	Floor	R.C.C. slab flooring				
7.4	Stairs	Dog-legged R.C.C.	staircase			

Openings Roofing Articulation  Finishes  Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Ventilation	Flat roof with terrace  Cornice band at floor I railing to balcony & wi	ack Basalt stone, interige value		
Articulation  Finishes  Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting	Cornice band at floor I railing to balcony & wind Externally exposed Bland painted Interiors, not of heritage Plastered brick wall wind Open space paved with	ndow ack Basalt stone, inter ge value ith concrete jali		
Finishes  Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting	railing to balcony & wind Externally exposed Black and painted Interiors, not of heritage Plastered brick wall wind Open space paved with	ndow ack Basalt stone, inter ge value ith concrete jali		
Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting	and painted Interiors, not of heritage Plastered brick wall with Open space paved with	ge value ith concrete jali	nally cement plastered	
Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting	Plastered brick wall wi	ith concrete jali		
Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting	Open space paved wit	•		
Buildings / Landscape  Services & Utilities  Lighting		th Shahabad tiles		
Lighting	Natural and artificial, f			
	Natural and artificial, f			
Ventilation		air natural lighting		
	Natural and artificial, fa	air natural ventilation		
Electricity	BEST			
Water Supply	MCGM			
Drainage (Plumbing and Sanitation)	MCGM			
Fire precaution	Not provided			
Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
Condition				
Plinth	Good (No settlement or cracks observed)			
Walls	Good (No dampness or cracks observed)			
Floor	Good (No sagging observed)			
Stairs	Good (No sagging or o	deflection observed)		
Openings	Good (wooden memb	ers in sound state)		
Roofing	Good (No deflection o	r leakage observed)		
Articulation & Finishes	Good (Exposed stone	façade in maintained	state)	
Services	Fair (Some pipes brok	en at few places)		
Outbuildings	Good			
Overall condition	Good	Maintenance level	Good	
Transformation				
Form	Box grill & sliding door	added subsequently.		
Structure	Top floor added later.			
Articulation & Finishes	No transformation			
DP Remarks / Perceived Threats	None			
Additional Notes / References / Documents Available	the accommodation factories of land was acquiplus point at that time will be abasaheb Ambedkar lamps. The plots here will be accommodation factories of lamps.	None  Note: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.		
	Electricity Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition  Transformation Form Structure Articulation & Finishes  DP Remarks / Perceived Threats  Additional Notes / References /	Electricity Water Supply MCGM Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Good (No settlement of Good (No sagging obstairs) Floor Good (No sagging obstairs) Good (No sagging or Good (No deflection of Good (No def	Electricity Water Supply MCGM Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Good (No settlement or cracks observed) Walls Good (No dampness or cracks observed) Floor Good (No sagging observed) Stairs Good (No sagging or deflection observed) Openings Good (No dampness in sound state) Roofing Good (No deflection or leakage observed) Articulation & Finishes Good (Exposed stone façade in maintained store) Good Overall condition Good Maintenance level Transformation Form Box grill & sliding door added subsequently. Structure Articulation & Finishes No transformation  DP Remarks / Perceived Threats  Additional Notes / References / Documents Available  Note: After the decision of Bombay Improveme the accommodation facilities in Dadar, Matunga plus point at that time was the grand 158 feet babasaheb Ambedkar Road) as its principal at abasaheb Ambedkar Road) as its principal at Babasaheb Ambedkar Road	



Front façade of Bang Bhavan from Dr.Bhalchandra road.



Detail of windows through lots of trees.



Detail of north corner of building with compound wall.



Detail of chajjah, concrete jali, pediments, cornice bands on north façade of building with compound wall.



<b>^</b>	D - C	NI -	
Common	Ret.	NO.	_

Card No.: F/n-11k

Ward (Part): F north-IV

**CS No.:** 118/10

**Plot Area:** 510.87 sq.m.

**B U Area:** 731.70 sq.m.

Date: April, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 119, Abhyankar Niwas



1.0	Denomination					
1.1	Name of Premises	119, Abhyankar Ni	119, Abhyankar Niwas			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1932's	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Hindu Colony Cros	s Road no. 5			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Trustees for Improv Abyankar	vement of City of B	ombay.	Shriram Vasude	V
3.2	Past	Trustees for Improv Abyankar	vement of City of B	ombay.	Shriram Vasude	V
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	Regular residential use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Rectangular plot facing Hindu Colony Cross Road no. 5, one of the minor roads in Hindu colony. Part of Hindu Colony Precinct.				
5.2	Architectural Description	A modest Vernacular structure with Mangalore tiled sloping roof. It has wooden floors, pediments and balconies. Building also has a symmetrical façade, semicircular arched windows with decorative architraves. Well-composed balconies with sloping roofs and wooden railing enhance its Vernacular architectural value and scale.				
5.3	Intrinsic	The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.				
5.4	Value Classification	A(arc), E, G(grp)		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Dressed Basalt sto	ne plinth 0.3 m. hig	jh		
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Wooden flooring w	ith wooden joists a	nd batte	ns	
7.4	Stairs	Wooden dog legge	d staircase with pla	ain railing	gs	

ngs	Rectangular wooden double windows and semi-circular arched entrance			
g	Sloping roof with Mangalore tiles			
ation	Decorative wooden balconies and cornice band	ds		
es	Internally and externally plastered			
rs (Movable & Immovable)	Interiors, not of heritage value			
ound / Fence / Gate	Brick wall with cast iron railing			
ge / Unbuilt Space / Out gs / Landscape	Compound has few trees and is paved with Sha	ahabad tiles		
es & Utilities				
g	Natural and artificial, good natural lighting			
tion	Natural and artificial, good natural ventilation			
city	BEST			
Supply	MCGM			
ge (Plumbing and Sanitation)	MCGM			
ecaution	Not provided			
(HVAC / BMS / Security ns)	Not provided			
tion				
	Good (No settlement or cracks observed)			
	Good (No dampness or cracks observed)			
	Good (No sagging observed)			
	Good (wooden members in sound state)			
ngs	Good (Window panes and wooden members in	sound state)		
g	Good (Mangare tiles, wooden members in mair	ntained state)		
ation & Finishes	Good (Façade attacked by moss)			
es	Fair (Some pipes broken, resulting in moss on	façade)		
ldings	Fair			
I condition	Good Maintenance level C	Good		
ormation				
	No transformation			
ıre	No transformation			
ation & Finishes	No transformation			
marks / Perceived Threats	None			
onal Notes / References / nents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			

## 119, Abhyankar Niwas



Front façade of Abhyankar Niwas from Hindu Colony road no.5.



Detail of projecting balcony with wooden railing and cornice band at floor level.



Detail of entrance, semi circular arched opening & balcony detail.



Card No.: F/n-11I

Ward (Part): F north-IV

**CS No.:** 99/10

Plot Area: 408.86 sq.m.

**B U Area:** 1146.9 sq.m.

Date: April 25, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale.

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 100, Vishnu Sadan



		·					
1.0	Denomination						
1.1	Name of Premises	100, Vishnu Sadan					
1.2	Earlier Name	Not applicable					
1.3	Built in	1925-35 Extension Date (if any) Not applicable					
2.0	Access						
2.1	Main	Lakhamshi Nappu Road					
2.2	Subsidiary	Cross Road no. 4					
3.0	Ownership Pattern						
3.1	Present	Trustees for improvement of city of BombayRamakant Kashinath Chipakar	ı				
3.2	Past	Shushilabai Kashinath Chipakar, Vasant Kashinath Chipakar, Madhukar Kashinath Chipakar, Kamalakar Kashinath Chipakar, Prabhakar Kashinath Chipakar.	Madhukar Kashinath Chipakar, Kamalakar Kashinath Chipakar,				
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential	Residential				
4.2	Past	Residential					
4.3	Usage	Regular residential use					
5.0	Significance & Value Classification	on					
5.1	Townscape (Natural / Manmade)	Corner plot at junction of Lakhamshi Napoo Road and Cross Roano. 4 in Hindu Colony. Part of Hindu Colony Precinct.	ad				
5.2	Architectural Description	A modestly ornamental building with an appropriately scaled sloping roof profile. The balconies supported on wooden and concrete brackets and railings with separate sloping roof profile supported on wooden posts add Vernacular character that is shared by most of the buildings in the precinct. Motif of Swastik o the cast iron compound railing is a special character.	on				
5.3	Intrinsic	The development of Hindu Colony commenced in 1925, by different trusts or private owners, who shifted from southern part of the Island City.	different trusts or private owners, who shifted from southern part of				
5.4	Value Classification	A(arc), E, G(grp) Recommended Grade	ı				
6.0	Topography						
6.1	Floors	G+2					
7.0	Construction						
7.1	Plinth	Dressed Basalt stone plinth 0.3 m. high					
7.2	Walls	Load bearing brick walls					
7.3	Floor	Wooden flooring with wooden joists and battens					

rs	Wooden dog legged staircase with highly decorative newel post			
enings	Rectangular and arched openings with wooden frames and glazed shutters			
fing	Flat roof with partly slo	pping roof		
culation	Highly decorative with Moorish arches	wooden railing, ornam	nental columns and	
shes	Internally and external	ly cement plastered ar	nd painted	
riors (Movable & Immovable)	Interiors, not of heritag	ge value		
npound / Fence / Gate	Plastered brick wall wi	th Swastik motif railing		
tilage / Unbuilt Space / Out dings / Landscape	Lots of trees within the	e compound		
vices & Utilities				
iting	Natural and artificial, g	good natural lighting		
tilation	Natural and artificial, g	good natural ventilation		
etricity	BEST			
er Supply	MCGM			
nage (Plumbing and Sanitation)	MCGM			
precaution	Not provided			
er (HVAC / BMS / Security tems)	Not provided			
dition				
th	Good (No settlement or cracks observed)			
ls	Good (No dampness or cracks observed)			
or	Good (No sagging observed)			
rs	Good (Wooden memb	ers in sound state)		
enings	Good (Well maintained	d)		
fing	Good (No leakage or l	oreaking of Mangalore	tiles observed)	
culation & Finishes	Good			
vices	Fair			
buildings	Good			
rall condition	Good	Maintenance level	Good	
nsformation				
m	No transformation			
cture	No transformation			
culation & Finishes	No transformation			
Remarks / Perceived Threats	None			
litional Notes / References / uments Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			
		principal access lit by	principal access lit by electric lamps. The plo	



Vishnu Sadan from junction of Lakhamahi Nappu road and Hindu colony road no 4 with ornamented façade.



Detail of balcony on 1<sup>st</sup> floor showing decorative wooden bracket, railing, post supporting roof.



Compound wall with cast iron Jali in it.



Balcony on top floor showing symmetrical composed elevation



Detail of balcony on 1<sup>st</sup> floor showing decorative wooden bracket, railing, post supporting roof.



West Elevation from Lakhamahi Nappu Road.



Common	Ref.	No.
--------	------	-----

Card No.: F/n-11m

Ward (Part): F north-IV

**CS No.:** 128 / 10

Plot Area: 795.99 sq.m.

**B U Area:** 981 sq.m.

Date: April, 2005


Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 129, Raj Griha





1.1						
	Name of Premises	129, Raj Griha				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1934	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Lakhamshi Nappu F	Road			
2.2	Subsidiary	Hindu Colony Road	l no 5			
3.0	Ownership Pattern					
3.1	Present	Trustees for improv Bhimarao Ambedka		ombay, \	⁄ashavantrao	
3.2	Past	Trustees for improv Bhimarao Ambedka		ombay, \	⁄ashavantrao	
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	An important historical landmark, the residence of Bharat Ratna, Dr. B. R. Ambedkar is located on the corner of an important road of Hindu Colony, Lakhamshi Nappu Road and an internal road, Road no. 5.				
5.2	Architectural Description	Responding to the corner building with a chamfered porch is a blend following an influence of Vernacular and Neo-classical architectural styles. A colonnade with circular columns with Doric capitals and a projecting entrance porch with circular columns along the chamfered corner enhance its architectural value. Cornice running at every floor level, balustrades to balconies, well composed simple rectangular windows adorns its façade.				
5.3	Intrinsic	Raj Griha, the residence of Dr. B. R. Ambedkar (1893-1956), main architect of Indian Constitution and Dalit leader was built in the Hindu colony, in the year 1934. It housed the biggest private library in India, which containing more than 50,000 books. It is still his family residence.				
5.4	Value Classification	A(arc), C(seh), D(bi	io), E, G(grp)	Recom	mended Grade	I
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Basalt stone plinth 0.	.45m. high			

7.2	Walls	Composite brick masonry			
7.3	Floor	R.C.C. floor slab			
7.4	Stairs	Wooden dog legged staircase with plain railing			
7.5	Openings	Rectangular windows with wooden frames and glazed shutters			
7.6	Roofing	Flat roof terrace			
7.7	Articulation	Projecting cornice bands and decorative entrance porch. North façade has a common colonnaded passage having Doric columns.			
7.8	Finishes	Internally and externally plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Plastered brick compound wall with CI railing and jali			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Part paved space with some trees in the compound			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fair natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	мсөм			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging or deflection observed)			
9.4	Stairs	Good (Wooden members in sound state, no deflection or breaking observed)			
9.5	Openings	Good (Well maintained)			
9.6	Roofing	Good (No leakage or deflection observed)			
9.7	Articulation & Finishes	Good (Repainting of façade required)			
9.8	Services	Fair (No leakage or breaking of pipes observed)			
9.9	Outbuildings	Fair			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation	· · · · · · · · · · · · · · · · · · ·			
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None.			
12.0	Additional Notes / References / Documents Available	Notes: Raj Griha, the residence of Bharat ratna, Dr. B. R. Ambedkar, a well known economist, politician and Dalit leader. He was the main architect of Indian constitution.			
		Hindu Colony: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			
		Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



Common passage on first floor supported with Doric columns having decorative jali in between.



View of Raj Griha from Lakhamshi Nappu road.



Detail of low height compound wall having cast iron railing in between along with decorative entrance gate.



North side elevation of Raj Griha.



View of Raj Gruha from junction of Lakhamshi Nappu road and Hindu colony road no. 5 showing decorative entrance porch.



Card No.: F/n-11n

Ward (Part): F-North IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April 26, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale


Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.:

133, IES Gujarati Bal Mandir and Primary

School



		SCHOOL				
1.0	Denomination					
1.1	Name of Premises	133, IES Gujarati Bal Man	dir and Prim	ary Sch	iool	
1.2	Earlier Name	Krishna Kunj	Krishna Kunj			
1.3	Built in	1933's Exten	1933's Extension Date (if any) Not applicable			
2.0	Access					
2.1	Main	Khareghat Road				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Trust				
3.2	Past	Private				
3.3	Status	Trust				
4.0	Use					
4.1	Present	Educational, Public				
4.2	Past	Residential				
4.3	Usage	Regular public use				
5.0	Significance & Value Classificat	on				
5.1	Townscape (Natural / Manmade)	Rectangular plot facing Khroads of Hindu colony. Pa				
5.2	Architectural Description	A modest and well proport ornamentation. Its recesse corners is unique feature. columns, semicircular arcl and first floor with recesse tiled sloping roof, all add to character.	ed entrance p The porch is hed windows ed timber bald	porch was supported to support to	vith beveled inwa rted by circular ner sides on grou n top floor, Mang	ınd
5.3	Intrinsic	The development of Hindu different trusts or private of the Island City.				art of
5.4	Value Classification	A(arc), B(des), B(uu), E, G	G(grp)	Recom	mended Grade	Ш
6.0	Topography	•				•
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Black Basalt stone course	d masonry p	linth 0.3	3m. high	
7.2	Walls	Load bearing brick walls				
7.3	Floor	R.C.C. slab flooring		•		

Stairs Openings Roofing Articulation	Wooden dog legged staircase  Rectangular with wooden frames and glazed shutters  Sloping roof with Mangalore tiles and wooden trusses			
Roofing				
	Sloping roof with Mangalore tiles and wooden trusses			
Articulation				
	Projecting cornice bands and small entrance porch with circular columns			
Finishes	Internally and externally plastered and painted			
Interiors (Movable & Immovable)	Interiors, not of heritage value			
Compound / Fence / Gate	Plastered brick compound wall with CI railing			
Curtilage / Unbuilt Space / Out Buildings / Landscape	Compound has few trees, rest area is paved in concrete			
Services & Utilities				
Lighting	Natural and artificial, poor natural lighting			
Ventilation	Natural and artificial, poor natural ventilation			
Electricity	BEST			
Water Supply	MCGM			
Drainage (Plumbing and Sanitation)	MCGM			
Fire precaution	Not provided			
Other (HVAC / BMS / Security Systems)	Not provided			
Condition				
Plinth	Good (No settlement or cracks observed)			
Walls	Fair (Crack observed at some places)			
Floor	Fair (Crack and deflection observed)			
Stairs	Fair (Wooden members need maintenance)			
Openings	Fair			
Roofing	Fair (Mangalore tiles and fascia need repairs)			
Articulation & Finishes	Fair (Need re-plastering)			
Services	Poor (Broken pipes to be replaced)			
Outbuildings	Fair			
Overall condition	Good Maintenance level Fair			
Transformation				
Form	No transformation			
Structure	No transformation			
Articulation & Finishes	No transformation			
DP Remarks / Perceived Threats	None			
Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			
	Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Ventilation  Electricity  Water Supply  Drainage (Plumbing and Sanitation)  Fire precaution  Other (HVAC / BMS / Security Systems)  Condition  Plinth  Walls  Floor  Stairs  Openings  Roofing  Articulation & Finishes  Services  Outbuildings  Overall condition  Transformation  Form  Structure  Articulation & Finishes  DP Remarks / Perceived Threats  Additional Notes / References /			



I.E.S. Gujarati Bal Mandir and Primary School (Plot no.133)



Detail of Front Elevation with recessed balcony and main entrance to the building.



Top floor with recessed balcony with wooden railing and wooden posts supporting the mangalore tile roof above. Stained glass pannels on first floor balcony.



Card No.: F/n-12

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: Water fountain



1.0	Denomination					
1.1	Name of Premises	Water fountain in M	lemory of Dr. M. V. I	Parulkar		
1.2	Earlier Name	Not applicable				
1.3	Built in	1940	Extension Date (if	any) I	Not applicable	
2.0	Access			1		
2.1	Main	Lakhamashi Nappu	Road			
2.2	Subsidiary	Not applicable	Not applicable			
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	For drinking water				
3.3	Status	Not in use				
4.0	Use					
4.1	Present	Not in use	Not in use			
4.2	Past	Public purpose				
4.3	Usage	Drinking water four	Drinking water fountain			
5.0	Significance & Value Classification	cation				
5.1	Townscape (Natural / Manmade)		de of Lakhamashi Na ck opposite Raj Grih		ad, parallel to	
5.2	Architectural Description	Constructed in Mala	A well proportionate fountain with decorative inbuilt stone basin. Constructed in Malad stone with stepped and molded profile on the plinth and at the top. Cornice band with a motif pattern provides the ornamentation. A recessed marble plaque gives the details about the donor			
5.3	Intrinsic	Bai Muktabai. It ser	), in the memory of I ves as an important tain in the Hindu col	infrastru		
5.4	Value Classification	C(seh), D(bio)	1	Recomm	nended Grade	Ш
6.0	Topography	•				
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Malad Stone				
7.2	Walls	Malad Stone				
7.3	Floor	Not applicable	Not applicable			
7.4	Stairs	Not applicable	Not applicable			
7.5	Openings	Not applicable				
7.6	Roofing	Not applicable				
\ dorko	r Associates Architects	88			10/	l E noi

7.7	Articulation	Cornice band on upper stone basin.	Cornice band on upper side of fountain with motifs. It has decora stone basin.		
7.8	Finishes	Exposed Malad stone			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Not applicable			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable			
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	Not applicable			
8.4	Water Supply	Not applicable			
8.5	Drainage (Plumbing and Sanitation)	Not applicable	Not applicable		
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Good			
9.8	Services	Not applicable			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Not applicable			
11.0	DP Remarks / Perceived Threats	Plot demarcated as Welfare Centre on Proposed Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Documents: C.S. She	ets, D.P. Sheets, Eich	er City Maps-Mumbai	

#### **Water Fountain**



Water Fountain on Lakhamashi Nappu road near RajGruh.



Plaque in Marble stating date



Water Fountain in Malad stone with decorative cornice band and basin



Card No.: F/n-13

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

**B U Area:** Not available

Date: February, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: Vaidya Garden



1.0	Denomination					
1.1	Name of Premises	Vaidya Garden				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 <sup>th</sup> century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Lakhamashi Nappu	Lakhamashi Nappu Road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Not available				
4.0	Use					
4.1	Present	Recreational, Publi	С			
4.2	Past	Recreational, Publi	С			
4.3	Usage	Regular public use				
5.0	Significance & Value Classificatio	n				
5.1	Townscape (Natural / Manmade)	Located on a triang the central railway		mashi N	lappu Road close	e to
5.2	Architectural Description	This landscaped ga Special section for				S.
5.3	Intrinsic	well placed open so today with the incre	The development of Hindu Colony which commenced in 1925 has well placed open spaces for recreation. They are very important today with the increase in population, presence of educational institutions and new development with increased FSI.			
5.4	Value Classification	C(seh), I(sce), J		Recom	nmended Grade	IIΒ
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Not applicable	Not applicable			
7.6	Roofing	Not applicable				
7.7	Articulation	Not applicable				

7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Low height peripheral random rubble wall with mild steel fencing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Ground covered with lawn and different kinds of shrubs and large trees		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, excellent natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Plot demarcated for recreational ground on proposed Development Plan (D.P).		
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai		



Vaidya Garden with low compound wall and fencing from Lakhamahi Nappu road



Card No.: F/n-14

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale


Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 720d, Bombay Electric

720d, Bombay Electric Supply and Transport

workshop



	l l					
1.0	Denomination		·			
1.1	Name of Premises	720d, Bombay Elec	ctric Supply and Tr	ansport	Workshop	
1.2	Earlier Name	Bombay Electric Su	upply and Tramwa	ys work	shop	
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (	if any)	Not applicable	
2.0	Access					
2.1	Main	Tilak Road (Matung	ga Road)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Bombay Electric Su	upply and Transpo	rt		
3.2	Past	Bombay Electric Su	upply and Tramwa	ys		
3.3	Status	Semi Government	owned			
4.0	Use					
4.1	Present	Workshop, Depot	Workshop, Depot			
4.2	Past	Workshop, Depot				
4.3	Usage	Administrative and	garage use			
5.0	Significance & Value Classificatio	n				
5.1	Townscape (Natural / Manmade)	A strategic large ar it. It occupies large important East-We	plot. It located on	Tilak Ro		
5.2	Architectural Description	Low scale, very long, G + 1 structure facing Tilak Road. It has Mangalore tiled sloping roof with large opening on façade. It is a load bearing structure in Vernacular style. This building accommodates offices. Lots of open space inside accommodates repair sheds. It also accommodates residential quarters which is a G+1 vernacular structure. Since access to the above premises was derived the information is not available in detail				
5.3	Intrinsic	Old Tram depot an is used as a bus de			ction in Dadar. No	ow it
5.4	Value Classification	B(uu), B(per), C(se	h), J	Recom	nmended Grade	II B
6.0	Topography					
6.1	Floors	Ground Floor, G +	1			
7.0	Construction					
7.1	Plinth	Dressed Black Bas	alt stone			
7.2	Walls	Load bearing brick	plastered			
7.3	Floor	Access denied				

12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai		
11.0	DP Remarks / Perceived Threats	Plot demarcated for BEST bus depot / station on proposed Development Plan (D.P).		
10.3	Articulation & Finishes	Not applicable		
10.2	Structure	No transformation		
10.1	Form	No transformation		
10.0	Transformation			
9.10	Overall condition	Fair Maintenance level Fair		
9.9	Outbuildings	Fair		
9.8	Services	Fair		
9.7	Articulation & Finishes	Good		
9.6	Roofing	Fair		
9.5	Openings	Good (Observed from outside)		
9.4	Stairs	Not applicable		
9.3	Floor	Access denied		
9.2	Walls	Good (Observed from outside)		
9.1	Plinth	Good		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
8.6	Fire precaution	Not applicable		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.1	Lighting	Natural and artificial, good natural lighting		
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Lots of Big trees, Open space, Tar and concreted space. Lots of sheds for repairing, Administrative office, Residential quarters.		
7.10	Compound / Fence / Gate	Plastered brick wall with iron fencing		
7.9	Interiors (Movable & Immovable)	Access denied		
7.8	Finishes	Externally and internally plastered and painted		
7.7	Articulation	Less ornamentation, concrete louvers and railing		
7.6	Roofing	glass panel  Sloping roof with Mangalore tiles		
7.5	Openings	Rectangular and semi circular opening with aluminium frame and		
7.4	Stairs	Not applicable		

# 720d, Bombay Electric Supply and Transport workshop



View of Best Workshop from Tilak Road showing arched opening.



Entrance to BEST Workshop from Tilak road.



Rare side of residential quarters from Tilak road.



Card No.: F/n-15

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.: 701, Vitthal Rakhumai Mandir



1.0	Denomination					
1.1	Name of Premises	701, Vitthal Rakhu	mai Mandir			
1.2	Earlier Name	Not applicable				
1.3	Built in	Late 19 <sup>th</sup> century	Extension Date (i	f any)	Not available	
2.0	Access					
2.1	Main	Katrak Road				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust owned				
4.0	Use					
4.1	Present	Religious				
4.2	Past	Religious	Religious			
4.3	Usage	Regular religious u	ise			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located on a large colony next to Wad	e rectangular plot or dala Gaothan.	n Katrak	Road on east of	Parsi
5.2	Architectural Description	Vernacular style temple located in Wadala. The entrance to the temple is through a Nagarkhana with wooden posts and trusses, supporting the Mangalore tiled pyramidal roof. <i>Garbhagriha</i> is constructed in Black Basalt stone coursed masonry. It has decorative Shikhar in Brick masonry supported on stone dome. Sabha Mandap is renovated in RCC roof supported on columns. Large open space around temple is used for social activities.				
5.3	Intrinsic		emples in Mumbai, oods (Gaothan) of I			as,
5.4	Value Classification	A(cul), A(his), C(se	eh)	Recon	nmended Grade	III
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Black Basalt stone	coursed masonry p	olinth hi	gh	
7.2	Walls	Load bearing wall	Load bearing wall of Garbhagriha in Basalt stone coursed masonry			
7.3	Floor	Marble floor				
7.4	Stairs	Not applicable				

7.5	Openings	Rectangular openings with wooden frame and paneling		
7.6	Roofing	Sloping roof supported on RCC columns (renovated), Garbh Gruh covered with ornamented Shikhar		
7.7	Articulation	Ornamented Shikhars. Decorative wooden doors.		
7.8	Finishes	Internally and externally exposed stone. Column, brackets painted.		
7.9	Interiors (Movable & Immovable)	Old Shrine of Lord Vitthal with wooden decorative doors		
7.10	Compound / Fence / Gate	Plastered brick masonry compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Open spaces with little shrubs		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good ((No settlement or cracks observed)		
9.2	Walls	Good (No leakage or dampness observed)		
9.3	Floor	Good (Recently finished in Marble)		
9.4	Stairs	Not applicable		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Good (No leakage observed. Mangalore tiles in good condition)		
9.7	Articulation & Finishes	Good (Recently painted)		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	Grills added to Sabha Mandap.		
10.2	Structure	One small room was added to Garbagriha subsequently.		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

#### Vittal Rakhumai Mandir



View of Vithal Rakhumai Mandir from Katrak road.




View of entrance to mandir through nagarkhana.



Decorative shikhar in brick masonary on temple.



Decorative shikhar in brick masonary on temple.



Shikhar from Inside constructed in stone over gabhara.



View of sabhamandap with decorative column supporting it.



Card No.: F/n-16

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Dadkar Garden



1.0	Denomination					
1.1	Name of Premises	Dadkar Garden				
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (	if any)	Not applicable	
2.0	Access					
2.1	Main	Lakhamashi Nappu	Lakhamashi Nappu Road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Not available				
4.0	Use					
4.1	Present	Recreational, Publi	Recreational, Public			
4.2	Past	Recreational, Public				
4.3	Usage	Regular public use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)		Located on a strategic location of junction Lakhamashi Nappu Road and internal road for Ruia college. Located parallel to Central Railway tracks.			
5.2	Architectural Description	Open garden shrubs and large trees at periphery. Pathways paved in cement tiles at periphery. It is used as playing ground for Matunga Gymkhana.			aved	
5.3	Intrinsic	Situated opposite Ruia & Poddar collage is extensively used by students and members of Matunga Gymkhana. The development of Hindu Colony which commenced in 1925 with well placed open spaces for recreation. They are very important today with the increase in population, presence of educational institutions and new development with increased FSI.				
5.4	Value Classification	C(seh), I(sce), J		Recom	nmended Grade	IIВ
6.0	Topography			•		
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				

7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Low height peripheral	random rubble wall wit	h no fencing
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Ground not covered with lawn and different kinds of shrubs and large trees		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, g	good natural lighting	
8.2	Ventilation	Natural and artificial, excellent natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Good
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Plot demarcated for playground on proposed Development Plan (D.P).		
12.0	Additional Notes / References / Documents Available	Note: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926. Used by many students as hangout space (Katta). It is extension to Matunga Gymkhana.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai		

### Dadkar Garden



View of garden from Lakhamashi Nappu Road.



Entrance to Garden from Lakhamashi Nappu Road.



Card No.: F/n-17

Ward (Part): F north-IV

**CS No.:** 758 / 10

Plot Area: 23112.2 sq. m.

**B U Area:** 18018 sq. m.

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.:

229-234, 244-246, Ramnarayan Ruia College



1.0	Denomination				
1.1	Name of Premises	229-234, 244-246, Ramnarayan Ruia College			
1.2	Earlier Name	Not applicable			
1.3	Built in	1938 Extension Date (if any) Not available			
2.0	Access				
2.1	Main	Lakhamashi Nappu Road			
2.2	Subsidiary	Hirlekar Chowk			
3.0	Ownership Pattern				
3.1	Present	Not available			
3.2	Past	Not available			
3.3	Status	Trust owned			
4.0	Use				
4.1	Present	Institutional			
4.2	Past	Institutional			
4.3	Usage	Regular institutional use			
5.0	Significance & Value Classification				
5.1	Townscape (Natural / Manmade)	Part of a group of educational institutions facing Lakhamashi Nappu Road overlooking Matunga Gymkhana and near the railway station.			
5.2	Architectural Description	Low-rise Art-Deco styled structure having corridors in front with rectangular columns on first and second floor. Cornice band at floor level. Staircase block and entrance foyer has columns with plain pediment. Main entrance to structure is from corner of plot facing the chowk. Both ends of building are highlighted by projection from Verandah giving a symmetrical character.			
5.3	Intrinsic	The Hindu colony is well laid out with infrastructure like open spaces and educational institutions. After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			
5.4	Value Classification	A(arc), B(uu) Recommended Grade II B			
6.0	Topography				
6.1	Floors	G + 3 ( Top floor added later )			
7.0	Construction				

7.1	Plinth	Malad dressed stone plinth		
7.2	Walls	Brick wall		
7.3	Floor	RCC Floor		
7.4	Stairs	RCC open well staircase		
7.5	Openings	Rectangular with wooden frames and glazed shutters		
7.6	Roofing	Flat roof terrace		
7.7	Articulation	Art Deco style structure with rectangular columns having no ornamentation spanning from first to second floors. Plain pediment and cornice band at floor level.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Old furniture		
7.10	Compound / Fence / Gate	Plastered brick wall steel fencing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Landscaped front open space as well as side opens spaces. Open space concreted. Big trees and shrubs used for landscape.		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Good ((No settlement or cracks observed)		
9.2	Walls	Good (No leakage or dampness observed)		
9.3	Floor	Good (Recently finished in Marble)		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good		
9.7	Articulation & Finishes	Good (Recently painted)		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	Grills added and interiors redone, windows changed.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot reserved for College on proposed Development Plan (D.P).		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

#### 229-234,244-246, Ramnarayan Ruia College



View of entrance to building from Lakhamshi Nappu Road.



West side elevation of Ruia College in Art Deco style.



Entrance to building from west side and decorative balcony over it.



Card No.: F/n-18

Ward (Part): F north-IV

**CS No.:** 758 / 10

Plot Area: 23112.2 sq. m.

**B U Area:** 18018 sq. m.

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above


**Photo** T-III-Fn:\Ward F north\ **Ref.:** 235-237, 241-243,

235-237, 241-243, Ramnirnjan Anandilala Podar College of Commerce and Economics



1.0	Denomination							
1.1	Name of Premises	235-237, 241-243, Ramnirnjan Anandilala Podar College of Commerce and Economics						
1.2	Earlier Name	Not applicable						
1.3	Built in	1937	Extension Date (i	if any)	Not available			
2.0	Access							
2.1	Main	Lakhamashi Nappu Road						
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Not available	Not available					
3.2	Past	Not available						
3.3	Status	Trust owned						
4.0	Use							
4.1	Present	Institutional	Institutional					
4.2	Past	Institutional						
4.3	Usage	Regular institutional use						
5.0	Significance & Value Classification							
5.1	Townscape (Natural / Manmade)	Part of a group of educational institutions facing Lakhamashi Nappu Road overlooking Matunga Gymkhana and near the railway station.						
5.2	Architectural Description	Expressing a strong horizontality, this Indo-Sarsenic style structure aquires a public scale by the raised staircase block which is treated as the Clock Tower. The long corridors with rectangular columns on first and second floors, cornice band at floor level provide the public scale. Both the ends of building is highlighted by projecting it out from Verhandah.						
5.3	Intrinsic	The Hindu colony is well laid out with infrastructure like open spaces and educational institutions. After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.						
5.4	Value Classification	A(arc), c (seh), I(sh	ne)	Recom	mended Grade	IIΒ		
6.0	Topography							
0.0	1 0 1 7							

7.0	Construction					
7.1	Plinth	Malad dressed stone plinth				
7.2	Walls	Malad stone and brick walls				
7.3	Floor	R.C.C floor				
7.4	Stairs	Wooden open well staircase				
7.5	Openings	Rectangular with wooden frames and glazed shutters				
7.6	Roofing	Flat roof terrace, dome on staircase block				
7.7	Articulation	Indo-Sarsenic style structure with rectangular columns having no ornamentation. Plain pediment and cornice band at floor level.				
7.8	Finishes	Parapet wall Internally and externally cement plastered and painted. Columns and staircase block exposed Malad stone.				
7.9	Interiors (Movable & Immovable)	Old furniture				
7.10	Compound / Fence / Gate	Malad stone wall with steel fencing				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Landscaped front open spaces as well as side open spaces. Open space concreted. Big trees and shrubs used for landscape.				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural lighting				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning at some places				
9.0	Condition					
9.1	Plinth	Good ((No settlement or cracks observed)				
9.2	Walls	Good (No leakage or dampness observed)				
9.3	Floor	Good (Recently finished in Marble)				
9.4	Stairs	Good				
9.5	Openings	Good				
9.6	Roofing	Good				
9.7	Articulation & Finishes	Good (recently painted)				
9.8	Services	Good				
9.9	Outbuildings	Good				
9.10	Overall condition	Good Maintenance level Good				
10.0	Transformation					
10.1	Form	Grills added and interiors redone, windows changed.				
10.2	Structure	Top floor added later.				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	Plot demarcated for College on proposed Development Plan (D.P).				
12.0	Additional Notes / References / Documents Available	Notes: Fits into streetscape. Must be preserved. After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				



View of Podar College from Lakhmshi Nappu road.




West side elevation of Podar College in indo-sarsenic style with clock tower.



North west corner of main building with decorative balcony.



Detail of clock tower and main entrance in indo - sarsenic style.



Card No.: F/n-19

Ward (Part): F north-IV

**CS No.:** 180 / 10

Plot Area: 909.70 sq.m.

**B U Area:** 1200 sq.m.

Date: April, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 212, Kamala Kunj



1.0	Denomination					
1.1	Name of Premises	212, Kamala Kunj				
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jehangir Road	d			
2.2	Subsidiary	Sir Bhalchandra Ma	arg			
3.0	Ownership Pattern					
3.1	Present	Municipal Corporati	ion for City of Bom	bay		
3.2	Past	Municipal Corporati	ion for City of Bom	bay		
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Corner plot at junction of Lady Jehangir Road and Sir Bhalchandra Marg on outskirts of Hindu colony			ındra	
5.2	Architectural Description	A sprawling bungal vernacular and Nec windows with concrarched entrance po above the façade.	o-classical vocabula rete jali, triangular p	ary. Sen pedimer	nicircular arched nt, semicircular	
5.3	Intrinsic	After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			areas, Γhe oal	
5.4	Value Classification	A(arc), B(des)		Recom	mended Grade	III
6.0	Topography			•		•
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone	coursed masonry p	olinth 0.6	6 m. high	
7.2	Walls	Composite brick ma	asonry			
7.3	Floor	Access denied				
7.4	Stairs	Access denied				
	-					

7.5	Openings	Rectangular with wood	den frames and glazed	shutters
7.6	Roofing	Flat terrace roof		
7.7	Articulation	Building has decorative entrance porch, concrete jali and semicircular arches		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Access denied		
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Compound is paved w	rith concrete blocks	
8.0	Services & Utilities			
8.1	Lighting	Access denied		
8.2	Ventilation	Access denied		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement of	or cracks observed)	
9.2	Walls	Good (No cracks obse	erved externally)	
9.3	Floor	Good (Access denied)	)	
9.4	Stairs	Good (Access denied)		
9.5	Openings	Good (Wooden memb	ers in sound state)	
9.6	Roofing	Good (Access denied)	)	
9.7	Articulation & Finishes	Good (Recently plaste	ered)	
9.8	Services	Good (Access denied)	)	
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Good
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



View of Kamala Kunj from Hirlekar chowk.



Corner of building showing different kinds of balconies behind dense vegetation.



Detail of entrance porch with decorative concrete jali above it. Arched decorative balcony on top floor.

Front façade is not visible due to dense vegetation



Card No.: F/n-20

Ward (Part): F north-IV

**CS No.:** 615A / 10

Plot Area: 819.30 sq.m.

**B U Area:** 1440 sq.m.

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 275, J.K. House



1.0	Denomination					
1.1	Name of Premises	275, J. K. House				
1.2	Earlier Name	Not applicable				
1.3	Built in	1932-35	Extension Date (if a	any)	Not applicable	
2.0	Access					
2.1	Main	Deodhar Marg				
2.2	Subsidiary	Telang Road	Telang Road			
3.0	Ownership Pattern					
3.1	Present	Trustees for improv	vement of city of Bom	nbay. J	ayraj Salgaokar.	
3.2	Past	Diggamber Balkrish	nna Gandbhir, Jayan	t Shivra	am Salgaokar	
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on the junction near the Ruia and Poddar colleges, this prominent building occupies a large foot print				is
5.2	Architectural Description	An imposing building due to its size and a proportionate pattern of bays of rectangular windows flanked by columns in Neo Classical Ionic and Doric style. Large balconies with metal railings, located at the end bays and the cornice bands at the floor levels enhance its high architectural value.			ical ed at	
5.3	Intrinsic	After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.				reas, he al
5.4	Value Classification	A(arc), A(grp),	F	Recomi	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	Black Basalt stone	plinth			
7.2	Walls	Brick walls				
7.3	Floor	R.C.C. slab				
7.4	Stairs	Wooden open well	staircase with woode	en balu	ısters	

7.5	Openings	Semi-circular arched and rectangular with wooden frames and glazed shutters		
7.6	Roofing	Mangalore tiled sloping roof with highly decorative wooden brackets		
7.7	Articulation	Rectangular glazed windows with semi-circular arches. Wooden open well staircase with decorative wooden balusters. Prominent balconies on the side.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Access denied		
7.10	Compound / Fence / Gate	Compound wall with simple CI railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Landscaping done all around the building		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No cracks observed externally)		
9.3	Floor	Good (Access denied)		
9.4	Stairs	Good (Access denied)		
9.5	Openings	Good (Wooden members in sound state)		
9.6	Roofing	Good (Access denied)		
9.7	Articulation & Finishes	Good (Recently plastered)		
9.8	Services	Good (Access denied)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	M.S. grills added and window air-conditioning units at some places.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Replastered and painted externally and internally.		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.		
		Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Front facade of building from Deodhar road along with compound wall having fencing of shrubs.



Detail of front façade showing different styles of columns on each floor with decorative motifs and concrete band.



Detail of corner of the building having decorative balcony.



Second floor showing Doric columns with cornice band, motifs along with concrete railing.



Balcony detail showing decorative brackets, cornice band and cast iron railing.



Card No.: F/n-21

Ward (Part): F north-IV

**CS No.:** 238 / 10

Plot Area: Not available

B U Area: Not available

Date: May, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 304, Matunga Primary

304, Matunga Primary School- English Medium



1.0	Denomination		<u>.</u>				
1.1	Name of Premises	304, Matunga Prima	ary School- English	n Mediu	m		
1.2	Earlier Name	Not applicable					
1.3	Built in	1937	Extension Date (if	f any)	Not applicable		
2.0	Access				•		
2.1	Main	Bhimani Street					
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Not available					
3.2	Past	Not available					
3.3	Status	Trust owned					
4.0	Use						
4.1	Present	School, Public	School, Public				
4.2	Past	School, Public					
4.3	Usage	School and public u	ıse				
5.0	Significance & Value Classification	n					
5.1	Townscape (Natural / Manmade)	Located on a small	plot on a narrow st	treet ne	ar Matunga Stati	on.	
5.2	Architectural Description	The structure is a continuous intervals. The windown in façade by plaster	ows on two upper f				
5.3	Intrinsic	One of the old prim planned by the Bon					
5.4	Value Classification	A (cul)		Recom	nmended Grade	Ш	
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth	Dressed stone plinth 0.9 m. high					
7.2	Walls	Composite brick masonry					
7.3	Floor	RCC slab	RCC slab				
7.4	Stairs	Access denied					
7.5	Openings	Rectangular openir	ngs with wooden fra	ames ar	nd glazed shutter	s	
7.6	Roofing	Flat roof terrace					

7.7	Articulation	Floor bands at all levels, simple architraves around windows, horizontal grooves on façade.		
7.8	Finishes	Internally and externa	lly plastered and painte	ed
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.10	Compound / Fence / Gate	Brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not provided		
8.0	Services & Utilities			
8.1	Lighting	Access denied		
8.2	Ventilation	Access denied		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement	or cracks observed)	
9.2	Walls	Good (No dampness	or cracks observed)	
9.3	Floor	Access denied		
9.4	Stairs	Access denied		
9.5	Openings	Good (Wooden memb	pers in sound state)	
9.6	Roofing	Access denied		
9.7	Articulation & Finishes	Good (Well maintaine	d)	
9.8	Services	Access denied		
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Good
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot reserved for Secondary school on proposed Development Plan (D.P).		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

### 304, Matunga Premier School, English Medium



View of school from Bhimani road showing south-side entrance.



Main entrance to school showing gate pillar and cast iron gate.



Corner detail of school showing stucco work around window, decorative motif below it. Coarsed Basalt stone plinth painted in red.



Rear side of school with moderate open scale.



Detail of stucco work around window on north side elevation.



Card No.: F/n-22

Ward (Part): F north-IV

**CS No.:** 241/10

**Plot Area:** 879.60 sq.m.

**B U Area:** 420.2 sq.m.

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 311, Shree Lakhamshi

Napoo Hall



		пароо пап					
1.0	Denomination						
1.1	Name of Premises	311, Shree Lakha	mshi Nappu Hall				
1.2	Earlier Name	Not applicable					
1.3	Built in	1932	Extension Date (if	f any) Not applicable			
2.0	Access	·		·			
2.1	Main	Telang Road					
2.2	Subsidiary	Cheda Sarkar Roa	ad				
3.0	Ownership Pattern						
3.1	Present	Trustees for impro	ovement of city of Bo	ombay, Premaji Velaji,			
3.2	Past	Trustees for impro	ovement of city of Bo	ombay, Velaji Lukhawsi			
3.3	Status	Trust					
4.0	Use						
4.1	Present	Multipurpose Hall,	, Public				
4.2	Past	Multipurpose Hall,	, Public				
4.3	Usage	Regular public use	Regular public use				
5.0	Significance & Value Classi	fication					
5.1	Townscape (Natural / Manma		Located on a corner plot at junction of Telang Road and Cheda Sarkar Road in Dadar Matunga estate				
5.2	Architectural Description	entrance of the ha	all. It has sloping cha	decorative columns at the decorative columns at the decoration of	or		
5.3	Intrinsic		y hall for social activi ped in 1920s and 30	ities in Dadar Matunga e	estate		
5.4	Value Classification	A(arc), B(uu), A (c	cul)	Recommended Grade	IIВ		
6.0	Topography						
6.1	Floors	Ground floor					
7.0	Construction	<u>.</u>					
7.1	Plinth	Dressed Malad sto	one coursed plinth				
7.2	Walls	Brick walls	Brick walls				
7.3	Floor	R.C.C. slab	R.C.C. slab				
			Access denied				
7.4	Stairs	Access denied					
7.4 7.5	Stairs Openings		ings with wooden fra	ames and glazed shutter	rs		

7.7	Articulation	Cornice bands at terrace level, architraves around windows		
7.8	Finishes		lly plastered and painte	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage	· · · · · · · · · · · · · · · · · · ·	
7.10	Compound / Fence / Gate	Brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not provided		
8.0	Services & Utilities	<u> </u>		
8.1	Lighting	Natural and artificial, f	air natural lighting	
8.2	Ventilation	Natural and artificial, f	air natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement of	or cracks observed)	
9.2	Walls	Fair (No dampness or	cracks observed)	
9.3	Floor	Fair (No sagging obse	erved)	
9.4	Stairs	Not applicable		
9.5	Openings	Fair (wooden member	rs in sound state)	
9.6	Roofing	Access denied		
9.7	Articulation & Finishes	Fair (Re-plastering red	quired)	
9.8	Services	Access denied		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot reserved for Publi	ic Hall on proposed Dev	velopment Plan (D.P).
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

# 311, Shree Lakhamshi Nappoo Hall



View of Shree Lakhamshi Nappoo Hall from junction of Telang road and Chandavarkar road



Deatail of window on east façade of hall



Plaque showing name of building



Decorative compound wall with pillars and cast iron gate of Shree Lakhamshi Nappoo Hall

#### **Mahavir Park Precinct**

Mahavir Park is one of the community settlements of the Gujarati Community in Mumbai. It has a character similar to a Baug or a Wadi. This Mahavir Park is excluded from Dadar Matunga Eastate which was planned by B.I.T. (Bombay Improvement Trust).

It is located near Matunga central railway station on Bhandarkar road. It has one very long chawl structure and one G + 4 building in Vernacular style. It has decorative cast iron railing, wooden louvers.

### Buildings in the Precincts:

- 1. Old Mahavir Chawl
- New Mahavir Building
- 3. Mahavir Sadan



Card No.: F/n-23

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Mahavir Building

Precinct



		Predinct	
1.0	Denomination		
1.1	Name of Premises	Mahavir Park Precinct	
1.2	Earlier Name	Not applicable	
1.3	Built in	Late 19 <sup>th</sup> century Extension Date (if any) Not applicable	
2.0	Access		
2.1	Main	Bhandarkar Road	
2.2	Subsidiary	Not applicable	
3.0	Ownership Pattern		
3.1	Present	Not available	
3.2	Past	Not available	
3.3	Status	Tenanted	
4.0	Use		
4.1	Present	Residential, Commercial	
4.2	Past	Residential, Commercial	
4.3	Usage	Regular residential and commercial use	
5.0	Significance & Value Classifica	tion	
5.1	Townscape (Natural / Manmade)	Located in the congested area on east side of Dadar Station abutting Bhandarkar Road.	
5.2	Architectural Description	The premises consist of 5 buildings, out of which 4 buildings are very old. The precinct depicts lifestyle of the working class population during the early 20 <sup>th</sup> century by narrow internal lanes along which open spaces and chawls are constructed. The structure abutting road is approximately 70m. long built in a vernacular chawl style has a road facing corridor running throughout the length, has only one straight flight staircase.  G + 3 structure in the interior has a corridor with wooden railings and louvers above. Three staircase blocks with semicircular arched openings divide the elongated façade in three parts.	
5.3	Intrinsic	One of the old community housing complex built for the Jain and Gujarathi Community in Dadar.	
5.4	Value Classification	A(arc), B ( per), C(seh), Recommended Grade	
6.0	Topography		
6.1	Floors	G + 1	
7.0	Construction		
7.1	Plinth	Not applicable	
7.2	Walls	Not applicable	
7.3	Floor	Not applicable	
Adarkar	Associates, Architects	122 Ward F north	

7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly paved central open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, poor natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Not applicable		
10.2	Structure	Not applicable		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Plot affected by shopline on proposed Development Plan. (D.P.)		
12.0	Additional Notes / References / Documents Available	Notes: Community precinct near Matunga station prime location.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

# **Mahavir Park precinct**



Front façade of Mahavir building showing symmetrical façade.



Mahavir chawl is G+1 elongated structure having only one staircase.



View of new Mahavir building.



Card No.: F/n-24

Ward (Part): F north-IV

**CS No.:** 293 / 10

Plot Area: 1614.55 sq.m.

**B U Area:** 1380 sq.m.

Date: April 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 395, Matunga Post and

Telegraph Office



1.0	Denomination						
1.1	Name of Premises	395, Matunga Post	and Telegraph Of	fice			
1.2	Earlier Name	Not applicable					
1.3	Built in	1930-35	Extension Date (i	if any)	Not applicable		
2.0	Access						
2.1	Main	Sir Bhandarkar Roa	ad				
2.2	Subsidiary	Telang Road	Telang Road				
3.0	Ownership Pattern						
3.1	Present	Central Governmen	nt Post & Telegram	n Depart	ment		
3.2	Past	Not available					
3.3	Status	Government owned	d				
4.0	Use						
4.1	Present	Post office, Public					
4.2	Past	Post office, Public					
4.3	Usage	Regular public use					
5.0	Significance & Value Classificatio	n					
5.1	Townscape (Natural / Manmade)	Corner plot at the ju on outskirts of Hind		kar Roa	nd and Telang Ro	ad	
5.2	Architectural Description	Vernacular style str scale building. The porch with square of balcony it has a Ma a symmetry.	structure is govern columns same feat	ned by a ure is u	recessed entrar sed on first floor	nce as a	
5.3	Intrinsic	One of the old Post of the infrastructure 1920s-30s	One of the old Post and telegraph offices built by the British as part of the infrastructure in the Dadar Matunga Estate developed in				
5.4	Value Classification	A(arc), B(uu), B(de	s), C(seh)	Recom	nmended Grade	IIΒ	
6.0	Topography						
6.1	Floors	G + 1					
7.0	Construction						
7.1	Plinth	Malad stone course	ed plinth				
7.2	Walls	Load bearing brick	walls				
7.3	Floor	R.C.C. slab	R.C.C. slab				
7.4	Stairs	Quarter turn R.C.C	. staircase				
7.5	Openings	Rectangular and ar	ched openings wit	h woode	en frames and gl	azed	

		shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Projecting cornice bands and window pediments, decorative columns at entrance		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall with CI railing and gate		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unbuilt space paved with Shahabad tiles, few trees around structure.		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Well maintained)		
9.5	Openings	Good (Wooden members in sound state)		
9.6	Roofing	Fair (Leakage observed at some places)		
9.7	Articulation & Finishes	Fair (Pipes need repairs)		
9.8	Services	Fair		
9.9	Outbuildings	Fair		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	One wall removed and replaced with steel stanchions and beam.		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot demarcated as Post & Telegram office on proposed Development Plan (D.P).		
12.0	Additional Notes / References / Documents Available	Notes: One of the old Post and telegraph offices built by the British for public service needs to conserve.		
		Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Front façade of Post office showing ramp and moderate front open space from main entrance on Bhandarkar road.




Decorative column detail on first floor Verhandah showing cornice bands.



Arched entrance to Post office Verhandah (less ornamentation).

Front façade is not visible due to dense vegetation and less front space



7.7	Articulation	Prominent wooden bra	ackets and balcony raili	ng	
7.8	Finishes	Internally and external	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall with CI railing	and gate	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unbuilt Space paved v	with concrete blocks		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	good natural lighting		
8.2	Ventilation	Natural and artificial, g	good natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement of	or cracks observed)		
9.2	Walls	Good (No dampness of	or cracks observed)		
9.3	Floor	Good (Well maintained	d)		
9.4	Stairs	Good (Wooden memb	ers in sound state)		
9.5	Openings	Good (No leakage obs	served)		
9.6	Roofing	Good (Well maintained	d)		
9.7	Articulation & Finishes	Good (No breaking or	cracking of pipes obse	rved)	
9.8	Services	Good			
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation	,			
10.1	Form	Sliding partition added	subsequently to balco	ny.	
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot affected by shopline on proposed Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

## 370, Ganger Niwas



Front elevation from Dr. Bhandarkar road.



Detail of Balcony showing cast iron railing.



East rear side view from Dr. Bhandarkar road.



Card No.: F/n-26

Ward (Part): F north-IV

**CS No.:** 483/10

Plot Area: 336.96 sq.m.

**B U Area:** 375 sq.m.

Date: April 28, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 67, Sanghvi Sadan



		-			
1.0	Denomination				
1.1	Name of Premises	67, Sanghvi Sadan			
1.2	Earlier Name	Not applicable			
1.3	Built in	1935 Extension Date (if any) Not applicable			
2.0	Access				
2.1	Main	Bhau Daji Road			
2.2	Subsidiary	Road no. 4			
3.0	Ownership Pattern				
3.1	Present	Municipal Corporation Greater Bombay.			
3.2	Past	Not available			
3.3	Status	Tenanted			
4.0	Use				
4.1	Present	Residential			
4.2	Past	Residential			
4.3	Usage	Regular residential use			
5.0	Significance & Value Classification	n			
5.1	Townscape (Natural / Manmade)	Located on a Bhau Daji Road, one of the major roads in Matunga. facing an open space.			
5.2	Architectural Description	Structure with a strong cubic form with minimal projection. It is characterized by rectangular windows with floor bands on first floor and terrace level. It has a Mangalore tiled pyramidal sloping roof.			
5.3	Intrinsic	Out of eight similar buildings in compound it is the only structure to which no floor is added.			
5.4	Value Classification	A(arc), G( grp) Recommended Grade			
6.0	Topography				
6.1	Floors	G + 2			
7.0	Construction				
7.1	Plinth	Plastered masonry plinth			
7.2	Walls	Load bearing brick wall			
7.3	Floor	R.C.C. slab beam			
7.4	Stairs	Open well R.C.C. staircase			
7.5	Openings	Rectangular with wooden frames and glazed shutters			
7.6	Roofing	Sloping roof with Mangalore tiles			
7.7	Articulation	Cornice band at floor level			

7.8	Finishes	Internally and external	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value		
7.10	Compound / Fence / Gate	Plastered Brick compo	ound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Paved with Shahabad	tiles		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	good natural lighting		
8.2	Ventilation	Natural and artificial, f	air natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not available			
8.7	Other (HVAC / BMS / Security Systems)	Not available			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging obs	served)		
9.4	Stairs	Good (Well maintained	d)		
9.5	Openings	Good (Wooden memb	ers in sound state)		
9.6	Roofing	Good (No leakage obs	served, Mangalore tiles	in sound state)	
9.7	Articulation & Finishes	Good (Recently replace	stered and painted)		
9.8	Services	Good (Well maintained	d)		
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



Card No.: F/n-27

Ward (Part): F north-IV

**CS No.:** 343 / 10

Plot Area: 4714.08 sq.m.

**B U Area:** 5550 sq.m.

Date: April, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 414-415, Byramjee

414-415, Byramjee Jeejeebhoy Home for Children Complex



1.0	Denomination					
1.1	Name of Premises	414-415, Byramjee Jeejeebhoy Home	414-415, Byramjee Jeejeebhoy Home for Children Complex			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century Extension Date (	if any) Not applica	able		
2.0	Access					
2.1	Main	Bhau Daji Road				
2.2	Subsidiary	Shraddhanand Road				
3.0	Ownership Pattern					
3.1	Present	Trustees for Improvement of City of E	Bombay, Kusum Kan	na		
3.2	Past	Nanabhoy Behramji Jeejeebhoy. Nar	nabai Maneklal Prem	chand		
3.3	Status	Trust				
4.0	Use					
4.1	Present	Children Home, Public and Social Se	rvice			
4.2	Past	Children Home, Public and Social Se	rvice			
4.3	Usage	Regular public and social use				
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	A large compound containing a comp from the Shraddhanand Road. since		as seen		
5.2	Architectural Description	structures with wooden balconies and	Premises consist of five buildings with vernacular character. G + 1 structures with wooden balconies and Mangalore tiled sloping roof. Since the access was denied the detailed information is not available.			
5.3	Intrinsic	One of important and old orphanages generous donations by Parsi commun		he		
5.4	Value Classification	A(arc), B(uu), C(seh), G(grp)	Recommended Gr	ade II		
6.0	Topography		•			
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone plinth				
7.2	Walls	Brick masonry wall				
7.3	Floor	Access denied				
7.4	Stairs	Access denied				
7.5	Openings	Rectangular openings with wooden fr	aming			
7.6	Roofing	Sloping roof with Mangalore tiles				
	•	•				

7.7	Articulation	Access denied		
7.8	Finishes	Access denied		
7.9	Interiors (Movable & Immovable)	Access denied		
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Densely wooded		
8.0	Services & Utilities			
8.1	Lighting	Access denied		
8.2	Ventilation	Access denied		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not available		
8.7	Other (HVAC / BMS / Security Systems)	Not available		
9.0	Condition			
9.1	Plinth	Fair		
9.2	Walls	Fair		
9.3	Floor	Access denied		
9.4	Stairs	Access denied		
9.5	Openings	Access denied		
9.6	Roofing	Access denied		
9.7	Articulation & Finishes	Access denied		
9.8	Services	Access denied		
9.9	Outbuildings	Access denied		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	Access denied		
10.2	Structure	Access denied		
10.3	Articulation & Finishes	Access denied		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



View of structure from Junction of Dr. Bhau Daji road & Shradhanand road.



Verandah covered with wooden railing & jali.



Main entrance with one of the main block behind it from Shradhanand road.



Main office block in Vernacular style from Shradhanand road.



Corner block with sloping roof, wooden jali & railing.

Front façade is not visible due to dense vegetation



Common	Ref.	No.:	

Card No.: F/n-28

Ward (Part): F north-IV

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 96, F/North Ward office



1.0	Denomination				
1.1	Name of Premises	96, F north Ward of	fice		
1.2	Earlier Name	Not applicable			
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (if any	) Not applicable	
2.0	Access				
2.1	Main	Dr. Bhau Daji Road			
2.2	Subsidiary	Not applicable	Not applicable		
3.0	Ownership Pattern				
3.1	Present	MCGM			
3.2	Past	MCGM			
3.3	Status	MCGM			
4.0	Use				
4.1	Present	Administrative			
4.2	Past	Administrative			
4.3	Usage	Regular Administra	Regular Administrative		
5.0	Significance & Value Classification				
5.1	Townscape (Natural / Manmade)		Structure is on rectangular plot facing Dr. Bhau Daji raod which is an important interior road in Matunga.		
5.2	Architectural Description	G + 1 Vernacular structure with sloping roof expresses a strong horizontal character. The simple façade has minimal ornamentation like cornice bands running at floor level. The architectural character is acquired by the proportionate identical windows highlighted by a small motif, on both the floors and by the large sloping roof.			
5.3	Intrinsic	MCGM owned old administrative office building in Matunga area built as infrastructure in the Dadar Matunga Estate developed in 1920s-30s			
5.4	Value Classification	A(arc), B(uu)	Rec	ommended Grade	III
6.0	Topography				
6.1	Floors	G+1			
7.0	Construction	•			
7.1	Plinth	Black Basalt stone	plinth		
7.2	Walls	Brick masonry wall			
7.3	Floor	Timber flooring			
7.4	Stairs	Wooden dog legged staircase			
7.5	Openings	Rectangular openin	gs with wooden frames	and glazed shutter	s
7.6	Roofing	Sloping roof with as	sbestos sheets		

7.7	Articulation	Cornice bands, pedim	ents around window a	nd motifs	
7.8	Finishes	•	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	-	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided	<u> </u>		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Buildings have open s	space in front concreted	d	
8.0	Services & Utilities	1			
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Fair (No settlement or cracks observed)			
9.2	Walls	Fair (No dampness or	cracks observed)		
9.3	Floor	Fair (No sagging obse	erved)		
9.4	Stairs	Fair			
9.5	Openings	Fair			
9.6	Roofing	Fair			
9.7	Articulation & Finishes	Fair (Plaster damaged	d)		
9.8	Services	Fair			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot demarcated for Municipal office and Municipal primary school on proposed Development Plan (D.P).			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

# 96, F/North Ward Office



View of F/North Ward Office from Dr. Bhaudaji Lad road.



Detail of windows in front façade.



Card No.: F/n-29

Ward (Part): F north-IV

**CS No.**: 547

Plot Area: 403.01 sq.m.

**B U Area:** 748 sq.m.

Date: April, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** F-North 3 and 4

F-North 3 and 4 Repairing Office & Municipal School



1.0	Denomination				
1.1	Name of Premises	F north 3 and 4 Re	F north 3 and 4 Repairing Office & Municipal School		
1.2	Earlier Name	Not applicable	Not applicable		
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (i	if any)	Not applicable
2.0	Access				
2.1	Main	Laxmi Narayan Lar	ne		
2.2	Subsidiary	Not applicable			
3.0	Ownership Pattern				
3.1	Present	Trustees for Impro	vement of City of B	ombay,	Ammi Mahavir
3.2	Past	Trustees for Impro	vement of City of B	ombay,	Ammi Mahavir
3.3	Status	B.M.C. office			
4.0	Use				
4.1	Present	Repair office of MC	Repair office of MCGM & School		
4.2	Past	Repair office of MC	CGM & School		
4.3	Usage	Regular administra	tive & educational	use	
5.0	Significance & Value Classification	1			
5.1	Townscape (Natural / Manmade)	Rectangular plot or Station (East).	n Laxmi Narayan L	ane nea	r Matunga Railway
5.2	Architectural Description	Modest structure following Neo-classical vocabulary in its entrance porch comprising of three semicircular arches with stuccowork. First floor has a terrace above porch with concrete jali. The structure has cornice band and decorative timber brackets to support the Mangalore tiled sloping roof above.			
5.3	Intrinsic	One of the building of Mumbai by the E			rpose in various parts I public use.
5.4	Value Classification	A(arc), B(uu)		Recom	nmended Grade II B
6.0	Topography				
6.1	Floors	G + 1			
7.0	Construction				
7.1	Plinth	Black Basalt stone	coursed masonry	plinth	
7.2	Walls	Load bearing brick walls			
7.3	Floor	Wooden flooring w	ith wooden joists a	nd batte	ns
7.4	Stairs	Wooden dog legge	d staircase		

7.5	Openings	Rectangular with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Projecting cornice bands, window pediments, CI railings and semi- circular arches seen on façade		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Random rubble compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large open space with few trees in compound		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, poor natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Poor (No settlement observed, cracks and dampness observed which makes the plinth weak)		
9.2	Walls	Fair (Crack seen on internal walls)		
9.3	Floor	Fair (Wooden members need maintenance)		
9.4	Stairs	Fair (Sagging observed at few places, some trees broken)		
9.5	Openings	Poor (Wooden members need maintenance)		
9.6	Roofing	Poor (Mangalore tiles broken at some places, leakage observed, fascia needs repairs)		
9.7	Articulation & Finishes	Poor (Plaster chipped off, façade attacked by moss, trees growth observed on facade)		
9.8	Services	Poor		
9.9	Outbuildings	Poor		
9.10	Overall condition	Poor Maintenance level Poor		
10.0	Transformation	<u> </u>		
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Note: Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

## F-north 3 & 4 repairing office and Municipal Office



Side block along with arched verandah from Varjivandas road.



Detail of semi circular arch with stucco work having decorative railing above.



Detail of central block showing concrete jali & arched opening.



South side of block from inside compound.



_			
Common	RΔt	NO .	
	1161.	110	

Card No.: F/n-30

Ward (Part): F north-IV

**CS No.:** 548

Plot Area: 292.64 sq.m.

**B U Area:** 240 sq.m.

Date: April, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Dharmkshetra

Dharmkshetra Compound



		Compound	
1.0	Denomination		
1.1	Name of Premises	Dharmkshetra Compound	
1.2	Earlier Name	Not applicable	
1.3	Built in	Early 20 <sup>th</sup> century Extension Date (if any) Not applicable	
2.0	Access		
2.1	Main	Varjivandas Marg	
2.2	Subsidiary	Not applicable	
3.0	Ownership Pattern		
3.1	Present	Trustees for Improvement of City of Bombay	
3.2	Past	Rukhminibai Gulab Dalia	
3.3	Status	Tenanted	
4.0	Use		
4.1	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Regular residential use	
5.0	Significance & Value Classification	on	
5.1	Townscape (Natural / Manmade)	A complex of three buildings plot facing Varjivandas Marg abutting to Central Railway line near Matunga Station (East).	
5.2	Architectural Description	The Dharmkshetra compound consists of three buildings, two with strong vernacular character. G + 1 structure is a chawl with corridor running throughout on ground and first floors. The balconies have M.S. decorative railings and wooden louvers above. The Mangalore tiled sloping roof has carved fascia. The ground floor structure is a Caretaker's residence in a modest vernacular style structure with load bearing walls and Mangalore tiles sloping roof.	
5.3	Intrinsic	Belongs to the typology of a Wadi in which a group of buildings or a large chawl is planned around a common community space away from the access road. Mainly seen in the central parts of the island city.	
5.4	Value Classification	A(arc), C(seh) Recommended Grade III	
6.0	Topography		
6.1	Floors	G + 2, G + 1, Ground floor	
7.0	Construction		
7.1	Plinth	Black Basalt stone random rubble masonry	
7.2	Walls	Load bearing brick walls	
7.3	Floor	Timber joist floor, M.S. floor	

7.4	Stairs	Single flight wooden staircase with decorative balustrades
7.5	Openings	Rectangular opening with wooden frames and glazed shutters
7.6	Roofing	Sloping roof Mangalore tiles
7.7	Articulation	Decorative cast iron railing to verandah of chawls
7.8	Finishes	Internally and externally cement plastered and painted
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value
7.10	Compound / Fence / Gate	Cast iron gate for premises
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal unpaved open space in premises
8.0	Services & Utilities	
8.1	Lighting	Natural and artificial, fair natural lighting
8.2	Ventilation	Natural and artificial, fair natural ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and Sanitation)	MCGM
8.6	Fire precaution	Not provided
8.7	Other (HVAC / BMS / Security Systems)	Not provided
9.0	Condition	
9.1	Plinth	Fair (No settlement observed, cracks observed at some places)
9.2	Walls	Fair (Dampness observed at some places)
9.3	Floor	Fair (Sagging observed at some places)
9.4	Stairs	Fair (Wooden members need maintenance)
9.5	Openings	Fair (Some windows need repairs)
9.6	Roofing	Fair (Mangalore tiles and fascia need repairs)
9.7	Articulation & Finishes	Fair (Plaster attacked by moss)
9.8	Services	Fair (Broken pipes need replacement)
9.9	Outbuildings	Fair
9.10	Overall condition	Fair Maintenance level Fair
10.0	Transformation	
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	No transformation
11.0	DP Remarks / Perceived Threats	None
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.

#### **Dharmkshetra Compound**



Main building with decorative wooden louvers, cast iron railing facia.



Decorative cast iron railing on first floor having common passage supported with wooden post. Decorative wooden facia is supported with small brackets.



Care takers house in vernacular style with levels in roof. Main building with decorative wooden louvers, cast iron railing facia.



Steel staunction supporting common passage alongwith cast iron railing. Wooden louvers on upperside of common passage.

Front façade is not visible due to proximity of neighbouring structure

The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Co-operative Society.

Many buildings in this precinct follow similar scale and proportions The buildings of the precinct are low rise (G + 2) and have a Vernacular character with typical balconies and with minimal ornamentation on the facade. Each building is located on an individual plot with trees along the tree lined road. Most of the buildings have out house used for servant or used as garage. The Five Gardens area is centrally located in the precinct. Infrastructural amenities like Rsustam Farmana Agiary, J. B. Vaccha School, Asharnan Parsi Madaresa are located around the Five Gardens. Some of the private plots are being developed haphazardly at present using TDR as G + 6 buildings

The Zoroastrian (Parsi) community of Bombay, mostly resided in colonies / precincts specially built for all the sections of the community, by the Parsi Trusts or Parsi Panchayat. They were located at various places in the island city. The 'Baugs' are sprawling colonies built around large open spaces mainly occupied by upper class. The middle and poorer precincts were often built in the high density localities on the main road extending inside along the narrow internal streets. An agiary (a Parsi temple) is often located within the precinct.



Card No.: F/n-31

Ward (Part): F north-IV & VI

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Parsi Colony Precinct



		•			
1.0	Denomination				
1.1	Name of Premises	Parsi Colony Prec	inct		
1.2	Earlier Name	Not applicable			
1.3	Built in	1920's	Extension Date (if a	ny) Not applicable	
2.0	Access	·		·	
2.1	Main		Road, Lady Jehangir R hed Road, Khareghat Katrak Road.		
2.2	Subsidiary		Dr. Ghanti Road, Dins y Road no. 1 to 14.	haw Master Road, Fi	rdausi
3.0	Ownership Pattern				
3.1	Present	Trustees for Impro	evement City of Bomba	ay, Parsi Panchayet	
3.2	Past	Trustees for Impro	ovement City of Bomba	y, Parsi Panchayet	
3.3	Status	Trust, Private, Ter	nanted		
4.0	Use	•			
4.1	Present	Not applicable			
4.2	Past	Not applicable			
4.3	Usage	Not applicable			
5.0	Significance & Value Classification	n			
5.1	Townscape (Natural / Manmade)	Colony Precinct.T	ion near Dadar on the his precinct is develop any garden spaces.		
5.2	Architectural Description	Many buildings in this precinct follow similar scale and proportions. The buildings of the precinct are low rise (G + 2) and have a Vernacular character with typical balconies and with minimal ornamentation on the facade. Each building is located on an individual plot with trees along the tree lined road. The Five Gardens area is centrally located in the precinct. Infrastructural amenities like Rustam Farmana Agiary, J. B. Vaccha School, Asharnan Parsi Madaresa are located around the Five Gardens. Some of the private plots are being developed haphazardly at present using TDR as G + 6 buildings			al ns.
5.3	Intrinsic	The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT). The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Co-operative Society.			

6.0	Topography			
6.1	Floors	Not applicable		
7.0	Construction			
7.1	Plinth	Not applicable		
7.2	Walls	Not applicable		
7.3	Floor	Not applicable		
7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	All buildings have uniform open space around it. It is paved or concreted. Little shrubs or big trees around buildings. Each building has out house for servant behind it or used as garage or servants residence room.		
8.0	Services & Utilities			
8.1	Lighting	Not applicable		
8.2	Ventilation	Not applicable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Not applicable Maintenance level Not applicable		
10.0	Transformation	<del>,</del>		
10.1	Form	Not applicable		
10.2	Structure	Not applicable		
10.3	Articulation & Finishes	Not applicable		
11.0	DP Remarks / Perceived Threats	Plots fall under a Residential Zone on proposed Development Plan. (D.P.)		

12.0	Additional Notes / References / Documents Available	Notes: The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community, by the Parsi Trusts or Parsi Panchayat. They were located at various places in the Island City. The 'Baugs' are sprawling colonies built around large open spaces mainly occupied by upper class. The middle and poorer precincts were often built in the high density localities on the main road extending inside along the narrow internal streets. An agiary (a Parsi temple) is often located within the precinct.
		Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai



View of Dinshaw Master road



View of parsi colony road no. 4



View of east side Firdausi road



View of Asharnan Maderesa in Parsi colony



Façade of Cawsjji Jehangir Block on Dinshaw Master road



View of west side Firdausi road



View of Meghs Bhuvan where Sane Guruji lived for some year on Dr. Ghanti road



Façade of Jeejibhoy block no.1 on Khareghat road



View of Jesia building on Jame Jamshet road



View of open ground on Khareghat road



View of Pehramji building no. 4 on Mancheraji Joshi road



Façade of Goola mansion Jame Jamshet road



Façade of Jeejibhoy block no.3 on Khareghat road



View of open ground on Parsi colony road no 14



Façade of Vipin Villa on Jame Jamshet road



Façade of Patel building on Jame Jamshet road



Façade of Turel terrace on A H road



Façade of Adenwala building on A H road



Façade of Adenwala building on A H road



Out building of Patel block on Mancheraji Joshi road



Façade of Seherenham building on Parsi colony road no. 14



Façade of Shanti building on H Adenwala road



Façade of Rati manzil on Mancheraji Joshi road



Façade of Amardad block on Parsi colony road no. 9



View of Band view building on Lady Jehangir road



View of building on Katrak road



View of Shree Ram building on Parsi colony road no. 4



View of Soban Bhuvan building on Mancheraji Joshi road




View of Khurshed Mahal on Dinshaw Master road



Detail of entrance to building with Farohar.



Detail of entrance to building



7.2	Walls	Load bearing brick walls		
7.3	Floor	Wooden flooring with wooden joists and battens		
7.4	Stairs	Wooden open well staircase with decorative wooden balustrades		
7.5	Openings	Rectangular with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses and a simple wooden fascia		
7.7	Articulation	Has ample open space around with some amount of landscaping done. Prominent balconies on external facades having Moorish arches on the second floor. Decorative wooden balusters.		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Kurla Basalt stone compound wall with CI decorative entrance gates and has decorative concrete jalis		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Has ample open space with some amount of landscaping done		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on side façade		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging or deflection observed)		
9.4	Stairs	Good (Well maintained)		
9.5	Openings	Good (Window panels and wooden members in sound state)		
9.6	Roofing	Good (Well maintained)		
9.7	Articulation & Finishes	Good (Recently re-plastered and repainted)		
9.8	Services	Good (No leakage of breaking of pipes observed)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Re-plastered and painted.		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

### 764D, Meherbai D. Wadia Building



View of building from Mancherji Joshi road.



Detail of second floor balcony showing decorative wooden railing fixed in wooden post with ornamented arch supporting sloping roof.



Card No.: F/n-31b

Ward (Part): F north-VI

**CS No.:** 526E/10

Plot Area: 510.10 sq.m.

**B U Area:** 664 sq.m.

**Date:** May 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: 764C, Baliwada Building




1.0	Denomination					
1.1	Name of Premises	764C, Baliwada Bu	ilding			
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Jame Jamshed Roa	ad			
2.2	Subsidiary	Dr. Ghanti Road				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)		ortant location with res at this junction of J ad and Tilak Road.			The
5.2	Architectural Description	The structure has decorative façade responding to the location on corner. This Vernacular building consists of balconies with arches and ornamental railing supported on carved concrete brackets. The balconies have sloping roof with Mangalore tiles in harmony with the large simple features like rectangular openings; plain cornice bands etc.				
5.3	Intrinsic	colonies / precincts community located colony is one of the	arsi) community of B specially built for al at various places in biggest community unity in India. Just lik y located centrally.	I the se the isla settlen	ections of the and city. Dadar Pa nents of the	arsi
5.4	Value Classification	A(arc), C(seh), G(g	rp)	Recom	mended Grade	III
6.0	Topography		,		<u>'</u>	
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Kurla Basalt stone p	olinth in ashlar masc	onry		
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Wooden flooring wi	th wooden joists and	d batter	ns	
		•				

7.4	Stairs	Wooden open well staircase with decorative wooden balustrades		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses and a simple wooden fascia		
7.7	Articulation	Has ample open space around with some amount of landscaping done. Prominent balconies on external facades having Moorish arches on the second floor. Balconies have decorative wooden balusters.		
7.8	Finishes	Internally and externally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Kurla Basalt stone compound wall with CI decorative entrance gates and has decorative concrete jalis		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Has ample open space around with some amount of landscaping done		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on side façade		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging or deflection observed)		
9.4	Stairs	Good (Well maintained)		
9.5	Openings	Good (Window panels and wooden members in sound state)		
9.6	Roofing	Good (Well maintained)		
9.7	Articulation & Finishes	Good (Recently re-plastered and repainted)		
9.8	Services	Good (No leakage of breaking of pipes observed)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Re-plastered and painted.		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Co-operative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

### 764C, Baliwada Building



Front façade of Baliwala building from Dr. Ghanti road.



Detail of Balconies of Baliwala building.



Detail of Balconies of Baliwala building.



View of corner Baliwala building from junction of Dr. Ghanti road and Mancheraji Joshi road.



Detail of wooden post, Moorish arch, glass panel on second floor of Baliwala building.



Detail of Balconies showing wooden railing, wooden brackets on first floor of Baliwala building.



Card No.: F/n-31c

Ward (Part): F north-VI

**CS No.:** 570 / 10

Plot Area: 928.93 sq.m.

**B U Area:** 1440 sq.m.

**Date:** May, 2005

Record by: Keshav S, Swapnil B


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\

Ref.: 762, Ahura



1.0	Denomination					
1.1	Name of Premises	762, Ahura				
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Mancherji Joshi Ro	oad			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	l use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located on a recta the major roads of	ngular plot facing N Parsi colony.	/lancher	ji Joshi Road. O	ne of
5.2	Architectural Description	interesting roof pro floors having decor decorative wooden project on the first railing on the secon	having sloping room offile and prominent rative wooden balus of columns character and third floors. Ba and floor supported of opound wall with steat at facade.	corridor sters. M rized the Iconies on deco	s on first and sec oorish arches ar e facade. Floor b have R.C.C. jali rative R.C.C.	cond nd ands
5.3	Intrinsic	colonies / precincts community located colony is one of the Zoroastrian Comm	Parsi) community of s specially built for a lat various places is biggest community in India. Just by located centrally.	all the son the islety settlen like any	ections of the and city. Dadar I ments of the	Parsi
5.4	Value Classification	A(arc), C(seh), G(g	grp)	Recom	nmended Grade	Ш
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
		Kurla Danalt danaa		linth		
7.1	Plinth	Kurla Basalt dresse	ed stone masonry p	ווווווווווווווווווווווווווווווווווווווו		

7.0	Floor	Mooden flooring with wooden inite and bettern		
7.3	Floor	Wooden flooring with wooden joists and battens		
7.4	Stairs	Wooden open well staircase with wooden balustrades and decorative newel post		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Prominent corridors on front facade with Moorish arches.  Decorative wooden balusters and prominent balconies supported on R.C.C. brackets.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Compound wall has M.S. railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Little space around building used for parking		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Wooden members in sound state)		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Good (No leakage or breaking of Mangalore tiles observed)		
9.7	Articulation & Finishes	Good (Well maintained)		
9.8	Services	Good (No breakage or leakage of pipes observed)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	Corridor on third floor enclosed, wooden beams are replaced by M.S. channels at some places.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Re-plastered and painted subsequently.		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Front façade balcony details with decorative cast iron entrance gate and post.



Front façade from Mancheraji Joshi road.



Detail of decorative wooden work on first floor.



Wooden Post, railing & arches details on first & second floor recessed balconies.



Balcony detail on first floor with decorative bracket, showing cornice band and motifs.

		Card N Ward (I CS No. Plot Ar B U Arc Date: A Record Review Interna	Part): F north-VI : 102 / 10 ea: 381.27 sq. m.	rth\	570 10	JOSHI A  SZII. 10  MAJABHAI MANSION  TEE	51 10 55 10 55 10 10 10 10 10 10 10 10 10 10 10 10 10
1.0	Denomination						
1.1	Name of Premises		761, Najabhai Mans	sion			
1.2	Earlier Name		Not available				
1.3	Built in		1935	Exte	nsion Date (if any)	Not applicable	
2.0	Access						
2.1	Main		Mancherji Joshi Ro	ad			
2.2	2 Subsidiary		Not applicable				
3.0	Ownership Pattern		,				
3.1	Present		Byramji Bhowngir, Faruk Bhowngir, Adi mehata, Perin Bhowngir			gir	
3.2	Past		Trustees for improv	emen	t of city of Bombay		
3.3	Status		Private				
4.0	Use						
4.1	Present		Residential				
4.2	Past		Residential				
4.3	Usage		Regular residential use				
5.0	Significance & Value Class	ification	<b>I</b>				
5.1	Townscape (Natural / Manma	ade)	Flat roof structure lo Joshi Road.	ocated	d on a rectangular p	lot facing Manche	erji
5.2	Architectural Description		G + 2 low rise structure with flat roof terrace having sloping roof with Mangalore tiles for staircase block only. Floor bands project on the first floor. Balconies have RCC jali railing on the second floor supported on decorative RCC brackets. Decorative stain glass ventilators for corridors on first floor. It has decorative wooden jali railing compound wall with decorative M.S. railing.			ect on oor s	
5.3	5.3 Intrinsic		The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.			Parsi	
5.4	Value Classification		A(arc), G(grp)		Recor	mmended Grade	III
6.0	Topography						
6.1	Floors		G + 2				
7.0	Construction						
7.1	Plinth		Kurla basalt dresse	d ston	ne plinth		
7.2	Walls		Brick load bearing v	valls			
7.3	Floor		Wooden flooring wi	th woo	oden joists, battens	and columns	

7.4	Stairs	Dog legged wooden s	taircase	
7.5	Openings	Rectangular openings and stain glass ventila	with wooden frames at	nd glazed shutters
7.6	Roofing	Flat roof terrace, slopii trusses over staircase	ng roof with Mangalore block	tiles and wooden
7.7	Articulation	Balconies have decorative RCC jali railing. Corridors on first floor have decorative wooden railing with stain glass ventilators.		
7.8	Finishes	Cement plastered and	painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.10	Compound / Fence / Gate	Brick compound wall with M.S. railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Front and side open s	paces	
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, f	air natural lighting	
8.2	Ventilation	Natural and artificial, f	air natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Good (No settlement of	or cracks observed)	
9.2	Walls	Good (No dampness of	or cracks observed)	
9.3	Floor	Good (No sagging obs	served)	
9.4	Stairs	Good (Wooden memb	ers in sound state)	
9.5	Openings	Good (Well maintaine	d)	
9.6	Roofing	Good (No leakage or l	oreaking of Mangalore	tiles observed)
9.7	Articulation & Finishes	Good (Well maintained	d)	
9.8	Services	Good (No breakage or	leakage of pipes obse	rved)
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Poor
10.0	Transformation			
10.1	Form		added, balconies enclos and columns replaced on ground floor.	
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

### 761, Najabhai Mansion



Front view of Najabhai Mansion from Mancherji Joshi road.



Detail of recessed balcony on first floor with cast iron railing and stained glass panel.



Detail of balconies on first floor and second floor of Najabhai Mansion building.



Card No.: F\n-31e

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.: 726, Phermarjee Building no. 5



1.0	Denomination					
1.1	Name of Premises	726, Phermarjee Bu	uilding no. 5			
1.2	Earlier Name	Not applicable				
1.3	Built in	1927	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Mancheraji Joshi Road				
2.2	Subsidiary	Dr. Dinshaw Maste	r Road			
3.0	Ownership Pattern					
3.1	Present	Trustees for improv	ement of city of Bo	mbay, I	Private	
3.2	Past	Trustees for improv	ement of city of Bo	mbay, I	Private	
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Corner plot at junct Master Road, which				
5.2	Architectural Description	G + 2 articulated building, mixed structure. Load bearing walls and R.C.C floor. Balconies supported on concrete brackets and its roof is supported on wooden posts. Wooden railing seen. Two side blocks have symmetrical balconies with cast iron railing. It forms symmetrical façade. It has Mangalore tiled sloping roof. It has Furoher motif on staircase block. Cornice band at floor level, pediments and motifs below window. Ground floor balcony has decorative concrete columns supporting above.				
5.3	Intrinsic	Corner plot facing Mancheraji Joshi Road, which is one of the major roads in Parsi colony. The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.				
5.4	Value Classification	A(arc), B(des)		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Coursed Black Bas	alt stone plinth			

7.2	Walls	Load bearing brick walls		
7.3	Floor	RCC slab flooring		
7.4	Stairs	Wooden dog legged staircase with highly decorative newel post		
7.5		Rectangular openings with wooden frames and glazed shutters		
	Openings			
7.6	Roofing	Sloping roof in Mangalore tiles		
7.7	Articulation	Highly decorative with cast iron railing, ornamental posts in wood. Pediments, motifs below windows. Cornice bands running at floor level. Decorative columns to balcony at ground floor.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Low height plastered brick wall with cast iron railing on it		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Trees within the compound. Front open space paved with Coursed Black Basalt stone.		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good (Roof joints open at some junction )		
9.7	Articulation & Finishes	Good (Need to be re-paint, cracks in brackets )		
9.8	Services	Fair		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

### 726, Phermarjee Building no. 5



View of Pehrmaji building from Mancherji Joshi road.




Detail of balcony on second floor with ornamented railing fixed wooden post supporting sloping roof.



View of staircase block showing decorative entrance to building.



West side elevation of building showing decorative balconies along with entrance gate.



7.0	Construction						
7.1	Plinth	Black Basalt dressed stone plinth					
7.2	Walls	Brick load bearing wall	ls				
7.3	Floor	RCC slab flooring	RCC slab flooring				
7.4	Stairs	RCC staircase with sto	one treads and C.I. bal	ustrades			
7.5	Openings	Rectangular openings	with wooden frames a	nd glazed shutters			
7.6	Roofing	Sloping roof with Mang	galore tiles and wooder	n trusses			
7.7	Articulation		ntel level on first floor. ( block. Plain architrave				
7.8	Finishes	Sand-faced cement pla	aster and paint				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value				
7.10	Compound / Fence / Gate	Brick compound wall v	vith decorative M.S. rai	ling			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large open spaces in	front and on the sides				
8.0	Services & Utilities						
8.1	Lighting	Natural and artificial, fa	air natural lighting				
8.2	Ventilation	Natural and artificial, fa	air natural ventilation				
8.3	Electricity	BEST					
8.4	Water Supply	MCGM					
8.5	Drainage (Plumbing and Sanitation)	MCGM					
8.6	Fire precaution	Not provided					
8.7	Other (HVAC / BMS / Security Systems)	Not provided					
9.0	Condition						
9.1	Plinth	Good (No settlement of	or cracks observed)				
9.2	Walls	Good (No dampness of	or leakage observed)				
9.3	Floor	Good (No deflection or	r sagging observed)				
9.4	Stairs	Fair (Wooden member	rs need maintenance)				
9.5	Openings	Good (Well maintained	d)				
9.6	Roofing	Fair (Leakage observe	ed at few places)				
9.7	Articulation & Finishes	Poor (needs painting a	and maintenance)				
9.8	Services	Fair (Down take pipes	maintenance)				
9.9	Outbuildings	Poor					
9.10	Overall condition	Fair	Maintenance level	Fair			
10.0	Transformation						
10.1	Form	Chajja added on a bald supported by CI rods.	cony on the first floor le	evel which is			
10.2	Structure	No transformation					
10.3	Articulation & Finishes	No transformation					
11.0	DP Remarks / Perceived Threats	None					
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.					

# 783, Pestonji Dhunjibhoy Patel Home (Student's Hostel)



Front view of building from Mancherji Joshi road.



Detail of recessed balcony.



Front façade of Kawalji Jehangir block.



Detail of main entrance to building and staircase block.



Card No.: F/n-31g

Ward (Part): F north-VI

**CS No.:** 599 / 10

Plot Area: 1729.94 sq.m.

**B U Area:** 1354.00 sq.m.

**Date:** May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.: 687, Seth Rustomji

Naserwanji Rustomfarmana Agiary



1.0	Denomination							
1.1	Name of Premises	687, Seth Rustomji	687, Seth Rustomji Naserwanji Rustomfarmana Agiary					
1.2	Earlier Name	Not applicable	Not applicable					
1.3	Built in	1929	Extension Date (	if any)	Not applicable			
2.0	Access							
2.1	Main	Mancherji Joshi Ro	pad					
2.2	Subsidiary	Khareghat Road						
3.0	Ownership Pattern							
3.1	Present	Trustees for Improv	vement of City of B	Bombay,	Jamshed Tarapo	ore		
3.2	Past	Rustomji framji Ker Rustomji Jassawala Engineer, Fredooa	a, Shawaksha Fak	irji Dhall	a, Bejon Dinshav	vji		
3.3	Status	Tenanted						
4.0	Use							
4.1	Present	Religious, place of	Worship					
4.2	Past	Religious, place of	Worship					
4.3	Usage	Regular religious u	Regular religious use					
5.0	Significance & Value Classification	n						
5.1	Townscape (Natural / Manmade)		Located in heart of the Parsi Colony on the junction of two major roads namely Mancherji Joshi Road and Khareghat Road.					
5.2	Architectural Description	of road at junction. running the rough of junction having sen bull torso, human he twin bull headed carved C.I. grills, garved C.I. grills, garved carved ca	Located in the midst of Parsi Colony the Agiary follows the profile of road at junction. The façade is governed by a grand verandah running the rough out the corner with an entrance porch opposite junction having semi circular arch and sarosh bergis (statue with bull torso, human head and wings) on either side. Features like twin bull headed capitals over circular columns, Furoher, motifs, carved C.I. grills, gate, interesting sloping roof profile with ventricular etc. adorn the façade.					
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.						
5.4	Value Classification	A(arc), A(cul), B(uu	ı), C(seh), G(grp)	Recom	nmended Grade	II A		
5.4 <b>6.0</b>	Value Classification  Topography	A(arc), A(cul), B(uu	u), C(seh), G(grp)	Recom	nmended Grade	II A		

7.0	Construction						
7.1	Plinth	0.9 m. high Basalt dress	0.9 m. high Basalt dressed stone coursed plinth				
7.2	Walls	Load bearing brick walls					
7.3	Floor	Access denied	Access denied				
7.4	Stairs	Access Denied					
7.5	Openings	Rectangular with woods	en frames and glazed	shutters			
7.6	Roofing	Partly flat roof with terra	ace and partly sloping	roof			
7.7	Articulation	Decorative arches, sard ball motifs	osh bergis at entrance	, Farohar motifs, twin			
7.8	Finishes	Internally and externally	/ cement plastered an	d painted			
7.9	Interiors (Movable & Immovable)	Access denied					
7.10	Compound / Fence / Gate	Plastered brick wall with decorative gate with pill		ngs with C.I.			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Paved side open spacir	ng. Part landscape are	ea with shrubs.			
8.0	Services & Utilities						
8.1	Lighting	Natural and artificial, go	od natural lighting				
8.2	Ventilation	Natural and artificial, go	ood natural ventilation				
8.3	Electricity	BEST					
8.4	Water Supply	MCGM					
8.5	Drainage (Plumbing and Sanitation)	MCGM					
8.6	Fire precaution	Not provided					
8.7	Other (HVAC / BMS / Security Systems)	Not provided					
9.0	Condition						
9.1	Plinth	Good (No settlement or	cracks observed)				
9.2	Walls	Good (No dampness or	cracks observed)				
9.3	Floor	Good (Well maintained)	)				
9.4	Stairs	Access Denied					
9.5	Openings	Good (Wooden membe	rs in sound state)				
9.6	Roofing	Good (Mangalore tiles,	fascia and external m	embers in sound state)			
9.7	Articulation & Finishes	Good (Painted recently)	)				
9.8	Services	Access denied					
9.9	Outbuildings	Good (Partly landscape	ed and maintained clea	an)			
9.10	Overall condition	Good	Maintenance level	Good			
10.0	Transformation						
10.1	Form	No transformation					
10.2	Structure	No transformation					
10.3	Articulation & Finishes	No transformation					
11.0	DP Remarks / Perceived Threats	None					
12.0	Additional Notes / References / Documents Available	Notes: This agiary at Parsi colony, Dadar was built in the memory of Rustomjee Naservanjee Rustomfarmana and his wife Putalibai in the year 1929. Many people from the Parsi community donated generously for the construction of this agiary.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.					

### 687, Rustom Farmana Agiary



Ornamented west side elevation of Rustom Farmana Agiary having circular columns with decorative animal head and low height compound wall with cast iron railing.



Front side elevation of Rustom Farmana Agiary from junction of Mancherji Joshi road and Khareghat road showing decorative entrance gate.



Detail of entrance porch to agiary.



Archival photograph of Rustom Farmana Agiary from Parasi Colony book.



Card No.: F/n-31h

Ward (Part): F north-VI

**CS No.:** 638A/10

Plot Area: 943.14 sq.m.

**B U Area:** 1296 sq.m.

**Date:** May 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 631a, Meher Villa



1.0	Denomination							
1.1	Name of Premises	631a, Meher Villa	631a, Meher Villa					
1.2	Earlier Name	Not applicable						
1.3	Built in	1928	Extension Date (if a	ıny)	Not applicable			
2.0	Access							
2.1	Main	Mancherji Joshi Ro	ad					
2.2	Subsidiary	Khareghat Road						
3.0	Ownership Pattern							
3.1	Present	Sorabji Homarji Ma	dan					
3.2	Past	Meher Sorabji Mad	an					
3.3	Status	Private						
4.0	Use							
4.1	Present	Residential						
4.2	Past	Residential						
4.3	Usage	Regular residential	use					
5.0	Significance & Value Classification							
5.1	Townscape (Natural / Manmade)	Located on a corne Khareghat Road.	Located on a corner plot at junction of Mancherji Joshi Road and Khareghat Road.					
5.2	Architectural Description	Corner building with an impressive, imposing entrance porch having intricate emblems on its facade. Balconies supported on decorative RCC brackets. The entrance porch has highly decorative parapet wall with concrete. The balcony on first floor of the rounded corner has ionic columns. Chajjas over windows have decorative wooden brackets on ground floor and has decorative CI brackets supporting chajja over the entrance.						
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.						
5.4	Value Classification	A(arc), C(seh), G(g	rp) R	Recom	mended Grade	Ш		
6.0	Topography							
6.1	Floors	G + 3						
7.0	Construction							
7.1	Plinth	Malad stone dresse	ed plinth, 1m. high					
7.2	Walls	Brick load bearing v	walls					
7.3	Floor	Wooden flooring wi	Wooden flooring with wooden joists and battens					

7.4	Stairs	Wooden open well wit	h decorative wooden b	alustrades				
7.5	Openings	Rectangular with wooden frames and glazed shutters and wooden louvered windows inside						
7.6	Roofing	Flat roof terrace						
7.7	Articulation		Balconies supported on R.C.C. brackets. Chajjas near entrance are supported on decorative brackets. Ionic columns on balcony.					
7.8	Finishes	Cement plaster and p	aint					
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value					
7.10	Compound / Fence / Gate	Brick compound wall v	with decorative M.S. rai	ling				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Open space paved wi	Open space paved with Shahabad tiles					
8.0	Services & Utilities							
8.1	Lighting	Natural and artificial, o	good natural lighting					
8.2	Ventilation	Natural and artificial, o	good natural ventilation					
8.3	Electricity	BEST						
8.4	Water Supply	MCGM						
8.5	Drainage (Plumbing and Sanitation)	MCGM						
8.6	Fire precaution	Not provided						
8.7	Other (HVAC / BMS / Security Systems)	Not provided						
9.0	Condition							
9.1	Plinth	Fair (No settlement, n	eeds maintenance of th	ne dampness)				
9.2	Walls	Good (Well maintaine	Good (Well maintained)					
9.3	Floor	Good (No sagging or	deflection observed)					
9.4	Stairs	Fair (Wooden membe	rs need maintenance)					
9.5	Openings	Fair (Windows panel b	oroken, wooden membe	ers need maintenance)				
9.6	Roofing	Good (No leakage or	deflection observed)					
9.7	Articulation & Finishes	Fair (Façade attacked	by moss and rain impa	act)				
9.8	Services	Fair (Well maintained)						
9.9	Outbuildings	Fair						
9.10	Overall condition	Fair	Maintenance level	Fair				
10.0	Transformation							
10.1	Form	Top floor added later, places.	Top floor added later, awnings made at entrance, chajjas at few places.					
10.2	Structure	No transformation						
10.3	Articulation & Finishes	No transformation						
11.0	DP Remarks / Perceived Threats	None						
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.						



View of Mehar Villa from junction of Khareghat road and Mancherji Joshi road.



Rare view of Meher Villa from Khareghat road.



Details of corner balcony of first floor and second floor of Meher Villa and entrance below it.



Card No.: F/n-31i

Ward (Part): F north-VI

**CS No.:** 657/10

Plot Area: 741.6 sq.m.

**B U Area:** 975.6 sq.m.

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 638, Mancherji Joshi

638, Mancherji Joshi Memorial Building



		_						
1.0	Denomination							
1.1	Name of Premises	638, Mancherji Joshi Memorial Building						
1.2	Earlier Name	Not applicable	Not applicable					
1.3	Built in	1925-35	Extension Date (if	f any)	Not applicable			
2.0	Access							
2.1	Main	Mancherji Joshi Roa	ad					
2.2	Subsidiary	Not applicable						
3.0	Ownership Pattern							
3.1	Present	Trustees for improv	ement of city of Bo	mbay.				
3.2	Past	Trustees for improv	ement of city of Bo	mbay.				
3.3	Status	Trust owned						
4.0	Use							
4.1	Present	Residential						
4.2	Past	Residential						
4.3	Usage	Regular residential	use					
5.0	Significance & Value Classification	า						
5.1	Townscape (Natural / Manmade)	Located on a rectar the major roads in [			ji Joshi Road. Oı	ne of		
5.2	Architectural Description	sloping roof with Ma legged wooden stai Pediment on the en wooden brackets or for the balconies. W	Corner building with a cubical form and modest façade It has a sloping roof with Mangalore tiles and decorative eaves board. Dog legged wooden staircase with decorative wooden balustrades. Pediment on the entrance and prominent balconies supported on wooden brackets on front and side façade. Simple wooden railing for the balconies. Windows on the ground floor have semi-circular arches. First floor has rectangular glazed wooden windows. Has an interesting roof profile.					
5.3	Intrinsic	colonies / precincts community located colony is one of the Zoroastrian Commu	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.					
5.4	Value Classification	A(arc), C(seh), G(g	rp)	Recom	nmended Grade	III		
6.0	Topography	•						
6.1	Floors	G + 1						
7.0	Construction	•						
7.1	Plinth	Black Basalt stone	coursed masonry p	linth				
7.2	Walls	Brick load bearing v	valls					
A dorko	r Associates, Architects	177			10/	d F north		

7.3	Floor	RCC slab flooring				
7.4	Stairs	Access denied				
7.5	Openings	Rectangular openings with wooden frames and glazed shutters				
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses				
7.7	Articulation	Balconies on all sides supported on wooden brackets				
7.8	Finishes	Cement plaster and paint				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.10	Compound / Fence / Gate	Brick compound wall with CI railing				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large front open space in front with landscaping				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, fair natural lighting				
8.2	Ventilation	Natural and artificial, fair natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on side façade				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging observed)				
9.4	Stairs	Fair (Wooden members need maintenance)				
9.5	Openings	Good (Leakage observed in passage, Mangalore tiles on tear side need repairs)				
9.6	Roofing	Fair (Back façade attacked by moss at some places)				
9.7	Articulation & Finishes	Fair				
9.8	Services	Fair				
9.9	Outbuildings	Not applicable				
9.10	Overall condition	Fair Maintenance level Fair				
10.0	Transformation					
10.1	Form	Balconies enclosed at some places.				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	Re-plastered and painted.				
11.0	DP Remarks / Perceived Threats	None				
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				

### 638, Mancherji Joshi Memorial Building



View of structure from Mancherji Joshi road showing symmetrical front elevation.



South corner of structure showing decorative balcony.



Decorative Balcony above entrance porch with concrete jali.



Card No.: F/n-31j

Ward (Part): F north-VI

**CS No.:** 655A / 10

Plot Area: 932.27 sq.m.

**B U Area:** 1707.32 sq.m.

**Date:** May, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 640b, Khorshed Villa



		Kei	640b, Knorsned Villa	1 					
1.0	Denomination								
1.1	Name of Premises	640b, Khorshed Villa							
1.2	Earlier Name		Not applicable						
1.3	Built in		1925-35	Exter	nsion Date (it	f any)	Not applicable		
2.0	Access								
2.1	Main		Mancherji Joshi Roa	ıd					
2.2	Subsidiary		Khareghat Road						
3.0	Ownership Pattern								
3.1	Present		Trustees for improve	ment	of city of Bo	mbay, S	Blloo Pesi Shaw		
3.2	Past		Pesi Manekshaw Sh	iaw					
3.3	Status		Tenanted						
4.0	Use								
4.1	Present		Residential						
4.2	Past		Residential						
4.3	Usage		Regular residential u	ıse					
5.0	Significance & Value Classi	fication	1						
5.1	Townscape (Natural / Manma	de)		Located on junction of Khareghat Road and Mancherji Joshi Road, an important road in Parsi Colony. It faces Rustom Farmara Agiary.					
5.2	Architectural Description		corner. It has promin Mangalore tiled slop brackets and decora	Building on a strategic location with impressive façade over a corner. It has prominent decorative balconies at the corner with Mangalore tiled sloping canopies. Balconies are supported on RCC brackets and decorative CI railing. It has a decorative entrance porch supported with RCC columns with decorative capitals.					
5.3	Intrinsic		The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.						
5.4	Value Classification		A(arc), C(seh), G(gr	p), I(s	ce)	Recom	mended Grade	III	
6.0	Topography							<del></del>	
6.1	Floors		G + 1						
7.0	Construction				_				
7.1	Plinth		Dressed Malad stone	e cou	rsed masonr	y plinth			
7.2	Walls		Brick load bearing w	alls					
7.3	Floor		Wooden flooring with	า woo	den joists ar	nd batter	าร		
7.4	Stairs		Access denied						

7.5	Openings	Rectangular openings	with wooden frames a	nd glazed shutters	
7.6	Roofing	Sloping roof with Man	galore tiles and wooder	n trusses	
7.7	Articulation	Balconies on all sides	supported on wooden	brackets	
7.8	Finishes	Cement plaster and p	aint		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Brick compound wall	Brick compound wall with CI railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Landscaping with lush	Landscaping with lush green lawns, pavements and shrubs		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, f	air natural lighting		
8.2	Ventilation	Natural and artificial, f	air natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on side façade			
9.0	Condition				
9.1	Plinth	Good (No settlement	or cracks observed)		
9.2	Walls	Fair (No dampness or	leakage observed)		
9.3	Floor	Fair (No sagging obse	erved)		
9.4	Stairs	Access denied			
9.5	Openings	Good			
9.6	Roofing	Good (No leakage or	deflection observed)		
9.7	Articulation & Finishes	Fair (Needs repainting	g)		
9.8	Services	Fair			
9.9	Outbuildings	Good (landscape dev	elopment done)		
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	Balconies enclosed at	some places.		
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Re-plastered and repa	ainted.		
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### 640b, Khorshed Villa



Detail of Khorshed Villa showing decorative balcony.



Front façade of Khorshed Villa from Mancherji Joshi road with decorative compound wall.



Balcony supported with decorative brackets having ornamental cast iron railing fixed with wooden post.



Detail of façade showing cornice band, decorative circular column and concrete jali.



Main entrance to Khorshed Villa from Khareghat road showing ornamental entrance porch with Corinthian column and decorative parapet wall.



Decorative gate pillar with ornamented cast iron fencing.



Card No.: F/n-31k

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

**Date:** May, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 792, Dina Manzil



1.0	Denomination					
1.1	Name of Premises	792, Dina Manzil				
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Tilak Road				
2.2	Subsidiary	Jame Jamshed Roa	ad			
3.0	Ownership Pattern					
3.1	Present	Trustees for improv	vement of city of Bo	mbay		
3.2	Past	Mehra Sorabji Mad	lan, Sohrabji Hormu	usji Mac	lan	
3.3	Status	Tenanted				
4.0	Use	·				
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)		ortant junction of Ja ning of Parsi Colony		shet Road and T	ilak
5.2	Architectural Description	Located on the corner junction, the structure shows site response with the projecting balconies and the porch at the corner. The building has a symmetrical façade about the junction carved brackets support the balconies with plain railing and Mangalore tiled sloping roof. First floor central balcony with balusters forms as an entrance porch on ground floor with two circular columns at two side.				
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.				
5.4	Value Classification	A(arc), B(per), C(se	eh), G(grp)	Recom	nmended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone masonry plinth 0.6 m. high				
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Wooden joist floor				

Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation) Fire precaution	Wooden dog legged with plain railing and newel post  Rectangular wooden fully glazed  Flat roof with terrace  Cornice Bands, balcony with plain railing and sloping roofs, central area demarcated by balcony with circular columns.  Internally and externally cement plastered and painted  Interiors, not of heritage value  Plastered brick wall with M.S. railing  Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM  Not provided		
Roofing Articulation  Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation)	Flat roof with terrace  Cornice Bands, balcony with plain railing and sloping roofs, central area demarcated by balcony with circular columns.  Internally and externally cement plastered and painted Interiors, not of heritage value  Plastered brick wall with M.S. railing  Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Articulation  Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation)	Cornice Bands, balcony with plain railing and sloping roofs, central area demarcated by balcony with circular columns.  Internally and externally cement plastered and painted Interiors, not of heritage value Plastered brick wall with M.S. railing Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation)	area demarcated by balcony with circular columns.  Internally and externally cement plastered and painted Interiors, not of heritage value Plastered brick wall with M.S. railing Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Interiors (Movable & Immovable)  Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Ventilation  Electricity  Water Supply  Drainage (Plumbing and Sanitation)	Interiors, not of heritage value  Plastered brick wall with M.S. railing  Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Compound / Fence / Gate  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Ventilation  Electricity  Water Supply  Drainage (Plumbing and Sanitation)	Plastered brick wall with M.S. railing  Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Ventilation  Electricity  Water Supply  Drainage (Plumbing and Sanitation)	Not partly landscaped, partly paved open space around  Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Buildings / Landscape  Services & Utilities  Lighting  Ventilation  Electricity  Water Supply  Drainage (Plumbing and Sanitation)	Natural and artificial, good natural lighting  Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation)	Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation)	Natural and artificial, good natural ventilation  BEST  MCGM  MCGM		
Electricity Water Supply Drainage (Plumbing and Sanitation)	BEST MCGM MCGM		
Water Supply Drainage (Plumbing and Sanitation)	MCGM MCGM		
Drainage (Plumbing and Sanitation)	MCGM		
Fire precaution	Not provided		
	The production of the producti		
Other (HVAC / BMS / Security Systems)	Not provided		
Condition Condition			
Plinth	Good (No settlement or cracks observed)		
Walls	Good (No dampness or cracks observed)		
Floor	Good (No sagging observed)		
Stairs	Good (Wooden members in good condition )		
Openings	Good (Window panes and wooden members in sound state)		
Roofing	Good (No deflection observed)		
Articulation & Finishes	Fair (Paint on terrace spoilt due to rains)		
Services	Good (Leakage observed in some places)		
Outbuildings	Good		
Overall condition	Good Maintenance level Good		
Transformation			
Form	No transformation		
Structure	No transformation		
Articulation & Finishes	No transformation		
DP Remarks / Perceived Threats	None		
Additional Notes / References /	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.		
( ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (	Outbuildings Overall condition  Fransformation  Form  Structure  Articulation & Finishes		



View of structure from junction of Tilak Road showing decorative balconies.



South side decorative balconies from Tilak road showing wooden railing & post.



Corner balconies with Entrance porch from Tilak road.



Corner Entrance porch with decorative column supporting the balcony above, which have decorative concrete railing.

		Card N Ward (I CS No. Plot Ar B U Are Date: N Record Review Interna Externa	Part): F north-VI : 524 / 10 ea: 936.46 sq. m. ea: 1170 sq. m. May, 2005 I by: Keshav S, Anup v by: Arun Kale I: As above al: As above T-III-Fn:\Ward F nor	orth\	FAMILY HOUSE 524 VO	TAME JAMSHED ROAD		1400 1740
4.5		Ref.:	793, Family House					
1.0	Denomination		700 5					
1.1	Name of Premises		793, Family House					
1.2	Earlier Name		Not applicable	Evtono:	ion Data /:	· and	Not applicable	
1.3 <b>2.0</b>	Built in Access		1925-35	⊏xtensi	on Date (if	any)	Not applicabl	e
2.0	Main		Jame Jamashed Ro	oad				
2.1	Subsidiary		Mancherji Joshi Roa					
3.0	Ownership Pattern		Wallerji Josili Ko	uu				
3.1	Present		Radhabai Mathurad	das Thak	ker. Rame	sh Nan	ii Thakker	
3.2	Past		Trustees for Improvement of City of Bombay					
3.3	Status		Tenanted					
4.0	Use							
4.1	Present		Residential					
4.2	Past		Residential					
4.3	Usage		Regular residential use					
5.0	Significance & Value Classi	fication	l					
5.1	Townscape (Natural / Manma	ide)	Located on an extre Jamashed Road an Parsi colony off Dr.	nd Manch	nerji Joshi İ	Road a	t the beginning	
5.2	2 Architectural Description		Vernacular architecture with fine intricate detailing is best seen in this residential block. Two side bays are highlighted by the bay windows whereas the recessed portion forms an elongated balcor with plain wooden railing and stain glass work with wooden geometrical patterns above lintel with timber post. The building is entered through a veranda on ground floor. The delicate features on façade with an interesting play of sloping roof profile make the façade a fine example of good proportions and forms.			bay balcony ing is tures		
5.3	Intrinsic		The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsicolony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct it also has an agiary located centrally.			r Parsi		
5.4	Value Classification		A(arc), B(per), C(se	eh), G(gr	p)	Recom	nmended Grad	e III
6.0	Topography							
6.1	Floors		G + 2					
7.0	Construction		I					
7.1	Plinth		0.6 m. high Black B	Basalt sto	ne course	d maso	nry plinth	
7.2	Walls		Load bearing brick	walls				
Adarkar	Associates, Architects		186				W	ard F north

7.3	Floor	Wooden joist floor		
7.4	Stairs	Wooden dog legged staircase with plain railing and decorative newel post		
7.5	Openings	Rectangular openings with wooden frames and glazed shutter		
7.6	Roofing	Sloping roof with Mangalore tiled in interesting profile		
7.7	Articulation	Cornice band, wooden railing, stain glass work on balcony, bay windows		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall with cast iron fence with gate		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly landscape space in front rest all open space concrete paved		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Excellent (No settlement or cracks observed)		
9.2	Walls	Excellent (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Excellent (No sagging observed, wooden members in sound state		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Good (No leakage or breaking of Mangalore tiles observed)		
9.7	Articulation & Finishes	Excellent (Recently repainted)		
9.8	Services	Good (No breaking or leakage of pipes observed)		
9.9	Outbuildings	Excellent (Maintained clean, partly landscaped)		
9.10	Overall condition	Good Maintenance level Excellent		
10.0	Transformation			
10.1	Form	M.S. grill added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

## 793, Family House



Front façade from Junction of Jame Jamshed road & Mancherji Joshi road.



Main entrance with verandahs on each floor with wooden railing with low compound wall.

Front façade of building is not visible due to dense vegetation



Card No.: F/n-31m

Ward (Part): F north-VI

**CS No.:** 602 / 10

Plot Area: 861.20 sq.m.

**B U Area:** 647.4 sq.m.

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 791, Percy Manor



1.0	Denomination					
1.1	Name of Premises	791, Percy Manor				
1.2	Earlier Name	Not applicable				
1.3	Built in	1927	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Jame Jamshed Roa	Jame Jamshed Road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Trustees for Improvement of City of Bombay, Bai Indoo Keki Kotawal				
3.2	Past	Keki Manekaji Kotawal				
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on Jame J the Parsi Colony.	ameshed Road, on	e of the	important roads	in
5.2	Architectural Description	Vernacular style bu features like woode around windows an wooden joists and b	n railings for balco d cornice bands at	nies, sir	mple architraves	has
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.				
5.4	Value Classification	A(arc), B(des), G(g	rp)	Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt regula	r coursed stone pli	nth, 2' fe	eet high	
7.2	Walls	Brick load bearing v	walls			
7.3	Floor	Wooden flooring wi	th wooden joists ar	nd batte	ns	

7.4	Stairs	Wooden dog legged staircase with decorative railing and newel post.		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Cornice bands at floor level, architraves and wooden railing, Furohar and sun motifs		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall with CI gate		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Side open space paved with Shahabad tiles		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Fair (needs plastering and painting)		
9.3	Floor	Fair (No sagging observed, Wooden members need maintenance)		
9.4	Stairs	Fair (Sagging observed at mid landing, handrail needs repair)		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Fair (No leakage observed)		
9.7	Articulation & Finishes	Good (No cracks or dampness observed on façade)		
9.8	Services	Fair (Some pipes needs repairs)		
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		




Front view of Percy Manor along with compound wall from Jame Jamshed road.



Main entrance to building with stained glass work.




Detail of front façade of Percy Manor building.



Detail of balcony on second floor with cast iron railing fixed in wooden post.

Ward F north



7.5	Openings	Rectangular opening v	with wooden frames an	d glazed shutters
7.6	Roofing	Sloping roof with Man	galore tiles and wooder	n trusses
7.7	Articulation	Cornice bands, woode posts	en decorative chajjas ar	nd decorative wooden
7.8	Finishes	Internally and external	ly cement plastered an	d painted
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.10	Compound / Fence / Gate	Plastered brick compound wall with CI gate		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Concreted side open space with few trees		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, f	air natural lighting	
8.2	Ventilation	Natural and artificial, f	air natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or	cracks observed)	
9.2	Walls	Fair (Internal walls sho	ow minor cracks)	
9.3	Floor	Fair (Sagging observe	d at some places)	
9.4	Stairs	Fair (Wooden membe	rs need maintenance)	
9.5	Openings	Fair (Wooden membe	rs need maintenance)	
9.6	Roofing	Fair (Leakage observe	ed at some places)	
9.7	Articulation & Finishes	Fair (Needs re-plaster	ing and repainting)	
9.8	Services	Fair (Some pipes need	ds repair)	
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		


# 619, Banoo Building



Front façade of Banoo building from Dr. Ghanti road.



Entrance detail with compound wall and posts.



**Card No.:** F/n-310

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

**Date:** May, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above


**Photo** T-III-Fn:\Ward F north\ **Ref.:** 764a, Naval House



1.0	Denomination						
1.1	Name of Premises	764a, Naval House	764a, Naval House				
1.2	Earlier Name	Not applicable					
1.3	Built in	1927-30	Extension Date (i	f any)	Not applicable		
2.0	Access						
2.1	Main	Dr. Ghanti Road					
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Trustees for improv	vement of city of Bo	ombay			
3.2	Past	Bai Manijeh dal Da	ruwala, Bai Manije	h dal Da	aruwala		
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential	use				
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade)	Located on a mino beginning of Parsi		ony - Dr	r. Ghanti Road at	: the	
5.2	Architectural Description	area with a central railing and sloping	The building follows a typology of Parsi residential blocks in this area with a central recessed bay with balconies having wooden railing and sloping roof. Concrete brackets for balconies, wooden Moorish arches on top floor balcony, plain cornice bands etc. adorn the facade.				
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.					
5.4	Value Classification	A(arc), B(per), C(se	eh), G(grp)	Recom	mended Grade	Ш	
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth	1.45 m. high course	ed Black Basalt sto	ne maso	onry plinth		
7.2	Walls	Load bearing brick walls					
7.3	Floor	R.C.C. slab flooring	9				
7.4	Stairs	Wooden dog legge	d staircase with pla	ain railin	gs		

7.5	Openings	Rectangular openings with wooden frames and glazed shutters			
7.6	Roofing	Sloping roof with Man	Sloping roof with Mangalore tile and Timber truss		
7.7	Articulation	Interesting profile, prodecorative balustrades	minent decorative balcos	onies having	
7.8	Finishes	Internally and external	ly cement plastered an	d painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Stone compound wall with CI decorative entrance gates and has decorative concrete jalis.			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly paved open space			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, f	air natural lighting		
8.2	Ventilation	Natural and artificial, f	air natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on side façade			
9.0	Condition				
9.1	Plinth	Good (No settlement of	or cracks observed)		
9.2	Walls	Good (No dampness of	or cracks observed)		
9.3	Floor	Fair (Sagging observe	d at some places)		
9.4	Stairs	Good (Wooden memb	ers in sound state)		
9.5	Openings	Good (Well maintained	d)		
9.6	Roofing	Fair (Fascia needs rep	pairs)		
9.7	Articulation & Finishes	Good (Well maintained	d)		
9.8	Services	Fair (Leakage of some	e pipes observed)		
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Co-operative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

## 764a, Naval House



View of Naval house showing corner block decorative balconies from Dr. Ghanti road.



Detail of balcony on second floor with ornamented railing fixed wooden post supporting sloping roof.



Detail of entrance showing cast iron gate, decorative gate pillar and ornamented lamp post on it.



Card No.: F/n-31p

Ward (Part): F north-IV

**CS No.:** 630 / 10

Plot Area: 1846.16 sq.m.

**B U Area:** 2100 sq.m.

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 622, Palia Mansion



<del></del>	<u> </u>					
1.0	Denomination	1				
1.1	Name of Premises	622, Palia Mansion				
1.2	Earlier Name	Not applicable			<u>,                                      </u>	
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jehangir Roa	Lady Jehangir Road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Tina Percy Patel				
3.2	Past	Meherji Cawsaji Pa Tinaz Cawsaji Palia				
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential	Residential			
4.2	Past	Residential				
4.3	Usage	Regular residential	Regular residential use			
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	Located on Lady Je important Roadsof			rdens, one of the	!
5.2	Architectural Description	except for semi-circ has wooden flooring	Simple low rise building with minimal ornamentation on the façade except for semi-circular arches on the second floor. The building has wooden flooring with wooden joists and battens supported by Corinthian columns. Projecting balconies supported by decorative CI brackets			
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.				
5.4	Value Classification	A(arc), B(des), G(g	rp), C(seh)	Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered plinth, 0.	6 m. high			
7.2	Walls	Brick load bearing	walls			
7.3	Floor	RCC slab flooring				

7.4	Stairs	Access denied		
7.5	Openings	Rectangular opening with wooden frames and glazed shutters and second wooden flooring with wooden joists and battens has semi-circular arched openings.		
7.6	Roofing	Flat roof terrace and party sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Projecting balcony with CI railing, arched openings with Corinthian columns		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall with CI gate and railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Concreted side open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Access denied)		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Good (Well maintained)		
9.7	Articulation & Finishes	Good (Recently re-plastering and repainting)		
9.8	Services	Good (Access denied)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	Sloping roof added above staircase block.		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Front view of Palia Mansion from Lady Jahangir road.



Rare view of Palia Mansion from open ground along Jame Jamshed road.



Detail of balcony from east façade of Palia Mansion.



Detail of arched opening to common passage of front façade of Palia Mansion road.



Card No.: F/n-31q

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

**Date:** May, 2005


Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 668, Desai Building



1.0	Denomination						
1.1	Name of Premises	668, Desai Building					
1.2	Earlier Name	Not applicable					
1.3	Built in	1925-35	1925-35 Extension Date (if any) Not applicable				
2.0	Access						
2.1	Main	Lady Jehangir road	d				
2.2	Subsidiary	Katrak Road					
3.0	Ownership Pattern						
3.1	Present	Trustees for Impro	vement of City of Bo	ombay			
3.2	Past	Not available					
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residentia	l use				
5.0	Significance & Value Classification	ue Classification					
5.1	Townscape (Natural / Manmade)	Located on an extremely commanding location at junction of Lady Jehangir Road and Katrak Road at the boundary of Parsi colony towards north east side.					
5.2	Architectural Description	Vernacular architecture with fine intricate detailing is best seen in this residential block. Two side bays are highlighted by the bay windows whereas the recessed portion forms an elongated balcony with plain wooden railing with wooden geometrical patterns above lintel with timber post. The building is entered through a veranda on ground floor. The delicate features on façade with an interesting play of sloping roof profile make the façade a fine example of good proportions and forms.					
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.					
5.4	Value Classification	A(arc), G(grp) Recommended Grade					
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth 0.6 m. high Black Basalt stone coursed masonry plinth						
7.2	Walls Load bearing brick walls						
A dorles	Associates Architects	201			14/	I E north	

7.3	Floor	R.C.C. slab flooring			
7.4	Stairs	Wooden dog legged staircase with plain railing and decorative newel post			
7.5	Openings	Rectangular openings with wooden frames and glazed shutter			
7.6	Roofing	Part flat slab and sloping roof			
7.7	Articulation	Cornice band, wooden railing, stain glass work on balcony, bay windows			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Plastered brick compound wall with cast iron fence with gate			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly landscape space in front rest all open space concrete paved			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good (No sagging observed, wooden members in sound state			
9.5	Openings	Good (Well maintained)			
9.6	Roofing	Good (No leakage or breaking of Mangalore tiles observed)			
9.7	Articulation & Finishes	Good (Recently repainted)			
9.8	Services	Fair (No breaking or leakage of pipes observed)			
9.9	Outbuildings	Good (Maintained clean, partly landscaped)			
9.10	Overall condition	Good Maintenance level Excellent			
10.0	Transformation				
10.1	Form	M.S. grill added later.			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

## 668, Desai Building



Side elevation of Desai Building from Katrak road showing balconies.



Front façade of Desai Buiding from Lady Jehangir road.



Detail of balconies on east side of Desai building showing cast iron decorative railing.



East side elevation from junction of Katrak road and Lady Jehangir road.

Side elevation of building is not visible due to dense vegetation



Ward (Part): F north-IV

Card No.: F/n-31r

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: March, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 602b, Dedhia House



1.0	Denomination					
1.1	Name of Premises	602b, Dedhia House				
1.2	Earlier Name	Not applicable				
1.3	Built in	1929-32	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Dr. Babasaheb Am	bedkar Road			
2.2	Subsidiary	Khareghat Road				
3.0	Ownership Pattern					
3.1	Present	Trustees for Improv	ement City of Bomb	oay		
3.2	Past	Trustees for Improv	ement City of Bomb	oay		
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	Regular residential use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on corner plot at junction of Dr. Ambedkar Road and Khareghat Road.				
5.2	Architectural Description	later on in 1950s. W from staircase block entrance porch. Ba	Load bearing structure, Basalt stone plinth. Third floor is added later on in 1950s. Well composed front façade. Balcony jetting out from staircase block supported by concrete columns forms entrance porch. Balcony on second floor running along front facade supported by concrete brackets has wooden railing			
5.3	Intrinsic	Building facing road with different character like Wada. The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Parsi colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.				
5.4	Value Classification	A(arc), B(des), E, G	6	Recom	mended Grade III	
6.0	Topography		•		<u> </u>	
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone plinth				
7.2	Walls	Brick masonry walls				
7.3	Floor	RCC floor slab	RCC floor slab			
7.0						

7.4	Stairs	Open well wooden staircase with decorative naval post			
7.5	Openings	Rectangular and arched openings with wooden frames and glazed shutters			
7.6	Roofing	Flat roof and partly sloping roof			
7.7	Articulation	Cornice band are seen at all floor levels and there are simple rectangle architraves around windows. The plinth has Black Basalt stone in coursed ashlar masonry. Wooden and concrete railings to balconies. Wooden posts supporting balcony roof.			
7.8	Finishes	Externally and internally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Plastered brick wall with cast iron railing.			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Paved side open spaces			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good (No sagging observed, wooden members in sound state			
9.5	Openings	Good (Well maintained)			
9.6	Roofing	Good (No leakage or breaking of Mangalore tiles observed)			
9.7	Articulation & Finishes	Good (Recently repainted)			
9.8	Services	Fair (No breaking or leakage of pipes observed)			
9.9	Outbuildings	Good (Maintained clean, partly landscaped)			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			



North elevation of house from Lady Jehangir road.



Front façade from Dr. Babasaheb Ambedkar road.



Rear side of house from Lady Jahangir road.



House behind dense trees from Dr. Babasaheb Ambedkar road.



Detail of north side entrance showing Semi-Circular Arch opening.

		Card N Ward (I CS No. Plot Ar B U Arc Date: N Record Review Interna	Part): F north-IV : 612 / 10 ea: 600 sq.m.	ri J	R AMBEDKAR ROAD	SO MA	HRAS HOUSE 12 /10  REGHAT ROAD
		Photo Ref.:	T-III-Fn:\Ward F no 607b, Sohrab Hous				
1.0	Denomination		ı				
1.1	Name of Premises		607b, Sohrab Hous	e			
1.2	Earlier Name		Not applicable	I			
1.3	Built in		1932	Exter	nsion Date (i	f any)	1969
2.0	Access		I				
2.1	Main		Dr. Babasaheb Am	bedka	r Road		
2.2	Subsidiary		Khareghat Road				
3.0	Ownership Pattern						
3.1	Present		Not available				
3.2	Past		Not available				
3.3	Status		Tenanted				
4.0	Use						
4.1	Present		Residential				
4.2	Past		Residential				
4.3	Usage		Regular residential	use			
5.0	Significance & Value Class	ification	1				
5.1	Townscape (Natural / Manma	ide)	Located on a junction of Khareghat Road and Dr. Babasaheb Ambedkar Road, a major North-South arterial road in Mumbai, on outskirts of the Parsi colony.				
5.2	Architectural Description	Building reflecting typical vocabulary of Parsi residential blocks. The building follows the general skyline of the building along Dr. Babasaheb Ambedkar Road; The structure exhibits balconies with sloping roofs and plain timber railing. Cornice band runs at first floor level with some motifs on façade the end two bays projecting with recessed area with balconies and balusters on terrace give it a typical character.					
5.3	Intrinsic	The Zoroastrian (Parsi) community of Bombay mostly resided in colonies / precincts specially built for all the sections of the community located at various places in the island city. Dadar Pars colony is one of the biggest community settlements of the Zoroastrian Community in India. Just like any other Parsi precinct, it also has an agiary located centrally.			ections of the and city. Dadar Parsi nents of the		
5.4	Value Classification		A(arc), C(seh), G(g	rp)		Recom	mended Grade III
6.0	Topography						
6.1	Floors		G + 2				
7.0	Construction						
7.1	Plinth		Black Basalt stone	randoi	m masonry p	olinth	
7.2	Walls		Composite brick ma	asonry	walls		

7.3	Floor	R.C.C. slab flooring				
7.4	Stairs	Wooden open well staircase with decorative wooden balustrade				
7.5	Openings	Rectangular openings with wooden frames and glazed shutters				
7.6	Roofing	Flat roof terrace and sloping roof for staircase block				
7.7	Articulation	Double windows with external rectangular glazed windows and internal louvered windows. Glazed wooden framed ventilators. It has a decorative concrete balustrade on facade.				
7.8	Finishes	Internally and externally cement plastered and painted				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.10	Compound / Fence / Gate	Brick compound wall with plain C.I. railing				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal partly landscaped front open space				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural lighting				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging or reflection observed)				
9.4	Stairs	Good (Well maintained)				
9.5	Openings	Good (Wooden members and windows panes need repairs)				
9.6	Roofing	Good (No leakage or dampness observed)				
9.7	Articulation & Finishes	Fair (Front façade attacked by moss)				
9.8	Services	Fair (Rain water pipe need repair)				
9.9	Outbuildings	Good				
9.10	Overall condition	Good Maintenance level Good				
10.0	Transformation					
10.1	Form	Chajjas added to windows.				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	Re-plastered and painted subsequently.				
11.0	DP Remarks / Perceived Threats	None				
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				



South side view from Khareghat Road showing symmetrical façade with balconies



Front façade of Sohrab House from Dr. Babasaheb Ambedkar road with semi circular balconies



South side entrance to Sohrab House



Detail of decorative balconies of Sohrab House



First floor balconies on east façade of Sohrab House



Card No.: F/n-31t

Ward (Part): F north-VI

**CS No.:** 677 / 10

Plot Area: 486.63 sq.m.

**B U Area:** 858 sq.m.

**Date:** May, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: 672, Sherewar



		- ,				
1.0	Denomination					
1.1	Name of Premises	672, Sherewar				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1927 E	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Parsi Colony Road no	o. 14			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential us	se			
5.0	Significance & Value Classificatio	n				
5.1	Townscape (Natural / Manmade)	Located on an internal road in Parsi colony, Road no. 14 facing a central triangular open space in interiors of Parsi colony.				
5.2	Architectural Description	Classical style seen grand balcony and ve arches, side bays proj	A very fine blend of Vernacular style architecture and the Neo Classical style seen during colonial period.Corinthian capitals, grand balcony and verandah with a series of semi circular arches, side bays projecting with respect to the central balcony and having an interesting sloping roof profile all contributr towards its architectural value.			
5.3	Intrinsic	The Zoroastrian (Pars colonies / precincts s community located at colony is one of the b Zoroastrian Commun it also has an agiary I	pecially built for a various places in iggest communit ity in India. Just l	all the se n the isl y settler ike any	ections of the and city. Dadar F ments of the	Parsi
5.4	Value Classification	A(arc), B(des), C(seh	), G(grp)	Recom	nmended Grade	III
6.0	Topography					•
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered masonry pl	inth			
7.2	Walls	Load bearing brick walls				
7.3						


7.4	Stairs	Wooden dog legged staircase with decorative wooden balustrades			
7.5	Openings	Rectangular openings with wooden frames and glazed shutters			
7.6	Roofing	Sloping roof with Mangalore tiles having a unique roof profile supported with wooden brackets			
7.7	Articulation	Decorative wooden eaves and cornice bands on ground and second floor. Semi-circular arches with wooden ventilators on first floor.			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Brick compound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Little open space around			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fair natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Windows air-conditioning units added at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging or deflection observed)			
9.4	Stairs	Good (No sagging observed, railing and well maintained in sound state)			
9.5	Openings	Good (Some windows need repair)			
9.6	Roofing	Good (No breaking of Mangalore tiles, no leakage observed, fascia in sound state			
9.7	Articulation & Finishes	Good (Well maintained)			
9.8	Services	Good (No breaking or leakage of pipes observed)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	Corridors enclosed and grills added later on first floor.			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			




Front façade of Sherewar from Parsi colony road no.14.



Detail of semicircular arched openimg.





	T				
Walls	Load bearing brick wall				
Floor	Timber joist beam floor				
Stairs	Open well wooden staircase with decorative balustrades				
Openings	Rectangular openings	with wooden frames a	nd glazed shutters		
Roofing	Sloping roof with Mang	alore tile and Timber t	russ		
Articulation	Little open space arour decorative balconies ha				
Finishes	Internally and externall	y cement plastered an	d painted		
Interiors (Movable & Immovable)	Interiors, not of heritage	e value			
Compound / Fence / Gate	Stone compound wall videcorative concrete jali		ance gates and has		
Curtilege / Unbuilt Space / Out Buildings / Landscape	Marginal open space a	round			
Services & Utilities					
Lighting	Natural and artificial, fa	air natural lighting			
Ventilation	Natural and artificial, fa	air natural ventilation			
Electricity	BEST				
Water Supply	MCGM				
Drainage (Plumbing and Sanitation)	MCGM				
Fire precaution	Not provided				
Other (HVAC / BMS / Security Systems)	Window air-conditioning	Window air-conditioning units on side façade			
Condition					
Plinth	Good (No settlement or cracks observed)				
Walls	Good (No dampness or cracks observed)				
Floor	Good (No sagging or deflection observed)				
Stairs	Good (No deflection observed)				
Openings	Good (Well maintained	Good (Well maintained)			
Roofing	Good (No leakage obse	Good (No leakage observed, Mangalore tiles in sound state)			
Articulation & Finishes	Good (Recently repaint	ted)			
Services	Good (No pipes broker	n or leaking)			
Outbuildings	Good				
Overall condition	Good	Maintenance level	Good		
Transformation					
Form	Wooden louvered windo	ws replaced with rectar	ngular glazed window.		
Structure	No transformation				
Articulation & Finishes	Re-plastered and painted.				
DP Remarks / Perceived Threats	None				
Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.				
		based on garden city in thus the colony was pla important intersections buildings were develop Parsi Panchayat and T	based on garden city ideas, prevailing in Eng thus the colony was planned with open space important intersections and junctions. By the buildings were developed here by private ent Parsi Panchayat and The Parsi Cooperative		




Front façade of Faridunmody House having playground in front from Parsi colony road no. 14.



Decorative balcony having wooden railing supported by wooden brackets having mangalore tile roof above.



Decorative Main Entrance to house from Parsi colony road no.14.



7.3	Floor	Wooden flooring with wooden joists and battens			
7.4	Stairs	Wooden dog legged staircase with decorative wooden balustrades			
7.5	Openings	Rectangular openings with wooden frames and glazed shutters			
7.6	Roofing	Sloping roof with Mangalore tiles having a unique roof profile supported with wooden brackets			
7.7	Articulation	Wooden eaves and cornice bands on ground and second floor. Semi-circular arches with wooden ventilators on first floor.			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Brick compound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal open space around, partly raved			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fair natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Windows air-conditioning units added at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging or deflection observed)			
9.4	Stairs	Good (No sagging observed, railing and well maintained in sound state)			
9.5	Openings	Good (Some windows need repair)			
9.6	Roofing	Good (No breaking of Mangalore tiles, no leakage observed, fascia in sound state			
9.7	Articulation & Finishes	Good (Well maintained)			
9.8	Services	Good (No breaking or leakage of pipes observed)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	Corridors enclosed and grills added later on first floor.			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



Front view of Ashtad from open ground



Arched window opening resting on decorative columns, along with sloping roof.



Card No.: F/n-31w

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: April, 2005


Record by: Gauri J, Anup S

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 640a, Philonmena



1.0	Denomination					
1.1	Name of Premises	640a, Philonmena				
1.2	Earlier Name	Not applicable				
1.3	Built in	1932-35	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Khareghat Road				
2.2	Subsidiary	Parsi Colony Road	no. 9			
3.0	Ownership Pattern					
3.1	Present	Private				
3.2	Past	Private				
3.3	Status	Private owned				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on a rectangular corner plot at junction of Khareghat Road and Parsi Colony Road no. 9, which is one of the prominent roads in Parsi colony. It is viewing triangular garden.				
5.2	Architectural Description	Typical Art Deco co block and rounded The form itself add from the structures from other balconie	corners of the build s to the novelty of the in its vicinity. Corne	ding. It h he struc	nas a convex forn cture setting it ap	n. art
5.3	Intrinsic	The various Art De cohesive image. Lil the new face of the Deco buildings and represent contemp	ke the Gothic buildi city and an expres precincts symboliz	ngs in tl sion of	heir time represe power, so too the	e Art
5.4	Value Classification	A(arc), B(des)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered masonry	plinth			
7.2	Walls	Brick masonry wall	Brick masonry walls			
7.3	Floor	RCC floor slab				
7.4	Stairs	RCC winding staird				

7.5	Openings	Rectangular openings	with wooden frames ar	nd glazed shutters
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	Chajjas act as continu Decorative cast iron ra	ous floor bands around ailing to balcony.	the building,
7.8	Finishes	Internally and external	ly cement plastered and	d painted
7.9	Interiors (Movable & Immovable)	Decorative entrance for	oyer	
7.10	Compound / Fence / Gate	Brick wall and M.S. fer	ncing	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Paved side open spac	e, planted with big tree	s and shrubs
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, g	ood natural lighting	
8.2	Ventilation	Natural and artificial, g	ood natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditionir	ng units at some places	
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good		
9.4	Stairs	Good (No sagging obs	served, railing and well	maintained in sound
9.5	Openings	Good (Some windows	need repair)	
9.6	Roofing	Good (No leakage obs	served)	
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes	need no replacement)	
9.9	Outbuildings	Good		
9.10	Overall condition	Good	Maintenance level	Good
10.0	Transformation			
10.1	Form	Sliding windows and g	rills added later.	
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	owned and developed The Zoroastrian buildin Kingsway (Now Dr. Babased on garden city in thus the colony was plimportant intersections buildings were develop Parsi Panchayat and Total Tot	rsi colony, Hindu colony by the Bombay Improving society acquired the abasaheb Ambedkar Ro deas, prevailing in Eng anned with open spaces and junctions. By the bed here by private enter the Parsi Cooperative Sets, D.P. Sheets, Eicher	rement Trust (BIT) land on the east of bad) The layout was land ant that time, es and gardens at year 1926, 125 erprise and by The Society.



View of Philomena from Khareghat road.



Detail of balconies of first and second floor of Philomena building in Art Decco style.



Detail of covered balcony on corner of Philomena building in Art Decco style.



Common	Ref.	No.	:
--------	------	-----	---

Card No.: F/n-31x

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

**B U Area:** Not available

Date: May, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: 653 B, Sol papa Cottage
/ Suriname Cottage



			ı			
1.0	Denomination	T				
1.1	Name of Premises	653B, Solpapa Cott	tage / Suriname Co	ottage		
1.2	Earlier Name	Not applicable			<u>,                                      </u>	
1.3	Built in	1925-35	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Fridays Road				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Private				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on a minor	internal road of Pa	arsi Colo	ny-Firdausi Roa	d.
5.2	Architectural Description	humble but cozy bu with Mangalore tiled recessed. Verandal opening. Architrave	Low rise Vernacular style building with a very unique ambience of a humble but cozy bungalow. The bungalow has a rectangular form with Mangalore tiled pitches roof. The entrance is grooved by a recessed. Verandah formed by an equilateral point arched opening. Architraves around the equilateral point arched windows, fanlights, motifs, decorative eaves and fascia boards etc. adore the			
5.3	Intrinsic	The Zoroastrian (Pacolonies / precincts community located colony is one of the Zoroastrian Communit also has an agiary	specially built for a at various places i biggest communit unity in India. Just	all the se n the isla ty settlen like any	ections of the and city. Dadar F nents of the	Parsi
5.4	Value Classification	A(arc), B(des), C(se	eh)	Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Black Basalt course	ed stone plinth, 0.6	m high		
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Wooden flooring wi	th wooden joists a	nd batte	ns	
Δdarkaı	: Associates, Architects	222			Ward	F north

7.4	Stairs	Wooden straight flight staircase		
7.5	Openings	Arched openings for ground floor and rectangular with wooden frames and glazed shutters		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	Simple architraves for arched windows and cornice bands		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Brick wall with piers and barbed wire		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Side open space paved in Shahabad tiles		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging or deflection observed)		
9.4	Stairs	Fair (Wooden members need maintenance)		
9.5	Openings	Good (Well maintained)		
9.6	Roofing	Good (Mangalore tiles, wooden members in sound state)		
9.7	Articulation & Finishes	Good		
9.8	Services	Fair (No Breakage or leakage of pipes observed)		
9.9	Outbuildings	Good (Plantation of shrubs and small trees)		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	Chajjas added subsequently to some windows.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		

### 653B, Solipapa Cottage / Shrinmai Cottage



Front view of Solipapa Cottage along with compound wall from Firdausi road showing decorative arches, balcony



Front façade of Solipapa Cottage



Decorative cast iron brackets supporting balcony on north side having wooden railing, post supports sloping roof



Card No.: F/n-31y

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.: 681A, Farmji Bamanji Jijeebhoy Block



			<u> </u>			
1.0	Denomination					
1.1	Name of Premises	681A, Farmji Bama	anji Jijeebhoy Block			
1.2	Earlier Name	Not applicable				
1.3	Built in	1925-35	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Firdausi Road				
2.2	Subsidiary	Khareghat Road				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Ceased				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residentia	l use			
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)		er plot at junction of one of the important			
5.2	Architectural Description	design vocabulary. Mangalore tiled roc externally good in second floor, plain	g stands on a stone . The building has pl of over the structure proportions. Some for motifs around recta açade. This owned b	lain ele but a s eatures ngular	vation with a larg strong form and is s like plain cornice windows	e S
5.3	Intrinsic	colonies / precincts community located colony is one of the Zoroastrian Comm	Parsi) community of Is specially built for a dat various places in biggest community bunity in India. Just live located centrally.	II the so the isl settle	ections of the and city. Dadar F ments of the	Parsi
5.4	Value Classification	A(arc), B(des)		Recom	nmended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	0.45 m. high cours	ed Black Basalt stor	ne plint	h	
7.2	Walls	Load bearing brick	wall			
7.3	Floor	R.C.C. slab floorin	g			

7.4	Stairs	Wooden dog legged staircase with plain railing			
7.5	Openings	Rectangular wooden f	rames and glazed shut	ters	
7.6	Roofing	Sloping roof with Mane	galore tile and Timber t	russ	
7.7	Articulation	Cornice band at secor	nd floor level, architrave	es around widows	
7.8	Finishes	Internally and external	ly cement plastered an	d painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value		
7.10	Compound / Fence / Gate	1.25 m. high brick com	npound wall		
7.11	Curtilege / Unbuilt Space / Out Buildings / Landscape	Unbuilt Space Paved	with concrete		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fa	air natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Windows air-condition	ing provided at some p	laces	
9.0	Condition				
9.1	Plinth	Good (No settlement of	or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging obs	served)		
9.4	Stairs	Good (Wooden memb	ers in good condition)		
9.5	Openings	Good (Window panes	and wooden members	in sound state)	
9.6	Roofing	Good (No deflection o	bserved)		
9.7	Articulation & Finishes	Good (Paint on terrace	e spoilt due to rains)		
9.8	Services	Good (Leakage observ	ved in some places)		
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	Asbestos corrugated o	chajjas added later on.		
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Babasaheb Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayat and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



View of block from junction of Khareghat road & Firdausi road.



A view of top floor of Framji Bamanji Jijeebhoy with decorative cornice & mangalore tile roof above.



Decorative windows with pediment around, along with decorative lintel and motifs above.



Card No.: F/n-31z

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

**B U Area:** Not available

Date: May, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 605-606, Parsi

605-606, Parsi Gymkhana



1.0	Denomination					
1.1	Name of Premises	605-606, Parsi Gyr	nkhana			
1.2	Earlier Name	Not applicable				
1.3	Built in	1931	Extension Date (if	any)	Not available	
2.0	Access					
2.1	Main	Dr. Babasaheb Am	bedkar road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Trustees for Improv	vement of City of Bo	mbay,	Parsi Panchayat	
3.2	Past	Trustees for Improv	vement of City of Bo	mbay,	Parsi Panchayat	
3.3	Status	Trust owned				
4.0	Use					
4.1	Present	Recreational				
4.2	Past	Recreational				
4.3	Usage	Regular recreations	al use			
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)		oasaheb Ambedkar ear Khodadad circle		ne of the arterial	
5.2	Architectural Description	Symmetrical front f	ructures with Manga açade. Two viewing façade. Open groun	balcor	nies projecting ou	t on
5.3	Intrinsic	colonies / precincts community located colony is one of the	arsi) community of Is specially built for a at various places in biggest community unity in India. Just liy located centrally.	II the se the islay settler	ections of the and city. Dadar P ments of the	arsi
5.4	Value Classification	C(seh), J		Recom	nmended Grade	IIΒ
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	0.6 m. high Basalt	dressed stone cours	sed plin	nth	
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Access denied				
7.4	Stairs	Access Denied				

7.5	Openings	Rectangular with wood	len frames and glazed	shutters		
7.6	Roofing	Partly flat roof with terr	ace and partly sloping			
7.7	Articulation	Decorative				
7.8	Finishes	Internally and externall	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Access denied				
7.10	Compound / Fence / Gate	Plastered brick wall with ornamental C.I. railings with C.I. decorative gate with pillars				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Paved walkways arour trees are at periphery.	nd structure. Open grou	und in front of it. Big		
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, go	ood natural lighting			
8.2	Ventilation	Natural and artificial, g	ood natural ventilation			
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (Well maintained)				
9.4	Stairs	Access Denied				
9.5	Openings	Good (Wooden member	ers in sound state)			
9.6	Roofing	Good (Mangalore tiles,	, fascia and external m	embers in sound state)		
9.7	Articulation & Finishes	Good (Painted recently	/)			
9.8	Services	Access denied				
9.9	Outbuildings	Good (Partly landscape	ed and maintained clea	an)		
9.10	Overall condition	Good	Maintenance level	Good		
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	Some of the parts are	reconstructed			
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	Plot reserved for Play (D.P.)	ground on proposed D	evelopment Plan.		
12.0	Additional Notes / References / Documents Available	Notes: The land of Par owned and developed The Zoroastrian buildir Kingsway (Now Dr. Ba based on garden city in thus the colony was pla important intersections buildings were develop Parsi Panchayat and T Documents: C.S. Shee	by the Bombay Improving society acquired the basaheb Ambedkar Rodeas, prevailing in Enganned with open space and junctions. By the ped here by private entitle Parsi Cooperative	rement Trust (BIT) land on the east of oad) The layout was land ant that time, es and gardens at year 1926, 125 erprise and by The Society.		

### 686, Parsi colony Gymkhana



Front façade of Parsi colony Gymkhana



Front view of Parsi colony Gymkhana along with compound wall from Dr. Babasaheb Ambedkar road



Cantilever Viewing balcony from entrance gate



Viewing balcony detail with Westside block from open ground



West side elevation of Gymkhana



Card No.: F/n-32

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: May, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 559-60, 571-72, Central

Institute for Research in Cotton premises



1.0	Denomination			
1.1	Name of Premises	559-60, 571-72, Ce	ntral Institute for Resea	arch in Cotton Premises
1.2	Earlier Name	Not applicable		
1.3	Built in	1930's	Extension Date (if any	Not applicable
2.0	Access			
2.1	Main	Hormusji Adenwala	Road	
2.2	Subsidiary	Not applicable		
3.0	Ownership Pattern			
3.1	Present	Government owned	I	
3.2	Past	Government owned	I	
3.3	Status	Government owned	I	
4.0	Use			
4.1	Present	Institutional, Resea	rch Centre	
4.2	Past	Institutional, Resea	rch Centre	
4.3	Usage	Institutional researc	h centre	
5.0	Significance & Value Classification	1		
5.1	Townscape (Natural / Manmade)		plot facing Hormusji Ad e of Five Gardens, nea	
5.2	Architectural Description	the road is a large the 1930's. A stark built windows at equal in window adore the factors.	ouilding in typology of it form, minimum ornam tervals, cornice bands	entation, rectangular and motifs below the the above premises was
5.3	Intrinsic	the accommodation 440 acres of land w	ras acquired for Dadar- residential with importar	tunga and Wadala areas, Matunga Scheme which
5.4	Value Classification	A(arc), B(uu)	Red	commended Grade II A
6.0	Topography			
6.1	Floors	Ground floor, G + 2		
7.0	Construction			
7.1	Plinth	Black Basalt stone	olinth	
7.2	Walls	Brick load bearing v	valls	
7.3	Floor	Access denied		

Stairs Openings	Access denied  Rectangular openings with wooden frames and glazed shutters		
Openings	Rectangular openings with wooden frames and glazed shutters		
Roofing	Flat roof terrace		
Articulation	Cornice bands, pediments, entrance canopy and pilasters		
Finishes	Internally and externally cement plastered and painted		
Interiors (Movable & Immovable)	Not applicable		
Compound / Fence / Gate	Access denied		
Curtilage / Unbuilt Space / Out Buildings / Landscape	Open space concreted, trees on periphery of plot		
Services & Utilities			
Lighting	Natural and artificial, good natural lighting		
Ventilation	Natural and artificial, good natural ventilation		
Electricity	BEST		
Water Supply	MCGM		
Drainage (Plumbing and Sanitation)	MCGM		
Fire precaution	Access denied		
Other (HVAC / BMS / Security Systems)	Access denied		
Condition			
Plinth	Good (No settlement or cracks observed)		
Walls	Good (No dampness or cracks observed)		
Floor	Access denied		
Stairs	Access denied		
Openings	Good		
Roofing	Access denied		
Articulation & Finishes	Access denied		
Services	Access denied		
Outbuildings	Access denied		
Overall condition	Access denied Maintenance level Access denied		
Transformation			
Form	Access denied		
Structure	Access denied		
Articulation & Finishes	Access denied		
DP Remarks / Perceived Threats	None		
Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.		
	Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems)  Condition Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition  Transformation Form Structure Articulation & Finishes  DP Remarks / Perceived Threats Additional Notes / References /	Internally and externally cement plastered and painted  Interiors (Movable & Immovable)  Compound / Fence / Gate  Access denied  Curtilage / Unbuilt Space / Out Buildings / Landscape  Services & Utilities  Lighting  Natural and artificial, good natural lighting  Ventilation  Natural and artificial, good natural ventilation  Electricity  BEST  Water Supply  MCGM  Drainage (Plumbing and Sanitation)  MCGM  Drainage (Plumbing and Sanitation)  Access denied  Other (HVAC / BMS / Security Systems)  Condition  Plinth  Good (No settlement or cracks observed)  Walls  Good (No dampness or cracks observed)  Floor  Access denied  Stairs  Access denied  Openings  Good  Roofing  Access denied  Articulation & Finishes  Access denied  Overall condition  Form  Access denied  Maintenance level  Access denied  Transformation  Form  Access denied  Access denied  Articulation & Finishes  Access denied  Access	



Main Block A front façade from H. Adenwala road.



Rear elevation of Block B from R. K. Parekh road.



Card No.: F/n-33

Ward (Part): F north-VI

**CS No.**: 556

Plot Area: Not available

B U Area: Not available

**Date:** May, 2005

Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\

Ref.: Wadia Park



	T.O.I.I	vvadia i aik			
1.0	Denomination				
1.1	Name of Premises	Wadia Park			
1.2	Earlier Name	Not applicable			
1.3	Built in	Early 20 <sup>th</sup> century Extension Date (if any) Not applicable			
2.0	Access				
2.1	Main	Parsi Colony Road No. 6			
2.2	Subsidiary	Not applicable			
3.0	Ownership Pattern				
3.1	Present	МСС			
3.2	Past	MCGM			
3.3	Status	MCGM			
4.0	Use				
4.1	Present	Recreational			
4.2	Past	Recreational			
4.3	Usage	Regular recreational use			
5.0	Significance & Value Classification	n			
5.1	Townscape (Natural / Manmade)	Located in interior of the Parsi colony along Parsi Colony Road no.6. One of the rare trees of the city exists are found here.			
5.2	Architectural Description	Large open space with landscape areas, lawns and old trees. Walkways are planned along its axis. It is surrounded by G + 6 buildings, provides most needed openness.			
5.3	Intrinsic	After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme which was developed as residential with important amenities like gardens and educational and research institutes.			
5.4	Value Classification	I(sce), J Recommended Grade II A			
6.0	Topography				
6.1	Floors	Not applicable			
7.0	Construction	·			
7.1	Plinth	Not applicable			
7.2	Walls	Not applicable			
7.3	Floor	Not applicable			
7.4	Stairs	Not applicable			
7.5	Openings	Not applicable			
7.6	Roofing	Not applicable			
Adarka	r Associates, Architects	234 Ward F north			

7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Grey stone around 1'	high with CI railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Walkways are paved	with concrete tiles		
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Not applicable			
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot demarcated as Recreational Ground on proposed Development Plan (D.P.)			
12.0	Additional Notes / References / Documents Available	Notes: The land of Parsi colony, Hindu colony and Shivaji Park was owned and developed by the Bombay Improvement Trust (BIT) The Zoroastrian building society acquired the land on the east of Kingsway (Now Dr. Ambedkar Road) The layout was based on garden city ideas, prevailing in England ant that time, thus the colony was planned with open spaces and gardens at important intersections and junctions. By the year 1926, 125 buildings were developed here by private enterprise and by The Parsi Panchayet and The Parsi Cooperative Society.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### Wadia Park



Pathways in garden with planned plantation.



Wadia Park Udyan from Parsi colony road no 6 with rear tree in Mumbai.



**Card No.:** F/n-34

Ward (Part): F north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ Ref.: Acworth Municipal

Hospital for Leprosy Premises



1.0	Denomination				
1.1	Name of Premises	Acworth Municipal Hospital for Leprosy Premises			
1.2	Earlier Name	Acworth Municipal Hospital for Leprosy			
1.3	Built in	1920's Extension Date (if any) Not applicable			
2.0	Access				
2.1	Main	Rathalal Parekh Road (Matunga Road)			
2.2	Subsidiary	R. Parmeshwaram Road			
3.0	Ownership Pattern				
3.1	Present	Municipal Corporation Of Greater Mumbai			
3.2	Past	Not available			
3.3	Status	Government owned			
4.0	Use				
4.1	Present	Leprosy Hospital			
4.2	Past	Leprosy Hospital			
4.3	Usage	Regular health care, public use			
5.0	Significance & Value Classification	า			
5.1	Townscape (Natural / Manmade)	Located on east side of Parsi colony on Rathalal Parekh Road. Large open space with dense vegetation. When it was planned by the Bombay Improvement Trust, it was isolated from main residential area.			
5.2	Architectural Description	A low scale campus planned in clusters. Main office building, is near the entrance and the other structures are used as Wards for Leprosy patients. Structures are in vernacular style with Mangalore tiled sloping roof and load bearing walls in Dressed Black Basalt stone. Bungalow for Dean of the hospital a G+1 vernacular style structure. Since access to the above premises was derined the information is not available in detail.			
5.3	Intrinsic	One of the oldest Leprosy Hospitals of Mumbai for public welfare.			
5.4	Value Classification	B(per), B(des),C(seh), D(bio), J Recommended Grade II B			
6.0	Topography	· · · · · · · · · · · · · · · · · · ·			
6.1	Floors	Ground Floor			
7.0	Construction				
7.1	Plinth	Dressed Black Basalt stone plinth			
7.2	Walls	Dressed Black Basalt stone walls			
7.3	Floor	Access denied			

7.4	Stairs	Not applicable			
7.5	Openings	Rectangular opening with wooden frame and glass panel			
7.6	Roofing	Sloping roof with Mangalore tiles			
7.7	Articulation	Less ornamentation, wooden louvers and railing			
7.8	Finishes	Externally and Internally exposed Black Basalt stone			
7.9	Interiors (Movable & Immovable)	Access denied			
7.10	Compound / Fence / Gate	Plastered brick wall with iron fencing			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Lots of Big trees, Open space, Tar roads. Bungalow for Dean of Hospital.			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	мссм			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Good			
9.2	Walls	Good (observed from outside)			
9.3	Floor	Access denied			
9.4	Stairs	Not applicable			
9.5	Openings	Good (observed from outside)			
9.6	Roofing	Fair			
9.7	Articulation & Finishes	Good			
9.8	Services	Fair			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair Maintenance level Fair			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Not applicable			
11.0	DP Remarks / Perceived Threats	Plot demarcated as Hospital on proposed Development Plan (D.P.)			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai			

### **Acworth Municipal Hospital for Leprosy Premises**




Office building along entrance road of Acworth Hospital.



Main Entrance gate of Acworth hospital.



Front façade of 'Bungalow for Dean of Hospital'.



Card No.: F/n-35

Ward (Part): F north-IV

**CS No.:** 2/10

Plot Area: 65699.33 sq.m.

B U Area: Not available

Date: May, 2005

Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 501-09, Veermata

501-09, Veermata Jijamata Technical Institute Premise



1.0	Denomination					
1.1	Name of Premises	501-09, Veermata	Jijamata Technical	Institute	Premise	
1.2	Earlier Name	Victoria Jubilee Te	chnical Institute (V.	J.T.I)		
1.3	Built in	1923	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	H. Mahajani Marg	(College Road)			
2.2	Subsidiary	Nathalal M. Parikh	Marg			
3.0	Ownership Pattern	wnership Pattern				
3.1	Present	Not available				
3.2	Past	Not available	Not available			
3.3	Status	Trust				
4.0	Use	se				
4.1	Present	Institutional, Residential				
4.2	Past	Institutional	Institutional			
4.3	Usage	Regular institutiona	Regular institutional, residential use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Nathalal M. Parikh on north side of Fiv The premises cons	Located on an oblong large plot between H Mahajani Marg and Nathalal M. Parikh Marg on the outskirts of Parsi colony. Located on north side of Five Gardens, one of the large garden in Mumbai. The premises consist of the college building, a hostel and an open recreational space allotted as playground.			
5.2	Architectural Description	The college building expresses grandeur in a well articulated Neo- classical style. The entrance porch is highlighted with imposing lonic columns and pediments decorated with dentils. Large dome over the staircase, sloping Mangalore tile roof with lonic pilasters, semi-circular arched windows on ground floor, cornice band at terrace level well detailed railing on first floor all contribute towards its high architectural value.				
5.3	Intrinsic	This institute was erected in Scheme V, developed by the Bombay City Improvement Trust in the Dadar-Matunga Estate, on 16 acres of land acquired from the improvement Trust. The building was completed in 14 <sup>th</sup> November 1923,. The institute was named after Queen Victoria since it was founded in the year she celebrated her Jubilee. ( detail note given at the end)				
5.4	Value Classification	A(arc), B(uu), B(de	s), H(tec)	Recom	mended Grade	IIΒ
6.0	Topography					
6.1	Floors	G + 1				

7.0	Construction				
7.1	Plinth	Malad stone dressed of	coursed masonry plinth		
7.2	Walls	Load bearing brick wa	lls		
7.3	Floor	R.C.C. slab flooring			
7.4	Stairs	R.C.C. open well stair	case		
7.5	Openings		wooden frames and gla ngular with wooden fra		
7.6	Roofing	Sloping roof with Man	galore tiles and wooder	n trusses	
7.7	Articulation	decorative cornice bar	e with ionic pilasters on nds at terrace level, dec gentrance porch with de e block.	corative R.C.C. railing	
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Old machinery inside	Old machinery inside the laboratories		
7.10	Compound / Fence / Gate	Stone wall with decorative MS railing			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Adequate front open s	Adequate front open space, also having large side open space		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning	ng units at some places		
9.0	Condition				
9.1	Plinth	Good (No settlement of	or cracks observed)		
9.2	Walls	Good (No dampness of	or cracks observed)		
9.3	Floor	Good (No deflection o	bserved)		
9.4	Stairs	Good (Well maintaine	d)		
9.5	Openings	Good (Window panes	and wooden members	in sound state)	
9.6	Roofing	Good (No leakage or	deflection observed)		
9.7	Articulation & Finishes	Good (Plaster and pai	nt finish in sound state)		
9.8	Services	Good (Well maintaine	d)		
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Maintenance work in p	Maintenance work in progress.		
		Plot reserved for college on proposed Development plan. (D.P.)			

## 12.0 Additional Notes / References / Documents Available

Notes: This leading institute, which of the first of its kind in the country, was established in 1887. this was largely due to initiative and foresight of Governor Lord Reay, the Bombay Millowners' Association and enlightened civic leader such as Sir Pherozeshah Mehta, Dadabhai Naoroji, Dinsha Wacha, Badruddin Tyabjee and Justice Mahadeo Govind Ranade and generous funding provided by Sir Dinshaw Manekji Petit, Baronate. The institute was named after Queen Victoria since it was founded in the year she celebrated her Jubilee, that is fifty years of her reign. Until the construction of the new building, the institute was housed in the former Elphinstone College (now Dr. Babasaheb Ambedkar Hospital opposite Jijamata udyan) in byculla and was started with two department to teach Mechanical Engineering and textile Manufacture. An Electrical Engineering Department was added in the early year of the 20<sup>th</sup> century and later, department of technical and applied Chemistry and Sanitary Engineering and Plumbing were also started. The institute awarded diplomas until degree courses were commenced in 1946

Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.



Front elevation of V.J.T.I College main block from H Mahajani road showing grand entry with double height porch supported by huge circular columns and dome on top



South corner of front façade of main block with cast iron fencing



Part front façade of V.J.T.I College main block



Ornamented cast iron Entrance gate of V.J.T.I College



Double height entrance porch with decorative columns supporting large pediment on top.



Detail of pediment and column capital with stucco work



View of V.J.T.I. Hostel and front open ground from H Mahajani road. It has arched common passage in front elevation.



Card No.: F/n-36

Ward (Part): F north-IV

**CS No.:** 758 / 10

Plot Area: 23112.2 sq.m.

**B U Area:** 18018 sq.m.

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 471-96, Khalsa College



1.0	Denomination						
1.1	Name of Premises	471-96, Khalsa Col	lege				
1.2	Earlier Name	Not applicable					
1.3	Built in	1933-35	Extension Date (i	f any)	Not applicable		
2.0	Access						
2.1	Main	Nathalal M. Parikh	Marg				
2.2	Subsidiary	D. M. Estate, Road	No. 32				
3.0	Ownership Pattern						
3.1	Present	Not available	Not available				
3.2	Past	Not available					
3.3	Status	Trust					
4.0	Use						
4.1	Present	College					
4.2	Past	College	College				
4.3	Usage	Regular institutiona	ıl use				
5.0	Significance & Value Classification	า					
5.1	Townscape (Natural / Manmade)	Located at Junction of Nathalal M. Parikh Marg and D.M. Estate, Road No. 32, on a prominent location in Matunga off Maheshwari Udyan. It is located on north side of Veermata Jijabai Technical Institute Premise.					
5.2	Architectural Description	Low-rise colonial st on first and second Staircase block has motifs.	floor. Geometric m	notifs on	the façade.		
5.3	Intrinsic	One of the old colle Parsi Colony and H Bombay Improvem	lindu colony at Dad				
5.4	Value Classification	A(arc), B(uu), B(de	s), C(seh)	Recom	mended Grade	II A	
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth	Malad dressed stor	ne coursed plinth				
7.2	Walls	Load bearing brick	walls				
7.3	Floor	R.C.C. slab floors a	and beams				
7.4	Stairs	Wooden open well	staircase				
7.5	Openings	Rectangular openir	ngs with wooden fra	ames an	d glazed shutter	ss	

7.6	Roofing	Flat roof terrace			
7.7	Articulation	Colonial style structure with circular columns having decorative capitals spanning from first to second floors. Plain pediment with floral motifs on staircase block.			
7.8	Finishes	Internally and externally cement plastered and painted. Ground floor in Malad stone.			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Plastered brick wall with C.I. railing			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Landscaped front open space and side open spaces			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No deflection observed)			
9.4	Stairs	Good (Well maintained)			
9.5	Openings	Good (Window panes and wooden members in sound state)			
9.6	Roofing	Good (No leakage or deflection observed)			
9.7	Articulation & Finishes	Good (Plaster and paint finish in sound state)			
9.8	Services	Good (Well maintained)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	Grills added and interiors redone.			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot reserved for college on proposed Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Notes: After the decision of Bombay Improvement Trust (BIT) to provide the accommodation facilities in Dadar, Matunga and Wadala areas, 440 acres of land was acquired for Dadar-Matunga Scheme. The biggest plus point at that time was the grand 158 feet wide Kingsway (Now Dr. Babasaheb Ambedkar Road) as its principal access lit by electric lamps. The plots here were laid out in 1926.			
		Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### Khalsa College



Front façade of Khalsa College from Matunga road.



Main entrance to the building with decorative circular columns.



Corner of Khalsa College from Matunga road behind dense vegetation.



Card No.: F/n-37

Ward (Part): F north-IV & II

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Assistant Commissioner

of Police & Special
Executive Magistrate,
Matunga Division
Premises



1.0	Denomination					
1.1	Name of Premises		Assistant Commissioner of Police & Special Executive Magistrate, Matunga Division Premises (All buildings)			
1.2	Earlier Name	Police Station				
1.3	Built in	1923	Extension Date (if any)	Not applicable		
2.0	Access					
2.1	Main	Laxmibai Kelakar N	Marg (Sion Road)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Maharashtra Police	•			
3.2	Past	Maharashtra Police	)			
3.3	Status	Government owned	t			
4.0	Use					
4.1	Present	Police station, public				
4.2	Past	Police station, public				
4.3	Usage	Frequent Public us	Frequent Public use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)		olot facing Laxmibai Kelaka uth road, next to King's circ			
5.2	Architectural Description	The premises have two main buildings facing the main road. One of them is Matunga Police station which is in the typology of city's many police stations in Vernacular style built in early 20 <sup>th</sup> century having two side bays with gable wall and recessed verandah and balcony. Ground floor has a semi-circular arched verandah, above which is a balcony with plain wooden railing and bar tracery. The Mangalore tiled sloping roof is in interesting profile. The two side blocks have a plain pediment on terrace parapet level.  The Other building is Sion Police station which is planned with some variation. The two parts projecting out from verandah have rectangular and cylindrical form. This typology is similar to 'European Bungalows' seen in Kala Chowky in cental Mumbai.				
5.3	Intrinsic	rule. After the decis provide the accomm Wadala areas, 440 Scheme which was	old Police-station buildings sion of Bombay Improvement modation facilities in Dadar acres of land was acquire developed as residential estations, gardens and entitle stations.	ent Trust (BIT) to r, Matunga and d for Dadar-Matunga with important		

5.4	Value Classification	A(arc), B(des) B(per), B(u J	ıu), C(seh),	Recom	mended Grade	IIΒ
6.0	Topography	<u> </u>		<u>I</u>		
6.1	Floors	G+1, G+2				
7.0	Construction	<u> </u>				
7.1	Plinth	Black Basalt stone course	ed masonry	0.6m hi	gh plinth	
7.2	Walls	Brick load bearing wall				
7.3	Floor	Wooden beam joist floor				
7.4	Stairs	Wooden dog legged staird decoration on risers with p			oden balustrades	5,
7.5	Openings	Rectangular openings with wooden frame and paneling				
7.6	Roofing	Sloping roof with Mangalo	ore tiled supp	orted o	n wooden truss	
7.7	Articulation	Cornice band at floor leve balconies. Pediments to v				
7.8	Finishes	Internally and externally li	me plastered	d and pa	ainted	
7.9	Interiors (Movable & Immovable)	Interiors, not of Heritage v	/alue			
7.10	Compound / Fence / Gate	Plastered brick wall with o	cast iron gate	)		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Open space paved with S quarters behind it.	Shahabad tile	s. Few	trees. Residentia	al
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural lighting				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
9.0	Condition					
9.1	Plinth	Good (No settlement or c	racks observ	/ed)		
9.2	Walls	Good (No dampness or c	racks observ	ved)		
9.3	Floor	Fair (Sagging observed a	t few places)	)		
9.4	Stairs	Fair (Wooden members n	eed mainten	nance)		
9.5	Openings	Good (Well maintained)				
9.6	Roofing	Good (Recently repaired,	Mangalore t	iles cha	nged)	
9.7	Articulation & Finishes	Good (Recently repaired)				
9.8	Services	Good (Well maintained)				
9.9	Outbuildings	Fair (Not utilized properly)	)			
9.10	Overall condition	Good Ma	aintenance le	evel	Good	
10.0	Transformation	I				
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	Plot reserved for Police S (D.P).	tation on pro	posed I	Development Pla	ın
12.0	Additional Notes / References / Documents Available	Notes: After the decision of provide the accommodation wadala areas, 440 acres Scheme. The biggest plus wide Kingsway (Now Dr. I principal access lit by elections)	on facilities in of land was so point at that Babasaheb A	n Dadar acquire It time w Ambedk	r, Matunga and d for Dadar-Matu as the grand 158 ar Road) as its	ınga 8 feet

	1926.
	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.

# Assistant Commissioner of Police & Special Executive Magistrate, Matunga Division Premises ( All buildings )



View of Matunga Police Station from pedestrian foot over bridge.



View of Matunga Police Station Premises from Sion road.



Main entrance to Matunga Police Station.



Front façade of Matunga Police Station with semi-circular arched openings behind vegetation.



Card No.: F/n-38

Ward (Part): F north-VI

CS No.: Not available

Plot Area: Not available

B U Area: Not available

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Jaykar Bungalow



1.0	Denomination					
1.1	Name of Premises	Jaykar Bungalow				
1.2	Earlier Name	Not applicable				
1.3	Built in	Late 19 <sup>th</sup> century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Off Barkat Ali Road	d			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Jaykar	Jaykar			
3.2	Past	Jaykar	Jaykar			
3.3	Status	Ceased				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	Located on the hill, the nearby settleme		la statio	n. It is isolated fr	om
5.2	Architectural Description	Modest vernacular Mangalore tiled slo entrance porch, an structure has been	ping roof, with deco	orative e	eaves board. It hat tures in the area.	as an
5.3	Intrinsic	One of the old vern to Jaykar family fro of the oldest comm	m the Pathare Pral			
5.4	Value Classification	B(per), C(seh)		Recom	nmended Grade	Ш
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Black basalt stone	random masonry p	linth		
7.2	Walls	Brick load bearing walls				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Rectangular with wand wooden frame				ws
7.6	Roofing	Sloping roof with M	langalore tiles and	wooden	trusses	

7.7	Articulation	Not much articulation on façade	
7.8	Finishes	Internally and externally cement plastered and painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value	
7.10	Compound / Fence / Gate	Not applicable	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large open space around with few trees	
8.0	Services & Utilities		
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and Sanitation)	MCGM	
8.6	Fire precaution	Not provided	
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places	
9.0	Condition		
9.1	Plinth	Fair (Cracks observed at some places)	
9.2	Walls	Fair (Dampness or cracks observed)	
9.3	Floor	Fair (Access denied)	
9.4	Stairs	Not applicable	
9.5	Openings	Fair (Wooden members need maintenance)	
9.6	Roofing	Fair (Part replaced by A.C. sheets)	
9.7	Articulation & Finishes	Fair (Plastered chipped off at some places)	
9.8	Services	Fair (Roof gutters need repairs)	
9.9	Outbuildings	Fair	
9.10	Overall condition	Fair Maintenance level Fair	
10.0	Transformation		
10.1	Form	No transformation	
10.2	Structure	Asbestos sheets provided on place of Mangalore tiles at the entrance porch.	
10.3	Articulation & Finishes	Re-plastered and painted subsequently.	
11.0	DP Remarks / Perceived Threats	Threat from the small shrubs growing at base of plinth.	
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.	

# Jaykar Bungalow



View of Jaykar Bungalow showing elevated rare entrance from north side.



Front façade of Jaykar bungalow having steps leading towards it.



Wooden truss supporting sloping roof above showing purlins and wooden boarding.



Common	Dof	No	
Common	Ret.	NO.	:

Card No.: F/n-39

Ward (Part): F north-V

**CS No.:** 60-64

Plot Area: 2051.84 sq. m.

B U Area: Not available

Date: May, 2005

Record by: Keshav S, Anup S

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Chinese cemetery



1.0	Denomination					
1.1	Name of Premises	Chinese cemetery,	Antop Hill			
1.2	Earlier Name	Not applicable				
1.3	Built in	1890	Extension Date (if a	any) Not a	pplicable	
2.0	Access	•		•		
2.1	Main	Shaikh Mishari Mar	g			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Trustees for improv	rement of city of Born	nbay. Malti M	lanjrekar	
3.2	Past	Papamiya Gulam N Vijay Chitale	lohhuddin, Mavel Pa	albina Fonse	ca, Suloch	ana
3.3	Status	Trust				
4.0	Use					
4.1	Present	Burial Ground				
4.2	Past	Burial Ground				
4.3	Usage	Occasional public u	ise			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Open space locate in the vicinity.	Open space located on Shaikh Mishari Marg with slum settlement in the vicinity.			
5.2	Architectural Description		netery in midst of cra rance wall has the hi			
5.3	Intrinsic	cemetery was cons	The 1826 census showed 37 Chinese families. The need for a cemetery was considered and the Chinese were allotted place at Antop Hill in 1880 during the relocation project of cemeteries to the then Muddy area. It was completed on 10 <sup>th</sup> February 1890.			
5.4	Value Classification	C(seh), E, F, I(sce)	F	Recommend	ed Grade	IIΒ
6.0	Topography					
6.1	Floors	Not applicable				
	FIOUIS	Not applicable				
7.0	Construction	Not applicable				
<b>7.0</b> 7.1	<u> </u>	Not applicable				
	Construction					
7.1	Construction Plinth	Not applicable				
7.1 7.2	Construction Plinth Walls	Not applicable  Not applicable				
7.1 7.2 7.3	Construction Plinth Walls Floor	Not applicable Not applicable Not applicable				

7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable	Not applicable		
7.10	Compound / Fence / Gate	Black Basalt stone co	mpound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Pathway paved with S	Pathway paved with Shahabad Tiles. Number of trees in the plot.		
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	мсөм			
8.5	Drainage (Plumbing and Sanitation)	мсөм			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable	Not applicable		
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Fair (Trenches for dra	inage)		
9.9	Outbuildings	Fair (slum encroachn	nent on periphery)		
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot reserved for cem	etery on proposed Deve	elopment plan (D.P.)	
12.0	Additional Notes / References / Documents Available	Notes: Group of Cantonese workers arrived in Bombay in the early 1880's on the East India Company ships. Containing silk for the mills in Parel and Byculla. The ships on their way back carried Cotton and Opium. The 1826 census showed 37 Chinese families grew the need for cemetery was considered and the Chinese were allotted place at Antop Hill in 1880 during the relocation project of cemeteries to a then Muddy area. It was completed on 10 <sup>th</sup> February 1890.  Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			



Holly wall next to entrance of cemetery. (Chinese people treat this wall as temple.)





Detail of plaque on wall in Chinese Cemetry.

### **Walchand Precinct**

The precinct is located in hilly and fairly wooded area near Antop hill. Vernacular structures constructed in random Black Basalt stone contributes to its heavy appearance. Three main bungalows are located at different levels on hill; servant quarters are located at the base of the hill. On the east side of the hill which has a stiff slope where as the west side gradually slopes towards the ground. The hill separates the salt pans from the main land. Overlooks the salt pans along with the Eastern waterfront.

Buildings in the Precincts:

- 1. 3 Bungalows
- 2. 3. Servant quarters
- Hill



Card No.: F/n-40

Ward (Part): F north-V

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Walchand Precinct



1.0	Denomination	
1.1	Name of Premises	Walchand Precinct
1.2	Earlier Name	Not applicable
1.3	Built in	Early 20 <sup>th</sup> century Extension Date (if any) Not applicable
2.0	Access	
2.1	Main	M. T. Vishwasrao Road
2.2	Subsidiary	Not applicable
3.0	Ownership Pattern	
3.1	Present	MCGM, Tenanted
3.2	Past	MCGM, Tenanted
3.3	Status	MCGM, Tenanted
4.0	Use	
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Regular residential use
5.0	Significance & Value Classificatio	n
5.1	Townscape (Natural / Manmade)	The precinct is located in hilly and fairly wooded area near Antop hill. Vernacular structures constructed in random Black Basalt stone contributes to its heavy appearance. Three main bungalows are located at different levels on hill; servant quarters are located at the base of the hill. The hill separates the salt pans from the main land. Overlooks the salt pans along with the Eastern waterfront.
5.2	Architectural Description	The buildings of the precinct are low-rise and have a strong vernacular style with minimal ornamentation on the facade. The buildings are located at different levels. One structure consists of two symmetrical blocks with a large open space around it.
5.3	Intrinsic	This is MCGM owned premises located on hill on central east of Mumbai. Typical planning of each block. Salt pans are next to it.
5.4	Value Classification	B(per), G(grp) Recommended Grade III
6.0	Topography	·
6.1	Floors	Not applicable
7.0	Construction	
7.1	Plinth	Not applicable
7.2	Walls	Not applicable
7.3	Floor	Not applicable

12.0	Additional Notes / References / Documents Available	Notes: Documents: Mumbai	C.S. sheets, D.P. Sheet	s, Eicher City Maps -		
11.0	DP Remarks / Perceived Threats	Plots reserved as re Plan. (D.P.)	Plots reserved as recreational ground on proposed Development Plan. (D.P.)			
10.3	Articulation & Finishes	Not applicable				
10.2	Structure	Not applicable				
10.1	Form	Not applicable				
10.0	Transformation					
9.10	Overall condition	Not applicable	Maintenance level	Not applicable		
9.9	Outbuildings	Not applicable				
9.8	Services	Not applicable				
9.7	Articulation & Finishes	Not applicable				
9.6	Roofing	Not applicable				
9.5	Openings	Not applicable				
9.4	Stairs	Not applicable				
9.3	Floor	Not applicable				
9.2	Walls	Not applicable				
9.1	Plinth	Not applicable				
9.0	Condition					
8.7	Other (HVAC / BMS / Security Systems)	Not applicable				
8.6	Fire precaution	Not applicable				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.4	Water Supply	MCGM				
8.3	Electricity	BEST				
8.2	Ventilation	Not applicable				
8.1	Lighting	Not applicable				
8.0	Services & Utilities	<u> </u>	·			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	The two buildings have lots of open space in between planted with shrubs and trees. Pathways concreted.				
7.10	Compound / Fence / Gate	Not applicable				
7.9	Interiors (Movable & Immovable)	Not applicable				
7.8	Finishes	Not applicable				
7.7	Articulation	Not applicable	Not applicable			
7.6	Roofing	Not applicable				

### **Walchand Precinct**



Walchand Bungalow no 1 from M. T. Vishwasroa road with long retaining wall and steps to Bungalow



Walchand Bungalow no 2 with landscape in front open space



Walchand Bungalow no 3 with lots of vegetation around



Servant's quarters at bottom of hill.



Walchand Bungalows from bottom of hill



Paved walkway in walchand precinct



Card No.: F/n-40a

Ward (Part): F north-V

**CS No.:** 3 / 351

Plot Area: 1009.33 sq.m.

**B U Area:** 450 sq.m.

**Date:** May, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Walchand Bungalow



1.0	Denomination					
1.1	Name of Premises	Walchand Bungalo	Walchand Bungalow			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Sheikh Mishari Mai	g			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	MCGM				
3.2	Past	The Indian Hume F	Pipe Ltd.			
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	outhouses enjoy th eastern waterfront,	Located on a hillock this settlement of three bungalows and outhouses enjoy the highest altitude in the vicinity with a view of eastern waterfront, though now interrupted by a scheme of recently built residential towers.			
5.2	Architectural Description	The bungalow can be either approached by a private Road or a paved pathway with steps leading to the top of hillock. The three identical bungalows all built in Black Basalt random rubble masonry with a cubic form and Mangalore tiled pitched roof. The bungalows have segmental arched double windows and minimal ornamentation on façade.				
5.3	Intrinsic		re allotted around si pe Company Ltd, sit			aff of
5.4	Value Classification	A(arc), B(seh)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Black Basalt stone	random masonry pli	nth		
7.2	Walls	Black Basalt stone	random masonry			
7.3	Floor	Wooden flooring wi	th wooden joists and	d batte	ns	
7.4	Stairs	Dog legged woode	<del></del>			

7.5	Openings	Rectangular double windows with wooden frames and glazed shutterss			
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses			
7.7	Articulation	Segmental arched openings, plain cornice band at floor level			
7.8	Finishes	Externally exposed Black Basalt stone, plastered and painted internally			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Black Basalt random masonry retaining wall on south side			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large unpaved open space around with outhouse			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (Dampness observed on western walls)			
9.3	Floor	Good (No sagging or deflection observed)			
9.4	Stairs	Fair (Wooden members need maintenance)			
9.5	Openings	Fair (Windows on western side attacked by strong wind and rains, some windows replaced by aluminum windows)			
9.6	Roofing	Fair (Two bungalows painted externally, fascia broken at many places)			
9.7	Articulation & Finishes	Fair (Leakage of some pipes observed)			
9.8	Services	Fair (Debris dumped at some places)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	M.S. grills and air-conditioning window units added later.			
10.2	Structure	Encroachments on ground floor, extension of terrace done by tenants on ground floor.			
10.3	Articulation & Finishes	Repainted externally.			
11.0	DP Remarks / Perceived Threats	Plot falls under recreational ground on proposed Development plan (D.P.)			
12.0	Additional Notes / References / Documents Available	Notes: The bungalows were used as staff quarters for the staff of the Indian Hume Pipe Company Ltd. Next to this plot.			

# **Walchand Bungalow**



Front façade of Walchand Bungalow no 2 from approaching road



Paved front open space of Walchand Bungalow no 2



Pedestrian entry to Walchand Bungalow



Card No.: F/n-41

Ward (Part): F north-V

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Ismail Sanatorium

premises



1.0	Denomination					
1.1	Name of Premises	Ismail Sanatorium Premises				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1940's	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Sheikh Misari Road	t			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust owned				
4.0	Use					
4.1	Present	Religious, Educatio	nal and Residentia	l		
4.2	Past	Religious, Educational and Residential				
4.3	Usage	Regular religious, e	Regular religious, educational and residential use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on east side of Sheikh Misari Road. Plot touches the Walchand precinct on south side.				
5.2	Architectural Description	demarcated by a la pinnacle on top. Fe decorate the façade water body and a p	Expressing horizontality this building is enhanced by the entrance, demarcated by a large Moorish arch gateway and a dome with a pinnacle on top. Features likes minarets, carvings, Moorish arches decorate the façade. The entrance leads to a central court with a water body and a prayer hall. Since access to the above premises was derived the information is not available in detail.			
5.3	Intrinsic	The sanatorium is located in the neighborhood that had a large Muslim population but at present has drastically declined. It accommodates Madaresa (education)and sanatorium(residential) facilities.				
5.4	Value Classification	A(arc),C(seh)		Recom	nmended Grade	IIΒ
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Plastered brick plin	th			
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Access denied				
7.4	Stairs	Access denied				

7.5	Openings	Semi circular and Moorish arch opening with wooden frame and glass panel			
7.6	Roofing	Flat slab, dome on er	ntrance		
7.7	Articulation	Floral motifs on façade of gateway with multifoil or Moorish arches. Decorative minarets at the corners and decorative floral motifs all over façade.			
7.8	Finishes	Externally plastered a	and painted		
7.9	Interiors (Movable & Immovable)	Access denied			
7.10	Compound / Fence / Gate	Access denied			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Access denied			
8.0	Services & Utilities				
8.1	Lighting	Access denied			
8.2	Ventilation	Access denied	Access denied		
8.3	Electricity	BEST			
8.4	Water Supply	мсөм			
8.5	Drainage (Plumbing and Sanitation)	мсөм			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Good			
9.2	Walls	Good (observed from	outside)		
9.3	Floor	Access denied			
9.4	Stairs	Access denied			
9.5	Openings	Good (observed from	outside)		
9.6	Roofing	Access denied			
9.7	Articulation & Finishes	Good			
9.8	Services	Access denied			
9.9	Outbuildings	Access denied			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plots demarked as Sa (D.P.)	antorium on proposed [	Development Plan.	
12.0	Additional Notes / References / Documents Available	Documents: C.S. She	eets, D.P. Sheets, Eiche	er City Maps-Mumbai	

### **Ismail Sanatorium Premises**




Front façade of Ismail sanatorium entrance block from Sheikh Misari road.



Ornamented entrance arch detail with cornice bands.



Detail of minarates of entrance block.



Detail of Main entrance with ornamented arch, minarates and dome above it.



Card No.: F/n-42

Ward (Part): F north-II

**CS No.:** 99 / 10

Plot Area: Not available

B U Area: Not available

Date: April, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** Vishwa Building



1.0	Denomination					
1.1	Name of Premises	Vishwa Building				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1935-38 Extens	ion Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Dr. Babasaheb Ambedkar F	Road			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Private owned				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Facing Dr. Babasaheb Ambedkar road, one of the major North-South roads of Mumbai, located near Sion circle, a busy junction.				
5.2	Architectural Description	An example of Indo Deco features as reflected in a modest residential building. The staircase block has a sloping roof with low rise and supported on multiple brackets. The staircase block closely resembles that of Shet Ranchoddas Sanatorium on Sion hill. Stained glass panels are fixed in top part of window opening.				
5.3	Intrinsic	It is part of the Sion estate a	along Dr. B	abasah	eb Ambedkar Ro	oad.
5.4	Value Classification	A(arc),		Recom	nmended Grade	III
6.0	Topography					
6.1	Floors	G+2				
7.0	Construction					
7.1	Plinth	Dressed basalt stone plinth	0.3 m. high	า		
7.2	Walls	Load bearing brick walls				
7.3	Floor	R.C.C. slab flooring				
7.4	Stairs	Wooden dog-legged stairca	se with hig	hly dec	orative newel pos	st
7.5	Openings	Rectangular and arched operation (stained glass)shutter	enings with	woode	en framed glazed	
7.6	Roofing	Flat roof with partly sloping	roof			

7.7	Articulation	Highly decorative with wooden railing, ornamental columns and Moorish arches			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Plastered brick wall w	ith cast iron railing		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Lots of trees within the	e compound		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	good natural lighting		
8.2	Ventilation	Natural and artificial, g	good natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness of	or cracks observed)		
9.3	Floor	Good (No sagging obs	served)		
9.4	Stairs	Good (Wooden memb	pers in sound state)		
9.5	Openings	Good (Well maintained	d)		
9.6	Roofing	Good (No leakage or I	breaking of Mangalore	tiles observed)	
9.7	Articulation & Finishes	Good (Needs to be pa	ninted)		
9.8	Services	Fair			
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Shee	ets, D.P. Sheets, Eiche	r City Maps-Mumbai.	

# Vishwa Building







Detail of staircase block roof of Vishwa Building



Card No.: F/n-43

Ward (Part): F north-l

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Sion Circle Garden



1.0	Denomination					
1.1	Name of Premises	Sion Circle Garder	1			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	Mid 20 <sup>th</sup> century	Extension Date (if	any) N	Not applicable	
2.0	Access					
2.1	Main	Laxmibai Kelkar R	oad			
2.2	Subsidiary	Sion Road No. 6				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Not available				
4.0	Use					
4.1	Present	Recreational, Publ	ic			
4.2	Past	Recreational, Publ	ic			
4.3	Usage	Regular public use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on a busy and a landmark circular junction Laxmibai Kelkar Road, one of main road in North-South direction and Sion Road no.6 Located on a very busy traffic junction.				
5.2	Architectural Description	Open garden located on a circular plot at a very busy traffic intersection. It is wooded with shrubs and large trees. Pathways paved in cement tiles divide the garden in a number of segments covered with lawns. However the columns of the Flyover are right inside the garden thereby destroying its naturescape.				nts
5.3	Intrinsic		ated in one of the old node on the highway		ge areas of Mu	mbai,
5.4	Value Classification	C(seh), I(sce), J		Recomm	ended Grade	II A
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Not applicable				
7.6	Roofing	Not applicable				
۸ طمعاده	Associates Architects	270			10/	I E north

7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Low height peripheral concrete wall with mild steel fencing			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Ground covered with lawn and different kinds of shrubs and large trees.			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, excellent natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Good			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot reserved for recreational ground on proposed Development Plan (D.P).			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai			

# Sion Circle Garden



View of Sion Circle Garden from South side.



View of Sion Circle Garden from north side.



View of Sion Circle Garden from Rani Lakshmi Bai chowk.



View of Sion Circle Garden from East side.



Card No.: F/n-44

Ward (Part): F north-I

CS No.: Not available

Plot Area: Not available

**B U Area:** Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

**Photo** T-III-Fn:\Ward F north\ **Ref.:** 230, Hanuman Mandir



1.0	Denomination					
1.1	Name of Premises	230, Hanuman Mar	ndir			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 <sup>th</sup> century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Sion Road No. 16				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Privately owned				
4.0	Use					
4.1	Present	Religious				
4.2	Past	Religious				
4.3	Usage	Regular religious use				
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located on a rectangular plot on Sion Road no 16 near Dr. Babasaheb Ambedakar Road. Earlier this area was known as Bhandarwada.				
5.2	Architectural Description	The entrance to the wooden posts and pyramidal roof. <i>Gal</i>	Vernacular style small scale temple located in Sion-Bhandarwada The entrance to the temple is through a semi-open <i>Mandapa</i> with wooden posts and trusses, supporting the mangalore tiled pyramidal roof. <i>Garbhagriha</i> is constructed in Black Basalt stone coursed masonry. It has decorative wooden beams and post, railing			
5.3	Intrinsic	Bhandarwada at Si with the vernacular built by the local fis the oldest temples Bhandarwada- neig	architecture in Mu hermen community in Mumbai, existing	mbai. H y in the g in one	Hanuman Mandir year 1880's. One	was
5.4	Value Classification	A(arc), A(cul), A(his	s), C(seh)	Recom	nmended Grade	Ш
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Black Basalt stone	coursed masonry p	olinth 0.	6m high	
7.2	Walls	Load bearing wall of	of <i>Garbhagriha</i> in B	Basalt st	one coursed mas	sonry
7.3	Floor	Marble floor				

7.4	Stairs	Not applicable			
7.5	Openings	Rectangular openings with wooden frame and paneling			
7.6	Roofing	Mangalore tiled sloping roof supported on wooden trusses			
7.7	Articulation	Ornamented columns and capitals. Decorative wooden railing.			
7.8	Finishes	Internally and externally exposed stone. Wooden column, brackets painted			
7.9	Interiors (Movable & Immovable)	Old shrine of Lord Hanuman with wooden carvings at some places			
7.10	Compound / Fence / Gate	Plastered brick masonry compound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Open spaces with little shrubs			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No leakage or dampness observed)			
9.3	Floor	Good (Recently finished in Marble)			
9.4	Stairs	Not applicable			
9.5	Openings	Good (Well maintained)			
9.6	Roofing	Good (No leakage observed. Mangalore tiles in good condition)			
9.7	Articulation & Finishes	Good (Recently painted)			
9.8	Services	Good			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	One small room was added to Garbagriha subsequently.			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### 230, Maruti Mandir



View of Maruti Mandir from Sion road.



Detail of entrance to temple showing wooden columns supporting sloping roof along with wooden railing.



Internal view of temple showing wooden beam resting on column supported by decorative bracket.Door is made up of old mosaic tiles.



Detail of wooden railing and wooden column resting on stone pad.

#### **Seth Ranchoddas Varjivandas Precinct**

The precinct is located on hilly area near Sion station; earlier this was the boundary of the island city. Sion fort is located on east side of the hill. This hill is historically important being as old as the Sion Fort which is an ASI listed monument.

The precinct can be entered from east and south side of the hill. The Sanatorium located at top of the wooded hill has a horizontal character. The servant quarters are located at the bottom of hill. It accommodates an old structure called Bapu Bawa's Samadhi. Bapu Bawa was the Guru of Iccharam Mancharam, a dealer in gold lace and embroidery from whom Seth Ranchoddas bought this property from himin the mid 19<sup>th</sup> century. Seth Ranchoddas Varjivandas bungalow is located on the east side facing the old Sion Lake.

'Postachi chawl' (resided by the postal stff), built a century ago, is on the south side of the precinct facing Sion station road. There is an old well in the precinct used for watering the gardening. In the early 20<sup>th</sup> century there was a big garden in this precinct maintain by Seth Ranchoddas.

There is a bastion on the top of the hill which was connected by a tunnel from the bottom of the hill.

#### Buildings in the Precincts:

- 1. Seth Ranchoddas Varjivandas Sanotorium
- 2. Bapu Bawa's Samadhi
- 3. Old gate and a plaque in wood
- 4. Seth Ranchoddas Varjivandas bungalow
- 5. Servant's quarters
- 6. Postachi Chawl
- 7. Old well
- 8. Tunel
- 9. Bassion



**Card No.:** F/n-45

Ward (Part): F north-I

CS No.: Not applicable

Plot Area: Not applicable

**B U Area:** Not applicable

Date: February, 2005

Record by: Keshav S, Gauri J


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Seth Ranchoddas

Varjivandas Precinct



1.0	Denomination					
1.1	Name of Premises	Seth Ranchoddas Va	arjivandas Precind	ct		
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 19 <sup>th</sup> century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Sion Station Road (M	lahim creek conn	ector)		
2.2	Subsidiary	N. S. Mankikar Marg	(Duncan causew	ay)		
3.0	Ownership Pattern					
3.1	Present	Trust, Tenanted				
3.2	Past	Trust, Tenanted				
3.3	Status	Trust, Tenanted				
4.0	Use					
4.1	Present	Residential, Health c	are, Commercial			
4.2	Past	Residential				
4.3	Usage	Regular residential, health care and commercial use				
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	The precinct is locate was the boundary of of the hill. This hill is Fort which is an ASI	the island city. Sinhistorically import	on fort i	s located on eas	t side
5.2	Architectural Description	Buildings belong to of style and scale. General and have a strong verthe facade. The build	erally the building ernacular style with	s of the h mode	precinct are low rate ornamentati	-rise
5.3	Intrinsic	This is a Trust owned island.	d premises located	d on the	e north end of Mu	ımbai
5.4	Value Classification	A(arc), G(grp)		Recom	nmended Grade	II B
6.0	Topography	•				
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Not applicable		_		

7.6	Roofing	Not applicable			
7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Not applicable			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Buildings have lots of open space in between planted with shrubs and trees. One bastion is located on top of hill, it has secret root which starts at bottom of hill.			
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Not applicable			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Not applicable Maintenance level Not applicable			
10.0	Transformation				
10.1	Form	Not applicable			
10.2	Structure	Not applicable			
10.3	Articulation & Finishes	Not applicable			
11.0	DP Remarks / Perceived Threats	Plots demarked proposed medical college Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

### **Seth Ranchhoddas Verjivandas Precinct**



View of Seth Ranchhodas Verjivandas Sanatorium from north end.



Rare View of Seth Ranchhodas Verjivandas Sanatorium from N. S. Mandkikar marg.



View of Seth Ranchhodas Verjivandas Sanatorium from south end.



Service block of Sanatorium.



View of staircase block showing main entrance of building.



Detail of decorative column capital supporting cantilever sloping roof.




View of south corner block with decorative balcony.



South façade of sanatorium.



Detail of wooden staircase.



Detail of ornamented grill on roof top.



Card No.: F/n-45a

Ward (Part): F north-I

**CS No.:** 19

Plot Area: 23882.30 sq.m.

**B U Area:** 2110 sq.m.

Date: May 7, 2005

Record by: Keshav S, Anup S


Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Seth Ranchoddas

Verjivandas Sanatorium



		verjivaridas Gariatoriairi					
1.0	Denomination						
1.1	Name of Premises	Seth Ranchoddas Verjivandas	Sanatorium				
1.2	Earlier Name	Not applicable					
1.3	Built in	1901 Extension [	Date (if any)	Not applicable			
2.0	Access						
2.1	Main	Sion Road					
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern	1					
3.1	Present	Trustees for Improvement of Cit	ty of Bombay	, Maniben Desai			
3.2	Past	Trustees for Improvement of Cit	Trustees for Improvement of City of Bombay, Maniben Desai				
3.3	Status	Trust	Trust				
4.0	Use	1					
4.1	Present	Residential	Residential				
4.2	Past	Residential	Residential				
4.3	Usage	Regular residential use	Regular residential use				
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade	Located on a hillock near Sion sattitude in the vicinity.	Station, the pl	lot enjoys highest			
5.2	Architectural Description	This large Kurla Basalt stone st due to its profile of the roof and roofs on the three staircase bloo on a series of brackets and dec ornamentation of pillasters on it	its built form. cks and on th orative eaves	The pyramidal sleecorners, supports board, the restra	oping rted iined		
5.3	Intrinsic	The sanatorium (for TB patients Varjivandas in memory of his Sconstruction cost was Rs. 1,41,	on Runchoda		3. The		
5.4	Value Classification	A(arc), B(uu), C(seh), I(sce)	Recor	mmended Grade	II B		
6.0	Topography	·					
6.1	Floors	G + 1					
7.0	Construction						
7.1	Plinth	Grey Kurla stone dressed plinth					
7.2	Walls	Grey Kurla stone coursed maso	nry walls				
7.3	Floor	Wooden flooring with wooden jo	oists and batte	ens			
7.4	Stairs	Wooden staircase with simple v	vooden tread:	S			
7.5	Openings	Rectangular wooden louvered v					

7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses			
7.7	Articulation	Rectangular pilasters having ornamental capitals. Building has 3 prominent staircase blocks with service corridor at rear of building. The prominent staircase blocks with a pyramidal roof. Rectangular pilasters with ornamental capitals, floor band above first floor, segmental arched windows.			
7.8	Finishes	Sand faced plaster			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Grey Kurla stone compound wall, 1' high with CI decorative railing			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large unpaved open space with a number of trees on hillock			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units on ground floor			
9.0	Condition				
9.1	Plinth	Fair (Crack observed at many places)			
9.2	Walls	Fair (Dampness and cracks observed on western walls)			
9.3	Floor	Fair (Sagging and deflection observed at some places)			
9.4	Stairs	Fair (Wooden members need maintenance)			
9.5	Openings	Fair (Many windows broken, Wooden members need maintenance)			
9.6	Roofing	Fair (Leakage observed at many places, Mangalore tiles need repairs)			
9.7	Articulation & Finishes	Poor (plastered chipped off, structural attacked by Wooden frames and glazed shutters)			
9.8	Services	Poor (Pipes need repairs)			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair Maintenance level Fair			
10.0	Transformation				
10.1	Form	Wooden louvered windows replaced by rectangular glazed windows at some places.			
10.2	Structure	Wooden members replaced by I sections at some places.			
10.3	Articulation & Finishes	Replastered and painted internally and externally.			
11.0	DP Remarks / Perceived Threats	Plot reserved for college in proposed Development Plan (D.P.)			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.			

### Seth Ranchoddas Verjivandas Sanatorium



Plaque stating construction date and cost.



Low height compound wall with ornamented cast iron railing.



Old cast iron railing made by Shorabji Shapurji Company.



View of Bapu Bawa samadh next to sanatorium.



Bungalow of Seth Ranchhoddas Verjivandas.



Entrance gate of Seth Ranchhoddas Verjivandos Prescient from N.S. Mandkikar road.



Rare side elevation of Seth Ranchhoddas Verjivandos Sanatorium from N. S. Mandkikar road.



Front façade of Postachi Chawl from Sion Station road.



Arched entrance to Seth Ranchhoddas Verjivandos Precient.



Card No.: F/n-46

Ward (Part): F north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Sion tank premises



1.0	Denomination	·				
1.1	Name of Premises	Sion Tank Premises				
1.2	Earlier Name	Parvati Shankar Kund				
1.3	Built in	Mid 19 <sup>th</sup> century Extension Date (if any)	1892			
2.0	Access					
2.1	Main	N. S. Mankikar marg (Duncan Causeway Roa	nd)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Not available				
4.0	Use					
4.1	Present	Religious / public				
4.2	Past	Religious / public				
4.3	Usage	Regular religious and public use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on N. S. Mankikar marg (Duncan Cathe Sion hill.	useway Road) ne	ar		
5.2	Architectural Description	An open water tank with steps around it tank. has a large semi circular arch in basalt stone used as route for horses to drink water as well	which was earlie	r		
5.3	Intrinsic	It serves as a holy water body used for religio Ganesh idol emersions.	us activities like			
5.4	Value Classification	A(his), A(cul), B(per), B(uu), I(sce), J Recom	nmended Grade	II A		
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Not applicable				
7.6	Roofing	Not applicable				
7.7	Articulation	Not applicable				

7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Low height peripheral random rubble wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Boundary levels (ghats) paved with Basalt stone. Lots of trees around tank. Barb wire fencing to road side.			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, excellent natural ventilation			
8.3	Electricity	Not applicable			
8.4	Water Supply	Not applicable			
8.5	Drainage (Plumbing and Sanitation)	Not applicable			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Good			
9.9	Outbuildings	Ghats are in dilapidated conductions, water body needs cleaning			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot demarcated for part of Central Labor Institute hostel block on proposed Development Plan (D.P).			
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai			

### **Sion Tank Premises**



View of Sion tank and steps leading to water.



View of Sion Tank from N. S. Mandkikar Marg.



View of semicircular old arch from south side of Sion Tank.



View of Sion Tank from east side viewing sion hill.



Card No.: F/n-47

Ward (Part): F north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Keshav S, Gauri J

Review by: Arun Kale

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\ Ref.: Under ground way (tunnel)



1.0	Denomination					
1.1	Name of Premises	Under Ground Wa	y (tunnel)			
1.2	Earlier Name	Not applicable				
1.3	Built in	Not available	Extension Date (if	any)	Not available	
2.0	Access			·		
2.1	Main	N. S. Mankikar ma	irg (Duncan Causew	ay Road)		
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Not available				
4.0	Use	Use				
4.1	Present	Not in use				
4.2	Past	Military purpose				
4.3	Usage	Military purpose				
5.0	Significance & Value Classification	on				
5.1	Townscape (Natural / Manmade)	Located on west s road) beside the h	ide of N. S. Mankika illock.	ar marg (D	uncan Causev	way
5.2	Architectural Description	hillock on west sid hill top. It has man	square shaped open e of the road. Its oth hole in the middle of bastion or watch to	er end is of the hill.	at the bastion	on the
5.3	Intrinsic	It is served as an e	escape route from th	ne bastion	or the watch t	ower
5.4	Value Classification	A(his), B(uu)		Recomm	ended Grade	II A
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Bottom rectangula	r opening near road	is in Basa	alt stone	
7.6	Roofing	Not applicable				

7.7	Articulation	Not applicable				
7.8	Finishes	Not applicable				
7.9	Interiors (Movable & Immovable)	Not applicable				
7.10	Compound / Fence / Gate	Not applicable				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable				
8.0	Services & Utilities					
8.1	Lighting	Not applicable				
8.2	Ventilation	Not applicable	Not applicable			
8.3	Electricity	Not applicable				
8.4	Water Supply	Not applicable				
8.5	Drainage (Plumbing and Sanitation)	Not applicable	Not applicable			
8.6	Fire precaution	Not applicable				
8.7	Other (HVAC / BMS / Security Systems)	Not applicable				
9.0	Condition					
9.1	Plinth	Not applicable				
9.2	Walls	Not applicable				
9.3	Floor	Not applicable				
9.4	Stairs	Not applicable				
9.5	Openings	Poor (man hole block	ed by constructing hut	s on it)		
9.6	Roofing	Not applicable				
9.7	Articulation & Finishes	Not applicable				
9.8	Services	Not applicable				
9.9	Outbuildings	Not applicable				
9.10	Overall condition	Poor	Maintenance level	Poor		
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	None.				
12.0	Additional Notes / References / Documents Available	Documents: C.S. She	ets, D.P. Sheets, Eich	er City Maps-Mumbai		

#### Kohinoor Mills 1 and 2

The mill is located on a prime location in the midst of a busy commercial and residential district at Dadar-East on Dr. Babasaheb Ambedkar Road which is one of the major north-south arterial roads in Mumbai. The mill follows the typology of industrial architecture of the Textile mills in the late 19<sup>th</sup> century.

The structures in the mill follow the vernacular vocabulary. The mill produces finished cloth out of the cotton from bale. The entire process involves various activities, step by step working and categorization. The mill is divided in various departments. Preparatory department consists of mixing, carding, blow room, combing sub departments. These are located on ground floor close to each other. Production of thread for weaving takes place in the Ring spinning department. The winding department consisting mainly of lady employees involved beaming of thread from small reels along with categorization and sizing. The beams with wrapped thread are then sent to where the cloth was woven on looms. The structure consists of a large hall with north light roof trusses and a looms lined up in series. The cloth produced in weaving department is then taken to the processing department where the cloth is made ready for dispatch after dyeing, printing and finishing.



Card No.: F/n-48

Ward (Part): F north-VI

**CS No.:** 12

Plot Area: 87932.00 sq m

B U Area: Not available

Date: January, 2005

Record by: Swapnil B, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above


**Photo** T-III-Fn:\Ward F north\ **Ref.:** Kohinoor Mills 1 and 2

compound



		compound				
1.0	Denomination					
1.1	Name of Premises	Kohinoor Mills 1 a	and 2 compound			
1.2	Earlier Name	Not applicable				
1.3	Built in	1896	Extension Date	(if any)	Not applicable	
2.0	Access					
2.1	Main	Mumbai Marathi (	Grantha Sangrahal	lay Marg		
2.2	Subsidiary	Dr. Babasaheb A	mbedkar Road			
3.0	Ownership Pattern					
3.1	Present	National Textile C	Corporation (N.T.C	.)		
3.2	Past	Killick Nixon & Co	).			
3.3	Status	Government				
4.0	Use					
4.1	Present	Vacant, not in use	Э			
4.2	Past	Textile mill, indus	Textile mill, industrial			
4.3	Usage	Vacant, not in use	Vacant, not in use			
5.0	Significance & Value Classificat	tion				
5.1	Townscape (Natural / Manmade)		cated on a prime ledkar Road, one of			
5.2	Architectural Description	masonry structure ornamentation or	ernacular style ard es. The structures a façade and repres lly the textile mills	do not ha sent the s	ve major tyle of industrial	ry.
5.3	Intrinsic		is mill land in hear sidential and comm ns of capital.			
5.4	Value Classification	A(arc), B(des), B(C(seh), H(tec), G		Recon	nmended Grade	II B
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				

7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly wooded unpaved open space in between the structures		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Automatic fire sprinkler system for some structures		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Poor (Tree growth on structures)		
9.8	Services	Poor (Completely shut down)		
9.9	Outbuildings	Poor		
9.10	Overall condition	Poor	Maintenance level	Poor
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Tree growth on façade of almost all structures.		
11.0	DP Remarks / Perceived Threats	Plot reserved for retention activity on proposed Development Plan (D.P.)		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Charles Correa committee report on N.T.C. mills of Mumbai		



Deatil of Ring Spinning



Detail of the ornamental features on façade



Side view - Carding and Spinning



Window detail of Carding unit



Ring Spinning – part elevation



Part of the demolished floor - Carding and Spinning unit



Card No.: F/n-48a

Ward (Part): F north-VI

**CS No.:** 12

Plot Area: 87932.00 sq m

B U Area: Not available

Date: January, 2005

Record by: Swapnil B, Gauri J


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-III-Fn:\Ward F north\
Ref.: Carding, Structure 8B,

Carding, Structure 8B, Kohinoor Mills No. 1 & 2



4.0	Denomination					
1.0	Denomination					
1.1	Name of Premises	Carding, Structure 8B, Kohinoor Mills No. 1 & 2				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1896	Extension Date (i	f any)	Not applicable	
2.0	Access	_				
2.1	Main	Mumbai Marathi Gı	rantha Sangrahalay	y Marg		
2.2	Subsidiary	Dr.Babasaheb Aml	Dr.Babasaheb Ambedkar Road			
3.0	Ownership Pattern	Ownership Pattern				
3.1	Present	National Textile Co	orporation (N.T.C.)			
3.2	Past	Killick Nixon & Co.				
3.3	Status	Government	Government			
4.0	Use					
4.1	Present	Carding, Industrial	Carding, Industrial			
4.2	Past	Carding, Industrial	Carding, Industrial			
4.3	Usage	Partly used for Industrial purpose				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	The mill land is located on a prime location at Dadar-East on Dr. Babasaheb Ambedkar Road, one of the major north-south arterial roads in Mumbai.				
5.2	Architectural Description	Elongated structure having features like plain floor band at 2 <sup>nd</sup> floor level, semicircular arched windows spanned from 1 <sup>st</sup> floor to 3 <sup>rd</sup> floor and have plain keystones. Plain pilasters on façade adorned by decorative pediment at the terrace level. Below the pediment are plain dentils on façade.				
5.3	Intrinsic	This sub department comes under the Preparatory Department. It is the most basic department in the mill where all the activities like mixing of cotton, blowing, carding and rowing take place. All these activities take place on ground floor and are located next to each other.				
5.4	Value Classification	A(arc), B(uu), C(se	h), G(grp), H(tec)	Recom	nmended Grade	II B
6.0	Topography			•		•
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	0.9m. high masonry plinth				
7.2	Walls	0.6m. thick brick load bearing walls				
7.3		M.S. flooring with jack arches				

7.4	Stairs	Main stone staircase main, internal staircase MS dog-legged		
7.5	Openings	Segmental arched windows with wooden frames and glazed shutters		
7.6	Roofing	A.C. sheet roofing with wooden trusses		
7.7	Articulation	Semicircular arched windows spanned from 1 <sup>st</sup> floor to 3 <sup>rd</sup> floor with plain keystones. Plain pilasters on façade, decorative pediment at the terrace level.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Adequate front and side open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Fair (No settlement and cracks observed at some places)		
9.2	Walls	Fair (Internal walls broken, tree growing on façade)		
9.3	Floor	Fair (Sagging observed at some places, Corrosion in M.S. members observed)		
9.4	Stairs	Fair (Needs maintenance of corroded M.S. members observed)		
9.5	Openings	Poor (Broken windows pains replaced by teen sheets)		
9.6	Roofing	Poor (Leakage observed at some places, A.C. sheets need repairs)		
9.7	Articulation & Finishes	Poor (Plaster chipped repairs off at many places)		
9.8	Services	Poor (Shut down, not in use)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Poor Maintenance level Poor		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot reserved for retention activity on proposed Development Plan (D.P.)		
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		



Card No.: F/n-48b

Ward (Part): F north VI

**CS No.:** 12

Plot Area: 87932.00 sq m

B U Area: Not available

Date: January 05

Record by: Swapnil B, Gauri J


Review by: Neera Adarkar

Internal: As above

External: As above

Ref.:

Photo T-III-Fn:\Ward F north\ Spinning & Ringing, Structure 8B, Kohinoor Mills No. 1 & 2



1.0	Denomination					
1.1	Name of Premises	Spinning & Ringing, Structure 8B, Kohinoor Mills No. 1 & 2				
1.2	Earlier Name	Not applicable				
1.3	Built in	1896 Extension Date (if any) Not applicable				
2.0	Access					
2.1	Main	Mumbai Marathi Granth Sangrahalay Marg				
2.2	Subsidiary	Dr.Babasaheb Ambedkar Road				
3.0	Ownership Pattern	Ownership Pattern				
3.1	Present	Vacant, not in use				
3.2	Past	Spinning and Ringing, Industrial				
3.3	Status	Vacant, not in use				
4.0	Use					
4.1	Present	National Textile Corporation (N.T.C.)				
4.2	Past	Killick Nixon				
4.3	Usage	Government Owned				
5.0	Significance & Value Classification	on .				
5.1	Townscape (Natural / Manmade)	The mill land is located on a prime location at Dadar-East on Dr. Babasaheb Ambedkar Road, one of the major north-south arterial roads in Mumbai.				
5.2	Architectural Description	Elongated, Massive typical mill structure having features like cornice band at first floor level and floor bands at the others. Ground floor has plain pilasters with semicircular pedimented capital. Top floor windows have semicircular arch with plain keystone. Parapet wall has plain triangular pediment.				
5.3	Intrinsic	This sub department comes under Ring Spinning department, largest department in the mill. The activities consist of Spinning of Cotton in bobbins, sending the reels for winding. The department works as a pre-function department and requires large amount of machinery. The chimney and boiler room is attached to this department.				
5.4	Value Classification	A(arc), B(uu), C(seh), G(grp), H(tec) Recommended Grade II B				
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	Black Basalt stone coursed masonry				
7.2	Walls	Load bearing brick walls				

7.3	Floor	Brick jack arch flooring		
7.4	Stairs	M.S. open well staircase with plain M.S. railing		
7.5	Openings	Segmental arched wooden frame glazed shutter windows		
7.6	Roofing	A.C. sheet roofing with M.S. truss		
7.7	Articulation	Plain pilasters with semicircular pedimented capital. Semicircular arch with plain keystone. Parapet wall has plain triangular pediment on parapet wall		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Adequate front and side open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (Settlement and cracks observed)		
9.2	Walls	Fair (Internal walls broken, tree growing on façade)		
9.3	Floor	Fair (Sagging observed at some places, Corosion in M.S. members observed)		
9.4	Stairs	Fair (Needs maintenance of corroded M.S. members observed)		
9.5	Openings	Poor (Broken windows pains replaced by teen sheets)		
9.6	Roofing	Poor (Leakage observed at some places, A.C. sheets need repairs)		
9.7	Articulation & Finishes	Poor (Plaster chipped repairs off at many places)		
9.8	Services	Poor (Shut down, not in use)		
9.9	Outbuildings	Poor		
9.10	Overall condition	Poor Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot reserved for retention activity on proposed Development Plan (D.P.)		
12.0	Additional Notes / References / Documents Available	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai.		