Intational Ga	allery of Modern Art (Sir Cowasji Jeha	angir Public Hall) 15
		Common Ref No: 156
		Card No: 214
		Ward (Part): A (Part III)
		Ward (Part): A (Part III) CS No: Indeterminable
		Plot Area: Indeterminable
	राष्ट्रीयडायुतिक कला मध्रतलय मुंबई सर कावसजी जहाँयोर पज्लिक हॉल	
	State Man on Annu and	B U Area: -
A DECEMBER		Date: 10/11/2004
		Recorded by: Zankhana Prajapati
		Reviewed by:
	NG	Int: Arun Wadhwa, Zankhana Prajapati
		Ext: Arun Wadhwa, Zankhana Prajapati
		Photo Ref.: 156_Cowasji Jehangir Hall
		WITT BE STATE
		Location Plan
1.0		Denomination
1.1	Name of Premises	National Gallery of Modern Art
1.2	Earlier Name	Sir Cowasji Jehangir Public Hall
1.2	Built in:	Foundation stone laid in 1911, completion in 1917 Extension Date: -
		opened in 1920 during World War I
<u> </u>		
2.0		Access
2.1	Main	Junction of Mahatma Gandhi Road and Madam Cama Road
2.2	Subsidiary	-
3.0		Ownership pattern
3.1	Present	Government of Maharashtra
3.2	Past	Government of Bombay
3.3	Status	Owner
4.0		Use
4.1	Present	Art Gallery and Lecture Hall
4.2	Past	Public hall for Theatre, Performance, Lecture, etc.
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Prominent corner building located at the S. P. Mukherji Chowk, with its wings on the
		Madam Cama Road, and Mahatma Gandhi Road The building is placed along a row of buildings with uniform scale on Madam Cama Road
		and is surrounded with buildings of different styles and periods including the YWCA, St.
		and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east.
		and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of
		and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road.
		and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of
		and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The portion below the topmost gallery is designed as a lecture hall with an inbuilt projector
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The portion below the topmost gallery is designed as a lecture hall with an inbuilt projector room.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The portion below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The portion below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a pair of ionic columns supporting entablature.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a pair of ionic columns supporting entablature. Semi-circular arched openings with ornate keystone all around the ground floor verandah.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a pair of ionic columns supporting entablature.
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a pair of ionic columns supporting entablature. Semi-circular arched openings with ornate keystone all around the ground floor verandah. Double storied colonnades punctuate the upper portion, with horizontal lintel stone
5.2	Architectural Description	 and is surrounded with buildings of different styles and periods including the YWCA, St. Annes School on the south and Wellington fountain to the east. The curvilinear building form is a site response, with its main entrance from south side of Madam Cama Road. It forms the vertex to the two wings of the Institute of Science. The curved building with its dominating entrance dome forms an important landmark in the urban scape. Planning The building is circular in plan with an extended porch at the intersection facing the Wellington fountain. The circular built space has a continuous verandah around with staircases on both sides beyond which Institute of Science building continues. The present renovation to turn it into a museum has semi circular galleries on split-levels with a central void. The space below the topmost gallery is designed as a lecture hall with an inbuilt projector room. The space below the shallow dome forms a large circular gallery. Central air conditioning unit, store and offices are placed below the gallery on the rear side Features The front has a large magnificent opening framed by two large ornate stone piers with a pair of ionic columns supporting entablature. Semi-circular arched openings with ornate keystone all around the ground floor verandah. Double storied colonnades punctuate the upper portion, with horizontal lintel stone openings and carved balusters and projecting comice bands.

auonal G	allery of Modern Art (Sir Cowasji Jehangir F		1
		punctuated with large openings and a projecting balcony at the first f	loor supported on
		highly ornate brackets.	
		Style	
		The building displays features of the Renaissance Revival style of an	chitecture
5.3	Intrinsic	This was the first cultural hall dedicated to the people of Bombay.	
5.4	Value Classification		Recommended
			jrade:
6.0		Topography	
6.1	Floors	G+4 with split level galleries	
7.0		Construction	
7.1	Plinth	The plinth is very low, constructed in buff basalt in regular courses.	
7.2	Walls	The walls are stone load bearing masonry, including arches, piers, e The verandah walls are in shallow dressed courses.	tc.
7.3	Floor		arabaa
1.5	FIOOI	The original flooring in verandahs and lobbies is supported on stone The renovated art gallery has ribbed floors supported on additional of	
		walls.	
7.4	Stairs	Two Staircases. Both the staircases are open well, constructed in sta (cantilevered) from the side load bearing walls with a wooden handra	
		iron railing.	
7.5	Openings	Ground floor verandah has semicircular arched openings, upper leve	
		lintels. The curvilinear verandah wall has openings with teakwood do	
		The projecting staircase block has openable glazed paneled window	
		Small circular fixed glass panels at the upper part of the shallow dom	
7.6	Roofing	Circular shallow dome in concrete, central portion raised to accomm	odate openings for
		light.	
		The surrounding verandah and staircase slab has a flat roof with terr	ace.
7.7	Articulation	Ornate key stone detail of the semicircular arched opening.	
		Cantilevered projecting balcony supported on ornate stone brackets	at the staircase enti
		The overlapping stone courses spanning the horizontal lintel opening	
		construction technique.	, ,
7.8	Finishes	External building facade and verandahs are dressed in buff basalt, ir	ternally the surface
		are plastered and finished in Plaster of Paris. Gypsum board panels	
		galleries.	
		Verandah and lobby areas have marble flooring whereas the renova	ted galleries have
		wooden flooring.	
7.9	Interiors (Movable & Immovable)	Movable	
	· · · · · · · · · · · · · · · · · · ·	-	
		Immovable	
		Marble statue of Sir Cowasji Jehangir at the entrance lobby.	
7.10	Compound/ Fence/ Gate	Originally very low stone verticals with iron chain connectors served	as compound fence
7.10	Compound, I cheer Gate	Presently a stone wall with high iron railing is built in between the ori	
		High iron gates with decorative motif atop on both sides of the porch	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Underground water tank and an electrical transformer in the open sp	
1.11	Landscape	entry.	
	Lanuscape	Plant and shrub growth around the entrance porch.	
		riant and shirab growin around the chirance porch.	
0 0		Services & Utilities	
8.0	Linkting		
8.1	Lighting	Artificial lighting throughout the building as it serves as an enclosed	gallery space.
8.2	Ventilation	Large central air conditioning system for the gallery spaces.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Smoke detector and fire alarm system with fire fighting equipment ha	
8.7	Other (HVAC/BMS/Security Systems)	Audio-visual camera surveillance system, private and state security Large central air conditioning plant	guards
0.0		Condition	
	Dliath	Fair - organic growth and weathering has deteriorated the stone courses.	
9.0 9.1	Plinth		
	Plinth Walls	Fair - rainwater seepage has led to deterioration of stone masonry in	
9.1 9.2	Walls	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition.	
9.1 9.2 9.3	Walls Floor	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition. Fair - original upper floor dismantled and redesigned	
9.1 9.2 9.3 9.4	Walls Floor Stairs	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition. Fair - original upper floor dismantled and redesigned Fair	
9.1 9.2 9.3	Walls Floor	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition. Fair - original upper floor dismantled and redesigned Fair Fair	
9.1 9.2 9.3 9.4	Walls Floor Stairs	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition. Fair - original upper floor dismantled and redesigned Fair Fair Fair	the staircase block
9.1 9.2 9.3 9.4 9.5	Walls Floor Stairs Openings	Fair - rainwater seepage has led to deterioration of stone masonry in The interior is modified with gypsum board panel for exhibition. Fair - original upper floor dismantled and redesigned Fair Fair	the staircase block

lational Gallery of Modern Art (Sir Cowasji Jehangir Public Hall) 15				
9.9	Out Buildings	-		
9.10	Overall Conditions	Fair Maintenance level Fair		
10.0		Transformation		
	Form	-		
	Structure	The whole internal space has been transformed by constructing split level galleries supported on additional columns and shear walls.		
	Articulation & Finishes			
11.0		DP Remarks/ Perceived Threats		
		College and Public Hall, building forms part of C1 zone		
12.0		Additional Notes/ References/ Documents available		
		 Additional Notes: The Hall is nearly a hundred feet in diameter. With a seating capacity of 1200, the origina Hall was the venue for art shows, lectures and musical performances for several years. This interiors were entirely redesigned in 1996 by Delhi architect, Romi Khosla, to accommodate the Bombay branch of the National Gallery of Modern Art. <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. 		



Side façade with arched and rectangular openings, projecting balconies, lintel and sill level bands, scroll bracket keystone



Curvilinear façade with arched and double height rectangular openings, frieze bands, balustrades



Rectangular verandah/ passage openings with frieze bands in geometric pattern, bands, floral motifs, scroll bracket keystone in floral pattern




Entrance porch with double height lonic columns, bands, arched openings

National Gallery of Modern Art (Sir Cowasji Jehangir Public Hall)



Detail of column with frieze bands in geometric pattern



Column Capitals with floral pattern Corinthian capitals



Internal circular staircase along the atrium



External rectangular door opening with glazed paneled shutter, vertical and horizontal bands



Semi Circular arches at ground floor with buff stone rusticated cladding



Free standing plaque explaining the details of the Sir Cowasjee Jehangir.





Verandah on ground floor level with arched openings






Detail of the scroll bracket keystone of the arched opening

Municipal	Corporation of Greater Mumbai Headqua	rters (Bombay Municipal Corporation Building)		157
	*	Common Ref No: 157	· 11/0/	
		Card No: 215	X	PR DADABHA
		Ward (Part): A (Part I)	- Alax	A A A A A A A A A A A A A A A A A A A
		CS No: 1452, 1449 (Fort division)		AB:
		Plot Area: 9206.23 sg m.	Kr.	le la la
		B U Area: -	M. M	MAHAPALIKA SABHAGRIMA MARG
	WW G HT BAC		and the	
1	TOTAL N. I.C. TANK	Date: 15/12/2004		ANN ROUTE
11	A COLORED	Recorded by: Sonal Modak	1	
		Reviewed by:	Mahapatin	
		Int: Sonal Modak	ALL ALL	
1 Part	Main Building	Ext: Sonal Modak	$(\Box) $	MARG -
		Photo Ref: 157_BMC	• • •	
	Annex Building			Location Plan
1.0		Denomination		
1.1	Name of Premises	Municipal Corporation of Greater Mumbai Hea	adquarters	
1.2	Earlier Name	Bombay Municipal Corporation Building		
1.3	Built in:	Foundation stone laid on December 9, 1884	Extension	1950's- Addition of an
		Commenced in 1889, Completion in 1893	Date	Annex wing on the north side
2.0		Access		
2.0	Main	Corner of Mahapalika Marg and Dr. Dadabha	i Nowroji Road	- nedestrian
		Mahapalika Sabhagriha Marg – vehicular and		- pedestriari
2.2	Subsidiary	Manapalika Sabhagrina Marg – Venicular and	pedestrian	
2.0		Ownership pottorn		
3.0		Ownership pattern		
3.1	Present	Municipal Corporation of Greater Mumbai		
3.2	Past	Brihan Mumbai Municipal Corporation		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Commercial – Municipal corporation offices		
4.2	Past	Commercial - Municipal corporation offices		
4.3	Usage	Daily		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	The MCGM building stands prominently on a and Dr. Dadabhai Nowroji Road among impu- like the Chhatrapati Shivaji Terminus on the n The building is accessed from the corner thro The building form is a response to the site con The building along with the Chhatrapati Shiv of style and scale and dominate the important Planning	ortant buildings orth, Capitol Cir ugh an extended ntext. aji Terminus, co	of different architectural styles nema on the south. d porch
	Architectural Description	The building consists of two wings in 'V' sha corner entrance porch, enclosing a central op The outer dome, houses the central main st first floor, connecting the arcaded corridors of the main entrance hall. A record room is situated above the entrance the entrance hall. Features The two wings along the two major roads hav Atop the central gable is a sculpture represent motto adopted the Municipal Corporation. The front side façade consists of an exter balustrade. The front side has a series of poi decorative capital. The porch has corner pil arches have decorative tympanum. The porch Multi-foiled window openings, pointed arches in wood along corridors facing the internal stone at various levels. One end of Corporation hall consists of full he Style	en space. aircase, leading unning around e above an inner e number of gab titing <i>Urbs Prima</i> nded porch with inted arches sup asters with ster n consists of dec s, minarets, bulb courtyard garde	from the entrance hall to the the central open atrium above dome, visible only from inside of fronts in Indis – the first city of India h a terrace above with stone oported on round columns with oped bands. The side pointed corative friezes. bous domes, sculpted jali-work en, bands of different colored

viunicipai	Corporation of Greater Mumbal Headquar	ters (Bombay Municipal Corporation Building)
		The building derives influence from Indo - Saracenic style of architecture
5.3	Intrinsic	-
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), D(bio), F, I(sce) Recommended grade I
6.0		Topography
6.1	Floors	G + 3 Main building, G + 6 Annex Building
7.0		Construction
7.1	Plinth	Medium height plinth in grey ashlar masonry in a stepped form.
7.2	Walls	Composite walls
7.3	Floor	RCC slabs and beam on RCC columns in most of the areas and wooden floors in corrido
7.4	Stairs	and passages Central main wide staircase constructed in stone leading from ground floor entrance atriu to first floor corridors around the atrium.
		Two elliptical staircases housed in smaller towers on either sides of the main south-easter façade topped by smaller onion shaped domes. Timber straight flight staircase from ground floor to first floor near gate no. 3.
7.5	Openings	Two circular cast iron staircases connecting all floors. All elevations punctuated with pointed arched windows with trefoil double arches w
7.0	Desfer	circular ventilators within the main arch placed in-between the low height step buttresses
7.6	Roofing	The main central open core capped by a bulbous dome. Dome is resting on <i>colonnettes</i> and arches on its four interior walls from which <i>fan vaults</i> spring to support the circle on low inner dome that sits upon this base.
7.7	Articulation	Multi-foiled window openings, pointed arches, minarets, bulbous domes, sculpted jali-wo in wood along corridors with wooden rafters and planks as flooring material.
7.8	Finishes	Walls have exposed buff regular dressed ashlar masonary externally. Internally plaster and painted. Marble treads on central staircase.
7.9	Interiors (Movable & Immovable)	Movable For the Corporation Hall specially designed furniture was made in black wood and teak. Immovable
7.10	Compound/ Fence/ Gate	-
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	A fountain at the center of interior court. At the entrance stands a bronze statue of Sir Phirozeshah Mehta – ' the Lion of Bombay '
	•	
8.0		Services & Utilities
8.1	Lighting	Adequate daylight in areas along external walls and supplemented by artificial lighting. Inadequate daylight through long window openings in some areas so supplemented artificial lighting. Main staircase atrium is poor lit and no provision of adequate artificial lighting made.
8.2	Ventilation	Natural ventilation is adequate. Dependent on supplementary ventilation devices like fa and AC's.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	When planned the building had a capacity to store 40,000 gallons of water in tanks wit the roof, to not only fight fires but also run the hydraulic lifts.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units installed in some areas.
9.0		Condition
	Dlinth	
9.1	Plinth	Fair – No evident damages observed. Planter boxes in the central courtyard cover plinth.
9.2 9.3	Walls Floor	Fair - No evident damages observed. Ceramic tile dados provided on some of the walls.
9.3		Poor – The wooden floor planks are broken in many areas of passages.
9.4	Stairs	Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all.
9.4		Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards.
9.4 9.5	Stairs	Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all.
9.4 9.5	Stairs Openings	 Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Bands broken in a few parts to house rainwater pipes.
9.4 9.5 9.6	Stairs Openings Roofing	 Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Bands broken in a few parts to house rainwater pipes
9.4 9.5 9.6 9.7	Stairs Openings Roofing Articulation & Finishes	 Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles.
9.4 9.5 9.6 9.7 9.8	Stairs Openings Roofing Articulation & Finishes Services	 Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Bands broken in a few parts to house rainwater pipes. Fair - No evident damages observed.
9.4 9.5 9.6 9.7 9.8 9.9	Stairs Openings Roofing Articulation & Finishes Services Out Buildings	 Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Fair - No evident damages observed. Fair - No evident damages observed.
9.4 9.5 9.6 9.7 9.8 9.9 9.9 9.10	Stairs Openings Roofing Articulation & Finishes Services Out Buildings	Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Fair – No evident damages observed. Fair – Alter – No evident damages observed. Fair – No evident damages observes observ
9.4 9.5 9.6 9.7 9.8 9.9 9.9 9.10	Stairs Openings Roofing Articulation & Finishes Services Out Buildings Overall Conditions	Fair – There is no structural damage to the main staircase. Secondary timber spiral staircases are in bad condition with loose, broken floorboards. Cleanliness not maintained at all. Fair – No evident damages observed except for some of the shutters being replaced. Poor – Wooden members have deteriorated, broken tiles. Fair – No major damage observed. Fair – No evident damages observed. Fair Maintenance level Poor

Iunicipal Corporation of Greater N	Iumbai Headquarters (Bombay Municipal Corporation Building) 15
	in some parts.
11.0	DP Remarks/ Perceived Threats
	Municipal Office, Building forms part of C1 zone.
12.0	Additional Notes/ References/ Documents available
12.0	
	Additional Notes: Soon after Chhatrapati Shivaji Terminus was completed in 1888 work began on new office for the Municipal Authority to celebrate its promotion to corporation status. The building is made 20 ft. taller than neighboring VT to ensure it was not overpowered b the adjacent structures. The extension wing of the Municipal Building added later on Mahapalika Marg is in harmon with the original building, at least in terms of materials, textures and scale. It was built in th 1950's or early 1960's. Both the buildings are interconnected by a passage at second floc level. Before the bay windows there used to stand a raised platform, to make speakers mor visible and audible.
	The tower rises to a height of 235 ft. <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct i Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. MARIAM DOSSAL (1996) Imperial designs and Indian Realities - The Planning of Bombay City - 1845-1875, Bombay : Oxford University Press.




Pointed arched opening with grey and buff stone voussoirs, rose window, carvings in tympanum



Buff stone clad building with arched openings on round columns, balustrade



Round column with floral pattern corinthian capital



Carvings in the balustrade



Internal double height space with overlooking balconies supported on highly ornamented brackets



Series of continuous pointed arches with stained glass ventilators, glazed wooden shutters, balustrade, dentil moulding cornice band



External pointed arch on round columns with decorative capitals, round, geometric and floral pattern in spandrel, frieze band



Internal entrance grand lobby with overlooking arched verandah openings surmounted with a dome



Internal dome with intricate carvings on the lower surface and ribbed vault



Arched opening with rose window, floral pattern in frieze band, highly intricate floral and animal carving in the spandrel, animal motif at the springing point.



Imposing tower with dome with a pinnacle, turrets, brackets, bands, balustrade



Rectangular openings with decorative sill and lintel level in geometric pattern

Municipal Corporation of Greater Mumbai Headquarters (Bombay Municipal Corporation Building)



Corner projecting porch with pointed arched openings, corner pilasters with animal statues at the parapet level, decorative motifs, balustrade.



Compound wall with pillars with decorative capitals and iron railing



Figurative Sculpture above the entrance porch



Side wing with steep double layered sloping Mangalore tile roof, with corner turrets, recessed brackets



157

Detail of the frieze with floral and geometric pattern



Rose window detail stone and glass panel with polychromatic stone voussoirs, in the background of carved jaliwork and buff stone facade



Marble fountain in the rear courtyard



Pointed arch with decorative intrados, motifs in the spandrel and stained glass ventilator, lintel level motifs



Intricately carved wooden paneled double shutter with exposed hardware



Wooden partition with carved paneling



Grand open well stone staircase with carved railing in floral pattern



Tracery work with central rose window with stain glass panel in the arched ventilator with grey and buff stone voussoirs



Internal Door glazed paneled shutters with internal half door shutters

157



Wide corridor with arched openings, ceiling with wooden rafters and beams, minton tile flooring.



Marble plaque explaining the details of the building construction



Arched opening with recessed arch bands on round columns with intricately carved corinthian capitals with floral and animal motifs

Municipal Corporation of Greater Mumbai Headquarters (Bombay Municipal Corporation Building)



Entrance porch with ribbed vaulted corridor



Internal staircase cast iron railing



Marble plaque with the foundation details



Animal sculpture at the staircase base on newel post



Recessed pointed arched window with stained glass ventilator panel, jail work and balustrade, round motifs in spandrel, dentil band at lintel level



Detail of the intricately carvings of floral and animal motifs, dentil moulding, floral pattern frieze bands in the extrados



Stained glass window



Window with round ventilator, double arched window opening with glazed paneled shutter, balustrade, arch bands.

Cama and A	Ibless Hospital for Women and Child	Iren		158
		Common Ref No: 158		
		Card No: 216		
		Ward (Part): A (Part II)	BALL CAN	1. 11 . P. M
	AND FOUND AND AND AND AND AND AND AND AND AND A	CS No: 1447 (Fort)	-////	
124		Plot Area: 22,680.78 sqm	1 - for the second	A Participation
		B U Area:		
Sugar States		1. Cama Hospital – 1985.00 sq m		Land 1. the
Constant.	Standard Barriston and Standard	2. Albless Hospital – 972.00 sq m	NA MA	a la
Sec. 14		3. Lady Doctors' Quarters – 318.00 sq m	NY NA	
		4. Old Nurses' and Stewards' Quarters -	NA BLA	12 ° Carlos
		432.00 sq m	C S ON	RELEVENT
11 1980		5. Servants' Quarters – 104.23 sq m	a friend	E A CALLANT - CE
		6. Mortuary – 86.00 sq m	Манарацика	N STRACT
		Date: 05/01/2005	ALI	S Stand
		Recorded by: Sonal Modak		N S S S S S
		Reviewed by:		ARG
		Int: Sonal Modak, Zankhana Prajapati	11/36 S N. 7.	1 1 Ber 11 11 11 11 11 11
		Ext: Sonal Modak, Zankhana Prajapati	LC	ocation Plan
		Photo Ref: 158_Cama and Albless Hospital.	-	
1.0		Denomination	1	
1.1	Name of Premises	Cama and Albless Hospital for Women and C	hildren	
1.2	Earlier Name	Cama and Albless Hospital for Women and C		
1.3	Built in:	1. Cama Hospital - 1886	Extension Date:	1954 – Administrative
		2. Albless Hospital -1890		Building was added on
		3. Lady Doctors' Quarters - 1890		south east of Cama
		4. Old Nurses' and Stewards' Quarters -1906		Hospital Building.
		5. Servants' Quarters -1906		
		6. Mortuary - 1910		
2.0	Math	Access		
2.1				
	Main	Mahapalika Marg – Vehicular and Pedestrian	hiaulan and Dadaat	
2.2	Subsidiary	Mahapalika Marg – Vehicular and Pedestrian Badruddin Tayabjee (Gymnasium) Road - Vel	hicular and Pedest	rian
2.2		Badruddin Tayabjee (Gymnasium) Road - Vel	hicular and Pedest	rian
2.2 3.0	Subsidiary	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern	hicular and Pedest	rian
2.2 3.0 3.1	Subsidiary Present	Badruddin Tayabjee (Gymnasium) Road - Vel	hicular and Pedest	rian
2.2 3.0	Subsidiary	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government	hicular and Pedest	rian
2.2 3.0 3.1 3.2	Subsidiary Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government	hicular and Pedest	rian
2.2 3.0 3.1 3.2 3.3 4.0	Subsidiary Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use		
2.2 3.0 3.1 3.2 3.3	Subsidiary Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo	d Bank, In Patien	
2.2 3.0 3.1 3.2 3.3 4.0 4.1	Subsidiary Present Past Status Present Present	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Co	d Bank, In Patien	
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2	Subsidiary Present Past Status Present Past Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital	d Bank, In Patien	
2.2 3.0 3.1 3.2 3.3 4.0 4.1	Subsidiary Present Past Status Present Present	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Co	d Bank, In Patien	
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3	Subsidiary Present Past Status Present Past Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily	d Bank, In Patien	
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification	d Bank, In Patien enter.	t Wards, Maternity and TB
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3	Subsidiary Present Past Status Present Past Present Past	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I	id Bank, In Patien enter. Mahapalika Road f	t Wards, Maternity and TB
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloc Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa	od Bank, In Patien enter. Mahapalika Road f	t Wards, Maternity and TB flanked with other important forth-west, Magistrate Court
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School	d Bank, In Patien enter. Mahapalika Road f ivier's College on r and Times of India	t Wards, Maternity and TB flanked with other important orth-west, Magistrate Court Building on norh-east.
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School of The main access is from the south-west side	d Bank, In Patien enter. Mahapalika Road f ivier's College on r and Times of India	t Wards, Maternity and TB flanked with other important orth-west, Magistrate Court Building on norh-east.
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School The main access is from the south-west side road on east of the plot.	d Bank, In Patien enter. Mahapalika Road f vier's College on r and Times of India e of the plot and s	t Wards, Maternity and TB flanked with other important orth-west, Magistrate Court Building on norh-east. ervice entry is from narrow
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School of The main access is from the south-west side	d Bank, In Patien enter. Mahapalika Road f vier's College on r and Times of India e of the plot and s	t Wards, Maternity and TB flanked with other important orth-west, Magistrate Court Building on norh-east. ervice entry is from narrow
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0	Subsidiary Present Past Status Present Present Usage	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School at The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning	d Bank, In Patien enter. Mahapalika Road f ivier's College on r and Times of India e of the plot and s rted by the reform	t Wards, Maternity and TB flanked with other important north-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School i The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform	t Wards, Maternity and TB flanked with other important north-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ca Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School I The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways and	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ictures providing v id landscaped gard	t Wards, Maternity and TB flanked with other important north-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens.
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School - The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform actures providing v id landscaped gard ess Hospital Build	t Wards, Maternity and TB flanked with other important forth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens.
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloc Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School at The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-west	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform actures providing v id landscaped gard ess Hospital Build	t Wards, Maternity and TB flanked with other important forth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens.
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School of The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-wese Cama Hospital	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ictures providing v id landscaped gard ess Hospital Build it.	t Wards, Maternity and TB flanked with other important oorth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all fens. ing, are located in the front
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School of The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-west Cama Hospital The building is located along south-west side	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ind landscaped gard ess Hospital Build it.	t Wards, Maternity and TB lanked with other important orth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all lens. ing, are located in the front in entrance from the south-
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School of The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-wese Cama Hospital	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ind landscaped gard ess Hospital Build it.	t Wards, Maternity and TB lanked with other important orth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all lens. ing, are located in the front in entrance from the south-
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Cettors, Staff and Servants' Quarters, PWD Cettors, Staff and Servants' Quarters, PWD Cettors, PWD Cettors, Staff and Servants' Quarters, PWD Cettors, Staff and Servants' Servants' Quarters, PWD Cettors, Staff and Servants' Quarters, PWD Cettors, Staff and Servants' Quarters, PWD Cettors, Staff and Servants' Servants' Servants' Servants' Servants' Servants' Settors, Staff and Servants' Staff and Servants' Settors, Staff and Servants' Settors, Staff and Servants' Settors, Staff and Servants' Staff and Servants' Settors, Staff and Servants' Settors, Staff and Servants' Settors, Staff and Servants' Settors, Staff and Servants' Settor, Staff and Servants' Settors, Servants' Setto	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reforme uctures providing v id landscaped garc ess Hospital Buildi it.	t Wards, Maternity and TB flanked with other important orth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens. ing, are located in the front in entrance from the south- ary entrances from all other
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ca Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School I The main access is from the south-west side road on east of the plot. The hospital was a result of a movement sta medical aid to women. Planning The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-west Cama Hospital The building is located along south-west side west side through a projecting porch with te sides to different departments. Building is symmetrical having rectangular pl building on north-eastern side. There are com	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ind landscaped gard ess Hospital Build it. e of plot with its ma rrace and subsidia an flanked by an a ridors along the loo	t Wards, Maternity and TB ilanked with other important iorth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens. ing, are located in the front in entrance from the south- ary entrances from all other added wing in center of the nger side on north-east and
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ca Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School - The main access is from the south-west side road on east of the plot. The hospital complex has around thirty stru over the plot interconnected with pathways an The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-west Cama Hospital The building is located along south-west side west side through a projecting porch with te sides to different departments. Building is symmetrical having rectangular pl building on north-eastern side. There are con south-west sides. The central lobby area hou	Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ind landscaped gard ess Hospital Build it. e of plot with its ma rrace and subsidia an flanked by an a ridors along the loo	t Wards, Maternity and TB ilanked with other important iorth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens. ing, are located in the front in entrance from the south- ary entrances from all other added wing in center of the nger side on north-east and
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloc Wards, Staff and Servants' Quarters, PWD Ce Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School at The main access is from the south-west side road on east of the plot. The hospital complex has around thirty structure over the plot interconnected with pathways and The main - Cama Hospital building and Alble part of the site facing main road on south-west Cama Hospital The building is located along south-west side west side through a projecting porch with te sides to different departments. Building is symmetrical having rectangular pl building on north-eastern side. There are com south-west sides. The central lobby area hou either sides house wards.	d Bank, In Patien enter. Mahapalika Road t vier's College on r and Times of India e of the plot and s rted by the reform ictures providing v id landscaped gard ess Hospital Buildi it. e of plot with its ma rrace and subsidia an flanked by an a ridors along the lou ises main open-we	t Wards, Maternity and TB flanked with other important forth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all dens. ing, are located in the front in entrance from the south- ary entrances from all other added wing in center of the nger side on north-east and ell wide staircase, wings on
2.2 3.0 3.1 3.2 3.3 4.0 4.1 4.2 4.3 5.0 5.1	Subsidiary Present Past Status Present Past Usage Townscape (Manmade)	Badruddin Tayabjee (Gymnasium) Road - Vel Ownership pattern State Government State Government Owner Use Hospital – Administrative offices, OPD, Bloo Wards, Staff and Servants' Quarters, PWD Ca Hospital Daily Significance & value Classification The plot is located on the north-east side of I buildings of different styles and period- St. Xa on south east, Anjuman-e-Islam High School - The main access is from the south-west side road on east of the plot. The hospital complex has around thirty stru over the plot interconnected with pathways an The hospital complex has around thirty stru over the plot interconnected with pathways an The main - Cama Hospital building and Alble part of the site facing main road on south-west Cama Hospital The building is located along south-west side west side through a projecting porch with te sides to different departments. Building is symmetrical having rectangular pl building on north-eastern side. There are con south-west sides. The central lobby area hou	d Bank, In Patien enter. Mahapalika Road f vier's College on r and Times of India e of the plot and s rted by the reform ictures providing v id landscaped gard ess Hospital Build it. of plot with its ma rrace and subsidia an flanked by an a ridors along the lou uses main open-we administrative buil	t Wards, Maternity and TB flanked with other important forth-west, Magistrate Court Building on norh-east. ervice entry is from narrow er Sorabji Bengali for better various facilities' spread all lens. ing, are located in the front in entrance from the south- any entrances from all other added wing in center of the nger side on north-east and ell wide staircase, wings on ding block is constructed in

Cama and Albless Hospital for Women and Children	158
	on eastern corner.
	Central porch bay rises higher than rest of the buildings having steep sloping roof with dormer windows. The main façade is flanked by two towers at either ends of the building and a narrow terrace on south-west side at second floor level.
	Ground and first floors are not in use and the second floor under the sloping roof serves as the residence of Deputy Superintendent of the Hospital.
	Albless Hospital The building is located in the south corner of the plot having main entrance through a
	projecting porch with terrace on south-western side. It is 'T' shaped in plan. The building has access from south-west side through porch.
	Subsidiary entrance is from north-west leading into a verandah. Through the porch one enters a common lobby having the main staircase. In the left wing is
	waiting room and the right wing is the ward. Along north-west and south-east sides there are verandahs.
	There is a dispensary in west corner of the building, which is accessed from the verandah. Toilet block is located in the north corner of the building standing independently accessed from the building. The central area serves as common ward for patients.
	Building has a typical floor layout and wards on first floor with Matron's room and private ward.
	The central bay has steep sloping gable roof rising higher than side bays. New building for labour ward and operation theatres is constructed in modern materials on north-eastern side of the building, which is connected by a covered passage.
	Lady Doctors' Quarters The building is located in the west corner of plot.
	It is a wooden structure with sloping gable roof. Main access is from north-west side. One enters directly the staircase lobby, which connects all the floors. Each floor houses single residential unit.
	Building has wooden semi-covered balconies along south-east side. Old Nurses' and Stewards' Quarters
	The building is located on north-west side of plot. It is 'L' shaped in plan with typical floor layout. Main access to the building is from south-west and south-east.
	All floors house common and private wards. Toilet block, servants' quarters and cooking room are located in an independent block
	connected to main building by a covered passage on north side. Building has wide corridors along sides facing internal enclosed space on north-west and north-east. Servants' Quarters
	This building is located in north corner of the plot. The building has simple 'L' shaped plan. It is a low-rise wooden structure with number o rooms as servant's quarters having timber sloping roof and common toilets. Main access to the building is from a corridor along south-west and south-east sides.
	Mortuary This structure is located in north corner of the plot behind servants' quarters block. Main access is from south-eastern side. Structure is rectangular in plan with three ramps to access the structure.
	Features <u>1. Cama Hospital</u> The symmetrical front façade has a central entrance porch with double <i>Lancet</i> arch resting on a central circular column with Corinthian column capital in front and single pointed
	segmental arch on the sides. The corners have buttresses, quatrefoil parapet and flying gargoyles on corner. Front Facade is punctuated with equilateral arches on either side o porch; four arches with spandrel having tri-foil ventilator on ground level and four simila
	arches on first floor level with hood moulding and <i>Antic</i> . The arches have multi-foil rose windows and double rectangular windows within. Features like <i>grotesque</i> are prominently seen on front façade on the Corinthian column capitals and arch springing points. The central bay behind the porch rises above by a floor till second floor. It has three
	equilateral arches at first floor level and pyramidal roof with dormer windows with finials atop.
	There are turrets at the corner at second floor level with conical tops, shaft resting or decorative corbels. Both the ends of the building have projecting stone balconies with tiled hip projecting
	bracketed roof. Dentils, rose windows, brackets, cornice bands circular columns with Corinthian capitals
	are prominent features on facades. <u>2. Abless Hospital</u> <u>The building here</u> current in a facade with control projecting peaks and many rable and
	The building has symmetrical façade with central projecting porch and many gable ends with finial atop and spirelets and finials at sides. Porch has three equilateral arches resting on circular columns and Corinthian column
	capitals in front and pointed segmental arch on sides. The openings are predominantly equilateral arches. Side elevations have projecting stone
	bracketed balconies at the corner. There are deep covered verandahs along all the sides

Cama and	Albless Hospital for Women and Children	
		with decorative wooden panels.
		There are, square turret like features on either sides of porch in front topped with a conica
		roof.
		Dentil, Rose windows, brackets, comice bands circular columns with Corinthian capitals Grotesque and circular ventilators are prominent feature on facades similar to the Cam
		, , , , , , , , , , , , , , , , , , , ,
		Hospital building. Style
		Neo-Gothic elements are predominantly observed like turrets, pointed arches, traceries etc
5.3	Intrinsic	neo-ootine elements are predominantly observed like turrets, pointed arches, tracenes ele
5.4	Value Classification	A(his), B(per), B (des), B (uu), F Recommended grade II B
J.4		
6.0		Topography
6.1	Floors	1. Cama Hospital – G+2 with part terrace.
0.1		2. Albless Hospital – G+1
		3. Lady Doctors' Quarters – G+1
		4. Old Nurses' and Stewards' Quarters – G+1
		5. Servants' Quarters – Ground floor structure
		6. Mortuary – Ground floor structure
		•
7.0		Construction
7.1	Plinth	Low and medium height plinth in grey stone with projecting plinth protection layer.
		Height of plinth varies from low to medium in each building
7.2	Walls	Thick load bearing stonewalls. Internal walls non-load bearing in places, or spaces defined
		by wooden partitions.
7.3	Floor	Timber floors with large wooden beams, wooden rafters and wooden floorboards.
		In some places wooden rafters are replaced by steel sections.
		Buildings added later have RCC floors.
7.4	Stairs	Main open well stone staircases with cast iron railing and wooden handrail.
		Number of small staircases in cast iron spiral, timber doglegged, RCC etc.
7.5	Openings	Most of the window openings are arched openings with rectangular double windows with
		multi-foil traceries.
		Rectangular openings with wooden framed glazed paneled double shutters.
		Corridors have stone arched openings; wooden verandahs with intricate wood paneling
		projecting stone bracketed balconies.
7.6	Deefer	Door louvered or paneled shutters, with fixed paneled ventilators.
1.0	Roofing	Cama Hospital buildings have arch braced timber truss hip and gable roofing with Mangalore roofing tiles.
7.7	Articulation	Corinthian column capitals, decorative arch springing points, equilateral arches, stone
1.1	Anodation	bracketed projecting balconies, wooden corridors with carvings.
7.8	Finishes	External facades of main structures are exposed stone ashlar masonry. Walls are mostly
		plastered and painted from inside.
		Newly constructed structures have plastered and painted walls.
7.9	Interiors (Movable & Immovable)	Movable
		Old beds, benches, tables, chairs, huge cupboards, racks, shelves etc.
		Immovable
		Statue of Lady Reay in a hall in Albless hospital building.
		Marble plaques displaying history of the Hospital.
		Wooden partitions with decorative carvings.
7.10	Compound/ Fence/ Gate	Front side along main access road is a stone masonry wall about 2 ft. high with fencing
		above. Stone pillars on either side mark entry gates.
		Hoop Iron fencing along the periphery on all sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Covered paved passages inter-connecting various buildings.
	Landscape	Oxygen Park with various species of trees.
		Watchman's cabins at access points.
		Waste disposal plant on north side of plot near the Mortuary.
		Water storage tanks near most of the buildings. Underground water storage tanks an
		Pump house on east side of plot.
		Canteen, generator room, servants' quarters, common toilet blocks spread over entire plot.
8.0		Services & Utilities
8.1	Lighting	Natural daylight through verandahs and skylights together with electrical lighting fixture
0.1	-igning	suspended from high ceiling.
8.2	Ventilation	Verandahs act as wind catchers allowing natural ventilation through traceries and openings
0.2	Vonuduon	Dormer windows supplement the ventilation process.
		Electrical fans have been suspended from the high ceiling and few rooms are provided with
		forced ventilation like Air- conditioners.
8.3	Electricity	
8.3 8.4	Electricity Water Supply	BEST MCGM

Cama and	Albless Hospital for Women and Children	158
8.6	Fire Precaution	Provision of equipments like, hosepipes and hose taps installed on each floor.
8.7	Other (HVAC/BMS/Security Systems)	Security guards posted.
9.0		Condition
9.1	Plinth	Fair – The Plinth of some buildings is almost negligible due to alterations.
3.1		The plinth of other buildings is in bad state with organic growth, seepage, chipping.
9.2	Walls	Poor - Some places there are leakages observed. Internal partitions have been added.
9.3	Floor	Fair - At some places the wooden members of the flooring are in a deteriorating state. Steel
0.0		sections replace some.
		Steel sections have been added for additional support.
9.4	Stairs	Fair – Main staircase in Albless Hospital building is not in use therefore not maintained. The
		stair well is used as dumping yards for the hospital.
		Some places supports have been added.
9.5	Openings	Fair - The openings have been blocked to house AC's, shutters have been changed. Few
		door openings have been in filled with brick masonry.
		Verandah openings have been blocked in an insensitive manner.
		Many changes in the internal and external openings of main buildings have been planned.
9.6	Roofing	Fair - Few places skylight material has been replaced, chajjas have been added.
9.7	Articulation & Finishes	Fair - Few places features are in a broken condition. The stone façade of the main building
0.0	0	is insensitively repaired.
9.8	Services	Poor – Service pipes are broken in many places causing leakages and dampness in walls.
9.9	Out Duildingo	The manholes are not covered. In many areas leakages are resulting in unhygienic ponds. Fair – cleanliness not maintained.
9.9	Out Buildings Overall Conditions	Fair Maintenance level Poor
9.10		
10.0		Transformation
	Form	Numerous new structures have been added in the plot using modern material.
	Structure	Verandahs have been enclosed.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Government Hospital, plot forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		The structure was designed by Muncherjee Murzban and the foundation stone was laid on
		22nd November 1883. The Hospital project was initiated by Mr. Pastonji Hormanji Cama.
		It was a result of a movement started by the reformer Sorabji Bengali for better medical aid
		to women and children.
		Overall construction cost for Hospital was Rs.1,71,722/-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Gothic Revival – Megan Aldrich, Phaidon



Grey stone clad building with highly ornamented façade with buff stone arches, floral frieze and round motifs, dentil moulding, corner turrets with conical roofs with finial.



Projecting balcony supported on decorative stone brackets, arched openings with buff stone voussoirs, floral motifs at springing point, floral and geometric carving in the tympanum

Cama and Albless Hospital for Women and Children



Arched openings with round openings above, dentil band



Cast iron capital and bracket detail



Round column with corinthian capitals with animal and floral motifs



Detail of the intricate tracery work



Internal open well staircase with cast iron railing



Series of arched openings on round columns with Corinthian capitals, with buff stone voussoirs, geometric pattern balustrade, floral motif, animal motifs at springing point



Interior view with arched openings with carved tracery work, floral arch band and keystone









Floral and animal motif in stone at the arch springing point



Presidency	y Magistrate's Court				159		
		Common Ref No: 159	×.	X YYEE			
		Card No: 217	1	BANNET:	-12 b		
		Ward (Part): A (Part I)					
	i Al	CS No: 1448 (Fort division)		- Alexandre			
	1 Alexandre	Plot Area: 8823.46 sqm.	- 15-	COF UUS			
		B U Area: -			ATHAN		
		Date: 14/04/2005		SSA SZ	and the second s		
		Recorded by: Sonal Modak	- <u>}</u>	STRA AND	15 KA		
		Reviewed by:		SVENCEM.	1 Stan		
			-	NC MARK	701		
		Int: Permission denied	-	AHAD	S.L.		
		Ext: Sonal Modak		71144	n n n n n n n n n n n n n n n n n n n		
	0 0 0 0 0 0	Photo Ref.: 159_Presidency Magistrate's		MAHAPALIKA MAPG	L.P.		
		Court		Location Plan			
				LUCALION FIAN			
1.0		Denomination					
1.1	Name of Premises	Presidency Magistrate's Court					
1.2	Earlier Name	Presidency Magistrate's Court					
1.3	Built in:	1889 (as per the inscription in glass)	Extensio	on Date: -			
2.0		Access					
2.1	Main	Mahapalika Marg – Vehicular and Pedestrian	n				
2.2	Subsidiary	-					
L.Ĺ							
2.0		Oursenable netters					
3.0	Descel	Ownership pattern					
3.1	Present	State Government					
3.2	Past	State Government					
3.3	Status	Owner					
4.0		Use					
4.1	Present	Institutional – Court of law					
4.2	Past	Institutional – Court of law					
4.3	Usage	Daily					
5.0		Significance & value Classification					
5.1	Townscape (Manmade)	The building stands on Mahapalika Marg, for	rms a part of	f aroup of Heritage Bu	ildings along		
••••	(maninaad)	the road such as BMC building, Cama and A			inan ge aleng		
		Main access to the building is through a pore	h from Mah	analika Marg on west	ern side with		
		separate entry and exit gates.		apalita marg on wood			
5.2	Architectural Description	Planning					
J.Z	Architectural Description	Planning Indeterminable as access to the bu	ulding donio	d			
		5	illuling derile	u.			
			Features				
			The Facade is punctuated with arches and columns supporting the verandahs and				
		corridors that run along the periphery. There					
		Rose windows on gable ends form typical N					
		Continuous bands run at each floor level res	ting on dent	ils at the topmost floor	r level.		
		Main entrance is through a porch with pointe	ed arches su	pported on circular co	lumns with		
		Corinthian column capitals.					
		Ornate multi-foil parapet at porch terrace and	d top floor le	evel.			
		Style					
		It derives a strong influence from Neo-Gothie	c style				
5.3	Intrinsic	-					
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), D(bio)	, F	Recommended	II A		
				grade			
6.0		Topography					
6.1	Floors	G + 2, G + 3 partly					
7.0		Construction					
7.1	Plinth	Medium plinth about 2 ft height in grey rough	n dressed as	hlar masonary			
7.2	Walls	Indeterminable	1 4100304 43	mar maoonary.			
7.3	Floor	Indeterminable					
7.4	Stairs	Indeterminable					
	Openings	Arched openings with wooden frame partly g	lazed panel	s with wooden louvers	s at bottom.		
7.5							
7.6	Roofing	Timber truss with mangalore roofing tiles.					
		Timber truss with mangalore roofing tiles. Corinthian column capitals, dentils, quatrefor	il openings e	etc.			
7.6	Roofing						

residency	v Magistrate's Court	15
		- Immovable -
7.10	Compound/ Fence/ Gate	A stone compound wall with MS fencing atop.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Indeterminable.
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable
9.0		Condition
9.1	Plinth	Fair - no evident damages seen. Blackening of stone.
9.2	Walls	Indeterminable
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Fair - At some places shutters have been replaced.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Fair – Damages to stone observed. Blackening of stone due to weathering.
9.8	Services	Indeterminable
9.9	Out Buildings	Indeterminable
9.10	Overall Conditions	Fair Maintenance level Poor
10.0		Transformation
	Form	Insensitive lift shaft added on the front facade
	Structure	Indeterminable
	Articulation & Finishes	Indeterminable
11.0		DP Remarks/ Perceived Threats
		Police Station and Court, plot forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.



Spire in stone with finial and gargoyles deriving influence from Neo-Gothic style of Architecture



Grey stone clad building with gable end roof in front with a rose window and animal statue finial

St. Xaviers (College	160
		Common Ref No: 160
		Card No: 218
		Ward (Part): A (Part I)
and a second		CS No: 1464 (Fort Division)
1.4.2.8		Plot Area: 12086.22 sg m.
FRE		B U Area: -
in the second	and a second	B U Alea
		Do Area Date: 09/02/05 Recorded by: Prachi Merchant
1. S. 11		
		Reviewed by:
		Int: Prachi Merchant, Zankhana Prajapati,
		Abhay Patil
	MARY ARE RECEIPTION	Ext: Prachi Merchant, Zankhana Prajapati,
1		Abhay Patil
1. 4.		Photo Ref: 160_St. Xavier's College.
I Charles		
- Sat		
		Location Plan
1.0		Denomination
1.1	Name of Premises	St. Xaviers College
1.2	Earlier Name	St. Xaviers College
1.3	Built in:	1869 Extension 1969
		Date
2.0	1	Access
2.0	Main	Mahapalika Marg
2.1	Subsidiary	Baddruddin Tayebji Road
2.2	Subsidially	Dauuruuunii rayevji rivau
3.0	-	Ownership pattern
3.1	Present	University and Jesuits Trust
3.2	Past	University and Jesuits Trust
3.3	Status	Owner - Tenant
4.0		Use
4.1	Present	Educational institution, Residential - staff and priests, Entertainment - Multipurpose Hall,
		Religious - Chapel
4.2	Past	Educational Institution, Religious - Chapel
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	The plot is located in the north end of Mahapalika Marg flanked by other important buildings
	,	of different styles and periods: Elphinstone Technical Institute on the north side, Cama and
		Albless hospital on the south and the Azad Maidan on the west.
		The building is one of the first missionary institutions planned on the Mahapalika Road.
		The access to the site is from the west side of the plot.
5.2	Architectural Description	Planning
		The building complex consists of group of interconnecting independent building structures
1		planned, enclosing three guadrangles.
1		planned, enclosing three quadrangles. The complex is oriented in the east west direction with its main entrance from the west
		The complex is oriented in the east west direction with its main entrance from the west
		The complex is oriented in the east west direction with its main entrance from the west side.
		The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages
		The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles.
		The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the
		The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts.
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped
		The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle.
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the south and the Social Science and Institute of communication building in the
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle.
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle. Administration Building:
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle. <u>Administration Building</u>: The building is a symmetrical longitudinal structure with its longer side aligned in north-
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the south and the Social Science and Institute of communication building in the east bound the third landscaped quadrangle. <u>Administration Building</u>: The building is a symmetrical longitudinal structure with its longer side aligned in north-south direction.
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle. Administration Building: The building is a symmetrical longitudinal structure with its longer side aligned in north-south direction. The building is accessed through an extended porch with a terrace above, leading through
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle. Administration Building: The building is a symmetrical longitudinal structure with its longer side aligned in north-south direction. The building is accessed through an extended porch with a terrace above, leading through the administration building to the first quadrangle.
		 The complex is oriented in the east west direction with its main entrance from the west side. The buildings in the complex are of similar heights and have verandahs and passages overlooking the quadrangles. The administration building on the west, chapel on the south, the science building on the north and the Hall building in the east, together form the basketball quadrangle, the first of the internal courts. The Hall building on the west, Gymkhana building on the south, Science building on the north and the Cardinal Gracias Hall building in the east bound the second landscaped quadrangle. The Cardinal Gracias Hall building on the west, Hostel building on the south, Science building in the east bound the third landscaped quadrangle. Administration Building: The building is a symmetrical longitudinal structure with its longer side aligned in north-south direction. The building is accessed through an extended porch with a terrace above, leading through

St. Xaviers Colle	ege	160
		and passages overlooking the front landscaped area on the west side. Wooden staircases
		are located in the north and south end. The ground floor houses the 'Heras' Institute of Indology, library and office areas. The first
		floor houses the office areas and classrooms. The second floor has the residence rooms
		and private chapel area.
		Science Building:
		The Science building is a longitudinal building oriented in the east west direction. The
		building starts from the west corner and continues with a marginal curve, ending in the east
		corner, forming a common façade to all three quadrangles, and connecting the
		perpendicular buildings. The building has rooms lined up on the north side with verandahs and passages on the
		east side, overlooking the quadrangles. The Hall and the library building are connected
		between the first and second quadrangles with open well 'C' shaped double stone staircases
		from opposite sides with intricately stone carved railing and soffit.
		The ground floor houses classrooms with verandahs opening into the quadrangle. The first
		and second floor has the library, classrooms and laboratory rooms. The second floor has
		the residential rooms of the priests. A wooden doglegged staircase at the north corner
		connects upper floors.
		A bridge wing with passages of arched openings and stone round columns connects the Administrative and Science building.
		Multipurpose Hall and Reference library:
		The building is rectangular and is oriented in the north south direction with ground floor hall
		accessed from the colonnade and the upper floor from the north end.
		The building houses a multipurpose hall with double height, with a colonnade of arched
		openings and internal door shutters opening up into both sides of the quadrangles.
		The first floor houses the reference library. The classrooms on the second floor have
		doubly loaded corridor. A recessed third floor has been newly added with temporary shed, on the terrace floor.
		Chapel Building:
		The building is a rectangular low scale structure oriented in the east west direction. The
		building is connected with the Administrative building and Hall building through a bridge at
		the first floor level.
		The ground floor has an arched colonnade and the first floor houses the chapel. The chapel
		entrance is from the west side from the first level through a lobby formed below a projecting
		balcony, supported on stone arch opening and columns. The apse is located on the east side.
		Features
		Administrative building:
		The building is clad with grey stone ashlar masonry. The entrance to the building is through
		a porch with surbased side arches and three semicircular arches from the front, supported
		on columns with intricately carved stone capital friezes. The stone frieze is in a floral
		pattern. The terrace above the porch has stone carved trefoil tracery work within the round pattern of the balustrade.
		The central wing has sloping Manglore tile gable roof supported on wooden members,
		ending into a finial. The side wings have sloping roof with a series of projecting eves,
		ending into a finial.
		The façade has pointed, semicircular, trefoil arches and single span arch with two arches
		within, in two or three numbers with columns with decorative capitals in the center.
		The façade is adorned with floral and geometric pattern frieze bands, bands defining levels
		and corner quoins. Internally the openings are arched, supported on columns with decorative capitals. The
		chapel has some intricate wooden wall paneling.
		Science Building:
		The building is clad with grey stone ashlar masonry. The building has a sloping Mangalore
		tile roof with side gable, ending in a finial.
		The façade has a semicircular arched colonnade, pointed arches, and geometric type of
		arched opening. The passages of the first floor have stone carved balustrade. The building has floor level bands and top floor has a cornice band.
		The staircase wing at the junction of Science building and the Hall is taller and is
		ornamental with spires in four corners and gothic arches.
		Multipurpose Hall and Reference library:
		The building is clad with buff stone ashlar masonry. The Hall on the ground floor has a
		pointed arched colonnade on the east and west side.
		The Hall has large arched openings with wooden paneled shutters, opening into the
		colonnade overlooking the quadrangle. The hall has a double height with balcony overlooking the lower level with the stage at a
		higher level on the south end with green rooms below. The balcony has wooden flooring,
		railing, paneling, a row of old photo frames, a row of ornamented wooden spires, wooden
		coffered ceiling. The openings also include ornamented rose windows.
		The reference library on the first level is highly ornamental with decorative coffered ceiling.

St. Xaviers	College	160
		The entrance to the library is ornamented with gothic features. The floor area has wooden partitions. Much old wooden furniture is still being used. Chapel Building:
		The chapel is clad with grey ashlar stone masonry. The building façade has horizontal bands and vertical decorative projections on the north side, which extend into spires. The north façade has an arched colonnade with its central wing higher than the rest of the wings. The central wing has an extended porch with spires and battlement parapets on the top and is higher than the side wings.
		The first floor chapel openings are large pointed arched opening with double arches and round opening within. The side wings on top end with stone battlement parapet. The entrance to the chapel is from west side through three arched opening into a lobby with a balcony supported on large arch and column above. The balcony railing is intricately carved in stone.
		The side openings are large arched openings with pointed arches, with double arches and quatrefoil openings within. The openings have stained glass shutters. The apse has chamfered walls with a series of arched window with stained glass shutters. The chapel ceiling is a highly ornamented groined vaulted roof, supported on a stone colonnette on square bases to form a colonnade along the nave. Style
		The building derives influences from Gothic Revival and Indo Saracenic style of Architecture.
5.3	Intrinsic	
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), C(seh), D(bio), E, F Recommended grade: II A
6.0		Topography
6.1	Floors	G + 3 Administrative, Hall and Science building. G + 1 Chapel Building.
7.0		Construction
7.1	Plinth	Low plinth clad with grey or buff stone with plinth protection buff stone band.
7.2	Walls	Load bearing stone walls.
7.3	Floor	Wooden flooring with wooden supporting members. Newer structures of RCC. Jack arch roofing in the lab.
7.4	Stairs	Buildings have wooden dog-legged staircase with wooden risers, treads and railing. Central main staircases connecting the Science building to Hall, open well double stone staircase with stone risers, treads and intricately carved railing in a geometric pattern. Chapel stone staircase with stone risers, treads and railing.
7.5	Openings	Verandah colonnade with arched openings. Arched (pointed, semicircular, pointed) door, window and openings with wooden paneled shutter.
7.6	Roofing	Sloping pitched, gable Mangalore tile roof supported on wooden members in administrative building; private chapel area has cross-braced wooden roof. Newer structures with flat terrace. Chapel building has ribbed groined vaulted roof. External façade arched windows have curved wooden projecting <i>chajja</i> .
77	Articulation	The extended floor above the Hall building terrace is covered with asbestos sheet roof. Arched openings and colonnade, bands, friezes, spires, finials.
7.7 7.8	Articulation Finishes	The walls are externally and façade facing the verandahs is clad with grey and buff stone and internally plastered and painted.
		Floor is finished with natural stone, cement tiles and wood at places.
7.9	Interiors (Movable & Immovable)	Movable Library furniture consisting of tables, chairs, reading tables, partitions, benches, library catalogue storage unit. Chapel and Hall seating furniture. Staff room furniture. Immovable Chapel reading ledge, wooden paneling, marble apse furniture. Private chapel in the Administrative building has fixed carved wooden paneling. Library wooden partitions.
7.10	Compound/ Fence/ Gate	Hall balcony railing, spires, stage railing. Brick compound wall with chain link above. Two MS gates with gate posts on the west side from the ends. Two MS gate on the south
7.11	Curtilage/ Unbuilt space/ Out Buildings/	side opening on the subsidiary road. The front portion is landscaped with some rare old trees. A curved landscaped island at the
	Landscape	entrance around the extended porch demarcating the two entry points from the west side. The first quadrangle is paved and has a basketball court and is also used for open-air concerts. The second and the third quadrangle have fenced landscaped islands with pathways
		around. Out buildings of Gymkhana, Canteen building, Hostel building and Institute of

St. Xaviers	College	160	
		communication has been added around the quadrangles.	
8.0		Services & Utilities	
8.1	Lighting	Adequate light through openings verandahs, supplemented by artificial lighting.	
8.2	Ventilation	Adequate ventilation through openings verandahs, supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Few rooms have window AC's installed on the south wall facing the subsidiary road.	
		Ocudition	
9.0	Diath	Condition	
9.1	Plinth	Fair – The level is reduced to almost negligible.	
9.2	Walls	Poor - Weathering of stone externally, cracks and leakages observed in the chape	
0.2	Floor	building, loose plaster. Internal Partitions have been added. Fair – at some places the wooden members of the flooring are in a deteriorating state	
9.3	Floor		
0.4	Otaira	Steel sections have been added for additional support.	
9.4 9.5	Stairs	Fair – wood parts at few places is deteriorating. Fair – The openings have been blocked to occupy AC's, shutters have been changed. Fev	
9.5	Openings		
9.6	Deefer	door openings have been closed with brick. Fair – Wooden supports are deteriorating at few places, window chaijas have beer	
9.0	Roofing	changed.	
9.7	Articulation & Finishes	Fair – Few places features are in a broken condition. Stone features have been painted a	
9.1	Anticulation & Finishes	places.	
9.8	Services	Fair – At few place pipes in toilet blocks and other electrical services have beer	
5.0	Services	insensitively added. Toilets have been added.	
9.9	Out Buildings	Fair – New buildings at the rear side are planned around the quadrangle.	
9.10	Overall Conditions	Fair Maintenance level Fair	
0.10			
10.0		Transformation	
	Form	Upper floors of the Hall building have been added.	
	Structure	Extensions have been made in various buildings.	
	Chuchard	I-sections have been installed to strengthen the floor.	
	Articulation & Finishes	Openings are blocked, opening size and shutters have been changed. Outbuildings have	
		been insensitively added around the guadrangle.	
		Chajjas have been replaced with asbestos sheet.	
		" I	
11.0		DP Remarks/ Perceived Threats	
		College, building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
		Division of International Thomson Publishing Inc.	
		MARIAM DOSSAL (1996) Imperial designs and Indian Realities - The Planning of Bombay	
		1 (the 19/h 19/h Domboy - () stord University Droop	
		City - 1845-1875, Bombay : Oxford University Press. SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.	



Grey stone clad administrative building façade with arched openings



Chapel elevation with Gothic Revival features such as lancet windows, round openings, finials etc

St. Xaviers College



New building of the Hostel



Façade of the Library building with arched openings, frieze bands, round motifs



Quadrangle 3 with old building with arched openings juxtaposed with the new building



Trifoiled arches opening with floral band at the column capital, bands



160

End detail of the receding turret in a floral pattern



Quadrangle 1 with grey stone clad buildings with a series of arched openings with sloping roofs



Side elevation of the grey stone clad building with arched openings



Frieze band with intricately carved floral and animal motif

St. Xaviers College



Entrance porch with arched opening with floral motif at the springing point, frieze band, balustrade



Internal verandah with arched opening



Wooden paneled partitions



Reading room wooden carved furniture



Detail of the frieze band with bird and floral motif



Arched opening with surface decoration at the lintel level and intricately carved wooden paneled double door shutter



Connecting wing between two buildings with arched openings, round motifs, decorative balustrade



Auditorium interior with overlooking balconies, wooden railing, furniture, double paneled shutters in arched opening



St. Xaviers College



Chapel interior with ribbed vaulted ceiling on buff stone clad round columns with carved base and capital, end apse, wooden benches in the nave



Reading room decorative coffered ceiling, wooden carved partition, furniture





Tower with Indo Saracenic style features like jaliwork, finials, spires



Open well stone staircase with carved railing

Elphinstor	ne Technical Institute		161
		Common Ref No: 161	Company of the second s
	A PART A PART OF T	Card No: 219	
		Ward (Part): A (part I)	- A C MAR
		CS No: 1469	- they are the second s
2016 B	A DECEMBER OF THE OWNER OWNER OF THE OWNER		- Contraction of the Contraction
		Plot Area: 18214.29 sqm.	- 1. 1. N. M M. M V.
		B U Area: -	A A ASIA A ANT H
	In Contract Contract	Date: 7/12/2004	
3		Recorded by: Arun Wadhwa	A A A A A A A A A A A A A A A A A A A
		Reviewed by:	
		Int: Arun Wadhwa, Zankhana Prajapati	T Ma Star Ist
		Ext: Arun Wadhwa, Zankhana Prajapati	AHAP STATISTICS
		Photo Ref.: 161_Elphinstone Technical	- Aller Aller
		Institute	Mahapatina Mango
	and the second	Institute	
			Landian alar
4.0		Describertion	Location plan
1.0		Denomination	
1.1	Name of Premises	Elphinstone Technical Institute	
1.2	Earlier Name	David Sassoon Building for the Elphinstone H	
1.3	Built in:	Commenced May 1872, Completed Novembe	er 1878. Extension Date: -
			· · · · ·
2.0		Access	
2.1	Main	Mahapalika Marg – Vehicular & pedestrian.	
2.1		manapalika mary – venicular & peuestilän.	
Z.Z	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	State government	
3.2	Past	State government	
3.3	Status	State Government.	
0.0			
4.0		llee	
4.0	Durant	Use	terrete of Table in the description to site to st
4.1	Present	School and Technical college, Office of Direc	torate of Technical Education, institute of
		Vocational Training,	
4.2	Past	School.	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	Landmark educational building with imposing	architecture
5.2	Architectural Description	Planning	
J.Z	Arcintectural Description	0	ith a broad flight of steps at the center leading
		to a large hall for cultural and convocation us	
		central hall with continuous veranda along the	
		ends. Staircase and toilet facilities planned or	n both sides. Extension wing in concrete
		construction added later on the northern end	for accommodating workshop facilities.
		Features	
		High pointed arch openings continuous along	the long facade supported on circular
		columns with intricate column capitals.	
		Segmental arch openings on the ground floor	
			nature, at floor levels. Intricately stone-carved
		column capitals with floral and animal motifs.	
		parapet and cornice features supported on cu	
		and railing.	arviniear brackets. Intricate iron raining gate
			mental factures at the environment and
		Groin vault forming entrance porch with ornal	
		Centrally located broad flight of stone steps w	vith decoratively paneled parapet leading to
		the first floor.	
		Stepped roof pavilion on terrace with stone fin	nial and intricately carved animal forms and
		cinquefoil openings in triangular pediment.	
		Style	
		The building displays characteristics influence	ed by the Neo Gothic style
5.3	Intrinsic	Ornately stone carved features of animal and	
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), F, I(sce	
			,
6.0		Topography	
	Flooro		
6.1	Floors	G + 3 (part floor)	
7.0		Construction	
7.1	Plinth	Low plinth about a foot, dressed in black base	alt ashlar masonry.
7.2	Walls	Load bearing rubble stone masonry walls.	· · ·
		Wooden floor boards supported on wooden ra	afters and steel girders for larger spans
7.3	Floor	Wooden floor boards supported on wooden r	atters and steel girders for larger spans,

Urban Design Research Institute

Elphinstone	e Technical Institute	16
		projecting stone blocks support wooden rafters, which in turn support wooden floorboards.
7.4	Stairs	Regular double flight stair constructed in wood, one in each of the two wings. Small stair
		Centrally located at the rear constructed in stone slab supported on load bearing walls.
		Wood finished handrail and decorative iron balusters.
7.5	Openings	Pointed and segmental arch openings in the verandas, Wooden louvered and glazed
		paneled shutters form the door-window openings. Glazed fixed panels in the circular
		openings high above.
7.6	Roofing	Steep sloping hip and gable roof covered with Mangalore tile and supported on elaborate
1.0	i toomig	wooden truss work. Stepped stone roof pavilion (6 nos.) at the terrace corners. Skylight
		above passageway on second floor.
7.7	Articulation	Intricate ornamental stone features forming column capital and cornice bands seem
1.1	/ intoliation	articulate conception.
7.8	Finishes	All external surfaces are ashlars course black basalt stone. Arch openings, circular colum
1.0		and ornamental features are in buff basalt, soft limestone respectively. External veranda
		surfaces are cyclopean course black basalt masonry. Plastered and painted internal wall
		surfaces. Varied and modified floor finishes though originally Minton tile.
7.0	Interiore (Maushle 8 Interestela)	
7.9	Interiors (Movable & Immovable)	Movable
		Polished wooden furniture in some portion of the building seems original part of the building
		scheme.
		Immovable
		-
7.10	Compound/ Fence/ Gate	Low stonewalls with iron railing above.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Expansive plot area with large trees and lawn to the front.
	Landscape	Several buildings in the compound including offices of directorate of technical education,
		workshops, and canteen, large stepped amphitheatre with performing stage structure to the
		east side facing the main building.
8.0		Services & Utilities
8.1	Lighting	Natural light through door-window openings supplemented by electric light fixtures.
8.2	Ventilation	Natural ventilation through door-window openings supplemented by electric fans and air-
0.2	ventilation	
0.0	The state of the	conditioning units.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No fire precaution except a few fire extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	Window unit air-conditioners installed at various locations.
9.0		Condition
9.1	Plinth	Poor - plant growth and seepage observed.
9.2	Walls	Fair – except Some areas on upper floor and staircase walls seem damp due to seepage
		from plumbing lines and rainwater.
9.3	Floor	Fair – except wooden supporting members and girders seem unfinished and damaged at
0.0	11001	few places.
9.4	Stairs	Fair except poor finishing and maintenance level.
9.5	Openings	Poor - Several openings are covered with iron grills, mesh and wooden panels, some
		ventilator openings shut with brickwork.
9.6	Roofing	Fair – except few missing tiles and leakage problem, wooden truss members decay-prone
9.7	Articulation & Finishes	Poor - Stone dressed surface non-uniform, discolored and dust laden.
		Ornamental features damaged and poorly maintained. Altered floor finishing, non-uniform
		and low in maintenance.
9.8	Services	Poor – neglected plumbing and messy electrical lines.
9.9	Out Buildings	Fair except the canteen structure due to poor finishing and low maintenance.
9.10	Overall Conditions	Fair except Poor finishes and articulation. Maintenance level: Low.
-		
10.0		Transformation
10.0	Form	Reinforced concrete building extension to the north side with connecting bridge seems
	Chruchura	incongruous to the original stone-faced structure.
	Structure	Addition of water storage tank supported on I-sections at terrace level,
	Articulation & Finishes	Bright and varied paint finish applied extensively in the second floor veranda seems
		insensitive and damaging. Ceramic tile dado in the verandas seems visually interrupting the
		building finishing.
11.0		DP Remarks/ Perceived Threats
		Secondary school, Open air theatre, building forms part of R zone
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:

Elphinstone Technical Institute	161
	Cathedral. <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.
FranceGrandBightOfStoreBightOfStoreBightOfStoreBight <th>Arched entrance opening with receding arches on round columns with high base and polychromatic stone voussoirs, intricately carved gate</th>	Arched entrance opening with receding arches on round columns with high base and polychromatic stone voussoirs, intricately carved gate
Frey stone clad building with arched openings, decorative backs to building with arched openings to building with arched opening with arched openi	
bands, brackets, balustrade	Iustrade
Urban Design Research Institute	MMR- Heritage Conservation Society



Detail of the column capital with floral pattern



Façade articulation with trifoil arched openings, balustrade, cornice bands, brackets, pediments with carved tympanum



Verandah with pointed arched openings, louvered paneled doors



Façade detail with use of polychromatic stone for arches, columns, façade cladding



Terrace level tower detail with conical roof, arched and round openings, finials, intricately carved human and floral motifs at the pediment joints



Ceremonial hall with double height space with arched openings, wooden ceiling and old wooden seating arrangement



Highly ornamented projecting balcony with stone brackets, balustrade, cornice bands



Column detail with marble stone cladding, frieze band



Frieze detail with floral pattern in buff stone



Arched window opening with louvered shutters and fixed trifoil arch louvered panel.



Arched door opening with double louvered shutters and fixed wooden ventilator panel



Internal frieze detail in wood

Atmasing	Jassasing Bankebihari Municipal ENT I	Hospital 162	
	1	Common Ref No: 162 Card No: 220 Word (Part): A (Part II)	
	An 2	Card No: 220	
	AS TO A		
	1140 63	CS No: 705 (Fort Division)	
		Plot Area: 1580.27 sg m.	
	7 Honda Ghit	B U Area -	
" 3		Date: 6/01/2005	
in.		Recorded by: Sonal Modek	
		Reviewed by:	
	CALGARA UL	Reviewed by: Int: Zankhana Prajapati, Sonal Modak	
		Ext: Zankhana Prajapati, Sonal Modak	
		Photo Ref: 162_ENT Municipal Hospital	
		The ref. 102_Err widnieger Hospital	
		Location plan	
1.0		Denomination	
1.1	Name of Premises	Atmasing Jassasing Bankebihari Municipal ENT Hospital.	
1.2	Earlier Name	City Improvement Trust Building.	
1.3	Built in:	Commenced in 1898, Completed in 1904. Extension Date: -	
2.0		Access	
2.1	Main	Maharshi Dadhichi Marg	
2.2	Subsidiary	Mahatma Gandhi Road, Murzban Road.	
3.0		Ownership pattern	
3.1	Present	Municipal Corporation of Greater Mumbai	
3.2	Past	The Trustees for the improvement of the city of Bombay and others	
3.3	Status	Owner	
0.0			
4.0		Use	
4.0	Present	Hospital	
4.1			
	Past	Offices.	
4.3	Usage	Daily.	
E 0		Simificance & Value Classification	
5.0 5.1	Townscape (manmade)	Significance & Value Classification The building is on the corner plot at the junction of Maharshi Dadhichi Marg and Mahatm	
5.1	Townscape (manmade)	Gandhi Road.	
		The main access to the building is from Maharshi Dadhichi Marg.	
		Very omate building emphasizing the corner of the two streets.	
5.2	Architectural Description	Planning	
5.2	Architectural Description	The building has a trapezoidal plan with the longer facade along Maharshi Dadhichi Mar and Mahatma Gandhi Road.	
		The building is ground plus two storied high with sloping roof and terrace.	
		Entrance of the building is from Maharshi Dadhichi Marg through the porch, which leads t	
		the entrance lobby and staircase area. Down the lobby you enter main corridor. On left	
		the office and pathology department with lift for patients and on right is the OPD, canteen	
		medicine counter, nurse station behind which is the toilet block. Two other toilet blocks ar	
		at the other two corners of the building. On the first floor on the left side there is the	
		operation theatre and other supporting rooms and on right are the RMO and nurse	
		residence and special wards. On second floor there are male and female wards.	
		Features	
		Decorative arched entrance porch with Corinthian style column capital and base	
		semicircular openings on ground and pointed arched openings on first and second floo	
		Stained glass and tracery in ventilator, a series of gable ends in front portion with ston	
		finials and dormer windows, arched opening in gable end, trefoil arches in second floor	
		medallions in porch. Bay windows, turrets, ornamental spandrel, strapwork bands along th	
		cornice band, cinquefoil and multifoil, decorative stone newel post, decorative heavy panel	
		wooden entrance door and side entrance enhanced by crocket tympanum with entrance	
		pier and colonnette.	
		Style	
		Building displays characteristics of the Neo-Gothic and Neo-Classical styles.	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), A(his), B(per), B (des), F, I(sce) Recommended grade II A.	
6.0		Topography	

	assasing Bankebihari Municipal ENT Hos		
6.1	Floors	G + 2.	
7.0		Construction	
7.1	Plinth	Medium height plinth of buff basalt stone with edging done for plinth protection.	
7.2	Walls	Load bearing composite wall with ashlar masonry and internal walls and arches are mad	
1.2	Trails	of bricks, which are plastered and painted.	
7.3	Floor	Flooring rests on load bearing walls and is composed of I-sections with wire mes	
		embedded in concrete with tiling.	
7.4	Stairs	Two staircases present.	
		The main staircase is a grand L-shaped stair with winder and other one is a spiral staircas	
		from the second floor to terrace.	
		Main staircase has decorative cast iron railing with wooden handrails and has a decorative	
		newel post, while spiral staircase has cast iron baluster and railing.	
7.5	Openings	Heavy paneled double leaf decorative door at entrance.	
		Ground floor has semicircular arched openings, first has pointed arched and second ha	
		trefoil arches within pointed arch openings.	
		Has double shutter glass window with either CI tracery or stained glass present a ventilator above and below ventilators are made of multifoil bands.	
7.6	Roofing	Partly terrace and partly sloping roof in Mangalore tiles supported on wooden rafters an	
1.0	Rooling	beams, with stone finials and CI finials, stone parapet walls, asphalting is done in a larg	
		portion, has a series of water tanks and cooling towers.	
7.7	Articulation	Medallions in porch, bay windows, turrets, ornamental spandrel, strapwork bands along th	
1.1	Anticulation	cornice band, cinquefoil and multifoil and side entrance enhanced by a crocket tympanu	
		with entrance pier and colonnette.	
7.8	Finishes	External walls in yellow stone ashlar masonry.	
1.0		Internal walls are plastered and painted.	
		Tiling is either marble patterned, cement mosaic, coba, kotah.	
7.9	Interiors (Movable & Immovable)	Movable	
	,	Tables, shelves, cupboard, benches, clock, fans and marble statue.	
		Immovable	
		Original wooden partition, door hinges and fixtures.	
7.10	Compound/ Fence/ Gate	MS fencing in front.	
		Rear has compound wall in brick - plastered and painted.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Open spaces in front, which forms footpath along the porch and certain area in rear.	
	Landscape	Pump house, waste storage and underground water tank forms the outbuildings.	
		Many decorative plants are planted in front.	
		Complete 0 1141141-0	
8.0	Linking	Services & Utilities	
8.1	Lighting	Inadequate natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire Extinguishers	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.	
0.7			
9.0		Condition	
9.1	Plinth	Poor - Covered with concrete in rear and planter box in front, has dust accumulation	
5.1		blackening of stone, loose surface, covered by pipes, addition of staircase, plant and mos	
		growth, paint droppings.	
9.2	Walls	Poor - Heavy cracks are seen in arches and wall surfaces, plant growth is seen both insid	
0.2		as well as outside, brickwork exposed, heavy seepage and dust accumulation.	
9.3	Floor	Dilapidated - Heavy seepage, concrete is falling off, patchwork is done, wire mes	
		exposed, damping is seen, cracks are visible, I beam are corroded, wooden beam	
		loosened at top floor.	
9.4	Stairs	Fair - Has dust accumulation, needs polish on handrail, painted balusters, broken treads a	
		certain places, while spiral staircase is corroded and has dust accumulation.	
9.5	Openings	Poor - Many arched openings are closed with plywood, GI sheets or brickwork, window	
		panes broken, addition of grills, broken stained glass, louvered windows closed	
		incongruously painted wooden members, addition of jalis, AC units and addition of awning	
9.6	Roofing	Poor - Heavy seepage and leakage problem, Mangalore tiles broken at certain areas	
		wooden members in roof lack maintenance.	
9.7	Articulation & Finishes	Poor - Cracks in arches, loose arch stones, cornice bands broken, finial blackened, colore	
		changed due to weathering and plant growth.	
		Internal walls have heavy seepage, plaster and paint was peeling off, patchwork is see	
		and haphazard arrangement of electrical wires.	
		External wall has blackening of stone, plant growth, seepage where drain pipes ar	

MMR- Heritage Conservation Society

tmasing	ing Jassasing Bankebihari Municipal ENT Hospital 162		
		present, dust accumulation, paint droppings, cracks on stone, patch work of cement, nails. Tiling have cracks, wear and tear, replacement of tiles, cementing is done, change c material, loose tiling and presence of voids.	
9.8	Services	Fair - Toilets are internally in good condition but service pipes layout is haphazard, leakage moss growth, original pipes are rusted, electrical layout haphazard, AC ducts exposed corridor and addition of hot and cold water pipes.	
9.9	Out Buildings	Poor - Neglected condition and not maintained. Rusting of AC sheet on storage shed.	
9.10	Overall Conditions	Poor. Maintenance level: Poor.	
10.0		Transformation	
	Form	Additions of lift block in rear for carrying patients and service duct enclosed by woode panels on side elevation.	
	Structure		
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats.	
		Municipal hospital, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: The building, completed in 1904, was designed in the neo-classical style by Charles Stevens (son of Frederick William Stevens) for the offices of the Bombay City Improvement Trust and was converted into the Bankebehari Ear, Nose and Throat Hospital in1964. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings an Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.	



Buff stone clad building with arched openings, bands, stone balustrade



Entrance porch with arched openings in buff stone, on slender round columns, balustrade, turrets



Series of pointed arched openings on round columns with corinthian capital, trifoil window ventilator opening, balustrade, frieze band



Frieze with geometric and floral motif, bands

Urban Design Research Institute



Subsidiary Entrance with arched opening with a pediment with carved tympanum, columns with turrets, frieze band



Carved railing detail



Stained Glass in rose window



Trellis work with intricate lattice work, floral pattern, star shaped



Intricately carved wooden paneled double shutter with exposed hardware.

Stone frieze detail with geometric pattern



Stone staircase with newel post, carved railing



Front elevation with arched openings, pediments, turrets, balustrade etc



Arch detail with carved openings, jail work



Marble bust



Window detail with recessed arches, round openings, carved spandrel




Arch detail with rose window, carved floral pattern in the ventilator.

Western R	ailway Headquarters offices Building	163
		Common Ref No: 163
	4]	Card No: 221
		Ward (Part): A (Part II)
	200	CS No: 710, 1/710 (Fort division)
		CS No: 710, 1/710 (Fort division) Plot Area: 14656.28 sqm. B U Area: - Date: 18/04/2005 Recorded by: Sonal Modak Reviewed by:
		B U Area: -
		Date: 18/04/2005
		Recorded by: Sonal Modak
and Ann		Reviewed by:
		Int: Permission denied
A LOUGH LAND		Ext: Sonal Modak Photo Ref.: 163_Western Railway HQ
	The second	
		Location Plan
1.0		Denomination
1.1	Name of Premises	Western Railway Headquarters offices Building
1.2	Earlier Name	Bombay Baroda & Central India Railway Head Quarters
1.3	Built in:	Commenced in May 1894, Completed in January 1899 Extension Date: -
2.0		Access
2.0	Main	Maharshi Karve Road– vehicular and pedestrian
2.1	Subsidiary	Veer Nariman Road, V. Thackersey Marg
3.0		Ownership pattern
3.1	Present	Central Government
3.2	Past	BB – LC. 1 Railway Companies (officers) & others, The Municipal Corporation of Bombay & others
3.3	Status	Owner
4.0		Use
4.1	Present Past	Railway Offices Railway Offices
4.2	Usage	Daily
4.0		Duny
5.0		Significance & value Classification
5.1	Townscape (Manmade)	Prominent building located at the junction of Maharshi Karve Road and Veer Nariman Road
		The building is a city landmark on an important and busy junction, dominating the skyline of
		the Churchgate area. The building is juxtaposed between buildings of different styles and periods of Architecture,
		forming an important nature of the townscape of the city.
		The building overlooks Oval Maidan in front with, row of Art Deco buildings and
		Victorian Neo-Gothic buildings like University building, Secretariat building, High Court and
		on its either side.
		The structure stands on the site of an old gate within bastions of Fort and is thus integral to
5.2	Architectural Description	the history of Bombay. Planning
J.Z	Architectural Description	Indeterminable
		Features
		The building is constructed in grey basalt stone with a central dome rising above.
		The unique central tower has been designed to be square from the base up to 100 feet in
		height, then becoming an octagon that gradually diminished into a smaller octagon
		culminating in a circular masonry dome. Multiple smaller domes form the skyline with finial like features at the top.
		Window openings have semicircular and pointed arches in various sizes with ventilators
		above
		Narrow smaller acoupled arched openings with the arches supported on yellow stone
		circular column with corinthian capitals form one of the significant features of the facades.
		Continuous bands at each floor level, decorative bands, dentils, quatrefoil arched openings,
		lion carved in stone atop the gable ends, gable ends with large rose window are some of
		the integral features displayed on facades. The two porches on the western and southern facades provide additional strength and
		The two porches on the western and southern facades provide additional strength and
		The two porches on the western and southern facades provide additional strength and character to the building.

Western Ra	ailway Headquarters offices Building	163
5.3	Intrinsic	other carved figures in Porbunder stone of griffins holding the BB&CI monogrammed shield were placed on the smaller gables. The central statue was commissioned from the studio of Roscoe Mullins of London togethe with two carved medallion portraits of Colonels French and Kennedy, the pioneers of the Company, which were placed in circular panels between the arches of the carriage porch on the west. Style The building shows evident influence of Indo Saracenic style of Architecture
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F, I(sce) Recommended grade:
		T
6.0 6.1	Floors	Topography G+2 with central and side domes higher than the rest of the structure
0.1	110015	
7.0		Construction
7.1	Plinth	Medium plinth about two ft high in grey rough dressed ashlar masonry.
7.2	Walls	Indeterminable
7.3	Floor	Indeterminable
7.4	Stairs	Indeterminable
7.5	Openings	Arched openings with wooden frame partly glazed panels with wooden louvers at bottom.
7.6	Roofing	Timber truss with Mangalore roofing tiles.
7.7	Articulation	Corinthian column capitals, dentils, quatrefoil openings etc.
7.8 7.9	Finishes Interiors (Movable & Immovable)	Externally grey ashlar masonry. Internal finishes indeterminable.
7.9		- Immovable -
7.10 7.11	Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/ Landscape	A stone compound wall with MS fencing atop. Indeterminable.
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable
9.0		Condition
9.1	Plinth	Fair - blackening of stone at places
9.2	Walls	Indeterminable
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Fair - At some places shutters have been replaced.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Fair – Damages to stone observed. Blackening of stone due to weathering.
9.8 9.9	Services Out Buildings	Indeterminable
9.9	Overall Conditions	Fair Maintenance level Good
5.10		
10.0		Transformation
	Form	No visible changes from outside
	Structure	No visible changes from outside
	Articulation & Finishes	No visible changes from outside
11.0		DP Remarks/ Perceived Threats
		Western Railway Headquarters, building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available Additional Notes: Frederick William Stevens designed the building on simple lines, with the total effect determined by the outline and massing. The building, with a length of 276 feet along the western façade and a central tower rising to 160 feet, has a facing of coursed blue basal stone with the domes, mouldings, capitals, columns, cornices and carved enrichments in

Vestern Railway Headquarters offices Building 16		
	Porbunder stone, white Kurla and Dhrangadhra red sandstone. Later, when these weathered badly, they were replaced with facsimiles in bronze, crafted by C Burns. The embellishments were prepared by Mr Gomez and students of the School of Art under the supervision of the Principal, Mr Greenwood. The contractors for the foundations were Gamajee Balajee and Company and those for the superstructure Jagooji Hanmantrao and Company. The coloured Maw's tiles, marble and coloured glasswork were executed by Sorabji Warden & Company while the contractors for the drainage and water supply and fittings were Richardson and Cruddas. The entire open ground both in front and behind the main building was laid out as a garden, separated from the road by ornamental railings and gates. The total cost of the building including drainage and water supply was exactly that estimated by Stevens – Rs 750,000. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House. RAHUL MEHROTRA and SHARADA DWIVEDI Anchoring A City Line – The History Of The Western Subarban Railway And Its Headquarters In Bombay: Eminence Designs Pvt. Ltd.	





Grey stone clad building with series of pointed arched openings on round Detail of the intricately carved frieze bands and spandrel columns with Corinthian capitals, frieze bands, carved spandrel, rose window



Arched opening on round columns with carved capitals, round openings, frieze bands



Central tower with receding floors, surmounted by a dome, carved balustrade, turrets, frieze and cornice bands



Cupola detail



Verandah arched openings on slender columns with stone balustrade



Arched opening with buff stone voussoirs, frieze bands



Gable end with rose window, animal statue finial, frieze band, cupolas



Animal feature detail at the finial

Chhatrapat	ti Shivaji Vastu Sangrahalaya (Prince of	Wales Museum)	164
		Common Ref No: 164	
		Card No: 222	3) in the line of
*		Ward (Part): A (Part IV)	22 Ann 24
Å		CS No: 33 (Fort Division)	HI BOOOD
		Plot Area: 24705.88 sq m.	DND TANK
		B U Area: -	
5 55		Date: 20/12/2004	AHA OBA
	A Serenmen B	Recorded by: Zankhana Prajapati	М
Ster and		Reviewed by:	CAMA ROAD
- me sm		III. Zalikilalla Frajapali, Sullai Wuuak	RG RG
S. LEANE		Ext: Zankhana Prajapati, Sonal Modak	
		Photo Ref: 164_Prince of Wales Museum.	A A A A A A A A A A A A A A A A A A A
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Chhatrapati Shivaji Vastu Sangrahalaya	
1.2	Earlier Name	Prince of Wales Museum	
1.3	Built in:	Foundation stone laid in 1905, designed in 1909,	Extension Date: 1938
		constructed in 1914 and opened to public in 1922.	
2.0	Mata	Access	
2.1	Main	Mahatma Gandhi Road.	
2.2	Subsidiary	K. Dubhash Marg.	
		O	
3.0		Ownership pattern	
3.1	Present	State Government	
3.2	Past	The Trustees of the Prince of Wales Museum of India	a and others.
3.3	Status	Owner/Tenant.	
4.0			
4.0		Use	
4.1	Present	Museum	
4.2	Past	During World War I, the building served as military ho	ospital and since 1922 is museum.
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	The building is situated on the crescent shaped site	in front of S.P. Mukheriee Chowk and
0.1	rownscape (maninade)	the National Gallery of Modern Art with Mahatma	
		road.	
		The main access to the building is from Mahatma G	andhi Road. The imposing presence of
		the building forms an important landmark of the city in	
5.2	Architectural Description	Planning	
0.2		The building is situated on crescent site with the rect	tangular building at the rear with longer
		façade along the Mahatma Gandhi Road.	angular bahang at the roar marienger
		The building is ground plus two storied high with the	central dome giving an additional floor
		height to the volume of the building. The building is n	
		Entrance of the building is from the center of the main	
		to an entrance lobby which houses reception, mus	
		adjacent to which is huge central atrium below the	
		floor and second floor level. On the left and right or	
		which house sculptural exhibits, flanked by Coor	
		exhibition area respectively. From atrium main sta	
		which is the Indian Pre and Proto History section	
		staircase. At the end of right side verandah one en	
		museum library and Natural history section. On	
		Miniature painting, decorative art, bronze, and office	
		area of painting, on right is exhibition gallery for N	
		building there is the Maritime history section and Pre	
		floor both left and right wings have collections of E	
		behind staircase and Arms and Armour exhibit at	
		terraces on second floor.	
		Features	
		It is a symmetrical building, with ends and center l	being emphasized by projecting bays
		The central bay is huge equivalent to four regular ba	
		six bays with the end bays projecting out.	
1			
I		The end bays are emphasized by having onion sha	aped dome arising from lotus leaf and

Chhatrapa	ti Shivaji Vastu Sangrahalaya (Prin	
		having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a
		projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening.
		The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch
		windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
		The central bay projects well ahead of end bays and having an entrance porch at the center which is formed of pendentive dome topped by <i>amlaka</i> and <i>kalash</i> , supported on Mughal arch openings and colonnette which is formed at the junction of two arches. Two intricately carved minarets mark the front of the porch. Central bay is further divided into three parts where the two flanking ones are identical and center bay is more ornate. The two side bays are slightly recessed from the central bay and are half the width of central bay. At the ground floor one sees small Mughal arch openings within rectangular buff stone frame; first floor has Rajput <i>jharokha</i> , second floor has <i>jalis</i> within Mughal arch openings above which
		Venetian dentil band is present and above which <i>chajjas</i> is supported on intricately carved decorative Gujarat style stone brackets. Above this a part terrace is formed in the third floor front side, which has high parapet with columns ending in onion shaped domes arising from lotus petals pilasters. The center portion at ground floor has a pendentive-domed porch, first floor has a series of three Mughal arch openings and second floor level and has a square base made of a series of Mughal arch openings over which the main central onion
		shaped dome arises from lotus petal. Surrounding the central dome there are series of minarets. The building uses different buff and blue basalt stone, Curla stone, limestone and gray stone. It has decorative column capitals inside and wooden galleries in central atrium. All
		the openings are largely Mughal arch openings but few at the rear are segmental arch openings. Style Ruiding represents influences of the Inde Screeping style
5.3	Intrinsic	Building represents influences of the Indo Saracenic style. The acquisition in 1915 of the collections of Sir Purshottam Mavji, the magnificent gift in 1921 by Sir Ratan Tata, and in 1933 by Sir Dorab Tata, of their valuable art collections, formed the nucleus of the museum's art section. The transfer of sculptures and coins of the defunct Poona Museum, of the collection of the Bombay Branch of Royal Asiatic society, consisting of valuable sculptures and epigraphs, and the co-operation between the board of trustees and the Bombay Natural History Society, helped in setting up the archaeological
		and Natural history sections. Currently it houses elite collection of sculptures from Gupta period, Mirpurkhas, Buddhist images, Aihole, Pauni, Pitalkhora, beside that varied collection from Indus Valley Civilization, best collection of paintings and illustrated manuscripts, Maritime heritage,
		Natural history has various habitat and species in display, vivid collection of decorative art in jade, wood, ivory, metal and other medium, fascinating panorama of the religious and artistic world of Nepal – Tibet, varied typology of Indian weaponry of which the main attraction is of Allauddin Khilji's <i>Khanda</i> and Akbar's cuirass with shield, has a major section on Far Eastern Art which has an iron snake of rare workmanship made by renowned Armour maker, Muni Yoshi, is today National Treasure of Japan, and exquisite
5.4	Value Classification	collection from early collectors of European oil paintings. A(arc), A(his), A(cul), B(per), B (des), B (uu), D(bio), E, F, Recommended grade I G(grp), I(sce), J
6.0		Topography
6.1	Floors	G + 2
7.0		Construction
7.1	Plinth	High gray stone plinth with buff basalt stone edging for plinth protection.
7.2	Walls	External wall is load bearing made of stone, buff and blue basalt stone and Curla stone ashlars masonry. Inside the walls are plastered and painted, some walls were paneled by wooden planks to avoid seepage.
7.3	Floor	In some areas timber flooring is observed, but largely, it is in RCC supported over beams and finished with tiling.
7.4	Stairs	Six staircases are present. Main staircase is made up of two L-shaped with common mid landing, secondary staircase is a C-shaped staircase with open well, has an elliptical staircase in annex building and

	ti Shivaji Vastu Sangrahalaya (Prince of Wa	
		spiral staircase for terrace.
		Primarily all staircases are made of stone with wooden handrail and baluster.
		The terrace spiral staircase is decorative in cast iron.
		On second floor wooden railing has lamppost placed at regular intervals.
7.5	Openings	All doors, windows and openings are Mughal arched openings but few are semicircula
		arched and rectangular openings.
		Many ventilators are present above and below of window and door, which are either don
		in <i>jali</i> work or glazed frame or mild steel grill.
		The windows are double, triple and fourth leaf with ventilators above and below the linter
		and sill respectively.
		All windows are glazed panels in wooden frame.
7.6	Roofing	The roof is a composition of domes, flat terraces, vaults, minarets and chatris. The dome
		covered with ceramic mosaic chips, pendentive vaulted arches support the domes an
		sloping roof above the side wings.
7.7	Articulation	All the features are in buff basalt stone especially carved stone brackets, jalis, Rajpu
		jharokas, onion shaped or bulbous dome arising from lotus petals seen in all minarets
		decorative cornice and corbels, floral motif and decorative column capital.
7.8	Finishes	External walls are in exposed stone ashlar masonry and many places have alternate bu
		and blue basalt masonry specifically observed in arches and certain areas in walls.
		Internal walls are plastered and painted.
		Flooring is varied from marble pattern flooring, wooden, china mosaic on terrace, kotah an
		ceramic tiles.
		Has false ceiling done in the entire exhibition and display area.
7.9	Interiors (Movable & Immovable)	Movable
1.9		
		Old furniture, panels, racks, display board, showcases, benches, artifacts, prehistor
		anthropological objects, weaponry, paintings, statuary, bronze gallery, ivory carvings, an
		all the other exhibits.
		Immovable
		Wooden columns and balusters, handrail, light fixtures.
7.10	Compound/ Fence/ Gate	The compound wall comprises of a stone wall over which a stone baluster and railing
		present over which cast iron grill work is present.
		Cast iron decorative entrance gate and side gates.
		Has carved stone gateposts.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Rear and side has open spaces.
	Landscape	Many outbuildings are present like two small sheds used as storage, fountain, pump roon
		entrance office, ticket counter, substation, guesthouse, residence building, Jehangir a
		gallery, Max Muller Bhavan, and chawl type houses.
		The site has a well-planned landscape layout with huge garden with a beautifully sculpte
		statue of King George V in naval uniform by George Wade fronting the museum. On the
		pedestal are bas-reliefs of the foundation stone laying ceremony and the reading of th
		address of welcome by members of the Municipal Corporation, weaponry, statues, fountai
		and carved stone relief work. Presence of many old trees which forms the main feature of
		the garden and site.
80		Services & Utilities
8.0 8.1	Lighting	Services & Utilities
8.0 8.1	Lighting	Adequate Natural light through door-window openings supplemented by electric light
8.1		Adequate Natural light through door-window openings supplemented by electric light fixtures.
	Lighting Ventilation	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fam
8.1 8.2	Ventilation	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning.
8.1 8.2 8.3	Ventilation	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST
8.1 8.2 8.3 8.4	Ventilation Electricity Water Supply	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM
8.1 8.2 8.3	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation)	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM
8.1 8.2 8.3 8.4	Ventilation Electricity Water Supply	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM
8.1 8.2 8.3 8.4 8.5	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation)	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST MCGM MCGM
8.1 8.2 8.3 8.4 8.5 8.6	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers.
8.1 8.2 8.3 8.4 8.5 8.6 8.7	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution	Adequate Natural light through door-window openings supplemented by electric ligh fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems)	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition
8.1 8.2 8.3 8.4 8.5 8.6 8.7	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution	Adequate Natural light through door-window openings supplemented by electric ligh fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems)	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems)	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3 9.4	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase completely painted.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase completely painted. Fair - Windows been closed by planks, addition of grills, pattern change at certain area
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3 9.4	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs	Adequate Natural light through door-window openings supplemented by electric ligitistures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase completely painted. Fair - Windows been closed by planks, addition of grills, pattern change at certain area unpolished AC units, window panes cracked, and broken painted frames.
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3 9.4	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs	Adequate Natural light through door-window openings supplemented by electric ligh fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase i completely painted. Fair - Windows been closed by planks, addition of grills, pattern change at certain area
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3 9.4 9.5	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings	Adequate Natural light through door-window openings supplemented by electric light fixtures. Adequate Natural ventilation through door-window openings supplemented by electric far and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Covered with planter boxes, stone blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase completely painted. Fair - Windows been closed by planks, addition of grills, pattern change at certain area unpolished AC units, window panes cracked, and broken painted frames. Fair - Cracks in the vaulted dome of ground floor in porch, main dome has seepage
8.1 8.2 8.3 8.4 8.5 8.6 8.7 9.0 9.1 9.2 9.3 9.4 9.5	Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings	Adequate Natural light through door-window openings supplemented by electric ligh fixtures. Adequate Natural ventilation through door-window openings supplemented by electric fan and air conditioning. BEST MCGM MCGM Presence of fire extinguishers. Window AC units. Condition Fair - Covered with planter boxes, stone blackened, moss growth, plant growth, broke edge and cracked stone. Fair - Cement pointing, dust accumulation, blackened stone, moss growth, arched broke at certain places, bird droppings, plant growth, cracks in stone and wall. Good - Cracks are present, dampening of floors through seepage. Good - Cement pointing, painted cast iron baluster, handrail unpolished, spiral staircase i completely painted. Fair - Windows been closed by planks, addition of grills, pattern change at certain area unpolished AC units, window panes cracked, and broken painted frames.

MMR- Heritage Conservation Society

Chhatrapa	ti Shivaji Vastu Sangrahalaya (Prin	
		stone at many places, moss and plant growth dust accumulation and bands broken due to
		service pipes.
9.8	Services	Fair - Regular maintenance is done, overall in fair condition.
9.9	Out Buildings	Poor - Sheds are neglected.
9.10	Overall Conditions	Good. Maintenance level: Fair.
0.10		
10.0		Transformation
10.0	Form	Addition of annex wing.
		0
	Structure	Addition of I-section in ground floor to strengthened the structural system.
	Articulation & Finishes	Painted internal arches and domes.
11.0		DP Remarks/ Perceived Threats
		Recreation ground, Museum and Art gallery, plot forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		The seed of this museum were sown in 1892 resolution adopted by the government of India
		for promotion of trade and industries, but in 1894, Lord Harris had referred to this resolution
		in opening address at Bombay Fine Art Exhibition. The idea remained dormant till 1904
		meanwhile a representative committee was set up for the purpose. Its principal
		recommendation was to set up museum with an educational bias combined with a public
		reading room and a library. The 'Crescent Site' was recommended as an ideal site fo
		locating the Museum. The idea got impetus in 1905, when the people of Bombay decided
		to commemorate the visit of the Prince of Wales of England by setting up a Museum.
		During WWII the museum was threatened the safety of the museum exhibits, and thus the
		major collection had to be removed out of the museum and away of Bombay. Subsequently
		in 1946, the task of resetting the galleries was taken up.
		Designed by George Wittet in the Indo-Sarasenic style, the Museum is situated in a vas
		crescent-shaped compound with beautiful gardens. Yellow and blue basalt stone quarrier
		in the Bombay region has been extensively but sensitively used in the building. The Prince
		of Wales laid the foundation stone in 1905 during his first visit to the city and the building
		was completed in 1914. During World War I the Museum was used as a military hospita
		and was formally opened by Lady Lloyd, the Governor's wife, only in 1923. The dome
		bears a striking resemblance to that of the Gol Gumbuz at Bijapur. Elements of traditiona
		architecture have been blended extensively and aesthetically in the facade, including small
		bulbous cupolas on the towers, jalis used as infills for the Saracenic arches, Rajput style
		jharokas, brackets of Hindu temples and semi open veranda spaces incorporated in
		response to the climate. In short, the building is an assembly of elements from diverse
		sources. In 1936, an extension new wing designed by Gregson, Batley & King was added
		to house an amazing collection of exhibits of Natural History.
		The contents of the Museum form a crucial part of the city's cultural heritage. A large
		portion of the Art collection was a gift of Sir Ratan Tata, comprising paintings, Orienta
		arms, a unique collection of jade, china and porcelain, Indian silver and bronzes and othe
		objets d'art. Sir Dorab Tata also presented to the Museum a collection of paintings, statuar
		and a collection of Mughal miniatures and several Maratha relics. The Museum also house
		a fine collection of Rajput miniature paintings. A recent addition has been the collection of
		the legal luminary, Karl Khandalawala who was a Trustee of the Museum for several years
		In the gardens can be seen a variety of Oriental bronze sculptures. There is a beautifull
		sculpted statue of King George V in naval uniform by George Wade fronting the museum
		On the pedestal are bas-reliefs of the foundation stone laying ceremony and the reading of
		the address of welcome by members of the Municipal Corporation.
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :
		Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence
		Designs Pvt. Ltd.
		ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai,
		Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House.
		SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.
	1	

Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum)



Grey stone clad building with buff stone pointed arches, central bay surmounted by large dome, intricately carved brackets



Residential quarters



Annex building with verandah with pointed arched openings



Jharokha detail with intricately carved brackets supporting balcony, columns with carved capitals, arched ventilator jail work



Front huge setback with landscaped gardens, paved pathways, statues etc



Rear of Jehangir Art Gallery with an ancillary structure



Arched window opening detail with glazed paneled shutters



Porch with arched roof profile, pointed arched opening with alternate buff and grey stone voussoirs, corner turrets

Urban Design Research Institute

MMR- Heritage Conservation Society



Gujrat architecture style intricately carved brackets in buff stone



Detail of cupola



Central space with large dome with arched openings, bands with an overlooking gallery



Verandah with arched openings with alternate grey and buff stone voussoirs, exhibits displayed, seating arrangement



Staircase with carved wooden railing



Stone gate post with carvings at the base and capital



Window



Main entrance with arched openings on round columns with carved capitals

Urban Design Research Institute

MMR- Heritage Conservation Society

Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum)



Interior view with double height space with curved ceiling, overlooking gallery.



Column with carved base in geometric pattern



Wooden paneling with Gujrat style ornamentation overlooking the central space



Stone staircase with carved railing



Floral pattern column capital



Column with carved capital in geometric pattern



Main central lobby with overlooking galleries with arched openings, wooden railings



Internal column detail with highly ornamented carvings

Elphinstone C	College	165
	•	Common Ref No: 165
		Card No: 223
1.9%		Ward (Part): A (Part III)
13		CS No: 144 (Fort Division)
1		Plot Area: Indeterminable
Alle Charles	AT I STATE TOUT I STATE	B U Area: - Date: 04/01/2005
	ALL AL ALL MAN MINIMUM	Recorded by: Arun Wadhwa
	A PAR Set	Reviewed by:
and the second second		
		Int: Arun Wadhwa, Prachi Merchant Ext: Arun Wadhwa, Prachi Merchant
		Photo Ref: 165_Elphinstone College.
1.0		Denomination
1.1	Name of Premises	Elphinstone College
1.2	Earlier Name	Cowasjee Jehangir Readymoney building for Elphinstone College.
1.3	Built in:	1889 Extension Date: -
2.0	Maia	Access
2.1	Main	Mahatma Gandhi Road (not used) – vehicular and pedestrian
2.2	Subsidiary	David Sasson Library Marg - vehicular and pedestrian
3.0		Ownership pattern
3.1	Present	Government of Maharashtra (B. Sc. I.T. Department.)
3.2	Past	Government of Bombay.
3.3	Status	Owner
4.0		Use
4.1	Present	Degree College and Department of Archives.
4.2	Past	Government Central press and State records.
4.3	Usage	Daily.
5.0		Significance & Value Classification
5.1	Townscape (manmade)	Landmark building close to the historic Kala Ghoda square alongside important institutional buildings with a mandatory pedestrian arcade along the road front forming one of the most important avenues within the Fort area.
5.2	Architectural Description	Planning Rectangular building with a central open quadrangle around which continuous verandah passages provide access to all rooms arranged around it. Main entrance from the arcaded east side leads to a spacious entrance lobby leading to wide stone stair. Subsidiary staircases are also provided in the three corners except the northeast. East front also has narrow veranda bays on upper two floors above the pedestrian arcade. Ground and west side of first floor is occupied by Department of Archives to serve as storage facilities. Rest of the first, second and upper floors are occupied by the college. Administrative areas and classrooms are located on first floor whereas library, teacher's room, cultural hall and laboratories are all located in the pitched roofed second floor. Grand spaces in the part third and fourth floor were planned to be Principal's residence but presently lie vacant. It is connected to an annex building to the west side through a bridge at second floor. Features Well-composed long symmetrical front façade with the high central portion topped by a steep pyramidal roof. Raised central and edge portions are marked by decorative stone spires at all the four corners. Pedimented central porch has the carved head of Sir Cowasjee Jehangir above the ornamentally treated front arch. Entire long façade is marked by alternate red and Porbunder stone arch openings, semicircular on ground arcade level and pointed arch on upper two floors. Central Arch openings are supported on finely carved capitals with floral and animal motifs. Finely carved stone relief cornice band at the second floor level. Projecting stone balconies with decorative brackets and stone relief parapet at both ends of the front façade. Highly omate iron railing in staircase parapet. Style The building displays Victorian Gothic style features.
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, I(sce) Recommended grade
6.0		Topography
6.1	Floors	G + 2 and part third and fourth floor.
7.0		Construction
7.1	Plinth	Low Plinth height about 0.3 m. dressed in Malad stone ashlar course.
7.2	Walls	Load bearing rubble stone masonry walls supported on steel girders, brick load bearing
L		walls on the third and fourth part floor.

Elphinston		165	
7.3	Floor	Shahabad stone slabs on wooden supports & heavy steel girders support large floor spans.	
7.4	Stairs	Overall four staircases. Central C- shaped stone stair supported on decorative brackets Two of the corner stairs are steel C- shaped with decorative railing and wooden handrail.	
7.5	Openings	Semis circular and pointed arch openings on the front and rear facades, also tracery within arch portions.	
7.6	Roofing	Sloping Mangalore tile roof on the three sides and steep pyramidal sloping roof supported on slender steel trusses. Central portion is also steep pyramidal roof.	
7.7	Articulation	High central bay with a projecting porch and stone spires at all the four corners and a semicircular projecting balcony with large ornamental corbel feature; intricately carved frieze band at the second floor level of the long façade; projecting balcony and supporting corbels, alternate buff and porbunder stone arches supported on richly carved capitals and circular columns. Stone parapet with trefoil and quatrefoil opening feature.	
7.8	Finishes	Buff basalt stone dressed external wall finishes and grey basalt stone in verandah walls and soft Porbunder stone for ornamental features. Brick faced arches in inner verandahs Plastered painted internal wall surfaces. Minton floor tiling in ground floor and wooder floorboard finishing on upper floors.	
7.9	Interiors (Movable & Immovable)	Movable Carved wooden furniture – benches and wall paneling have decorative value. Portraits of Dadabhai Nowroji present Immovable Original wooden partition panels and furniture some embellished with relief work.	
7.10	Compound/ Fence/ Gate	North and south sides have chain link fencing whereas the east front abuts the road and west side has ancillary structure forming compound boundary. Iron railing and gate, recently installed fences in the open front arcade but seems very incongruous to the open nature of arcade. Gate to the north side forms the main entry.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved quadrangle inside the building is the hub of college activities. Second floor bridge connects to the west side annex building in the Old Secretariat compound. Also a water tank and small pump room along with watchman's cabin in the north side open space.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light also relying on artificial light.	
8.2	Ventilation	Adequate natural ventilation also relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM - Underground and overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	Fire extinguishers only.	
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.	
9.0		Condition	
9.1	Plinth	Fair, except the rear and side facades.	
9.2	Walls	Fair, except some damp patches due to seepage.	
9.3	Floor	Fair, up to second floor; poor neglected and vandalized third and fourth floor.	
9.4	Stairs	Fair, except wear and tear.	
9.5	Openings	Fair, except neglected and vandalized openings on third and fourth floor.	
9.6	Roofing	Fair, roof over second floor under repair; neglected and vandalized roof over fourth floor.	
9.7	Articulation & Finishes	Fair, front façade and internal finishes, dilapidated rear and side facades.	
9.8	Services	Fair, with minor repairs required.	
9.9	Out Buildings	Poor, dilapidated and damaged NCC building.	
9.10	Overall Conditions	Fair, except neglected third and fourth floor, Maintenance level: Fair except abandoned and rear Western facade. third and fourth floors.	
10.0		Transformation	
	Form	Small G+1 classroom extension to the south side of internal courtyard. Connecting bridge at second floor rear side to the annex building.	
	Structure	Inner wooden verandas seem to be reconstructed in concrete.	
	Articulation & Finishes	•	
11.0		DP Remarks/ Perceived Threats	
11.0		College, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available Additional Notes: The Elphinstone College is named after Mount Stuart Elphinstone, a former Governor of Bombay who championed the cause of education. Marble tablet at the spacious entrance lobby records the commencement of building giving details: Architect Khan Bahadur M. C. Murzbhan. Cost Rs. 7,41,497/-	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd.	

Elphinstone College	165
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminence Designs Pvt. Ltd.
	ABHA NARAIN LAMBAH <i>Through the Looking Glass</i> – <i>The Grade I Heritage of Mumbai</i> , Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House.
	<i>Buildings of the Kalaghoda Art District</i> , (2000) Marg Publications, Max Mueller Bhavan Bombay, Urban Design Research Institute.
	SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.



Buff stone clad symmetrical building with central imposing wing and corner bays with sloping roof



Central bay balcony detail with intricately carved receding ornamentation, frieze with geometric and floral pattern, jail work, arched opening with motif at the springing joint, brackets etc



Arch opening with buff and white painted stone voussoirs, animal motif at the springing point, round columns in red stone with floral pattern capital



Projecting balcony with carved brackets, carved jaliwork in balustrade



Series of pointed arched openings with fixed ventilator panel, glazed wooden paneled shutters, stone balustrade, carved spandrel



Arcade with arched openings on round columns with carved capital, round floral motifs etc

Elphinstone College



Entrance with arched opening, frieze band, carved spandrel, corner turrets, first floor terrace balustrade



Column with floral pattern capital




Carved cast iron brackets



Window with detail jaliwork



Central balustrade detail with a marble bust with jaliwork in geometric pattern above, finial etc of the entrance porch



Ornamentation in the spandrel with intricately carved floral and animal motif pattern



Internal courtyard with building verandah opening in it



Marble plaque with building foundation details

Elphinstone College







Arched door opening with glazed louvered double shutter



Frieze detail in stone



Staircase with cast iron railing

Main entrance door opening with carved paneled wooden shutters



Column with intricately carved capital in floral pattern



Frieze detail with floral pattern

David Saso	oon Library and Reading Room		166
		Common Ref No: 166	and an an an
	4	Card No: 224	
		Ward (Part): A (Part III)	1876 No.
		CS No: 145	
		Plot Area: 2240.81 sqm.	Testa Testa
i		B U Area: -	
Ami		Date: 02/11/04	
	descent and the second s	Recorded by: Prachi Merchant	
	AAA AAA AAA SAN	Reviewed by:	
		Int: Arun Wadhwa, Prachi Merchant	
÷.		Ext: Arun Wadhwa, Prachi Merchant	
	Strate All States	Photo Ref.: 166_David_sasoon_library	- Reading Storm
			HOPE STREET
			Location Plan
1.0		Denomination	
1.1	Name of Premises	David Sasoon Library and Reading Room	
1.2	Earlier Name	The Sasoon Mechanic's Institute/ The David	Sasoon Mechanic's Institute and Library
1.3	Built in:	Construction of building in 1867, Completed	in 1870 Extension Date: -
			• · · ·
2.0		Access	
2.1	Main	Mahatma Gandhi Road	
2.2	Subsidiary	Library Marg	
3.0		Ownership pattern	
3.1	Present	Trust	
3.2	Past	Trust	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Library and Reading room, Commercial sho	ps on the street front
4.2	Past	Library and Reading room	
4.3	Usage	Institutional, Library, and Commercial shops	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	One of the first Library buildings planned on	the Esplanade.
		It forms a part of well-integrated buildings ha	aving an extended porch and an arcade, along
		the Kalaghoda precinct	
		The series of buildings form an interesting v	ista and skyline.
5.2	Architectural Description	Planning	
			r side facing the main road. The building opens
		into a garden at the rear.	
		· · · · ·	al foyer with a corridor leading to the main hall
		with administrative offices and toilets on eith	
		The garden serves as a relaxing and readin	g area for the library members.
			ire rooms are on the mid and first floor levels.
		Features	
		The building is clad in coarse buff colored b	
		Façade elements consist of black stone colu	1 1 0 0
			a, black and white bands over arched openings,
			on balustrade, delicate spires, rose windows,
		circular trefoil glazed openings, pediments,	
		Gothic arched openings with the black and	
		gable roof over the imposing porch and the	clock tower with spires, forms a distinctive
		character of the building.	
		Style The building derives influences from Venetia	an Gathia stula
5.3	Intrinsic		an oound style.
5.3 5.4	Value Classification	A(arc), B(des), B(uu), E, F, I(sce)	Recommended
U.T		, (aro), b(aco), b(au), c, 1, (occ)	grade
			J
6.0		Topography	
6.0 6.1	Floors	Topography G+1 with a mezzanine floor, clock tower rise	es from the terrace level.
6.0 6.1	Floors	Topography G+1 with a mezzanine floor, clock tower rise	es from the terrace level.
	Floors		es from the terrace level.
6.1	Floors Plinth	G+1 with a mezzanine floor, clock tower rise Construction	
6.1 7.0		G+1 with a mezzanine floor, clock tower rise	

David Sas	oon Library and Reading Room	160
		Terrace slab is an RCC beam structure with IPS waterproof finishing. Vaulted floor over reading room in the verandah.
7.4	Stairs	Main open well staircase with stone risers and treads and cast iron balustrade with floral
		pattern and teakwood handrail. Narrow spiral staircase from the verandah to the terrace with risers, treads and railing in
		wood.
		A teakwood steep ladder leading from terrace to the clock tower.
7.5	Openings	Doors and Openings
		The main porch is a gothic pointed arch opening with trefoil and tracery work. The arch
		springs from Corinthian capitals. The arch is extended into a pediment with a pinnacle above.
		The grand main entrance wooden doors have single panel double shutters with a post box
		integrated in the shutter, loose stone stoppers. The ventilator of the door is an intricate
		tracery work of cast iron painted in black and gold.
		The administrative room doors have thick wooden frames of the wall thickness, with double
		paneled double leaf wooden shutters. Terrace doors are teakwood, flushed doors with an arched ventilator opening above.
		The reading room door openings are in the form of pointed arch, with radiating type stained
		glass fixed in the ventilators above. The double leaf double paneled wooden folding
		louvered shutter doors are fixed to a wooden frame.
		A row of arched openings in the verandah run through the entire width of the building. The
		spring from polished slender black column with Corinthian capitals.
		The internal arches in the verandah are joined to the array of smaller similar arched openings by the capital band.
		Windows
		Mid-landing consist of French windows with the height divided into two parts. The upper
		and lower part are wooden paneled double shutter, with the lower shutters protected with
		cast iron railing.
		The small independent reading room windows have long French windows, with the height divided into two parts. The outside upper and lower windows are wooden paneled double
		shutter. The upper inside shutters are double shutter hinged louvered shutters. The lower
		shutters are protected with cast iron railing.
		Windows at the main reading room entrance have wooden openable glazed shutters with
		grills inside.
		Windows along the longer sides of the reading room have full height arch shaped wooden long glazed openable sash window shutters with teakwood transoms on the outside and
		teakwood louvered shutters on the inside.
		Main reading room consists of ventilators above windows with radiating wooden members
		and coloured glass panels.
		Windows along the smaller sides of the reading room consist of long French windows with glazed openable shutters.
		Terrace consists of arch shaped wooden glazed openable sash window shutter with
		circular glazed fixed ventilator.
7.6	Roofing	Main staircase block has a unique wooden collar braced roof with teakwood planks and
		framing members.
		Pitched Mangalore tiled roof over administrative block.
		RCC slab and beam structure over main library hall. Verandah has wooden planks roof cladding over concrete slab in the center and vaulted
		concrete and steel section roofing over side sections.
		Clock room has Mangalore tile roof with wooden framework below.
7.7	Articulation	Coursed buff basalt stone cladding with alternate black and white stone bands along the
		arched openings forms the main feature of the building. Bands of alternate black and white
7.8	Finishes	limestone over arch openings Walls are finished with coarse buff basalt with thin mortar pointing externally, and plastered
1.0	T manes	and painted internally.
		Minton tile having different patterns segregate each area.
		Wooden flooring in independent reading rooms and with teak wood joists and rafters in
		clock tower.
7.9	Interiors (Moyable & Immeyable)	Verandah and mezzanine floor have cast iron railing with floral pattern. Movable
1.9	Interiors (Movable & Immovable)	Large teak wood reading tables, a grand reception table, librarian's table and other working
		table form furniture having antiquity value along with wooden chairs, chaises and benches.
		A clock along with various photo frames adorns the interior.
		Donors list exhibited at the entrance foyer.
		Marble plaque at the library entrance.
		Statue of David Sassoon in the entrance lobby. A marble sculpture on granite pedestal of James Berkley has been installed in the mid-
		anding of the staircase.
		Another marble plaque has been installed at the entrance of the main reading room stating
	1	the fund provider, earlier purpose of the library, its cost, and year of completion.

David Saso	on Library and Reading Room	16
		Immovable
		Wooden paneling within the entrance foyer.
7.10	Compound/ Fence/ Gate	Compound wall on two sides, upto 2'-0", with fencing and chain link above.
		Narrow alley between David Sassoon Library and Army Navy Building, which is not in use.
		Original iron-gate on the rear side.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Garden serves as a reading area.
	Landscape	Old trees in the garden create an ambience for reading.
		Paved pathways, benches, tables, lampposts, form a part of the landscaped garden.
8.0		Services & Utilities
8.1	Lighting	Adequate natural daylight through long openable windows from the verandah of first floor
		and garden area.
		Adequate artificial lighting through electrical light fixtures such as old chandeliers in the
		lobby area, and suspended tube lights in the reading room.
8.2	Ventilation	Verandah, long windows, doors act as the natural ventilation.
0.2		Electrical fans have been suspended from high ceiling.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Sprinkler system has been installed in the main library and reading room.
		Sphinkler system has been installed in the main library and reading room.
8.7	Other (HVAC/BMS/Security Systems)	-
		Assultant and a second s
9.0	D# //	Condition
9.1	Plinth	Fair – organic growth on the rear side of the building on the garden side.
		Chipping of stone on the rear side.
9.2	Walls	Fair - Loose plaster at few places.
		Dampness on walls of the clock tower and mezzanine area.
		Absence of maintenance of walls of terrace and clock tower.
9.3	Floor	Fair – deteriorated in the main reading hall.
9.4	Stairs	Fair - few railing and handrail parts of the main staircase have been replaced.
9.5	Openings	Fair - at certain places window ventilator glass has been replaced, grills have been added.
9.6	Roofing	Roof is in a fairly good condition with few broken Mangalore tiles.
9.7	Articulation & Finishes	Fair - low maintenance of the cladding on the rear side of the building.
9.8	Services	Fair - The ducting of new electrical wires, plumbing pipes have caused considerable
5.0	Services	damage, water cooler has been insensitively installed in the verandah reading area.
		The drainage gutter at the verandah reading room level has been used as the electrical
		channel.
9.9	Out Duildings	
	Out Buildings	Fair - low maintenance in comparison to the main building.
9.10	Overall Conditions	Fair Maintenance level Fair
40.0		Transformation
10.0	F erry	Transformation
	Form	A shed housing the canteen has been added in the corner of the rear garden, abutting the
		compound wall.
		Toilets have been added in the space below the main staircase, with punctures made in the
		walls for ventilation.
		Asbestos sheet <i>chajjas</i> have been used to serve as weather shading devices for the
		ventilators.
	Structure	No major changes in the structure have taken place.
	Articulation & Finishes	Painting has been done over the external and internal stone cladding, columns and all
		decorative front façade and verandah elements.
		Door shutters at the terrace and clock tower area have been changed.
11.0		DP Remarks/ Perceived Threats
		Library and RG, building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
12.0		Auditional Notes/ References/ Documents available

David Sasoon Library and Reading Room



Coarsed buff basalt stone clad building central clock tower with corner turrets, gable end housing the clock, pinnacles, arched openings



Entrance porch with trifoil arch, carved bands, columns with accoplement with carved capitals



Wooden spiral staircase leading to the Clock Tower



Verandah reading area overlooking the road side, with old furniture




Entrance Door with carved ventilator jail work



Marble bust







Vaulted ceiling with floral pattern at the joint of groins



Tablet with foundation details



Marble statue of David Sassoon at the entrance lobby

Armv and	Navy Building		167
		Common Ref No: 167	
		Card No: 225	
		Ward (Part): A (Part III)	A. S. D'MELLO ROAD
- 1		CS No: 146	
- ALLER AND	in the sale is a second second	Plot Area: 1861.21 B U Area: -	147
		Date: 10/11/2004	
		Recorded by: Arun Wadhwa	
		Reviewed by:	
	The second section (second	Int: Arun Wadhwa, Zankhana Prajapati	
		Ext: Arun Wadhwa, Zankhana Prajapati	
VOVO		Photo Ref.: 167_Army and Navy building	W W W W W W W W W W W W W W
			Location plan
1.0		Denomination	
1.1	Name of Premises	Army and Navy Building	
1.2	Earlier Name	Army and Navy Store.	
1.3	Built in:	Commenced 1897, Completed 1904.	Extension Date: -
2.0		Access	
2.1	Main	Mahatma Gandhi Road – Vehicular and pede	strian
2.2	Subsidiary	A. S. D' Mello Road. – Service entry.	
3.0		Ownership pattern	
3.1	Present	Private, owned by Tata Sons.	
3.2	Past	Private, Army Navy store	
3.3	Status	Ownership with multi tenanted premises.	
4.0		Use	
4.1	Present	Departmental store on ground floor, several p	rivate offices and Department of Fisheries
		located on the higher floors	····
4.2	Past	Exclusive Departmental store selling naval me	erchandise.
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	Prominent building along a row of buildings fa	cing Kala Ghoda square. Accessed from east
0.1		side front façade and also subsidiary entry fro	m west side narrow lane. Conceived as a
		unifying street façade and continuous pedestr	ian arcade with adjoining buildings in the
		prominent intersection of Kala Ghoda.	
5.2	Architectural Description	Planning	
		The building occupies the entire plot leaving n	
		departmental store. The structure is supported	o the North. Probably conceived as open plan
		The building originally had a central courtyard	
			ies up to the street line with the central portion
		forming a projecting porch. Staircases are pla	
		building. The rear side has two entries at eithe	er end meant to serve as service as well as
		subsidiary access. The top floor cantilevers or	ut beyond the building line on the rear side
		and is supported on decorative brackets.	
		Features	ich ornamontal features and tarred by a
		Symmetrical stone dressed front façade with r distinct pediment feature. Projecting central ba	
		Various decorative elements like arched open	
		stone balustrades.	
		Style	
		Neo Classical with rich ornamentation on the	
5.3	Intrinsic	Amongst the earliest buildings to have an RCI Amongst the earliest to have a basement. Stru innovative construction technique.	
5.4	Value Classification	A(arc), B(per), B (des), E, F, I(sce)	Recommended grade: II A
6.0		Topography	
6.1	Floors	G + 3 upper floors with partial mezzanine to the	
		Mezzanines have been added. Presence of a considerable height from the terrace level	n elevated overhead water tank at a

7.0	Navy Building	Construction 167
7.1	Plinth	The plinth rises unto two feet, constructed in dressed buff basalt. The two side facades are
7.1	1 11/101	constructed in rough black basalt.
7.2	Walls	A large portion of the building has a basement. External load bearing brick walls with local sandstone ashlar masonry and lime plastered
1.2	waiis	internally.
		The front façade is in dressed buff basalt and light colored, porbander stone forming the projecting features and ornamentation.
		The side and rear walls are in black basalt with light colored porbander stone for projecting features.
7.3	Floor	The floors are constructed in RCC, one of the earliest examples of this type of construction,
7.4	Stairs	supported on steel girders. The girders rest on round plain cast iron columns. Both the staircases are open well, constructed in stone slab supported (cantilevered) from
		the load bearing walls. Wooden members strengthen it from below. The side to the open well has wooden handrail and decorative iron railing.
7.5	Openings	•
7.6	Roofing	Series of pitched roof supported on teakwood trusses and covered with mangalore tiles. The central portion has an asbestos cement sheet roof being a later addition.
7.7	Articulation	The detailing has been sculpted on stone and finished with plaster
7.8	Finishes	Dressed buff basalt and soft porbander stone as projecting features form the exterior
		finishing to the front façade. Two sides and rear façade are in black basalt along with plastered surfaces. Internally the
		surfaces are plastered and painted. Extensive modifications have led to various different kind of paint and texture finishes.
7.9	Interiors (Movable & Immovable)	Movable:
1.5		
		Immovable: Multiple decorative cast iron objects e.g. spiral staircase, brackets, etc.
7.10	Compound/ Fence/ Gate	External wall of the building forms the compound on the front and rear side.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	The sides along the north and south have low stone compound with iron railing above.
1.11	Landscape	-
8.0		Services & Utilities
8.1	Lighting	Large door and window openings provide ample daylight, certain portion of corridor and staircase seems inadequately lit, supplemented with electric lighting.
8.2	Ventilation	Natural ventilation through large windows, forced ventilation using air conditioners. Internal passages are inadequately lit.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Absence of integrated fire fighting system though individual tenanted offices have installed smoke detectors, fire alarms, etc.
8.7	Other (HVAC/BMS/Security Systems)	Presence of central air-conditioning system for the departmental store at the ground floor. Several offices have installed window and split unit air-conditioners. Absence of integrated security system for the whole building. Installation of the air conditioning plant on the terrace of the first floor.
		• · · · ·
9.0	Diath	Condition
9.1 9.2	Plinth Walls	Fair- Presence of plant growth and weathering action lead to deterioration of stone courses. Fair - The north side along Watson's Hotel is dilapidated and lacking maintenance. Water seepage present in some portion in the staircase. Internal partition walls accommodate exposed services in an unplanned and incongruous manner. Plant growth and damage to
9.3	Floor	plaster at a few places on the side and rear façade. Fair - The floor seems to be stable in most places, except the mezzanines.
		Varied floor finishes like ceramic, mosaic, and granite in tenanted premises.
9.4	Stairs	Fair - Rear staircase has some balusters missing, damaged and lacks maintenance.
9.5	Openings	Fair - Several alterations to window and door openings observed. Openable window shutters have been replaced with fixed glazed panels. Full height glass doors in place of wooden paneled shutters. Some window openings are damaged with missing panes and broken shutters on the side and rear facades.
9.6	Roofing	Fair - Mangalore tile roof is quite old and prone to water seepage. Though asphalt layer has
9.7	Articulation & Finishes	been laid at many places still inadequate to protect from heavy lashes of monsoon rains. Fair - The stone finish seems uneven and blackish in appearance as a result of weathering and ficus growth.
9.8	Services	Fair - Services are exposed in many places and are planned in an incongruous manner.
9.9	Out Buildings	Fair - At the rear side extended portion houses toilet block and air conditioning equipments.

Army and N	Army and Navy Building		
9.10	Overall Conditions	Fair	Maintenance level: Fair
10.0		Transformation	
	Form	No change	
	Structure	Mezzanine floors have bee was closed during major re	en added. The building originally had a central courtyard, which enovation work in 1950's
	Articulation & Finishes	Detailing has been insensi	tively painted.
11.0		DP Remarks/ Perceived	Threats
		Building forms part of C1 z	one
12.0		Additional Notes/ Reference	nces/ Documents available
		Civil Engineers <u>References:</u> INTACH (1990) Preliminary Structures listed for Conse RAHUL MEHROTRA, GUI in Bombay – Conserving a FRANCIS D.K.CHING and Division of International Th SHARADA DWIVEDI and Designs Pvt. Ltd.	VTER NEST and SANDHYA SAVANT (1994) <i>The Fort Precinct</i> <i>n Image Centre</i> , 2 Vols, Bombay. VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> ,



Buff stone clad building with white painted features inclusive of arched opening, ornamentation, balconies etc



Carved bracket supporting the ceiling





Projecting balcony with intricately carved brackets, motifs, balustrade, dentil bands



Arched arcade

MMR- Heritage Conservation Society



Grey stone clad rear façade with rectangular openings, projecting topmost floor supported on brackets



Column with floral pattern capital



Staircase with cast iron and wooden railing



Stone vault ceiling

Esplanade	Mansion (Watson's Esplanade Hotel)	168
		Common Ref No: 168
		Card No: 226
		Ward (Part): A (Part III) A.S.Demello Road
-		CS No: 147
		Plot Area: 1240.80 sqm.
The last		B U Area: - Date: 17/11/2004 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Zankhana Prajapati
		Recorded by: Arun Wadhwa
		Reviewed by:
		Int: Arun Wadhwa, Zankhana Prajapati
1		Ext: Arun Wadhwa, Zankhana Prajapati
		Photo Ref.: 168_Watson's Hotel
		Location plan
1.0	News (Develop	Denomination
1.1	Name of Premises	Esplanade Mansion
1.2	Earlier Name Built in:	Watson's Esplanade Hotel (Mahendra Mansion) Commenced 1867 in and completed 1869 Extension Date: -
1.3		Commenced 1807 In and completed 1809 Extension Date
2.0		Access
2.1	Main	University Road
2.2	Subsidiary	Mahatma Gandhi Road
	, ,	
3.0		Ownership pattern
3.1	Present	Sadiq Ali - Private
3.2	Past	Built by Mr. John Watson, wealthy city draper, later owned by Tatas for a brief period.
3.3	Status	Ownership with multi tenanted premises.
4.0		
4.0 4.1	Present	Use Shops, Offices, and institutional organizations.
4.1	Past	Large luxury hotel, first of its kind in Bombay
4.3	Usage	Daily
4.0		
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Landmark corner building facing the Kala Ghoda square at the intersection of Mahatma
		Gandhi road with university road.
		Accessed from the north side entrance through a high arcaded front, forms part of the
		continuous arcaded street front along with adjoining buildings in the Kala Ghoda precinct as per the urban design regulations laid by City improvement trust.
5.2	Architectural Description	Planning
0.2		The Building stands on a corner plot, with its east and north elevations facing the roads.
		The Internal layout included a provision for 130 rooms, a grand central atrium around which
		were placed the dining rooms and shops, and a colonnaded ground floor.
		The atrium once opened out onto a garden on the south – the present site of Army and
		Navy building. The present building accommodates numerous subdivision and accretions within and
		outside the main building.
		Features
		The building reflects strong structural grid in the external facades, exposing the vertical
		lines of the cast iron columns and the horizontal bands of the balustrades at each level.
		Decorative cast iron balusters and railings with monogrammed letters of Watson's hotel.
		The atrium at ground floor was once a fashionable lobby housing the banquet hall.
		Style
5.3	Intrinsic	Early Post Industrial Architecture The building witnessed the first screening of a motion film in India, Lumiere Brothers
5.5		cinematograph in 1896.
		First Cast Iron structure in India, with most of the structural members being manufactured in
		England and shipped into Bombay for assembly.
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), E, F, I(sce) Recommended grade: II A
6.0		Topography
6.1	Floors	G + 4 (extensive mezzanines added within the large floor heights)
7.0		Construction
7.0	Plinth	Construction Plinth and bases of the arcaded columns are constructed of red colored stone imported
1.1		directly from the town of Penrith in Cumberland, Watson's home county.
7.2	Walls	Non-load bearing infill brick masonry walls, largely imported from Webster's manufactory in
		Burnham, England.
-		

	Mansion (Watson's Esplanade Hotel)	168
7.3	Floor	Timber floor boarding was installed on a structural grid of prefabricated cast iron columns
		and wrought iron beams.
		The structure supports a continuous band of balconies at each level.
7.4	Stairs	Centrally located grand straight flight stair overlooking the atrium has treads and balusters
		made in timber.
		The support is derived from wrought iron girders supported on cast iron columns.
7.5	Openings	Generally all openings are punctuation in the infilling brick walls. The sides to the east,
		north, and west have doors opening onto projecting balconies. The door shutters are timbe
		panels with top hung ventilator above. The south side with adjoining Army and Navy
		building has similar window openings.
		Decorative tracery window at the upper part of ground floor opening.
7.6	Roofing	The ground floor atrium covered by a gable roof supported on steel truss and Mangalore
		tile finishing with a few skylights. The roof is constructed of flat slab covered with water
		proofing membrane on top
7.7	Articulation	-
7.8	Finishes	Lime mortar finishing to both the internal and external surfaces throughout the building.
		Timber partitioning to divide internal spaces. Timber boards formed the floor finishing
		including staircase. Door and window openings finished with paint.
7.9	Interiors (Movable & Immovable)	Movable
		-
		Immovable
		-
7.10	Compound/ Fence/ Gate	Building itself forms boundary along the three road fronts to the east, north and west side,
7.10		shares a narrow open space along the south side with adjoining building.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	
7.11	Landscape	
	Lanuscape	
0 0		Services & Utilities
8.0	Linkting	
8.1	Lighting	Adequate natural light also supplemented by artificial means.
8.2	Ventilation	Adequate natural ventilation also supplemented by artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire extinguishers installed at places
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Poor - Plumbing line additions have caused seepage problem to the plinth causing
		weakening and dilapidation.
9.2	Walls	Poor - All external as well as internal walls are in a state of neglect and severely
		dilapidated. Unchecked plant growth and leakages cause efflorescence resulting in fissures
		and weakening of walls. Steel structural system shows corrosion at many places, caused
		by water seepage.
9.3	Floor	Poor - Wooden floorboards damaged and unleveled insensitively covered with varied tiling
		and plain cement.
		Cracks and holes visible in the balcony slab.
9.4	Stairs	Poor - Timber treads are in a state of decay and are rotting with some structural damage
		and missing rivets along the girder.
		Betel nut stains and poor lighting add to the neglected and poor maintained state of the
		once grand staircase.
9.5	Openings	Poor - Door as well as window openings are lacking maintenance and in a poor state of
3.5	Opermigo	preservation. Decay to the wooden members of frames and panels, poor and incongruous
0.6	Depfing	finishing.
9.6	Roofing	Poor - Neglected state, in need of repair and waterproofing, also terrace parapet damaged.
9.7	Articulation & Finishes	Poor - Original wall finishes are either in a neglected state or are transformed with newer
		and incongruous materials.
9.8	Services	Poor - Various additions and modifications in services like electrical, plumbing and air-
		conditioning done in a haphazard and unplanned manner to accommodate growing
		demand.
9.9	Out Buildings	
9.10	Overall Conditions	Extremely: Poor Maintenance level: Poor
40.0		Transformation
10.0		Balcony encroachment seems to hamper the façade.
10.0	Form	Dalcony encloaciment seems to namper the laçade.
10.0	Form Structure	
10.0		Addition of mezzanine on ground floor approached by a concrete stair cause structural over-loading.
10.0		Addition of mezzanine on ground floor approached by a concrete stair cause structural

Esplanade	Mansion (Watson's Esplanade Hotel)	168
		balcony extension on the north facade. Bamboo props have been temporarily added to support sagging structural members and slab. Balcony encroachment.
	Articulation & Finishes	Insensitive advertisements in the form of hoarding and painting damage and obscure the façade
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes: The oldest building at the Kala Ghoda Circle, located at the corner site next to the Army & Navy Building, was once the grand Watson's Esplanade Hotel, erected between 1867-69 by John Watson, a wealthy city draper, who imported all the building materials from England. While still under construction, the building, with its unique cast iron frame imported from England, was described by one writer as a 'huge birdcage'. The spacious arcade at street level displays the original cast iron pillars. History was created here in 1896 when the foundations of the Indian Cinema industry – now the largest in the world – were laid with the screening of the Lumière Brothers' Cinematograph. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay: Eminence Designs Pvt. Ltd.






Steel structure building with projecting balconies with carved railing



Castellated beam detail

Arcade with steel columns







Balcony with carved railing, overlooking the Kalaghoda area



Skylight over atrium in a dilapidated condition



Single flight staircase with carved railing



Steel columns with high base with geometric pattern

Old Oriental Bank Building (Old Treacher and Co. building) 169				
		Common Ref No: 169 (Part of 176) Card No: 227 Ward (Part): A (Part II) CS No: 156 (Fort division) Plot Area: - Date: 11/01/2005 Recorded by: Sonal Modak Reviewed by: Int: Sonal Modak, Prachi Merchant Ext: Sonal Modak, Prachi Merchant		
1.0		Denomination		
1.1	Name of Premises	Old Oriental Bank Building		
1.2	Earlier Name	Old Treacher and Co. building (corner part of the present day Old Oriental Bank Building)		

Refer Card No: 234, Building no: 176, Old Oriental Bank building

N. M. Wadia	Building	170
		Common Ref No: 170
	Sama	Card No: 228
	TIME	Ward (Part): A (Part III)
		CS No: 104 (Fort Division).
		T
		Plot Area: 809.37sq m. Image: Constraint of the second secon
		Date: 9/11/2004
		Date: 9/11/2004
		Recorded by: Zankhana Prajapati
		Reviewed by:
		Int: Zankhana Prajapati, Arun Wadhwa Ext: Zankhana Prajapati, Arun Wadhwa Photo Ref: 170_N M Wadia building.
		Ext: Zankhana Prajapati, Arun Wadhwa
100 Cont		Photo Ref: 170_N M Wadia building.
		10 Heat Wedge Duilding
		NANIK MOTWANI MARG
		NANIK
		Location Plan
1.0		Denomination
1.1	Name of Premises	N. M. Wadia Building
1.2	Earlier Name	N. M. Wadia Building
1.3	Built in:	Indeterminable Extension -
		Date
-		5410
2.0		Access
2.0	Main	Mahatma Gandhi Road
2.1	Subsidiary	Nanik Motwani Marg
2.2	Subsidially	Nahik Wolwahi Walg
2.0		Ourserskin nettern
3.0	Dresset	Ownership pattern
3.1	Present	Trust
3.2	Past	Indeterminable
3.3	Status	Tenant
4.0	-	Use
4.1	Present	Commercial- bank, private offices and club
4.2	Past	Commercial
4.3	Usage	Daily.
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Part of the arcaded street front, in the main building line of the Kala Ghoda area facing
		M.G. Road. The height and scale of the building coheres with the entire row of building on
		M.G. Road. A corner tower emphasizes the junction of the two streets.
5.2	Architectural Description	Planning
		A long building with the narrow front facing the road with the main staircase and lift block on
		the northern side of the building. The staircase area leads to a corridor with offices flanking
		the right side. Building has a subsidiary entry to the eastern end of the south façade, where
		residential quarters for some of the building workers can be found. Adjoining buildings abut
		the northern and eastern side of the building with a very narrow space between.
		Features
		It is a very ornate building with the façade divided in four bays. It has an arcade at the
		ground level and a cornice band marks all floors. All window openings are either
		rectangular, segmental or semicircular arched openings with architraves along the frame,
		dentil bands, intricately carved spandrels in floral patterns, ornately treated columns with
		festoon and floral motif. Balcony projections and pilasters can also be seen. A very ornate
		lift block in cast iron with wooden frame is both of which are carved intricately. Ground floor
		has an ornate marble handrail and balustrade. Decorative sill and lintels made of stone
1		projections can be seen on both sides of the elevation. Column like projections on the
		façade are very ornately treated. Projecting stone canopies at first and third floor level.
		Style
		It derives a strong influence from the Neo-Classical style of architecture.
5.3	Intrinsic	Presence of Ripon Club is one of the important characteristics of the building. The club is on the 3 rd and 4 th floors of the building.
5.4	Value Classification	A(arc), B (per), F Recommended II B
-		grade
6.0		Tanagraphy
6.0		Topography
6.1	Floors	G + 4 with terrace.
7.0		Construction
7.0		Construction

	a Building	17 D'inth is af basely store of 0.0 mth bainty with an unreal surray of Darbardon store.
7.1	Plinth	Plinth is of basalt stone of 0.6 mt. height with an upper layer of Porbander stone.
7.2	Walls	Walls are constructed in stone masonry. At certain places in the front façade buff colore stone is exposed to enhance features of the elevation.
7.3	Floor	Floor is supported on wooden rafters resting on cast iron columns. Marble flooring is see
7.4	Stairs	in the entire building. Wooden staircase and decorative balusters form one of the important features of the
		building. The ground floor has an omate marble handrail and balustrade. The staircase doglegged staircase with narrow well.
7.5	Openings	Façade is punctuated with a series of windows on its front and south elevations. Most
		the windows are flat arched while some windows had semi-circular openings. Windows a largely double shutter and four shuttered. All doors and windows have a wooden framewo with ventilators above. Doors are heavy paneled and made in teak wood.
7.6	Roofing	A flat roof is present in the building. The latter half of the building has a low terrace wh the front part has an additional floor with the corner of the building being emphasized raising its height with respect to the front building line.
7.7	Articulation	Stone projections at sill and lintel level with emphasis on the keystones are one of the features repeated on the entire façade. Cornice band is seen at the terrace parapet level.
7.8	Finishes	The entire building has plaster (lime mortar) both inside and outside. At certain places of the front façade buff colored stone is exposed to enhance features of the elevation.
7.9	Interiors (Movable & Immovable)	Movable Many pieces of old furniture and a clock were seen in wood carved very intricately. Or could also see an old sofa, high desk and other furniture made in black wood. Chair tables and storage desk in Ripon Club are also of black wood and are very ornamental. Immovable Light and fan fixtures of wrought iron. Wooden handrail of the staircase is very ornate.
7.10	Compound/ Fence/ Gate	Building occupies the entire plot area so it does not have any compound/fence/gate.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	Ample daylight is available through window openings supplemented by electric lights.
8.2	Ventilation	Ample ventilation through windows supplemented by suspended fans and A.C's.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Presence of fire extinguishers in a few places but no advance fire fighting mechanis prevails.
8.7	Other (HVAC/BMS/Security Systems)	AC units.
9.0		Condition
9.1	Plinth	Fair - Plinth abutting the street has some stones damaged.
9.2	Walls	Fair - No visible damage to the wall is seen as the wall is plastered both inside and outsic though in certain places the plaster is peeling off. All the recent repairs of the building a carried out in brickwork.
9.3	Floor	Fair - At second floor, in lobby area new flooring is being done.
9.4	Stairs	Fair - Ventilation of the staircase block is inadequate, as the adjacent building is plac very nearby.
9.5	Openings	Poor – At many places windowpanes were broken, replaced and even entire windor pattern was changed. Many A.C. units have now destroyed the uniformity of the façade a are incongruously placed. At places one also sees the usage of grills that do not go with t character of the building.
9.6	Roofing	Fair – fairly maintained.
9.7	Articulation & Finishes	Fair - Plaster is peeling off from side façade at certain places. Hoarding and Advertisi boards disturb the façade of the building.
9.8	Services	Poor - Near the rear entry, where there are quarters for servants working in the building very poorly maintained, it has loose wires running around, haphazard placing of meter a terrible sanitation conditions.
9.9 9.10	Out Buildings Overall Conditions	- Fair Maintenance level Fair.
10.0		Transformation
	Form	-
	Structure Articulation & Finishes	At ground floor Travancore Bank is situated and they have constructed a mezzanine floor Addition of advertising hoardings covering articulation.
11.0		DP Remarks/ Perceived Threats Building forms part of C1 Zone

N. M. Wadia B	uilding	170
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :
		Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.



Arched opening with prominent keystone, carved spandrel, balustrade



Corner tower of a buff stone and white painted symmetrical building with arched and rectangular openings with prominent keystone, chajja projections, vertical motifs, cornice bands, balustrade etc



Side façade with rectangular openings



Corner detail with geometric and floral pattern, floor and sill bands, sloping chajjas



Rusticated buff stone arched arcade



Staircase with wooden steps and carved railing



Lift cage with wooden paneling and jaliwork



Column detail with floral motifs, bracket above



Marble bust on a pedestal

Jhulelal H	ouse		17
Jhulelal H	<image/>	Common Ref No: 171 Card No: 229 Ward (Part): A (Part III) CS No: 98 Plot Area: 922.24 sqm. B U Area: - Date: 26/11/2004 Recorded by: Zankhana Prajapati Reviewed by: Int: Permission denied Ext: Zankhana Prajapati Photo Ref.: 171_Jhulelal_house	17 MAHATMA GANDHI ROAD
1.0		Denomination	
1.1	Name of Premises	Jhulelal House	
1.2	Earlier Name	Jhulelal House	
1.3	Built in:	Early 2000	Extension Date: -
		A	
2.0 2.1	Main	Access Mahatma Gandhi Road	
2.1	Subsidiary		
۷.۷	Subsidially	-	
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Private	
3.3	Status	Owner	
0.0			
4.0		Use	
4.1	Present	Commercial	
4.2	Past	Offices	
4.3	Usage	Commercial	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)		
5.2	Architectural Description	The building lies on Mahatma Gandhi Road a is no trace of the original building.	and has been completely reconstructed. There
5.3	Intrinsic	N.P.	
5.4	Value Classification	Nil	Recommended Delete grade:
6.0		Topography	
6.1	Floors	G + 3	
0.1			
7.0		Construction	
7.1	Plinth		
7.2	Walls		
7.3	Floor		
7.4	Stairs	The propert dependence is a second state 11 - 1	ling
7.5	Openings	The present structure is a reconstructed build	ung.
7.6	Roofing		
7.7	Articulation		
7.8 7.9	Finishes Interiors (Movable & Immovable)	Movable	
		- Immovable	
7.10	Compound/ Fence/ Gate	-	
7.10	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	

Jhulelal H	louse	171	
8.1	Lighting	Natural supplemented with artificial means	
8.1 8.2	Ventilation	Natural supplemented with artificial means	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
9.0		Condition	
9.1	Plinth		
9.2	Walls		
9.3	Floor		
9.4	Stairs	The present structure is a reconstructed building	
9.5	Openings	The present structure is a reconstructed building.	
9.6	Roofing		
9.7	Articulation & Finishes		
9.8	Services		
9.9	Out Buildings	-	
9.10	Overall Conditions	- Maintenance level -	
10.0		Transformation	
	Form		
	Structure	Original building has been completely reconstructed. No trace of the original building	
	Articulation & Finishes	Original building has been completely reconstructed. No trace of the original building.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	



The new building on the old site facing Mahatma Gandhi Road

Standard Cha	artered Bank building		172
	v	Common Ref No: 172	
		Card No: 230	
States of the local division of the local di		Ward (Part): A (Part II)	
		CS No: 155 (Fort)	
and the second s	and a state of the	Plot Area: 1775.09 sq m.	
		B U Area: -	
· 公司		Date: 11/02/2005	-
Super Contractor		Recorded by: Arun Wadhwa	
A MARK			
NEZ		Reviewed by:	
		Int: Sonal Modak, Arun Wadhwa	
In the second second	Alex State	Internal photography permission denied Ext: Sonal Modak, Arun Wadhwa	
	12- 2 44 . 21	Photo Ref: 172_Grindlays Bank Building	UNIVERSITY ROAD
	The state of the second		
			······································
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Standard Chartered Bank building	
1.2	Earlier Name	Grindlays Bank Building	
1.3	Built in:	1865	Extension -
			Date
2.0		Access	
2.1	Main	Mahatma Gandhi Road – Pedestrian	
2.2	Subsidiary	University Road – Pedestrian	
	+	Dr. Kane Road – Vehicular and Pedestrian	
3.0		Ownership pattern	
3.0	Present	Standard Chartered Bank – Owner	
3.2	Past	Grindlays Bank – Owner	
3.3	Status	Owner.	
4.0		Use	
4.1	Present	Institutional – Bank	
4.2	Past	Institutional – Bank	
4.3	Usage	Daily	
5.0		Circuition on A Malua Olana tion	
5.0 5.1	Townscape (Manmade)	Significance & Value Classification	g roads on three sides. Main customer access
5.1	Townscape (Mannade)		n side through a wide arcade on ground level.
			n University Road on southern side and other
		one from Dr. Kane Road on western side.	
		The West and South entries are reserved for	staff.
5.2	Architectural Description	Planning	
		Rectangular plan with an arcade on the east	
		Ground floor serves as a grand banking lobby	
			ad to offices on upper floors and the western
		sides & rear. A.C. plant is located in the base	ervices and toilet facilities are placed along the ment
			ernal subdivisions for functional and security
		concerns.	·····
		Features	
		Symmetrical main façade with central pedime	
			rusticated masonry. The front façade has an
			d on six fluted circular Corinthian columns
			wo square engaged columns at ends. Ground oper floors have semicircular arched openings.
		Ground floor has semicircular arched arcade	
			s with predominantly semicircular arched
		balustrade openings.	
		balustrade openings. The building has two prominent cornice ban	ds, one at the pediment level and the second
		balustrade openings. The building has two prominent cornice ban above arches. The interiors have fluted tall C	
		balustrade openings. The building has two prominent cornice ban above arches. The interiors have fluted tall C Style	orinthian columns.
52	Intrincia	balustrade openings. The building has two prominent cornice ban above arches. The interiors have fluted tall C	orinthian columns.
5.3 5.4	Intrinsic Value Classification	balustrade openings. The building has two prominent cornice ban above arches. The interiors have fluted tall C Style	orinthian columns.

stanuaro C	hartered Bank building	172	
6.0		Topography	
6.1	Eleore	G + 3	
7.0	Floors	Construction	
7.1	Dlinth		
	Plinth Walls	Medium plinth in grey stone about 2 ft. in height.	
7.2		Load bearing rubble stone masonry walls & cast Iron pillars.	
7.3	Floor	Indeterminable due to false ceiling.	
7.4	Stairs	Totally three staircases. Main staircase is located near the north-east corner is open well timber staircase having lishaft in the central open well. One straight flight RCC staircase along northern side in front part of the building. Separate doglegged timber staircase for staff is located along the southern side having the formation of the southern side having the so	
7.5	Openinge	direct entry from road.	
7.5	Openings	Arched external openings with wooden framed glazed panel shutters, some full door heig also with separate ventilator panels. Ground floor arcade on front has semicircular arches with rustication.	
7.6	Roofing	Indeterminable	
7.7	Articulation	Corinthian column capitals. Square fluted engaged columns and fluted circular columns of front façade. Decorative keystones.	
7.8	Finishes	Yellow stone dressed ashlar on all façades with quoins, rusticated masonry and painte features. Original Minton floor tiles have been replaced with varied floor finishes rangin from Granite, marble & ceramic tiles. Plastered/ painted internal wall surfaces.	
7.9	Interiors (Movable & Immovable)	Movable	
		Immovable	
7.10	Compound/ Fence/ Gate	Building itself forms the boundary along the road fronts on three sides, except north sid with an adjacent bank building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape		
8.0		Services & Utilities	
8.1	Lighting	Largely relies on artificial light.	
8.2	Ventilation	Centrally air-conditioned.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)	Smoke detectors & Fire extinguishers. Centrally with an. A.C plant. Electronic door locking devices. A/V monitoring of specific areas.	
9.0		Condition	
	Plinth		
9.1		Good - Except some plant growth & plumbing interventions externally.	
9.2	Walls	Good - Except service areas.	
9.3	Floor	Undetermined due to false ceilings.	
9.4	Stairs	Good - Except minor cracks & wear tear.	
9.5	Openings	Good - Except modifications made to door & window shutters.	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Good - Façade restoration carried out. Very well maintained internal finishes.	
9.8	Services	Good - Well maintained	
9.9	Out Buildings	-	
9.10	Overall Conditions	Good Maintenance level Good	
10.0		Transformation	
	Form	-	
	Structure	-	
	Articulation & Finishes	Signage strip runs continuously at first floor level affecting the stone clad façade. Whi wash to arches and ornamental features. Gold color applied over internal column capitals.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References:	

Standard Chartered Bank building	172
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay: Eminence Designs Pvt. Ltd.



Buff stone rusticated arched arcade enteres B



Wooden extended rear side porch



Articulation detail with intricately carved spandrel, floral pattern frieze band



Buff stone rusticated clad façade with arched openings, carved spandrel, scroll bracket keystone, cornice bands



Detail of buff stone rusticated opening



Fluted column with floral pattern corinthian capital

Bank of In	dia building	173
		Common Ref No: 173
		Ward (Part): A (Part II)
		CS No: 153, 154 (Fort)
	THE FULL BE	
And the second second second	Amedian D. Barth . I water at a state	
Television and		B U Area: 91947.15 sq m.
		B U Area: 91947.15 sq m. Date: 02/02/2005
		Recorded by: Sonal Modak
1 1 5		Reviewed by:
TE E		Int: Sonal Modak, Zankhana Prajapati
		Internal photography permission denied
		Ext: Sonal Modak, Zankhana Prajapati
- -		Photo Ref: 173_Bank of India Bldg.
		Location Plan
1.0		Denomination
1.1	Name of Premises	Bank of India building
1.2	Earlier Name	Bank of India building
1.3	Built in:	1942 Extension Date: 1952 - fourth and fifth floors were
1.0	Duit in	added.
2.0		Access
2.1	Main	Mahatma Gandhi Road - Pedestrian
2.2	Subsidiary	Dr. Kane Road - Pedestrian
3.0		Ownership pattern
3.1	Present	Private – Bank of India
3.2	Past	Private – Bank of India, The Secretary of State for India & others.
3.3	Status	Owner
4.0		Use
4.1	Present	Institutional - Bank
4.2	Past	Institutional - Bank
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	The building stands on Mahatma Gandhi Road facing east.
		It has a central main access from an arcade at ground level.
		It has a massive rectangular front elevation with a central void forming a small terrace at
		first floor level, defined by tall tapering octagonal columns on either side spanning the
5.2	Architectural Description	height from the first floor to third floor. Planning
5.2	Architectural Description	It has a wedge shaped, roughly rectangular plan with central access from eastern side
		through an arcade.
		Different floors cater to the various departments of the bank.
		Parking, electric substation and AHU are located in the basement.
		Staircases and service areas are located on rear (western) side of the building.
		The building has symmetrical front (eastern) façade with an arcade on ground floor level. A
		central entrance bay defined by recessed, corbelled arches.
		Above is a high ceiling terrace at first floor level having two massive, three storey high
		circular columns resting on projecting cornices supported by two stone brackets.
		Central bay extends a floor higher.
		Features
		Corbelled pendant bracketed cornices above rectangular window opening at topmost floor
		level.
		Recessed, corbelled arches, at the central arched opening.
		Style
		It displays no specific style. Has influence of art deco, classical and vernacular styles of architecture.
5.3	Intrinsic	architecture.
5.4	Value Classification	A(arc), B (per), B (des), B (uu), E, F, G(grp) Recommended grade II A.
0.4		
60		Lonography
6.0	Floors	G + 5 with basement
6.0 6.1	Floors	G + 5 with basement
	Floors	

Bank of Ind	lia building	173	
7.2	Walls	Thick load bearing external walls. Internal non-structural brick walls with RCC columns to	
		support RCC floors.	
7.3	Floor	RCC slabs with deep RCC beams.	
7.4	Stairs	Five staircases totally.	
		Two of them open well RCC staircases on north and south end of the building.	
7 5		Other two doglegged RCC staircases in the rear part of the building.	
7.5	Openings	On either side of the central bay are rectangular windows at all floor levels recessed within the six engaged columns, which has a broad projecting cornice like the <i>chhajja</i> above.	
7.6	Roofing	Partly sloping hipped roof with timber trusses. Overhangs supported by wooden brackets.	
		Partly slightly sloping RCC slab at fourth floor level.	
7.7	Articulation	Corbelled pendant brackets supporting projecting cornices.	
7.8	Finishes	Exposed grey ashlar masonry externally on eastern facade. Western facade is clad with	
		glass mosaic tiles. Internally walls are plastered and painted. Marble mosaic dado in	
		stairwells. Flooring is of marble mosaic tiles in most of the areas.	
7.9	Interiors (Movable & Immovable)	Movable	
		·	
		Immovable	
= 10			
7.10	Compound/ Fence/ Gate	The building covers the entire plot.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Cooling towers at terrace level. Water storage tanks for fire fighting equipment. Basement	
	Landscape	houses parking, BEST substation and Air Handling Unit of central AC system.	
0.0		Comisso 9 1141144ing	
8.0 8.1	Lighting	Services & Utilities	
8.2	Lighting Ventilation	Inadequate daylight available therefore almost completely dependent on artificial lighting.	
8.3		Inadequate ventilation therefore almost completely dependent on forced ventilation. BEST	
8.4	Electricity Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)	•	
0.7	Other (ITVAC/BING/Security Systems)	-	
9.0		Condition	
9.1	Plinth	Fair – covered with planter boxes and all the ventilators are closed.	
9.2	Walls	Fair – Minor cracks are observed.	
9.3	Floor	Good – No evident damages seen, well maintained.	
9.4	Stairs	Good – No evident damages seen, well maintained.	
9.5	Openings	Good – No evident damages seen, well maintained.	
9.6	Roofing	Fair - Wooden members deteriorating in some parts. Reinforcement exposed in few areas	
	Ğ	of the RCC slab.	
9.7	Articulation & Finishes	Fair - Plaster peeling off in some areas due to dampness.	
9.8	Services	Good – Well maintained	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level Fair	
10.0		Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
44.0		DB Devended Devendent	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notas/ References/ Resuments susilable	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		-	
		- References:	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	

Bank of India building



Buff stone clad symmetrical building with a central higher bay, triple height ionic columns, ground floor arched arcade, inset rectangular windows etc



Rear elevation with changed facade



Central bay rising high with projecting chajjas supported on intricately carved brackets



Terrace with services added later



Arcade with buff stone rectangular openings, coffered ceiling



Spiral staircase with wooden railing

New India	Assurance building		174
non maia		Common Ref No: 174	11- ST 8-S
		Card No: 232	MAHATMA GANDHI ROAD
		Ward (Part): A (Part III)	AT AT THE TOTAL SALE
Carles on	A DECEMBER OF THE OWNER OWNER OF THE OWNER OWNE OWNER OWNER OWNER	CS No: 156 (Fort)	A Z · ····
		Plot Area: Part of 1657.19 sgm.	GA G
		B U Area: -	GIND
		Date: 22/03/2005	H. AST MELL
		Recorded by: Sonal Modak	
			A D
	111 7 1	Reviewed by:	TAMARIND LANE
N 18 1		Int: Sonal Modak, Arun Wadhwa	
15		Internal photography permission denied	
		Ext: Sonal Modak, Arun Wadhwa	
1		Photo Ref: 174_New India Assurance	HE HE
		Building.	In the second se
			H KE
			e
			Location Plan
1.0		Denomination	
1.1	Name of Premises	New India Assurance building	
1.2	Earlier Name	New India Assurance building	
1.3	Built in:	1930's	Extension -
			Date
2.0		Access	
2.1	Main	Mahatma Gandhi Road – Pedestrian.	
2.2	Subsidiary	Ash Lane - Pedestrian, Nagindas Master Roa	d – Pedestrian.
3.0		Ownership pattern	
3.1	Present	New India Assurance Company Ltd. – Owner.	
3.2	Past	Mr. Dorabji Tata – Owner.	
3.3	Status	Owner and Tenant.	
3.5	Status		
4.0			
4.0		Use	
4.1	Present	Commercial – Offices, Institutional – Bank on	Ground Floor.
4.2	Past	Commercial – Offices.	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	This significant building stands on a corner p	
		and Ash Lane facing west. Accessed central	
		massive rectangular symmetrical front elevat	
		tall tapering engaged columns on either sides	spanning full height from first to last floor.
5.2	Architectural Description	Planning	
		Large building roughly rectangular in plan with	h slightly inclined sides along the road fronts,
		accessed centrally through a high arcade into	a wide lobby and staircase.
		Office spaces are planned around all the three	
		side. Staircase, lift and lobbies are centrally lo	cated flanked by internal chowks for light and
		ventilation. Main toilets are placed along the	
		internal chowk. East side wing has a setback	at the fourth floor forming a terrace. Part sixth
		and seventh floor seem to be added later. A b	asement is provided serving as AC plant and
		service area.	
		Features	
		Building has an impressive scale and a sy	mmetrical western facade with a prominent
		raised central bay. The verticality of the b	uilding is emphasized by pilasters/engaged
		square columns and rectangular recessed	d window openings. The central bay is
		accentuated with bas-relief at top, which rises	
		the staircase block.	
		The south corner is curvilinear with a recesse	d entrance at ground floor. Splayed corner at
		the east side intersection. Flat arch opening	
		features depicting peasants and craftsmens.	
		Style	5 5 1 1 1 1 1
		Art Deco features observed.	
5.3	Intrinsic	Bas-relief carved features on front facade.	
5.4	Value Classification	A(arc), B (per), B (des), B (uu), E, F, G(grp)	Recommended grade II A
6.0		Topography	
6.1	Floors	G + 6 with basement.	
L			

	Assurance building	174	
7.0	Dr. 4	Construction	
7.1	Plinth	High plinth about 1.2 m. in height dressed in grey basalt ashlar masonry also accommodating basement ventilators.	
7.2	Walls	Thick load bearing external walls with buff basalt ashlar masonry facing. Internal non-load bearing walls.	
7.3	Floor	RCC slab supported on RCC beams and columns.	
7.4	Stairs	Total three staircases. Main open well wide C- shaped RCC staircase.	
7.4		Total three staircases. Main open well wide C- shaped RCC staircase. Second wide doglegged staircase in rear part of the building. Third doglegged steel staircase with treads supported on central beam connecting sixth and seventh floors.	
7.5	Openings	Plain rectangular window openings with metal framed glazed panel openable shutters Large wood paneled folding door shutters at the main entrance. Plain wooden door shutters in all the upper floors.	
7.6	Roofing	Partly timber sloping roof with Mangalore roofing tiles and partly flat RCC slab roof.	
7.7	Articulation	Bas-relief motifs on western façade. Emphasized verticality on front (western) façade.	
7.8	Finishes	Buff basalt ashlar masonry externally. Walls plastered and painted internally. Rich white marble dado cladding at the entrance lobby on ground and first floor.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	Building occupies entire plot.	
7.10	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	
8.1	Lighting	Adequate daylight through door/window openings and artificial lighting.	
8.2	Ventilation	Adequate ventilation through windows with a provision of forced ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Provision made for fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Building is centrally Air Conditioned. The AHU is placed in the basement and cooling towers are placed on terrace. Also window AC units have been installed.	
9.0		Condition	
9.1	Plinth	Fair – Red granite dado covering plinth externally on front side. No evident damages observed.	
9.2	Walls	Fair – Blackening of stone due to lack of maintenance and weathering.	
9.3	Floor	Fair - No evident damage observed.	
9.4	Stairs	Fair - Marble treads are damaged due to wear and tear and in need of repair or replacement in few places.	
0.5	Onenines		
9.5	Openings	Fair – Shutters have been replaced in many places by aluminum frames.	
9.6	Roofing	Fair – Except for some damp patches & exposed reinforcement in the basement roof slab.	
9.7	Articulation & Finishes	Fair - Stone dressed side & rear facades with blackening, plant growth & A.C units observed.	
9.8	Services	Fair	
9.9	Out Buildings	•	
9.10	Overall Conditions	Fair Maintenance level Fair	
10.0		Transformation	
10.0	Form	Terrace enclosed on rear side fourth floor and front side fifth floor.	
	Structure	Sixth and seventh floor seem to be later added.	
	Articulation & Finishes	- Sixth and seventh floor seem to be later added.	
11.0		DP Remarks/ Perceived Threats Building forms part of C1 Zone	
		, .p	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes:	
		Designed by Master, Sathe and Bhuta in the 1930's. Monolithic relief figures were sculpted by N. G. Pansare.	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		INTACH (1990) Preiminary unealed iisting of Unbrotected Monuments. Buildings and	
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :	

Iew India Assurance building 174	
	in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Buff stone clad side façade with art deco features of vertical bands, rectangular openings



Central bay rising high with vertical bands ending into human face motifs



Relief sculpture in buff stone at the entrance depicting the 'labour work'



Arcade with rectangular openings, coffered ceiling

Hona Kona	Bank Building		175
		Common Ref No: 175	411
		Card No: 233	
		Ward (Part): A (Part II)	
	44 44		
	The second secon	CS No: 151, 152 (Fort Division)	
		Plot Area: 1794.41 sq m.	DR. Kan E Marg
	THE REAL PROPERTY AND ADDRESS OF	B U Area: 91947.15 sq m.	м на
	HSBC(D)	Date: 19/01/2005	F S
		Recorded by: Zankhana Prajapati	
14		Reviewed by:	
A		Int: Zankhana Prajapati, Sonal Modak	MA GA
		Ext: Zankhana Prajapati, Sonal Modak	
		Photo Ref: 175_Hongkong Bank Building.	HAI HAI
1		Thoto Net. 175_Hongkong Bank Ballang.	
<u> </u>			The second secon
			Location Plan
1.0		Denomination	Loodion Fidi
1.1	Name of Premises	Hong Kong Bank Building	
1.2	Earlier Name	Mercantile bank Building	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Mahatma Gandhi Road.	
2.2	Subsidiary	Mahamaho Padhya Dr. Kane Road.	
3.0		Ownership pattern	
	Dresset		
3.1	Present	Private	
3.2	Past	Private - The Secretary of State for India & oth	ners, The Merchantile Bank of India Ltd.
3.3	Status	Owner/tenant	
4.0		Use	
4.1	Present	Bank and MSEB offices	
4.2	Past	Indeterminable	
4.3	Usage	Daily.	
4.5	Usage	Daliy.	
5.0			
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	The building is on the corner plot of Mahatm	na Gandhi Road and Mahamaho Padhya Dr.
		Kane Road with the entrance from the corner.	
		The main access is from the Mahatma Gandh	i Road and subsidiary access from the corner
		of the building.	
		It is one of the buildings in the Flora Fountain	precinct with an arcade at the ground floor in
		the Art-Deco Style.	
5.2	Architectural Description	Planning	
	'	The building is trapezoidal with the longer faça	ade along the main road.
		The building is ground plus seven-storied high	with a terrace
		Entrance of the building is from Mahatma Ga	
		which leads to corridor and lift and staircase b	
		all the service utilities.	IUCK. TOHEIS are beside the stall case and also
		The bank occupies most floors and only few sp	paces have been occupied by the MSEB.
		Features	
		Building has a plain façade with minimal orna	
		facing Flora Fountain, the building is clad in	
		with cornice band at first and sixth floor level	, with continuous windows from first to fourth
		floor intercepted by huge circular columns; fift	h floor is defined as one horizontal band and
		sixth and seventh floor are recessed with part	
		entrance door, lion statues at entrance and an	
		Style	
		Building displays characteristics of the Art-Dec	no style
5.3	Intrinsic		
		- (dec) $P(max) = P(dec) = P(max) = P(max) + (dec) = P$	
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp), I(s	sce) Recommended grade II A.
6.0		Topography	
6.1	Floors	G + 7 + terrace.	
7.0		Construction	
7.1	Plinth	Medium height plinth clad with granite.	
7.2	Walls	Load bearing wall clad with marble.	

	Bank Building	17 Net visible due to false exiling
7.3	Floor Stairs	Not visible due to false ceiling.
7.4	Stairs	Three staircases are present.
		The main staircase is C-shaped RCC and the other two are fire escapes- doglegged RCC
7 5	0 mailean	Has a parapet wall as divider between the flights.
7.5	Openings	Rectangular door openings with heavy paneled double leaf wooden door.
7.0		All windows are huge rectangular openings running across all the floors.
7.6	Roofing	Flat terrace, with cable net, dish net, AC units, water tanks, blowers, chimney.
7.7	Articulation	Circular column with decorative capital and lion statues at entrance.
7.8	Finishes	External walls are clad in marble.
		Internal walls are plastered and painted.
		Flooring is varied - in some portions, marble, granite and vitrified tiles.
7.9	Interiors (Movable & Immovable)	Movable
		•
		Immovable
		-
7.10	Compound/ Fence/ Gate	Building sits on the entire plot.
		No fencing is seen.
		Entrance door forms the entry gate.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	No unbuilt space.
	Landscape	No outbuildings.
		Presence of a planter box.
		•
8.0		Services & Utilities
8.1	Lighting	Supplemented by electric light fixtures.
8.2	Ventilation	Central AC system.
8.3	Electricity	BEST
	,	
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Integrated fire precaution system with smoke detectors, sprinkler system, alarm system a
		fire extinguisher.
8.7	Other (HVAC/BMS/Security Systems)	Remote Accessing System and Central AC
9.0		Condition
9.1	Plinth	Good - Well maintained.
9.2	Walls	Good - External wall has some hoardings.
9.3	Floor	Good - Well maintained.
9.4	Stairs	Good - Well maintained.
9.5		Good - Well maintained.
	Openings	
9.6	Roofing	Good - At some area dampness was seen due to AC units and water tank.
9.7	Articulation & Finishes	Fair - Externally the building is in good condition, at certain places plaster and paint wa
		peeling off.
9.8	Services	Good - Well maintained.
9.9	Out Buildings	-
9.10	Overall Conditions	Good Maintenance level: Good
10.0		Transformation
	Form	No visible changes
	Structure	No visible changes
	Articulation & Finishes	No visible changes
	Articulation & Finishes	No visible changes
44.0		DD Domantical Deventional Threads
11.0		DP Remarks/ Perceived Threats.
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :
		Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinc.
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		EDANCIE D.K. CHING and VAN MORTBAND DEINILOLD Visual distignant of Architecture
		Division of International Thomson Publishing Inc.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.

Hong Kong Bank Building



Imposing corner marble clad building with vertical bands, rectangular openings



Side entrance opening



Rear façade with rectangular openings



Lobby Space with round columns

Urban Design Research Institute



Entrance Area with grand wooden paneled door shutter, lion statue in the corner



Carved lamp at the building entrance



Interior view with new modifications



Old Orienta	I Bank Building (inclusive of Building No	p:169 Old Treachers and Co, building)	176
	Common Ref No: 176	FLORA
		Card No: 234	FOUNTAIN
		Ward (Part): A (Part II)	MAHATMA GANDHI ROAD
		CS No: 156 (Fort division)	A
			TAZ
Red A		Plot Area: 1657.19 sq m.	A 6
i i		B U Area: -	ANDAS
1 1 1 1 K		Date: 11/01/2005	H AS
E E		Recorded by: Sonal Modak	ROA S TISF
227		Reviewed by:	A D w T breaken G
		Int: Sonal Modak, Prachi Merchant	
		Ext: Sonal Modak, Prachi Merchant	ROA UT
		Photo Ref: 176_Old Oriental Bank building.	
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Old Oriental Bank Building (inclusive of Old Tre	eachers and Co. building)
1.2	Earlier Name	Old Oriental Bank Building	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Mahatma Gandhi Road – Pedestrian	
2.2	Subsidiary	Nagindas Master Road – Pedestrian	
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Indeterminable	
3.3	Status	Owner. Tenant	
0.0	- Clalus		
4.0		Use	
4.1	Present	Commercial –Shops, Offices. Institutional – Ba	ink
4.2	Past	Commercial –Shops, Offices	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	It is a wedge shaped corner building with a	
		Mahatma Gandhi Road, which is the western f	açade located near Flora Fountain.
5.2	Architectural Description	Planning	
		The corner building, initially called as 'Old Tre Old Oriental Bank building and are connected	achers and Co. building is now a part of the
		Wedge shaped corer plot. Main entrance from	
		side. Ground floor totally occupied by shops f	
		first floor occupied by a bank. Above floors are	occupied by different offices
		All the various premises accessed through a l	
		building centrally.	
		Wooden projecting balconies along the length	of the building on western façade.
		Features	
		Although the two buildings are connected toge	ether internally, externally the façade features
		are different.	
		The corner building derives its shape with site and dentil band. The side part of the buildi	
		columns, railing, and brackets.	ing has balcomes with decorative cast from
		Segmental arches, semi-circular arches as wi	indow openings. Decorative stone corbels to
		support comice bands forming chhailas above	window openings
		support cornice bands forming <i>chhajjas</i> above Buff basalt bands at each floor level.	window openings.
			window openings.
		Buff basalt bands at each floor level. Style The corner building displays features of Neo	classical style of Architecture, side building
		Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence	classical style of Architecture, side building
5.3	Intrinsic	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence	classical style of Architecture, side building
5.3 5.4	Intrinsic Value Classification	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence	classical style of Architecture, side building
5.4		Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp)	classical style of Architecture, side building
5.4 6.0	Value Classification	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp) Topography	classical style of Architecture, side building
5.4		Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp)	classical style of Architecture, side building
5.4 6.0 6.1	Value Classification	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp) Topography G + 2 with mezzanine on all the floors.	classical style of Architecture, side building
5.4 6.0 6.1 7.0	Value Classification Floors	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp) Topography G + 2 with mezzanine on all the floors. Construction	classical style of Architecture, side building
5.4 6.0 6.1	Value Classification	Buff basalt bands at each floor level. Style The corner building displays features of Neo displays vernacular architecture style influence - A(arc), B(per), B(des), G(grp) Topography G + 2 with mezzanine on all the floors.	classical style of Architecture, side building s. Recommended grade II A

Old Orienta	al Bank Building (inclusive of Building No:16	
7.3	Floor	Mostly covered by false ceiling so not visible.
		Ladi coba with MS sections in some areas.
7.4	Stairs	Open well timber staircase.
7.5	Openings	Arched openings with wooden glazed shutters and ventilators above which have bee
	replaced in many places.	
7.6	Roofing	Front wing has timber sloping hipped roof. Remaining part has flat RCC slab.
7.7	Articulation	Decorative cast iron columns, railing, and brackets. Segmental arches, semi-circular arche
		as window openings. Decorative stone corbels to support cornice bands forming chhajja
		above window openings.
7.8	Finishes	Walls are plastered and painted externally as well as internally.
		Ceramic tile dado in some areas. Various flooring tiles have been used as per th
		occupant's choice.
7.9	Interiors (Movable & Immovable)	Movable
	, , , , , , , , , , , , , , , , , , ,	
		Immovable
7.10	Compound/ Fence/ Gate	Building sits on the entire plot.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	-
	Landscape	
8.0		Services & Utilities
8.1	Lighting	Inadequate daylight in some parts of the building supplemented by artificial lighting.
8.2	Ventilation	Inadequate ventilation in some parts of the building supplemented by drailed righting.
0.2	Ventilation	systems.
8.3	Electricity	BEST
	Water Supply	
8.4		MCGM MCGM
8.5	Drainage (Plumbing & Sanitation)	
8.6	Fire Precaution	No Traces.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed wherever necessary.
9.0		Condition
9.1	Plinth	Fair – Ground floor shops have modified plinth as per individual need. Plinth is not visible.
9.2	Walls	Fair – Plant growth. Layout has been modified as per the occupant on each floor.
9.3	Floor	Fair – Floors have been strengthened by MS sections wherever are visible.
9.4	Stairs	Fair – Finishing materials completely replaced. Cleanliness not maintained.
9.5	Openings	Fair – Shutters have been replaced. Broken features.
9.6	Roofing	Poor – Totally neglected state. Broken Mangalore tiles. Parapet wall in bad state.
9.7	Articulation & Finishes	Poor – Cast iron features are corroded. Façade features are broken in some places. Pla
•		growth seen.
9.8	Services	Poor – Cleanliness not maintained. Corroded service pipes with cracks. Leakages resultin
0.0		in dampness. Plant growth.
		Haphazard electrical wiring.
9.9	Out Buildings	
9.10	Overall Conditions	Poor Maintenance level Poor
3.10		
10.0		Transformation
10.0		Transformation
	Form	Ground floor arcade encroached upon by hawkers. Insensitive provision of hoardings a
	Objection	first floor shops level. Addition of toilet block on terrace.
	Structure	MS sections to strengthen floors and staircase.
	Articulation & Finishes	•
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 Zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay:
		Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture
		Division of International Thomson Publishing Inc.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminene Designs Pvt. Ltd.
		LIBSIOUS EVI. LTO



Front façade with balconies with carved railing, sloping chajjas and incongruous additions done to the building



Rear façade with arched openings in a neglected state



Detail of façade articulation with dentil bands, floral pattern bands



Façade articulation with balustrade, rusticated columns, cornice band



Corner curved building in Flora Fountain area – Old Treachers and Projecting balcony stone balustrade, rusticated columns, bands. Co. building





Balconies with intricately carved railing, sloping chajjas supported on carved brackets and slender columns



Façade articulation with intricately carved frieze bands, dentil bands, carved scroll brackets



Craved cast iron brackets



Projecting cornice band



Detail of the carved brackets supporting the balcony

Old Orienta	I Insurance building		177
	ž	Common Ref No: 177	a har and the
		Card No: 235	OR OAOAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
	and state.	Ward (Part): A (Part II)	R
A Black		CS No: 428	MAHATMA GANDHI 90,48H41 NOWPOLIMA
40		Plot Area: 1552.13 sq m.	
12.1		B U Area: -	A Driven bullens
L.		Date: 28/12/2004	O O
- 2 2-	FILLER HILL	Recorded by: Arun Wadhwa	NI N
		Reviewed by:	A H
		Int: Arun Wadhwa, Zankhana Prajapati	AL
		Int. Arun Wadhwa, Zankhana Prajapati	E Origina R
	HER press Children and	Ext: Arun Wadhwa, Zankhana Prajapati	وب [*]
		Photo Ref: 177_Oriental Insurance building.	-
			Assessment
			The second secon
			FLORAFOUNTAIN
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Old Oriental Insurance building	
1.2	Earlier Name	Oriental Insurance building	
1.3	Built in:	1885	Extension Date: -
2.0		Access	
2.1	Main	Mahatma Gandhi Road - vehicular and peder	strian.
2.2	Subsidiary	Dr. Dadabhai Nowroji Road - vehicular and pe	
			-
3.0		Ownership pattern	
3.1	Present	Life Insurance Corporation.	
3.2	Past	Indeterminable	
3.3	Status	Owner, Tenants.	
4.0		Use	
4.1	Present	Offices.	
4.2	Past	Offices.	
4.3	Usage	Daily.	
5.0		Significance and Value Classification	
5.1	Townscape (manmade)		ountain square, accessed from the two main
			west side with distinctly projecting porch. High
			rks the strong urban character the building
		provides to the area.	· · · · · · · · · · · · · · · · · · ·
5.2	Architectural Description	Planning	
0.2			lel to the bifurcating streets with an attached
			central portion in-between the two wings was
			I service stair. Main entrance is from the wes
			se and lift. Typical layout of office spaces with
			nd additional stair to the rear north side. High
		third floor has access to attic floor and central	
		Features	tower space below the steep roof profile.
			ornice bands and topped by steep pyramida
		roof and corner stone turrets. Two main sy	mmetrical lacades sumounted with a pair o
		also a setting this is a set of a set of a set of a set of the set	
			rrets culminating with steep stone spires at the
		corners. The facades are punctuated with an	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands
		corners. The facades are punctuated with an Varied arch openings- large shallow arches	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands with smaller trefoil and circular openings se
		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sel I relief pediment panels. Projecting balcony
		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sel I relief pediment panels. Projecting balcony
		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet.
		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s.
5.3	Intrinsic	corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.3 5.4	Intrinsic Value Classification	corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s.
5.4		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce)	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.4 6.0		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.4		corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce)	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.4 6.0	Value Classification	corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.4 6.0	Value Classification	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings sei I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower.
5.4 6.0 6.1	Value Classification	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands, with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.
5.4 6.0 6.1 7.0	Value Classification Floors	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature: Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands, with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	corners. The facades are punctuated with an Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction Plinth height about 0.5 M dressed in Malad s cornice band.	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands, with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction Plinth height about 0.5 M dressed in Malad s cornice band. Load bearing rubble masonry stonewalls and	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands, with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction Plinth height about 0.5 M dressed in Malad s cornice band. Load bearing rubble masonry stonewalls and Shahabad stone slabs on wooden supports a	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands, with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	corners. The facades are punctuated with ar Varied arch openings- large shallow arches within. Intricately stone-carved cornice and feature supported on corbels and decorative s Style Influence of Gothic Revival style in its feature Stone carved heads of three eminent citizens A(arc), B(per), B (des), E, F, G(grp), I(sce) Topography G + 3 floors and roof attic Construction Plinth height about 0.5 M dressed in Malad s cornice band. Load bearing rubble masonry stonewalls and Shahabad stone slabs on wooden supports a in the extended central portion.	rrets culminating with steep stone spires at the ch openings, regular cornice and lintel bands. with smaller trefoil and circular openings set I relief pediment panels. Projecting balcony stone baluster parapet. s. on all the three sides of the corner tower. Recommended grade II A.

Old Orienta	I Insurance building	177		
7.5	Openings	Arched window openings on the two main facades, large rectangular architrave window openings on the North side. Wooden paneled door shutters, outer wood framed glazed panel and wooden louvered internal window shutters. Few stained glass multifoil circular ventilator openings.		
7.6	Roofing	Steep sloping Mangalore tile roof gable ended in both the wings with flat concrete slab ove central portion. Also high pyramidal Mangalore tile roof over central tower. Stone spires atop octagonal terrace blocks.		
7.7	Articulation	Circular stone turrets at the corners, relief carved cornice bands at floor levels, decorative column capitals, architrave rectangular rear side windows with quoin surface.		
7.8	Finishes	Grey basalt stone dressed external wall surfaces and soft Porbander stone for ornamenta features. Plastered painted internal wall surfaces. Varied floor finishes as modified by		
7.9	Interiors (Movable and Immovable)	occupants in the building. Movable - Immovable		
7.10	Compound/ Fence/ Gate	Building itself forms the plot boundary along the road fronts on all sides.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Statue of Dadabhai Nowroji at the pavement facing the Flora Fountain intersection.		
8.0		Services and Utilities		
8.1	Lighting	Adequate natural light except for service stair also relies on artificial light.		
8.2	Ventilation	Adequate natural rentilation but relies on A.C. units.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM- Underground and overhead water tank		
8.5	Drainage (Plumbing and Sanitation)	Drainage connected to municipal sewers of MCGM		
8.6	Fire Precaution	Fire extinguishers only, fire detection system absent		
8.7	Other (HVAC/BMS/Security Systems)	Window and Split unit A.C.		
9.0		Condition		
9.1	Plinth	Poor - Plant cultivation around the plinth area and plumbing interventions to the north side.		
9.2	Walls	Fair- except some damp patches due to seepage.		
9.3	Floor	Fair- except replaced wooden supporting members with steel sections.		
9.4	Stairs	Fair- except for poor state of service stair.		
9.5	Openings	Poor - Iron grills enclosing veranda openings, damaged and poorly finished door window shutters. Addition of metal sheet <i>chajjas</i> and bamboo mat over window openings.		
9.6	Roofing	Poor - decay of wooden truss members. Also neglected and vandalized stone spires.		
9.7	Articulation and Finishes	Poor - Blackened stone-faced facades and damaged carved features at some places.		
9.8	Services	Poor - Old, neglected electrical and plumbing services.		
9.9 9.10	Out Buildings Overall Conditions	Fair except poor external finishes, Maintenance level: Well maintained interiors		
		roof spires and services. but neglected externally.		
10.0		Transformation		
	Form	-		
	Structure	-		
	Articulation and Finishes	Iron grills and A.C brackets damage stone façade and ornate features.		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 Zone		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes: J. A. Fuller was the Architect. Urban Heritage Award 1995 to American Express Bank located on Ground floor. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and</i> <i>Structures listed for Conservation.</i> SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) <i>The Fort Precinct</i> <i>in Bombay – Conserving an Image Centre</i> , 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminence Designs Pvt. Ltd.		



Corner rising tower with sloping roof, arched openings, human face bas relief, floor bands, corner turrets



Double height arched window openings with carved frieze bands, balustrade



Gable end detail with intricately carved round openings, floral motifs, corner turret



Grey stone clad building with arched openings with trifoil arched openings, stone balustrade, frieze band



Rising stone spire with carved jaliwork triangular portion with a finial, arched openings with animal motifs at springing point



Side elevation with rising corner spire, central gable end bays and corner sloping roof tower $% \left({{{\rm{S}}_{\rm{s}}}} \right)$



Detail of corner tower with sloping roof, corner turrets, intricately carved cornice bands, human face bas relief etc.



Cast iron railing



Roof articulation with animal motif at the finial point



Wooden high sloping roof supported on wooden truss



Window detail with louvered shutters, fixed glazed ventilator panel

Standard	Chartered Bank Building	178
		Common Ref No: 178
Anton		
Kan the		Ward (Part): A (Part II)
W.E.	1	CS No: 707 (Fort Division)
	1012 40 28 9 28	Plot Area: 2717.41 sq m.
	CORP H. TOWN	3 7 8
* Interite		BUArea: -
	No. 2 . Variation	Date: 11/02/2005
Super State	and the second	Recorded by: Arun Wadhwa
a far		Reviewed by:
		Int: Arun Wadhwa, Sonal Modak
1-1-	The second second second	Ext: Arun Wadhwa, Sonal Modak
RALE OF		Photo Ref: 178_Chartered Bank.
		Location Plan
1.0		Denomination
1.1	Name of Premises	Standard Chartered Bank Building
1.2	Earlier Name	Chartered Bank Building
1.3	Built in:	1902 Extension Date: 1922 mezzanine added.
1.0	Built in	
2.0		Access
2.1	Main	Mahatma Gandhi Road – Vehicular and Pedestrian.
2.1	Subsidiary	Connon Road - Vehicular and Pedestrian.
<i>L.L</i>		
3.0		Ownership pattern
3.1	Present	Standard Chartered Bank – Owner
3.2	Past	Chartered Bank of India, Australia and China.
3.3	Status	Owner.
0.0		
4.0		Use
4.1	Present	Offices – Bank
4.2	Past	Offices
4.3	Usage	Daily
4.0		
5.0		Significance and value Classification
5.1	Townscape (Manmade)	Landmark building along M.G. Road with well composed symmetrical façade rich in
0.1		architectural detailing. Main customer access is from M.G. Road into the grand banking
		lobby whereas north and south entries are reserved for staff.
5.2	Architectural Description	Planning
		Rectangular plan with a projecting porch on the north side and curved corner at the
		south-east end is C-shaped from second floor upwards due to rear and central areas
		being ground and one. Ground floor serves as grand banking lobby with a mezzanine
		added later to accommodate more office spaces. Staff entrances from north and south
		side staircases lead to offices on upper floors. Floor layout seems complicated due to
		internal subdivisions for functional and security concerns. Services and toilet facilities
		are placed along the sides and rear. Front and two sides with narrow veranda like
		spaces presently accommodate cabin areas. A.C. plant is located at the rear east side.
		Features
		Symmetrical main façade with central tetrastyle central portico raised on rusticated high
		ground floor with triangular pediment bearing a flagpole at its apex above which a
		sculptural group represents Britannia, India, Australia and China. Also a pair of domed
		terrace features flanks both symmetrical sides. Carved figures in the triangular pediment
		and tympanum within the main entrance archways. Semicircular arches with distinct
		keystones on the external stone facades. Side façade is marked by colonnaded
		triangular pediment entrance. Intricately carved human heads adorn the keystone. Decorative capitals over circular iron columns within the high internal spaces. Neo
		Classical marble water fountain arranged centrally within a petal shaped pond in the center of large banking lobby at the ground floor.
		Style
		Influence of Neo Classical - Italian style.
5.3	Intrinsic	Neo Classical marble water fountain
5.4	Value Classification	A(arc), B(per), B (des), E, F, G(grp) Recommended grade II A.
0.1		
6.0		Topography
6.1	Floors	G + 3, part fourth and mezzanine
7.0		Construction
7.1	Plinth	About 0.6 m. height, gray basalt stone finish.
7.2	Walls	Load bearing rubble stone masonry walls and cast iron pillars.
7.3	Floor	Shahabad stone slabs supported over wooden/ iron members.
7.4	Stairs	Main C-shaped stone stair with a central open well serving as a lift shaft from the
		southern side entrance. Narrow C-shaped wooden service stair on the rear eastern side.

Standard	Chartered Bank Building	178	
7.5		Marble clad stair leading from the large ground floor hall to the mezzanine level. Narrow spiral fire escape staircase to the northern side.	
7.5	Openings	Semicircular arch external openings with wood framed glazed panel shutters some full door height also with separate ventilator panels. Many door window shutters replaced with only glass panes.	
7.6	Roofing	Sloping Mangalore tile hip roof over south wing on third and north wing of fourth floor. Flat roof on central portion of second floor. Domed gallery on fourth floor terrace.	
7.7	Articulation	•	
7.8	Finishes	Yellow stone dressed façade on ground floor, buff basalt on first and second floor. Decorative features like cupolas, cornices, column capitals and carvings are in Porbander, Seoni and Bath stone. Original Minton floor tiles have been replaced with varied floor finishes ranging from granite, marble and ceramic tiles. Plastered painted internal wall surfaces.	
7.9	Interiors (Movable and Immovable)	Movable	
		- Immovable Italian marble fountain with classical design of cherubs and vine leaves is placed centrally in the grand banking lobby.	
7.10	Compound/ Fence/ Gate	Building itself forms the boundary along the road fronts on three sides, except north side with a masonry boundary wall to the adjacent school building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services and Utilities	
8.1	Lighting	Largely relies on artificial light.	
8.2	Ventilation	Centrally air-conditioned.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and Sanitation)	MCGM	
8.6	Fire Precaution	Smoke detectors and Fire extinguishers.	
8.7	Other (HVAC/BMS/Security	Centrally A.C plant. Electronic door locking devices.	
0.7	Systems)	A/V monitoring of specific areas.	
9.0 9.1	Plinth	Condition Fair - except some plant growth and plumbing interventions externally.	
9.1	Walls	Fair - except some plant growth and plantoing interventions externally.	
9.2	Floor	Undetermined - due to false ceilings.	
9.4	Stairs	Fair - except minor cracks and wear tear.	
9.5	Openings	Fair - except modified door and window shutters.	
9.6	Roofing	Fair - except minor damage to Mangalore tiles.	
9.7	Articulation and Finishes	Fair - façade restoration carried out. Very well maintained internal finishes.	
9.8	Services	Fair - Well maintained	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level Good	
10.0		Transformation	
	Form	-	
	Structure		
	Articulation and Finishes	Signage strip runs continuously at first floor level affecting the stone clad façade. White wash to arches and ornamental features. Gold color applied over internal column capitals.	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes/ References/ Documents available Additional Notes: One of the last works of famous British Architect F. W. Stevens, carried out by Gregson, Batley and King after the death of Stevens in 1900. Conferred with Urban Heritage Award 1991. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay - Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence	



Buff stone clad building with white painted features, ionic columns with Corinthian capitals supporting the pediment and its carved features



Side entrance with carved pattern in the lintel, pediment above with carved spandrel, dentil band



Arched and round opening with intricately carved spandrel in floral motif, human face motif keystone, scroll bracket keystone



South side façade with arched openings, floor bands, vertical bands



Façade Detail with arch profile pediment, carved tympanum, arches with prominent keystone, balustrade etc



Human face keystone in buff stone



Decorative column capital with floral pattern



Internal arched openings with scroll bracket keystone



Carved human figure at the finial point of the pediment



Wooden carved emblem



Interior view with modifications



Corner tower surmounted with a dome with carved façade features, cornice bands

Cathedral a	and John Connon Junior School	179
		Common Ref No: 179 Card No: 237 Ward (Part): A (Part III)
j.		Ward (Part): A (Part III)
Á		CS No: 706 (Fort division)
		Plot Area: 1225.75
		B U Area: -
		Date: 20/11/2004
		Recorded by: Zankhana Prajapati
11	The second second second	Reviewed by:
	A STATUTE A STATUTE A STATUTE	
		Int: Arun Wadhwa, Zankhana Prajapati
Contraction of the local division of the		Ext: Arun Wadhwa, Zankhana Prajapati
	TOODO /	Photo Ref.: 179_Cathedral and John Cannon
		706
		Location Plan
1.0		Denomination
1.1	Name of Premises	Cathedral and John Connon Junior School
1.2	Earlier Name	Cathedral and John Connon Junior School
1.3	Built in:	Commenced on April 1878, Completed in November 1881. Extension Date: 1960'
		s
2.0		Access
2.1	Main	Mahatma Gandhi Road
2.2	Subsidiary	Marzban Road
2.5		
3.0		Ownership pattern
3.1	Present	Private
		Scottish education society
3.2 3.3	Past	
3.3	Status	Owner
4.0		Use
4.1	Present	Institutional - Primary school
4.2	Past	Institutional - Primary school
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	The building forms an important landmark on Mahatma Gandhi Road.
		The building is juxtaposed between other important buildings of different styles like ENT
		hospital and Standard Chartered Bank building.
5.2	Architectural Description	Planning
		The original stone faced building fronting Mahatma Gandhi road planned with spacious
		verandahs on both east and west sides with classrooms in between and circular staircases
		at the ends.
		Extension wing to the east is connected by the central passage with rooms to the north and
		east and two wide staircases.
		Western entry leads to a large hall for plays and cultural activities.
		The eastern side includes an entry, administration, gymnasium and stilt area to the south.
		Upper floor rooms serve as classes, library, staff room, toilets, etc
		Features
		West façade is dressed in cyclopean coursed grey stone with continuous arched openings,
		large and pointed on ground and first floor, small semicircular on second floor.
		Highly ornate column capitals on four circular columns in red stone.
		Intricately stone carved Lion head at the western arched entry.
		Intricately carved flora and fauna features on the column capital.
		Triangular gable portion with small continuous arches and decorative relief work pediment
		topped by stone finial.
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade.
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within.
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within. Stone parapets with quatrefoil and ornate geometric openings.
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west facade. Arches have trefoil, quatrefoils openings within.
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within. Stone parapets with quatrefoil and ornate geometric openings. Projecting balcony feature at third floor supported on curvilinear ornate brackets. Style
		topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within. Stone parapets with quatrefoil and ornate geometric openings. Projecting balcony feature at third floor supported on curvilinear ornate brackets. Style The building displays features of the Gothic Revival style
5.3	Intrinsic	topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within. Stone parapets with quatrefoil and ornate geometric openings. Projecting balcony feature at third floor supported on curvilinear ornate brackets. Style The building displays features of the Gothic Revival style One of the oldest educational institutes in the city.
5.3	Intrinsic Value Classification	topped by stone finial. Conical sloping roof on hexagonal base with bracket like feature at the northern end of the west façade. Arches have trefoil, quatrefoils openings within. Stone parapets with quatrefoil and ornate geometric openings. Projecting balcony feature at third floor supported on curvilinear ornate brackets. Style The building displays features of the Gothic Revival style

Cathedral a	and John Connon Junior School	179
6.0		Topography
6.1	Floors	G+3 with upper storeys with pitched roof onto the third floor
•••		
7.0		Construction
7.1	Plinth	Low height of about a foot, dressed in regular stone masonry course, the extension wing is plaster finished.
7.2	Walls	Load bearing stone masonry dressed in ashlar and cyclopean courses. The extension wing is a brick masonry and concrete structure with plaster finish.
7.3	Floor	Stone slabs supported on wooden rafters and stone masonry walls and arches. Extension wing has concrete floor supported on columns and beams.
7.4	Stairs	Wooden narrow circular stairs at the north and south ends of the original building supporte on load bearing stone masonry.
		Two spacious open well staircases in concrete built during extension work with wrought iron railing topped by wooden handrail.
7.5	Openings	West verandas through all the floors have continuous arched openings, door to classes have arched openings with wooden louvered shutters and ventilator above. Upper portion of some door shutters have trefoil fixed glazed panels.
		Extension portion has aluminum section operable windows and wooden glazed panel doors.
7.6	Roofing	High steep sloping roof with Mangalore tile finishing supported on wooden trusses, replaced with steel sections recently.
7.7	Articulation	Ornate decorative work on the main façade and in details like the grills and parapets
7.8	Finishes	Externally grey stone in cyclopean course dressing with decorative features in light colored Porbunder stone and circular columns in red stone. Internally rooms are cement plastered. Exterior of extension wing is plastered and painted with projecting window opening.
7.9	Interiors (Movable & Immovable)	Movable Much of the original furniture seems to still exist in a relatively good condition in the building. These include cupboards, etc. The new furniture that has been added keeps with the general aesthetic of the building Immovable
7.10	Compound/ Fence/ Gate	Railings, balustrades, etc exist well maintained. Low stonewall with wrought iron railing above; to the west and south side, north side has high wall and chain link fence whereas the building itself forms the eastern front.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space within the building serves as play area. Landscaping in the form of plants and shrubs along the boundary wall.
8.0	L'ables	Services & Utilities
8.1 8.2	Lighting Ventilation	Adequate natural light through openings, supplemented by artificial lights. Adequate natural ventilation through openings of veranda supplemented by artificial
0.2	ventilation	ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Dry riser fire equipment has been installed.
8.7	Other (HVAC/BMS/Security Systems)	Window air-conditioning units have been installed
9.0		Condition
		The building has been completely renovated and has been maintained well
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair
9.8	Services	Fair
9.9 9.10	Out Buildings Overall Conditions	- Fair Maintenance level Good
10.0		Transformation
	Form	New annexes have been added to the rear side of the building.
	Structure	Wooden trusses and roof rebuilt in steel and concrete finished in Mangalore tiles. Steel sections added to re-strengthen floor structure.
	Articulation & Finishes	Additional Iron railing over stone parapet wall has been installed for security.
11.0		DP Remarks/ Perceived Threats
		Secondary School, building forms part of C1 zone

Cathedral and John Conne	on Junior School 175
12.0	Additional Notes/ References/ Documents available
	Additional Notes: Designed by John Adams; commenced April 1878 and completed November 1881. Estimate as sanctioned Rs. 87555. Named after a prominent citizen, John Connon, Chief Presidency Magistrate of Bombay and directed Bombay Gazette and took keen interest in education for Anglo-Indian community. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.



Balcony projection



Central high rising bay with gable end, finial, arched openings, bracket, projecting balconies



Corner tower with steep sloping roof, floor bands, arched openings



Arched opening on round columns with stone carved railing



Corner curved bay with sloping roof, arched openings



Modified main entrance

Cathedral and John Connon Junior School



Verandah with trifoiled arches on red stone round columns with carved capitals, balustrade







Internal view with arched openings, louvered paneled door shutters, minton tile flooring



Column capital with floral and animal motifs

ERROR: stackunderflow OFFENDING COMMAND: ~

STACK:

Bombay G	Symkhana	180
		Common Ref No: 180
		Card No: 238
		Ward (Part): A (Part II)
		CS No: 730
-		Plot Area: 5717.43 sq m.
		B U Area: - Date: 10/12/2004 Recorded by: Sonal Modak
		Recorded by: Sonal Modak
		Reviewed by:
Martin Martin Stra		Reviewed by: Int : Sonal Modak
		Ext : Sonal Modak
		Photo Ref: 180_Bombay Gymkhana.
and the second se		Thou her. Too_boniday Cynninana.
		Location Plan
1.0		Denomination
1.1	Name of Premises	Bombay Gymkhana
1.2	Earlier Name	Bombay Gymkhana
1.3	Built in:	Club formed in 1875, New pavilion completed in 1907 Extension Date: -
2.0		Access
2.1	Main	Mahatma Gandhi Road – Vehicular and Pedestrian.
2.2	Subsidiary	Hazarimal Somani Marg – Pedestrian.
2.2		
3.0		Ownership pattern
	Dresent	Trust – Bombay Gymkhana Ltd.
3.1 3.2	Present Past	Trust
-		
3.3	Status	Owner
4.0		10
4.0		Use
4.1	Present	Club House
4.2	Past	Club House
4.3	Usage	Daily
5.0		Significance & value Classification
5.1	Townscape (Natural/ Manmade)	Located on a prime site of Azad Maidan in South Mumbai.
		Main access is from Mahatma Gandhi Road on western side and secondary entrance is
		from Hazarimal Somani Marg on eastern side.
5.2	Architectural Description	Planning
		It's a linear building dividing Azad <i>Maidan</i> into two uneven parts.
		It has a wide and airy verandah offering a view of maidan. The ground floor houses the dressing rooms, a central hall, a billiards room, a bar, a lounge
		and administrative offices. On the first floor are the Committee Room, a central lounge, a ladies' cloakroom and a reading room with an adjunct that could be used as a stage.
		The entire first floor is constructed with movable partitions that could be used as a stage.
		space converted into a large concert hall or ballroom.
		Features
		The building is a typical Colonial building in the steel frame structure, timber floors, wide
		timber staircase, timber sloping roofs and Verandahs fronting the pavilion.
		Style
		Derives influence from Colonial and Vernacular styles of architecture.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), B(des), B (uu), F, I(sce), J Recommended grade II A.
6.0		Topography
6.1	Floors	G + 1
7.0		Construction
7.1	Plinth	Very low plinth about 1 ft. high in grey basalt shallow courses.
7.2	Walls	External load bearing thick walls, internal non load-bearing walls.
7.3	Floor	Timber floors with wooden floorboards and rafters, supported by wooden joists and load
1.5		bearing walls. Kitchen having RCC slab floors.
7.4	Stairs	Main open well staircase in timber, wooden balustrade and handrail.
1.4	Stalls	Narrow spiral steel staircase from service area (kitchen) to first floor.
		Another straight flight staircase on Murzban Road side.
7.5	Openings	Rectangular door/window openings with wooden frame glazed shutters.
1.5	Opennigo	A verandah facing Azad maidan on northern side through out the length of the building.
7.6	Poofing	
7.6	Roofing	Timber truss gable end sloping roof with wooden planks and Mangalore roofing tiles.

Urban Design Research Institute

MMR- Heritage Conservation Society

Bombay Gy		180
7.7	Articulation	•
7.8	Finishes	Walls plastered and painted internally and externally. Wooden flooring in Badminton hall, party hall, reading room and lounge. Polished Kotah flooring in lobby area.
7.9	Interiors (Movable & Immovable)	Movable Teak wood tables, a standing clock in teak, intricately carved showcases, racks etc. Immovable Old lampshades in lobby area, Paneling on walls etc.
7.10	Compound/ Fence/ Gate	Continuous steel rod fencing defining the plot boundaries.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Numerous structures like electric substation, water storage tank, pump house etc. Small Mangalore tile structure serving as residence for secretary at the south end of the premises.
0 0		Services & Utilities
8.0 8.1	Lighting	Natural light through door-window openings and verandahs supplemented by electric light
8.2	Ventilation	fixtures. Naturally through door-window openings supplemented by electric fans and air-conditioning
-		units in the administrative offices, reading room and lounge areas.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No trace of fire fighting or precautionary system.
8.7	Other (HVAC/BMS/Security Systems)	Window unit air-conditioners installed at various locations.
		 Bd
9.0		Condition
9.1	Plinth Walls	Good - No evident damages.
9.2 9.3	Floor	Good - No evident damages. Fair - Additional closely spaced steel flats support RCC slab ceiling in kitchen area.
9.3 9.4	Stairs	Good - Staircase maintained well except for wear and tear in certain areas.
9.4	Openings	Fair - At many places A.C. units block the window openings.
9.6	Roofing	Good - No evident damage. Roofing in Party hall has been renovated few years back.
9.7	Articulation & Finishes	-
9.8	Services	Fair – Service pipes are leaking in some places. Plant growth.
9.9	Out Buildings	Good – Maintained well.
9.10	Overall Conditions	Good Maintenance level: Good
40.0		Transformation
10.0	Form	Transformation No visible changes
	Structure	No visible changes
	Articulation & Finishes	No visible changes
11.0		DP Remarks/ Perceived Threats
		Recreational Ground.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Until the restructuring of the Fort area in the 1860s after the demolition of the ramparts, the foreshore beaches and <i>maidans</i> of the city, such as the Bombay Green and the Esplanade formed the core of Bombay's social and sporting life. The British had their Hunt and gymkhanas, swimming, yachting and racing clubs but had no formal club-houses. The historic meeting of members of the various clubs to formally establish the Bombay Gymkhana was held on 19 June 1875 concluding in the formation of Bombay Gymkhana. The total cost of construction of the building was Rs.18,625/ The new pavilion was completed in 1907 at a total cost of around Rs.88,000/-, was designed by Charles Fredrick Stevens as a steel frame structure. It has a wide and airy verandah, which offered a pleasing view of the <i>Maidan</i> . References: INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and</i> Structures
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. www.bombaygymkhana.com

Bombay Gymkhana



View of building from across lawns



Sloping roof with wooden supporting truss



Verandah with sloping lean to roof with wooden supporting members



Sloping roof with wooden paneling, terrace space overlooking the lawn area



Interior View with rectangular and round openings



Wooden staircase with carved railing, newel post etc

Madhavda	s Laxmidas Kothari Pyaav		181	
		Common Ref No: 181		
		Card No: 239	5 Patrol Pump	
		Ward (Part): A (Part I)	and the set	
a new star	A CARLEN AND A CARLEND	CS No: - 7/729 (Fort Division)		
2.1.1		Plot Area: 755.86 sq m.		
	and part of the second se	B U Area: -		
		Date: 17/01/2005	OA	
		Recorded by: Arun Wadhwa	Haw the	
		Reviewed by:	AZAD MAIDAN	
SAME NAME		Int: NA	C C C C	
		Ext: Arun Wadhwa, Madhuri Tawde	AZAD MAIDAN	
		Photo Ref: 181_Madhavdas Pyaav.	HA HA	
			6 1	
		-	Location Plan	
1.0		Denomination		
1.1	Name of Premises	Madhavdas Laxmidas Kothari Pyaav		
1.2	Earlier Name	Madhavdas Laxmidas Kothari Pyaav		
1.3	Built in:	1913 (as per Tablet)	Extension Date: -	
2.0		Access		
2.1	Main	Mahatma Gandhi Road		
2.2	Subsidiary	-		
_				
3.0		Ownership pattern		
3.1	Present	Bombay Municipal Corporation		
3.2	Past	Bombay Municipal Corporation - Erected by	v Madhavdas Lavmidas Kothari	
3.3		Government	y Maunavuas Laxiniuas Rotinan.	
3.3	Status	Government		
10				
4.0		Use		
4.1	Present	Not in use.		
4.2	Past	Water fountain.		
4.3	Usage	Not in use		
5.0		Significance & Value Classification		
5.1	Townscape (manmade)	Small ornamental fountain located on footp	ath, close to the main road west side.	
5.2	Architectural Description	Planning		
		Two symmetrical square ornamental fountains with a low basin in between to feed water to		
		animals. Later a simple addition was carried out to serve as a drinking water fountain		
		between the two fountains.		
		Features		
		,	al fountains with low basin in between presently	
			ch of the fountains is decoratively treated with	
			o lower molded plinth base, central portion has	
		projecting jharoka and top is steep pyramid	lal shikara.	
		Style		
		Hindu temple features observed		
5.3	Intrinsic	-		
5.4	Value Classification	A(arc), B(des), B (uu)	Recommended grade: II B	
6.0		Topography		
6.1	Floors	Ground floor structure		
7.0		Construction		
7.1	Plinth	-		
7.2	Walls	Brick masonry walls.		
7.3	Floor			
7.4	Stairs	-		
7.5	Openings	_		
		- Duromidal obikara with kalooh facture at the	a tan aanatruatad in briek maaanny	
7.6	Roofing	Pyramidal shikara with kalash feature at the	e top constructed in brick masonry.	
7.7	Articulation	Pyramidal <i>shikara</i> feature		
7.8	Finishes	Buff basalt stone dressed external surfaces	5.	
7.9	Interiors (Movable & Immovable)	Movable		
		Immovable		
1		-		
			testesting and the second s	
7.10	Compound/ Fence/ Gate	Ornamental fountain stands open on the	tootpath with iron railing to one side, added by	
7.10 7.11	Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Building	unauthorized occupants.	to the rear side of the footpath. Also roadside	

	s Laxmidas Kothari Pyaav Landscape	dwellers occupy the pavement around.
	Lanuscape	
8.0		Services & Utilities
8.1	Lighting	
8.2	Ventilation	· ·
8.3	Electricity	· ·
8.4	Water Supply	- MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	
		·
8.7	Other (HVAC/BMS/Security Systems)	•
9.0		Condition
9.1	Plinth	Poor - Plant growth and blackening
9.2	Walls	Poor - Neglected state
-		
9.3 9.4	Floor Stairs	-
-		•
9.5	Openings	
9.6	Roofing	Poor - Damaged and neglected state
9.7	Articulation & Finishes	Poor - Damaged and painted features
9.8	Services	Poor – non-functional condition.
9.9	Out Buildings	•
9.10	Overall Conditions	Poor Maintenance level: Negligible
10.0		Transformation
	Form	Addition of a small brick structure in between the two decorative fountains.
	Structure	-
	Articulation & Finishes	Painted stone surfaces.
11.0		DP Remarks/ Perceived Threats
		Structure forms part of R zone
12.0		Additional Notes/ References/ Documents available
12.0		
		Additional Notes: Pyaav erected by Madhavdas Laxmidas Kothari in memory of his parents late Sh
		Laxmidas Jivandas Kothari and Smt. Nanibai Laxmidas Kothari for the use of drinking wat to feed Horses and Cattles and presented to the Municipal Corporation of Bombay.
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.



Four projecting bays with gujrat architectural style features with carved brackets, bands etc



Marble tablet with foundation details



Stone tablet with foundation details



Shikhara of the pyaav in stone with carved edges, brackets

Headguarter	s Maritime Air Operations		182
		Common Ref No: 182	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		Card No: 240	
		Ward (Part): A	
and the second second		CS No: 1442	
1 A 1 4		Plot Area: 8244.21 sqm.	ANADIA TODAN TODA ANADIA TODAN TODA TOTAL
		B U Area: -	ANANDILAL POUN
24		Date: 11/04/2005	ANANDILA ANANA BASA BASA BASA BASA BASA BASA BA
			T HE HOMBAY A 130
2419		Recorded by: Arun Wadhwa, Sonal Modak	AND
		Reviewed by:	B
Same St.		Int: Permission denied	AZAB MAIDAN
		Ext: Arun Wadhwa, Sonal Modak	THE THE THE THE
		Photo Ref.: 182_hq. maritime air operations	Location Plan
1.0		Denomination	Econton Finn
1.1	Name of Premises	Headquarters Maritime Air Operations	
1.1	Earlier Name	Headquarters Maritime Air Operations	
1.2		1925 (stone tablet near the west end)	Extension Date:
1.3	Built in:		Extension Date: -
2.0		Access	
2.0	Main	Mahatma Gandhi Road.	
2.2	Subsidiary	-	
2.2			
3.0		Ownership pattern	
3.1	Present	Indian Army	
3.2			
-	Past	Army - Government	
3.3	Status	Government	
4.0	_	Use	
4.1	Present	Air force offices and residences.	
4.2	Past	Army offices and residences.	
4.3	Usage	Daily.	
5.0		Significance & value Classification	
5.1	Townscape (manmade)	Stone dressed corner building along the plan side of Mahatma Gandhi Road. Main access presently reserved for Chief of Air force wher gate into the plot	through a porch at the corner intersection
5.2	Architectural Description	long parking shed. The corner portion is pre- accessed from the corner porch entrance wh residences of defence officers. Features Grey basalt stone dressed façade with high g continuous semicircular arch openings formir portion and end bays are marked by high gat	I. Continuous verandas along both the front ig. The long wings are intercepted by on each floor with extended wing to the rear se entry in the form of spiral stairs also je open central space is presently serving as a sently being used as Air force offices and ereas the rest of the building serves as pround floor with rusticated features marked by ig verandas. The inclined projecting corner ble end stone façade with decorative relief used of recessed openings spanning two floors parapet features. Openings along the corner h. A prominent cornice band marks the top angular openings. Rear side is simple with
5.3 5.4	Value Classification	- A(arc), B(per), B(des)	Recommended grade: II B
J.T			
6.0 6.1	Floors	Topography G + 3 floors.	

7.0		Construction
7.1	Plinth	Plinth height of about 0.9 M with a distinct coping at the top-dressed in grey basalt stone
7.2	Walls	Indeterminable
7.3	Floor	Indeterminable
7.4	Stairs	Indeterminable
7.5	Openings	Semicircular arch and rectangular openings externally. Wood framed glazed panel door and window shutters. Wooden louvered ventilator panels in the arch portion of window openings.
7.6	Roofing	Sloping Mangalore tile roof supported on steel truss system.
7.7	Articulation	Gable end corner and end bays with a central decorative relief feature, continuous corni band at floor levels, rusticated ground floor with continuous arch openings and cornice feature.
7.8	Finishes	Grey stone dressed front road side façade, plain plaster painted rear and internal wall surfaces. Internally indeterminable.
7.9	Interiors (Movable & Immovable)	Movable Indeterminable Immovable
		Indeterminable
7.10	Compound/ Fence/ Gate	High compound wall about 1.8 M in height, constructed in masonry and plaster finished.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Gates provided along the ends and corner of the two side road fronts, simple Iron gates Large plot with wide internal open space presently serving as parking sheds, also ancilla buildings added to the rear north side serving as canteen stores for Army personnel.
		Constant & Helliston
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST.
8.4	Water Supply	MCGM.
8.5	Drainage (Plumbing & Sanitation)	MCGM.
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.
9.0		Condition
9.1	Plinth	Fair except neglected state.
9.2	Walls	Fair externally indeterminable internally.
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Fair externally indeterminable internally.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Fair externally, Indeterminable internally.
9.8	Services	Fair externally, Indeterminable internally.
9.9	Out Buildings	Fair externally.
9.10	Overall Conditions	Fair externally Maintenance level: Fair
10.0		Transformation
	Form	-
	Structure	-
	Articulation & Finishes	Painting of stone dressed wall surfaces.
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available Additional Notes: Stone tablet mentions the project as Bombay Military land scheme: Architect Jacob Fernandes Esq. and Chief Engineer R S J Gillespie References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

Headquarters Maritime Air Operations



Grey stone clad façade with sloping roof, arched, rectangular and round openings, bands, gable end with round opening, pediment band, floor bands etc



Wooden railing detail

Subsidiary building with sloping chajjas on brackets, wooden trellis and railing work



Marble tablet 2 with foundation details



Double height arched opening with sill and lintel level frieze bands





Extended porch with rusticated stone clad arch



Marble tablet 1 with foundation details



The Indian	Globe Insurance Co. Ltd (Padhya Buildi	na) 183
		Common Ref No: 183
		Card No: 241 Nagar Chowk
	C The Residence Contraction of India There 11 11	Ward (Part): A (Part II)
		CS No: 1383
		Plot Area: 428.93
	H H HIMA	B U Area: -
		B U Area: - Date: 17/05/06
		Recorded by: Prachi Merchant
	INDIAN CALLAND C3	Recorded by: Prachi Merchant
		Reviewed by.
1		Int: Permission denied
1		Ext: Prachi Merchant
19 ¹⁰		Int: Permission denied Ext: Prachi Merchant Photo Ref: 183_Padhya building Location Plan
1		
	6 T	Location Plan
1.0		Denomination
1.1	Name of Premises	The Indian Globe Insurance Co. Ltd
1.2	Earlier Name	Padhya Building
1.3	Built in:	- Extension -
		Date
2.0		Access
2.1	Main	Junction of Walchand Hirachand Marg and Mangesh Shenoy Street
2.2	Subsidiary	Mangesh Shenoy Street
3.0		Ownership pattern
3.1	Present	Life Insurance Corporation of India
3.2	Past	Life Insurance Corporation of India
3.3	Status	Owner
0.0		
4.0		Use
4.1	Present	Commercial
4.2	Past	Commercial
4.3	Usage	Daily
т.0		Daily
5.0		Significance & value Classification
5.1	Townscape (Manmade)	Building is located at the junction of Walchand Hirachand Road and Mangesh Shenoy
5.1	Townscape (Marinade)	Street at the prime node of Nagar Chowk.
5.2	Architectural Description	Planning
J.Z	Architectural Description	Corner building with circular corner portion with two wings on either side of the road.
		Ground floor forms part of the arcade along Walchand Hirachand Road.
		All floors occupy office spaces
		Features
		Buff stone clad building with vertical and horizontal bands, recessed rectangular openings.
		Style.
5.2	Intrincia	Derives influence from Art Deco style of Architecture
5.3	Intrinsic	-
5.4	Value Classification	- Recommended Deleted
		grade:
6.0		Topography
6.1	Floors	G + 7
7.0		Construction
	Plinth	Low plinth
7.1		
7.2	Walls	Indeterminable
		Indeterminable
7.2	Walls	
7.2 7.3 7.4	Walls Floor Stairs	Indeterminable Indeterminable
7.2 7.3 7.4 7.5	Walls Floor Stairs Openings	Indeterminable Indeterminable Rectangular openings with glazed shutters
7.2 7.3 7.4 7.5 7.6	Walls Floor Stairs Openings Roofing	Indeterminable Indeterminable Rectangular openings with glazed shutters Indeterminable
7.2 7.3 7.4 7.5 7.6 7.7	Walls Floor Stairs Openings Roofing Articulation	Indeterminable Indeterminable Rectangular openings with glazed shutters Indeterminable Vertical and horizontal bands
7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes	Indeterminable Indeterminable Rectangular openings with glazed shutters Indeterminable Vertical and horizontal bands Fair
7.2 7.3 7.4 7.5 7.6 7.7	Walls Floor Stairs Openings Roofing Articulation	Indeterminable Indeterminable Rectangular openings with glazed shutters Indeterminable Vertical and horizontal bands
7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes	Indeterminable Indeterminable Rectangular openings with glazed shutters Indeterminable Vertical and horizontal bands Fair

The Indian	Globe Insurance Co. Ltd (Padhya Building) 183
7.10	Compound/ Fence/ Gate	No compound wall
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	-
8.2	Ventilation	-
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	
8.7	Other (HVAC/BMS/Security Systems)	
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Indeterminable
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Shutters have been altered, blocked to install AC units.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Ground floor bands have been covered by hoardings
9.8	Services	Fair
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	
	Structure	
	Articulation & Finishes	Ground floor bands have been covered by hoardings, Shutters have been altered, blocked to install AC units.
11.0		DP Remarks/ Perceived Threats
		Residential Zone + Part No Reservation
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

Ballard Ho	ouse		184 & 280
		Common Ref No: 184 & 280	
		Card No: 242	
		Ward (Part): A (Part II)	
		CS No: 1185 (Fort Division)	III / 1180 / 118
		Plot Area: - 957.26 sqm.	
			III BRACON III BRACON III BRALENDINUUSE
		B U Area: -	
		Date: 23/03/05	Adi Mu
		Recorded by: Zankhana Prajapati	Adi Murzban street
		Reviewed by:	1 in 182 AVA
		Int: Zankhana Prajapati, Prachi Merchant	1 Mill July Marsh and Marsh
		Ext: Zankhana Prajapati, Prachi Merchant	
		Photo Ref: 184 & 280_Ballard House	LI BERN HUSE
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Ballard House	
1.2	Earlier Name	Ballard House	
1.3	Built in:	1837.	Extension Date: -
1.0	Duitent	1001.	Extension Bate.
2.0		A	
2.0		Access	
2.1	Main	Adi Murzban Street.	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	J. D. Murzban Trust.	
3.2	Past	-	
3.3	Status	Owner/Tenant	
0.0	Status	Owner/Terlant	
4.0		Use	
4.1	Present	Algorithms, Shipping Co., Aquarius Marine C	Co. and other offices.
4.2	Past	Offices	
4.3	Usage	Daily.	
	Ŭ		
5.0		Significance & Value Classification	
5.0	Toursoone (menmede)	The building is situated along Adi Murzban S	Streat
J .1	Townscape (manmade)	The building is situated along Adi Muizban S	
		The main access to the building is from the o	xenter. Hittaa aasida kaa fiis saatas kaa kaa sid kaa kaist
			ed trapezoidal roof in central bay and has brick
		tile cladded on its exterior wall.	
5.2	Architectural Description	Planning	
		The building is symmetrical and has a rectar	
		The building is ground plus two storied high	with a mezzanine.
		Entrance of the building is from Adi Murz	zban Street, from the center, which leads to
			e staircase, offices are located. The toilet block
			he building has a sloping roof on the side bays
		and the central bay has a high-pitched trape	
		Features	
			10. 0
			ith the central one as the staircase shaft. Entry
			g bearing the name of the building with a cas
			ids projects out and has a pediment on top with
		decorative floral tympanum, with a coat of a	rms motif. A cornice band is seen at each floo
		level with decorative bargeboard.	
		Style	
		Indeterminable	
5.3	Intrinsic	-	
		- A(ara) $P(ara) P(daa) P(uu) F O()$	Decommonded grade U.A
5.4	Value Classification	A(arc), B(per), B(des), B (uu), F, G(grp)	Recommended grade II A
6.0		Topography	
6.1	Floors	G + 2 with mezzanine.	
7.0		Construction	
7.1	Plinth	Low height plinth clad with brick tiles.	
7.2	Walls	Brick wall with external wall clad with brick til	05
			C5.
7.3	Floor	Jack arch flooring.	
7.4	Stairs		ith lift block in well. It has wooden decorative
		balusters with wooden handrail.	
7.5	Openings	All doors are rectangular openings with singl	e or double leaf wooden shutters.
1.5		and a second sec	
1.5		All windows are either semicircular or rec	tangular arch openings in the front and side
1.5		All windows are either semicircular or rec	
7.6	Roofing	All windows are either semicircular or rec elevations, while rectangular opening in rear Sloping roof with asbestos as well as Manga	. They are two leaf-glazed shuttered.

Articulation	Pediment on top with decorative floral tympanum, with coat of arms motif. Cornice band a
	each floor level with decorative bargeboard.
Finishes	External walls clad with brick tiles.
	Internal walls are plastered and painted.
	Tiling is varied but largely of cement tiles.
Interiors (Movable & Immovable)	Movable
	- Immovable
Compound/ Fence/ Gate	Decorative cast iron entrance gate.
Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
	Services & Utilities
Lighting	Adequate Natural light through door-window openings supplemented by light fixtures.
	Adequate Natural ventilation through door-window openings supplemented by fans.
	BEST
	MCGM
	MCGM
	-
	AC units.
Other (TVAC/Divio/Security Systems)	
	Condition
Dlinth	Fair – covered with earth and broken edging.
	Fair - Has plant growth and rear façade plastered and painted.
	Fair - Is in good condition, most of the places covered with false ceiling.
	Fair – dust accumulation, rusting of grill around lift block.
Openings	Poor - Have grills added, opening are closed, frames painted, transformed, addition of window AC units.
Roofing	Indeterminable.
Articulation & Finishes	Poor – articulation is blackened and has dust accumulation. Internal plaster and paint peeling off at certain places.
Services	Indeterminable.
	-
	Fair. Maintenance level: Poor.
	Transformation
Form	Roofing changed, chajjas added.
	-
	Changed external fascia clad with brick tiles.
	DP Remarks/ Perceived Threats
	Building forms part of C1 zone
	Building forms part of or zone
	Additional Notes/ References/ Documents available
	Additional Notes: Former residence of the chairman of Bombay Port Trust, Mr. Ballard and also the office and press of Jame Jamshed – Bombay oldest dailies. 1832. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bomba
	Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/ Landscape Lighting Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes



Stone carved parapet in geometric pattern



Main entrance through an arched opening



Staircase with wooden railing



Exposed red brick symmetrical building with central bay with arched openings, triangular roof and corner bays with pediments, floor bands.



Corner bay with carved motif, pediment with carved tympanum, finial etc

Jaiji Mansion			185(a)
		Common Ref No: 185(a)	the fill the former of
	FIGER OF THE STATE STATE AND THE STATE	Card No: 243	10000 × 398
		Ward (Part): A (Part III)	The states
1		CS No: 1/389 (Coalaba)	The second second
	and the second	Plot Area: 1134.15 sq m.	ARTINE AND
a la la halar	States and Barris	B U Area: -	HENRY ROAD
	A STALL AND A STALL AND A	Date: 04/01/2005	ROAD
	1	Recorded by: Sonal Modak	H Joji Mont
		Reviewed by:	
		Int: Sonal Modak, Zankhana Prajapati	o funda for the state
		Internal photography permission denied	frend the main "
		Ext: Sonal Modak, Zankhana Prajapati	900 E
		Photo Ref: 185(a)_Jaiji Mansion.	and the first of the
			the set of the set
		10	
1.0		Denomination	Location Plan
1.1	Name of Premises	Jaiji Mansion	
1.1	Earlier Name	Jaiji Mansion	
1.3	Built in	,	ension Date: -
1.5			
2.0		Access	
2.1	Main	Shri Boman Kawasji Boman Behram Marg – Vehicu	ular and Pedestrian
2.2	Subsidiary	Henry Path - Pedestrian	
L .L	Cubbindity		
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	The Trustees of Port of Bombay	
3.3	Status	Owner and Tenant	
4.0		Use	
4.1	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Daily	
5.0	_	Significance & Value Classification	
5.1	Townscape (Manmade)	It is one of the many buildings on Shri Boman Kav	
		form an important streetscape in the tourist area corner plot at a junction.	s of the city. The building stands on a
		Main entrance is from Shri Boman Kawasji Boma	an Rohram Mara facing west through a
		porch.	an Demain marg lacing west through a
		A subsidiary entrance can be found from Henry Pat	th on the northern side
5.2	Architectural Description	Planning	
-		The building is symmetrical, rectangular in plan ha	aving a central main entrance through a
		porch with a main central staircase leading to upper	r floors.
		All floors have a typical layout with service areas,	toilets and servants' quarters located on
		the rear side. One can find narrow projecting balco	
		façade and on all floors on the northern and southe	
		Access to the building was denied so determining the	he internal planning is difficult.
		Features	
		Ground floor window openings have semicircular a	
		are provided with segmental arches and the rest are	e all rectangular openings.
		Style The facade Neo-Classical features.	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), E, G(grp), F Reco	ommended grade II B
		(····, - (r···, -, - (0·r·)) · · · · · · · · · · · · · · · · ·	
6.0		Topography	
6.1	Floors	G + 3 front wing, G + 5 rear wing housing servants'	quarters
7.0		Construction	
7.1	Plinth	Medium plinth in grey stone about 2 ft. 6 inches in	n height with projecting plinth protection
		band in buff basalt.	
7.2	Walls	Thick load bearing walls.	
7.3	Floor	Indeterminable	
7.4	Stairs	Total two staircases.	stands and band 19
		Main doglegged timber staircase with wooden balus	strade and handrall.

Jaiji Mansion		185(a)
		A narrow cast iron spiral staircase on rear (south-east) to access servants block.
7.5	Openings	Rectangular door openings with wooden panel shutters. Arched window openings with
		wooden frame shutters with glazed panels.
		Projecting balconies on all floors on northern and southern façades with wooden balustrade
		in geometric pattern. Balcony on western façade at first floor level with stone balustrades.
7.6	Roofing	Interminable
7.7	Articulation	Cornice bands at each floor level.
1.1	Alticulation	Decorative balustrades, which support the projecting balconies.
7.8	Finishes	Walls plastered and painted internally as well as externally.
7.9	Interiors (Movable & Immovable)	Movable
1.0		-
		Immovable
		-
7.10	Compound/ Fence/ Gate	There is no compound wall on the western side. In other places one finds a brick masonry
		wall about 2 ft 6 inches high with MS fencing above.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Garages on south-east corner.
	Landscape	Planter boxes along compound wall on north side.
		Servant's room, water storage tank, pump house on east side.
8.0		Services & Utilities
8.1	Lighting	Interminable
8.2	Ventilation	Interminable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Interminable
8.7	Other (HVAC/BMS/Security Systems)	Interminable
9.0		Condition
9.1	Plinth	Fair – Chipping off plinth protection stone.
9.2	Walls	Interminable. Minor cracks seen externally on walls.
9.3	Floor	Interminable.
9.4	Stairs	Fair – Not maintained well. Broken treads at places.
9.5	Openings	Fair – Door/window shutters are replaced in many places.
		Balconies on north and south side are enclosed in some parts.
9.6	Roofing	Interminable.
9.7	Articulation & Finishes	Broken bands to house service pipes. Major cracks observed in brackets, which support the
0.0	0i.u.	balconies.
9.8	Services	Poor - Requires urgent repairs. Broken service pipes causing leakage and dampness in
9.9	Out Buildings	the walls. Plant growth.
9.9	Out Buildings Overall Conditions	Fair – Repairs underway. Maintenance level Fair
9.10		Fair – Repairs underway. Maintenance level Fair
10.0		Transformation
10.0	Form	-
	Structure	- Addition of lift well in the lobby space.
	Articulation & Finishes	Repairs underway.
		itepailo uliuciway.
11.0		DP Remarks/ Perceived Threats
11.0		Building forms part of R zone
		Dunuing ionno part of N 2016
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:
		- References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and
		managing the area, (2004) Urban Design Research Institute





Building with rusticated stone clad ground floor with arched and rectangular openings, terrace balustrade, pediments etc



Side façade with modifications



Balcony with wooden glazed panels and new modifications



Verandahs with sloping roof with wooden carved panels



Extended entrance porch with rusticated stone cladding, terrace level balustrade etc





Arched openings with railing projections

Aamer Ho	use	185(b)
1.0		Common Ref No: 185(b) Card No: 244 Ward (Part): A (Part III) CS No: 399 (Colaba division) Plot Area: 732.54 sqm. B U Area: - Date: 04/01/2005 Recorded by: Sonal Modak Reviewed by: Int: Sonal Modak, Arun Wadhwa Internal photography permission denied Ext: Sonal Modak, Arun Wadhwa Photo Ref: 185(b)_Aamer House. Denomination
1.1	Name of Premises	Aamer House
1.1	Earlier Name	Aanie House
1.2	Built in	1902 Extension Date: -
1.0		
2.0		Access
2.1	Main	Shri Boman Kawasji Boman Behram Marg – Vehicular and Pedestrian
2.2	Subsidiary	Henry Path - Vehicular and Pedestrian
3.0		Ownership pattern
3.1	Present	Private – Mr. Zaidy
3.2	Past	Private – Mr. Abdeali Shaikh Tayebali Zaidy
3.3	Status	Owner and Tenants
4.0	-	Use
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Daily
5.0		Significance & value Classification
5.1	Townscape (Manmade) Architectural Description	It is one of the many buildings on Shri Boman Kawasji Boman Behram Marg forming an important streetscape in the tourist-frequented areas of the city. The building stands on a corner plot at junction. The main entrance is from Shri Boman Kawasji Boman Behram Marg facing west. A subsidiary entrance is from Henry Path on southern side. Planning The building has a rectangular plan with shorter side along Shri Boman Kawasji Boman Behram Marg on west. Entrance of the building is from Henry Path, which leads to a common lobby and staircase area having access to individual flats on each floor. Each floor has two residential units with a typical floor plan. On one side are servant's quarters with toilet block in corner and the access to servant's quarters is through a spiral staircase. Features Oriel windows span first and second floor height on north and south façade resting on petal shaped corbel. Intricately carved spandrels, semicircular window openings can also be seen. Decorative bands are seen at impost level. Arch springing point is decorative in nature.
		The façade displays Neo-classical features.
5.3		
5.4	Value Classification	A(arc), B(per), E, G(grp), F Recommended grade II B
6.0		Tonography
6.0	Eleore	Topography
6.1	Floors	G + 4 front wing, G + 6 rear wing housing servants' quarters
7.0		Construction
7.0 7.1	Plinth	Construction Medium plinth in grey stone about 2 ft. in height with plinth protection band in buff basalt.
7.1	Walls	External thick load bearing walls. Internal non-load bearing brick walls.
7.3	Floor	Indeterminable as access denied.
1.5		ווועטנטווווומטוב מז מטבזז עבווובע.

7.4	Ise Stairs	Total two staircases. 185(b
7.4	Stairs	Main doglegged timber staircase with wooden balustrade and handrail.
7 5	Onerine	A narrow cast iron spiral staircase on rear (south-east) to access servants block.
7.5	Openings	All door openings are rectangular with wooden paneled double shutters.
		Ground floor arched window openings with wooden framed glazed double shutters.
		Upper floor rectangular windows with wooden frame glazed panels.
		Oriel windows span first and second floor height on north and south façade resting on peta
7.0		shaped corbels.
7.6	Roofing	Partly flat RCC slab roof. Partly timber truss hipped roof with Mangalore roofing tiles.
7.7	Articulation	Petal shaped corbels supporting oriel windows.
		Decorative arch springing point. Carved spandrels.
		Wooden decorative fascia board.
7.8	Finishes	Walls plastered and painted internally as well as externally.
7.0		Terracotta flooring tiles.
7.9	Interiors (Movable & Immovable)	Movable
		Immovable
		•
7.10	Compound/ Fence/ Gate	Low height brick masonry compound wall with MS fencing above on three sides and the
		external wall of building forms boundary on Henry Road (south) side.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Water storage tank, Pump house on eastern side. Landscape and big trees on wester
	Landscape	side.
8.0		Services & Utilities
8.1	Lighting	Adequate daylight is supplemented with artificial lighting equipments wherever necessary.
8.2	Ventilation	Adequate ventilation through windows and verandahs supplemented with electrical fans a
		required.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No Traces
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed.
0.7	Other (ITVAC/BING/Security Systems)	
9.0		Condition
9.1	Dliath	Fair - Dampness
9.1	Plinth Walls	
•••=		Fair – Minor cracks. Plant growth.
9.3	Floor	Fair
9.4	Stairs	Fair – Cleanliness not maintained.
9.5	Openings	Fair – Shutters are replaced in many places.
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair - Brackets, on which the projecting balconies rest, have developed major cracks.
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	No visible changes
	Structure	No visible changes
	Articulation & Finishes	No visible changes
11.0		DP Remarks/ Perceived Threats
11.0		Building forms part of R zone
		Duniung ionis part of R 2018
40.0		A delivery of New York and December 10 and the second second second second second second second second second s
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and
		managing the area, (2004) Urban Design Research Institute



Building façade with arched openings, floor bands, projecting bay windows, sloping chajjas etc



Arched opening with scroll bracket keystone, carved spandrel detail



Projecting bay window with sloping chajja, sill frieze band, tapering band feature etc

AnA MARG
sion Date: -
Location Plan
sion Date: -
r and Pedestrian
r and Pedestrian
r and Pedestrian
Boman Kawasji Boman Behram
,
awasji Boman Behram Marg.
d displays a blend of Neo-Classical
g the Shri Boman Kawasji Boman
g the Shiri Bollian Nawasji Bollian
alatia fram Chri Damaa Kawasii
plot is from Shri Boman Kawasji
which connects all the floors having
toilet block in corner and access to
ι.
brackets and wooden louvers.
d partly glazed panels.
, , , , , , , , , , , , , , , , , , ,
and Vernacular styles.
mended grade II B
on laver.
on layer. earing brick walls.

Alexandra	House	185(c)
		columns. Most of the areas have false ceiling concealing the original floors.
7.4	Stairs	Total two staircases.
		Main open well timber staircase accessed from southern side.
75	Orariana	Other service staircase on rear (northern) side as service staircase.
7.5	Openings	All door/window openings are rectangular openings. The windows have ventilators above with wooden frames, double leaf-glazed panels with
		wooden louvers in the upper part.
		Verandahs on rear side
7.6	Roofing	Partly flat partly sloping with timber trusses and Mangalore roofing tiles.
7.7	Articulation	Decorative cast iron brackets, which support projecting balconies.
7.8	Finishes	Kotah, marble mosaic tiles provided as flooring material.
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable -
7.10	Compound/ Fence/ Gate	Grey stone ashlar masonary about 2 ft. in height with concrete coping and cast iron fencing. Entrance to plot is defined by two stone pillars.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Building has marginal open space on all sides, which is not maintained and is used as a
	Landscape	garbage dump.
		Garages, watchman's quarters, underground water storage tank on rear side.
8.0	Linking	Services & Utilities
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric light fixtures.
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.
8.3	Electricity	BEST
8.4 8.5	Water Supply Drainage (Plumbing & Sanitation)	MCGM MCGM
8.5 8.6	Fire Precaution	No trace.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
0.7		
9.0		Condition
9.1	Plinth	Poor – Minor cracks in masonary. Seepage, drainage water seeping into plinth, dust
		accumulation, and stone weathered.
9.2	Walls	Fair - Exposed brickwork, plant growth, cracks and seepage.
9.3	Floor	Poor –Severe leakage. Cracks at certain places, exposed corroded steel sections, seepage and totally damaged servant's quarter area.
9.4	Stairs	Fair - Main staircase is in fair condition, only some treads were loose and need polishing, but spiral staircase has corroded and is not maintained.
9.5	Openings	Poor - Window transformed, opening pattern changed, verandah enclosed, addition of grills, painted wooden frames, closed ventilators, addition of awnings, AC units.
9.6	Roofing	Fair - Eaves board and wooden members needs maintenance, rest not visible.
9.7	Articulation & Finishes	Poor - Plant growth, all features blackened due to dust accumulation, comice band broken,
		plaster and paint peeling off, wooden railing of parapet is broken and patch work of plaster is seen.
9.8	Services	Poor - All plumbing pipes have leakage; pipes are broken, have moss growth and are totally neglected and unhygienic condition.
9.9	Out Buildings	Poor – In totally neglected and annygenic condition.
9.10	Overall Conditions	Fair Maintenance level: Poor
10.0		Transformation
	Form	-
	Structure	Steel sections replace all wooden structural members.
	Articulation & Finishes	Ad hoardings and nameplates on articulation. False ceiling done in some areas.
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
·		
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		- Poferonana
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and managing the area, (2004) Urban Design Research Institute



Rear façade with intricate wooden panel work, louvered shutter, railing etc



Wooden staircase with wooden railing



Window with carved frieze band at sill level, sloping chajja supported on bracket



Open space

Churchill Ch	ambers		185(d)
		Common Ref No: 185(d)	mile i ans A
		Card No: 246	
		Ward (Part): A (Part III)	BESTMARG
		CS No: 403 (Colaba Division)	MARA
		Plot Area: 712.84 sq m.	- G G
			Bodo Han B ADA N TO
		B U Area: -	- Contranting the of the second
		Date: 11/01/2005	
		Recorded by: Arun Wadhwa	A Contraction of the second se
		Reviewed by:	ALLANA MARG
		Int: Zankhana Prajapati, Arun Wadhwa	403 403
		Internal photography permission denied	ALL Standard T
		Ext: Zankhana Prajapati, Arun Wadhwa	ALLANA MARG
TINTERN VE.		Photo Ref: 185(d) Churchill Chambers.	ARG Di Arme
			Sorgent Ha
			To The Most Addant The C
1.0		Denomination	Location Plan
1.0	Name of Description	Denomination	
1.1	Name of Premises	Churchill Chambers	
1.2	Earlier Name	Churchill Chambers	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Shri Boman Kawasji Boman Behram Marg.	
2.2	Subsidiary	J. A. Allana Marg.	
2.2			
2.0		Oursership notto	
3.0		Ownership pattern	
3.1	Present	Poonawalla.	
3.2	Past	Bhiwandiwalla Under Power of Appointing Tr	rustee given to Phiroze & others
3.3	Status	Owner/Tenant.	
4.0		Use	
4.1	Present	Residential, Consulate and little Wizard clinic	n
4.2	Past		5.
4.2			
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)		nction of Shri Boman Kawasji Boman Behram
		Marg and J.A. Allana Marg.	
		The main access to the building is from Shri	
			e road, displays a blend of Neo-Classical and
		Vernacular style features in its articulation.	
5.2	Architectural Description	Planning	
		The building has a rectangular plan with th	ne shorter side along the Shri Boman Kawasi
	· · · · · · · · · · · · · · · · · · ·		
		Boman Behram Marg	ie cherter dies dielig the entit Bernah Rahag
		Boman Behram Marg. Entrance of the building is from Shri Boman	
		Entrance of the building is from Shri Boman	ı Kawasji Boman Behram Marg, which leads to
		Entrance of the building is from Shri Boman corridor and staircase area, through which le	i Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The	Nawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar	Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled ter's region is through a spiral staircase.
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor	Nawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats.	Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase.
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features	a Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floor	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floor	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floor decorative floral tympanum with cartouche	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with the topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectange	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with a topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toilet ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations.
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations. uilloche band, medallion, cornice band are seen
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toilet ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations.
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen.	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations. uilloche band, medallion, cornice band are seen
		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style	Awaasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations uilloche band, medallion, cornice band are seer n dome top pilaster and a classical column with
53		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen.	Awaasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations uilloche band, medallion, cornice band are seer n dome top pilaster and a classical column with
5.3	Intrinsic	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol alar window openings with prominent scrol alar window openings with prominent scrol in verandah are located in two-side elevations alloche band, medallion, cornice band are seer n dome top pilaster and a classical column with al and Vernacular style in its features.
5.3 5.4		Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style	Awaasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations uilloche band, medallion, cornice band are seer n dome top pilaster and a classical column with
5.4	Intrinsic	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica - A(arc), B(per), E, G(grp), F	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol alar window openings with prominent scrol alar window openings with prominent scrol in verandah are located in two-side elevations alloche band, medallion, cornice band are seer n dome top pilaster and a classical column with al and Vernacular style in its features.
5.4 6.0	Intrinsic	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica - A(arc), B(per), E, G(grp), F	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol alar window openings with prominent scrol alar window openings with prominent scrol in verandah are located in two-side elevations alloche band, medallion, cornice band are seer n dome top pilaster and a classical column with al and Vernacular style in its features.
5.4	Intrinsic	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica - A(arc), B(per), E, G(grp), F	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol alar window openings with prominent scrol alar window openings with prominent scrol in verandah are located in two-side elevations alloche band, medallion, cornice band are seer n dome top pilaster and a classical column with al and Vernacular style in its features.
5.4 6.0	Intrinsic Value Classification	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica - A(arc), B(per), E, G(grp), F	A Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to differen rear corner has servant's quarters with toile ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with e topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol alar window openings with prominent scrol alar window openings with prominent scrol in verandah are located in two-side elevations alloche band, medallion, cornice band are seer n dome top pilaster and a classical column with al and Vernacular style in its features.
5.4 6.0	Intrinsic Value Classification	Entrance of the building is from Shri Boman corridor and staircase area, through which le residential flats, clinic and office area. The block in corner and access to servant's quar The ground floor is residential, first floor residential flats. Features Semicircular arched arcade at ground floo decorative floral tympanum with cartouche Corinthian column capital and some addition keystone. All other floors have rectangu keystone. Wooden ventilators and brackets Besides this certain additional feature like gu at all floor levels. Terrace parapet has onior fluted shaft is seen. Style Building displays derivatives of Neo Classica - A(arc), B(per), E, G(grp), F	Kawasji Boman Behram Marg, which leads to eads a narrow passage, connecting to different rear corner has servant's quarters with toiled ter's region is through a spiral staircase. has clinic and Consulate office and rest has or, entrance marked with two pediments with the topped by anthemion. Arcade column has nal features like cinquefoil and prominent scrol ular window openings with prominent scrol ular window openings with prominent scrol in verandah are located in two-side elevations. uilloche band, medallion, cornice band are seen in dome top pilaster and a classical column with al and Vernacular style in its features.

Urban Design Research Institute

Churchill C		185(d)	
7.2	Walls	Load bearing brick walls plastered and painted externally as well as internally.	
7.3	Floor	Jack arch flooring with I section.	
7.4	Stairs	Two staircases are present. The main staircase is L-shaped with winders where as second is a spiral staircase. The main staircase is a wooden staircase with a wooden handrail and baluster while spiral staircase is of cast iron.	
7.5	Openings	All doors have rectangular opening. All windows are either semicircular or flat arch openings. The windows are double leaved with ventilators above and below the lintel and sil respectively. All windows are glazed paneled in wooden frames.	
7.6	Roofing	Partly terraced and part sloping roof supported on wooden framework with Mangalore tiling and eaves board.	
7.7	Articulation	Entrance with two pediments with decorative floral tympanum with cartouche, Corinthiar column capital, cinquefoil, scroll keystone, guilloche band, medallion, cornice band at al floor levels. Terrace parapet has onion dome top pilaster.	
7.8	Finishes	External walls are plastered and painted. Internal walls are plastered and painted. Flooring is varied.	
7.9	Interiors (Movable & Immovable)	Novable - Immovable	
7.10	Compound/ Fence/ Gate	- Big compound wall at rear and low compound wall in sides. Entrance gate is collapsible.	
-	Curtilage/ Unbuilt space/ Out Buildings/	Chain link fencing on other side. Open spaces at rear.	
7.11	Landscape	Landscape is done on J.A. Allana Road.	
8.0 8.1	Lighting	Services & Utilities Adequate natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace.	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.	
9.0		Condition	
9.1	Plinth	Poor - Seepage, drainage water seeping into plinth, dust accumulation, and stone weathered.	
9.2	Walls	Fair - Exposed brickwork, plant growth, cracks and seepage.	
9.3	Floor	Poor - Cracks at certain places, exposed reinforcement, seepage and totally damaged and dilapidated servant's quarter area.	
9.4	Stairs	Fair - Main staircase is in fair condition, only some treads were loose and needs polishing, but spiral staircase is corroded and not maintained.	
9.5	Openings	Poor - Window transformed, opening pattern changed, verandah enclosed, addition of grills, painted wooden frames, closed ventilators, addition of awnings, AC units.	
9.6	Roofing	Fair - Eaves board and wooden members need maintenance, rest not visible.	
9.7	Articulation & Finishes	Poor - Plant growth, all features blackened due to dust accumulation, cornice band broken, plaster and paint peeling off, wooden railing of parapet is broken and patch work of plaster is seen.	
9.8	Services	Poor - All plumbing pipes have leakage; pipes are broken, have moss growth and are totally neglected and in unhygienic condition.	
9.9	Out Buildings	•	
9.10	Overall Conditions	Fair. Maintenance level: Poor.	
10.0	Form	Transformation	
	Structure	Reconstructed verandah by replacing wooden members by I – section, cantilevered verandah is supported on I – section column.	
	Articulation & Finishes	Advertising hoarding on articulation	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
· _ · v			

Churchill Char	nbers	185(d)
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and managing the area, (2004) Urban Design Research Institute



Pediment with intricately carved tympanum, dentil band, scroll brackets, carved balustrade



Arched window opening with scroll bracket keystone



Cast iron bracket detail supporting the projection



Column with carved capital



Staircase with wooden railing

Abbas Hou	use		185(e)
		Common Ref No: 185(e)	
		Card No: 247	and from the second
		Ward (Part): A (Part III)	Alang Road
		CS No: 397(Colaba Division)	
Ċ.		Plot Area: 973.24 sq m	Allana Road
		B U Area: -	- Sad - Long - And
	Section in Property of the		and a second sec
		Date: 07/01/2005	- The the second of the
0		Recorded by: Sonal Modak	and the second s
		Reviewed by:	H I' U I I I I I I I I I I I I I I I I I
		Int: Sonal Modak, Arun Wadhwa	A LI THE
1		Ext: Sonal Modak, Arun Wadhwa	answer and the second s
		Photo Ref.: 185(e)_Abbas House	The second second
\tilde{b}			
2			Location Plan
1.0		Denomination	
1.0	Name of Premises	Abbas House	
1.2	Earlier Name	Abbas House	
1.3	Built in:	1920's	Extension Date: -
2.0		Access	
2.1	Main	Shri Boman Kawasji Boman Behram Ma	rg – Vehicular and Pedestrian
2.2	Subsidiary	-	<u> </u>
<i>L.L</i>			
2 0		Ownership - offer	
3.0		Ownership pattern	
3.1	Present	Private -	
3.2	Past	Private – Mr. Bundiwala	
3.3	Status	Owner and Tenant	
4.0		Use	
4.1	Present	Commercial – Clinic, Offices, Lodge. Re	sidential
4.2	Past		
		Residential	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	The building is one of the buildings in a	series on Shri Boman Kawasji Boman Behram
		Marg.	
		The main access to the building is from	Shri Boman Kawasji Boman Behram Marg.
			the road, displaying a blend of Neo-Classical and
		Vernacular styles.	
5.2	Architectural Description	Planning	
5.2	Architectural Description		shorter side along the Shri Boman Kawasji Boman
			shorter side along the Shiri Doman Nawasji Doman
		Behram Marg.	la de la la la como de la Deserve d'ante de la como de l
			ce; access to plot is from Shri Boman Kawasji
			ain staircase, which connects all the floors having
		different residential flats, clinic and office	
		The rear corner has servant's quarters v	vith toilet block in corner and access to servant's
		quarter's block is through narrow timber	a fa fa sa sa s
1		qualité é éléétile alleugh haite i allee	staircase.
		The ground floor has residential, first ha	staircase. s clinic and offices and the rest have residential
		The ground floor has residential, first ha flats.	
		The ground floor has residential, first ha flats. Features	s clinic and offices and the rest have residential
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora	s clinic and offices and the rest have residential tive cast iron brackets and railing.
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor	s clinic and offices and the rest have residential tive cast iron brackets and railing.
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings.	s clinic and offices and the rest have residential tive cast iron brackets and railing.
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style	s clinic and offices and the rest have residential tive cast iron brackets and railing. level.
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings.	s clinic and offices and the rest have residential tive cast iron brackets and railing. level.
5.3	Intrinsic	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- -	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles.
5.3 5.4	Intrinsic Value Classification	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style	s clinic and offices and the rest have residential tive cast iron brackets and railing. level.
5.4		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- -	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles.
		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - A(arc), B(per), E, G(grp), F Topography	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B
5.4		The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - A(arc), B(per), E, G(grp), F Topography	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B
5.4 6.0	Value Classification	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - A(arc), B(per), E, G(grp), F	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B
5.4 6.0 6.1	Value Classification	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - A(arc), B(per), E, G(grp), F Topography G+4 with part terrace, G+6 Servants' qu	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B
5.4 6.0 6.1 7.0	Value Classification Floors	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - A(arc), B(per), E, G(grp), F - Topography G+4 with part terrace, G+6 Servants' qu Construction	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B arters' block.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - - A(arc), B(per), E, G(grp), F - Topography G+4 with part terrace, G+6 Servants' qu Construction Medium plinth in grey basalt with plinth g	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B arters' block.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - - A(arc), B(per), E, G(grp), F - Topography G+4 with part terrace, G+6 Servants' qu Construction Medium plinth in grey basalt with plinth p Thick load bearing external walls. Intern	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B arters' block. protection layer. al non-load bearing brick walls.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - - A(arc), B(per), E, G(grp), F - Topography G+4 with part terrace, G+6 Servants' qu Construction Medium plinth in grey basalt with plinth p Thick load bearing external walls. Interm Jack arch flooring with steel sections su	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B arters' block.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	The ground floor has residential, first ha flats. Features Covered balconies supported on decora Continuous cornice bands at each floor Rectangular door/window openings. Style Building displays characteristics of Neo- - - A(arc), B(per), E, G(grp), F - Topography G+4 with part terrace, G+6 Servants' qu Construction Medium plinth in grey basalt with plinth p Thick load bearing external walls. Intern	s clinic and offices and the rest have residential tive cast iron brackets and railing. level. Classical and Vernacular styles. Recommended grade II B arters' block. protection layer. al non-load bearing brick walls.

bbas Hou	se	185(
		Main open well staircase accessed from northern side.
		Other service staircase on rear (southern) side as service staircase.
7.5	Openings	All door/window openings are rectangular openings.
		The windows have ventilators above with wooden frame, double leaf-glazed panels with
		wooden louvers in the upper part.
7.6	Roofing	Partly flat partly sloping with timber trusses and mangalore roofing tiles.
7.7	Articulation	Decorative cast iron brackets, which support projecting balconies.
7.8	Finishes	Kotah, marble mosaic tiles provided as flooring material.
7.9	Interiors (Movable & Immovable)	Movable
1.0		-
		Immovable
7.10	Compound/ Fence/ Gate	Grey stone ashlar masonary about 2 ft. in height with concrete coping and cast iron fencir
1.10		Entrance to plot is defined by two stone pillars.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Building has marginal open space on all sides, which is not maintained and is used as a
1.11	Landscape	garbage dump.
	Edituscape	Garages, watchman's guarters, underground water storage tank on rear side.
		Carages, watchinian's quarters, underground water storage tank on rear side.
0 0		Services & Utilities
8.0	Liebtie e	
8.1	Lighting	Adequate Natural light through door-window openings supplemented by electric light
		fixtures.
8.2	Ventilation	Adequate Natural ventilation through door-window openings supplemented by electric far
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No trace.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
9.0		Condition
9.1	Plinth	Poor – Minor cracks in masonary. Seepage, drainage water seeping into plinth, dust
0.1	1 11101	accumulation, and stone weathered.
9.2	Walls	Fair - Exposed brickwork, plant growth, cracks and seepage.
9.2	Floor	Poor –Severe leakage. Cracks at certain places, exposed corroded steel sections, seepa
9.5	FIOOI	
0.4		and totally damaged servant's quarter area.
9.4	Stairs	Fair - Main staircase is in fair condition, only some treads were loose and needs polishing
		but spiral staircase is corroded and is not maintained.
9.5	Openings	Poor - Window transformed, opening pattern changed, verandah enclosed, addition of
		grills, painted wooden frames, closed ventilators, addition of awnings, AC units.
9.6	Roofing	Fair - Eaves board and wooden members need maintenance, rest not visible.
9.7	Articulation & Finishes	Poor - Plant growth, all features blackened due to dust accumulation, cornice band broken
		plaster and paint peeling off, wooden railing of parapet is broken and patch work of plaste
		is seen.
9.8	Services	Poor - All plumbing pipes have leakage; pipes are broken, have moss growth and are
		totally neglected and in unhygienic condition.
9.9	Out Buildings	Poor – In neglected condition.
9.10	Overall Conditions	Fair Maintenance level: Poor
10.0		Transformation
	Form	-
		Steel sections replace all wooden structural members.
	Structure Articulation & Finishes	Ad hoardings and nameplates on articulation. False ceiling in some areas.
		nu nuarunys anu namepiales un aniculation. Faise ceiliny in some aleas.
44.0		DD Devender (Devender di There (
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture
		Division of International Thomson Publishing Inc.
		Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and
		managing the area, (2004) Urban Design Research Institute

Abbas House





Projecting balcony with carved brackets, wooden paneling, bands etc



Bracket detail



Stone finial detail



Building with new modifications



Open well wooden staircase with wooden railing



Carved railing detail

Sandhurst I	House and Reay House	185(f)
		Common Ref No: 185(f) Card No: 248 Ward (Part): A (part III) CS No: 401 (Colaba Division) Plot Area: 2915.76 sq m B U Area: 7895.44 sq m Date: 18/1/2005 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Sonal Modak Ext: Arun Wadhwa, Sonal Modak Photo Ref.: 185(f)_Sandhurst House
		Card No: 248
		Ward (Part): A (part III)
		CS No: 401 (Colaba Division)
		CS No: 401 (Colaba Division) Plot Area: 2915.76 sq m B U Area: 7895.44 sq m
1		B U Area: 7895.44 sq m
		Date: 18/1/2005
		Recorded by: Arun Wadhwa
and the second		Reviewed by:
the star		Int: Arun Wadhwa, Sonal Modak
3	A REAL PROPERTY AND ADDRESS OF A DESCRIPTION OF A DESCRIP	Ext: Arun Wadhwa, Sonal Modak
<u></u>		Photo Ref.: 185(f)_Sandhurst House
S.J.		
		a lo
	The second se	A Oly The and a grant of the second s
		1 1 201 201 201 204
1000		The second s
		Location plan
1.0		Denomination
1.1	Name of Premises	Sandhurst House and Reay House
1.2	Earlier Name	Donald House and Fern House
1.3	Built in:	Indeterminable Extension Date: -
2.0		Access
2.1	Main	Shri Boman Kawasji Boman Behram Marg - Vehicular & Pedestrian
2.2	Subsidiary	BEST Marg - Vehicular and pedestrian
3.0		Ownership pattern
3.1	Present	Private Owner
3.2	Past	Indeterminable
3.3		
3.3	Status	Tenants.
4.0		Use
4.1	Present	Residences
4.2	Past	Residences
4.3	Usage	Daily.
5.0		Significance & Value Classification
5.1	Townscape (manmade)	Corner plot with two symmetrical buildings placed side by side slightly setback from the
		road front with narrow open spaces on all sides. Access is from the west side and also from
		abutting north road. Building is characterized by verandah fronts.
5.2	Architectural Description	Planning:
		Rectangular plan with narrow front and longer sides with central staircase cutting the plan
		into symmetrical front and rear wings accommodating two similar apartments. The building
		being just ground and four floors seems high due to large floor heights and in the process
		also accommodates intermediate floor in the rear long side. The residential units are
		accessed through a staircase landing into open verandah fronts stretching on two sides
		providing circulation within the house. Principal living and bedrooms are arranged along this
		veranda whereas kitchen, guest room and toilets are to the other side connected to the
		servant's wing, having smaller heights accommodating intermediate levels. Separate
		access to the servant's wing through narrow spiral stair accessing all the G + 7 levels. Both
		the buildings are just a mirror image along the central open space with servant's side facing
		each other.
		Features:
		Projecting Wooden verandahs to the two main facades with trellis and parapet features
		supported on decorative steel brackets. Front ground floor has stone relief frieze band,
		column capital. Brick faced façade is marked by cornice bands, framed windows and brick
		arch openings marking entrance and staircase.
		Style:
		Colonial and Vernacular style features.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), E, G(grp), F Recommended grade II B
6.0		Topography
6.1	Floors	G + 4 and G + 7 intermediate levels in servant's wing.
7.0		Construction
7.1	Plinth	High plinth height about 1.2 M except in servant's wing where it is 0.3 m high; dressed in
	-	grey basalt stone cyclopean course.
7.2	Walls	Brick masonry load bearing walls and wooden supporting members.
7.3	Floor	Wooden floorboards supported on wooden rafter and beam members.

Sandhurst I	House and Reay House	185(f)	
7.4	Stairs	Main stair is regular double flight wooden staircase with wooden balusters and handrail	
		Servant's wing has narrow spiral steep stair supported on central wooden post.	
7.5	Openings	All door/window openings are rectangular openings.	
		The windows have ventilators above with wooden frame, double leaf-glazed.	
7.6	Roofing	Sloping Mangalore tile roof over wooden boards with overhangs on the two symmetrica wings and central staircase concrete slab.	
7.7	Articulation	Relief features at front ground floor, brick arch openings, wooden trellis in verandas.	
7.8	Finishes	Brick faced external wall finishes with painted arch and lintel bands. Plaster painted internative wall surfaces. Ceramic and altered floor finishes observed.	
7.9	Interiors (Movable & Immovable)	Movable -	
		Immovable -	
7.10	Compound/ Fence/ Gate	Low compound wall on three sides	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Underground water tank and pump room in the central open space between the two wings Trees and plants seen in front and side open spaces.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light; also relies on artificial means.	
8.2	Ventilation	Adequate natural ventilation, also relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM- Underground and overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.'s	
9.0		Condition	
9.1	Plinth	Poor – poor finishing with cladding done over the stone finish.	
9.2	Walls	Poor – cracks, damaged brickwork and damp external walls though fair internally.	
9.3	Floor	Fair except reconstructed verandas and restrenghtening of floor with steel sections.	
9.4	Stairs	Poor – uneven and loose treads, poorly maintained.	
9.5	Openings	Poor – damaged and non-maintained shutters. Altered and encroached verandal openings.	
9.6	Roofing	Fair except some missing Mangalore tiles and decayed eaves board.	
9.7	Articulation & Finishes	Poor – damaged external wall surfaces, though fair internally, except servant's wing.	
9.8	Services	Poor – leaking and corroding plumbing lines.	
9.9	Out Buildings		
9.10	Overall Conditions	Poor externally and Fair internally Maintenance level: low	
10.0	_	Transformation	
	Form		
	Structure	Open verandahs encroached. Reconstructed inner verandas also steel supports added to wooden floor structure.	
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
40.0			
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		The Bombay Port trust reclaimed several acres of land at Colaba and Apollo Bunder durin 1873 to 1903 to provide spacious and valuable residential estates. It evolved as a planne residential scheme. As part of the scheme, shops were set up at the lower floors unified by the mandatory requirement of an Arcade along Merewether road. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading an managing the area, (2004) Urban Design Research Institute	

Sandhurst House and Reay House



Front façade with intricate wooden panel work, railing, sloping chajjas supported on brackets







Side view with new modifications



Ground level detail with carved pediment, motifs etc



Detail of column capital and frieze band



Façade with brick pointing, sill and lintel level bands etc

Hanny Hou	ISE			185(g)	
		Common Ref No: 185(g)		(3)	
	1000 March 1000	Card No: 249		10/1/00000	
	N CONTRACTOR	Ward (Part): A (part III)	NO	Real The series	
	ANT - CANADA	CS No: 413 (Colaba division)	WROJI	a 1 1 2 18	
	SAM DEPART	Plot Area: 1676.34 sq. mts	- 11 11	FARDIN TO NO	
		B U Area: -	- AF	ROAD	
		Date: -	PIT	40,3111	
			- C- //	PL SHA	
		Recorded by: Prachi Merchant	Mandlik Mai		
		Reviewed by:	and mai	9 TER	
5		Int: -	15	The share h	
	A DECEMBER OF A	Ext: Vrushali Pawaskar	e The	TAU MAHALA	
		Photo Ref: -	- KO	HOTECS	
IGHT			and the second s	the last	
11			ORANIC		
				Location Plan	
		• • • •			
1.0		Denomination			
1.1	Name of Premises	Sunny House			
1.2	Earlier Name	Hanny House		-	
1.3	Built in:	Indeterminable	Extension	-	
			Date		
2.0		Access			
2.1	Main	Shri Boman Kawasji Boman Behram	Varg - Vehicular & Ped	estrian	
2.2	Subsidiary	Mandlik Marg - Vehicular and pedestri			
3.0		Ownership pattern			
3.1	Present	Private			
3.2	Past	The Treasurer, Charitable Edowment	hy Rombay Presidency	& Others	
-	Status		by Duffibay Freshericy	& Others	
3.3	Status	Private			
4.0					
4.0		Use			
4.1	Present	Commercial and residential			
4.2	Past	Residential			
4.3	Usage	Daily			
ļ					
5.0		Significance & value Classification			
5.1	Townscape (Manmade)	Corner plot, forma a part of group		lereweather road with similar	
		features. Building is characterized by I	balcony fronts.		
5.2	Architectural Description	Planning			
		Corner building with ground floor arcade with commercial usage, upper floors residential			
		blocks with projecting balconies Features			
		Arcade with rusticated joints, projectir	ng balconies on bracke	ts	
		Style			
		Derives influence from Vernacular styl	le of Architecture		
5.3	Intrinsic	-			
5.4	Value Classification	A(arc), B(per), E, G(grp), F	Recommende	d IIB	
			grade:		
6.0		Topography			
6.1	Floors	G + 3			
7.0		Construction			
7.1	Plinth	Normal height			
7.1	Walls				
		Indotorminght-			
7.3	Floor	Indeterminable			
7.4	Stairs	Wooden staircase			
7.5	Openings	Rectangular openings, projecting libra	ries		
7.6	Roofing	RCC			
7.7	Articulation	Arcade, balconies with extended brack	kets		
7.8	Finishes	-			
	Interiors (Movable & Immovable)	Movable			
7.9					
7.9		-			
7.9		- Immovable			
7.9	Compound/ Fence/ Gate	-			

lanny House	•	185(g)
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	Natural lighting added with artificial means
8.2	Ventilation	Natural ventilation added with artificial means
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Blocked to take AC, grills added etc
9.6	Roofing	Fair
9.7	Articulation & Finishes	Hoardings blocking the façade articulation, grills and jails blocking openings
9.8	Services	Haphazard planning
9.9	Out Buildings	
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	
	Structure	Balconies enclosed
	Articulation & Finishes	Hoardings blocking the façade articulation, grills and jails blocking openings, opening blocked to take AC, grills added
11.0		DP Remarks/ Perceived Threats
11.0		No reservation
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Ground floor arcade, projecting balconies above



Transformations made to the structure

Candy Ho	use		185(h)	
		Common Ref No: 185(h)		
		Card No: 250	MANDLIK ROAD	
1		Ward (Part): A (part III)	ANDLIN	
		CS No: 411 (Colaba Division)	an Swastlya	
		Plot Area: 442.87 sqm.	- Towan sthya	
1		B U Area: 2077.78 sqft.	J C C IV	
		Date: 03/1/2005	410 Condy House	
		Recorded by: Arun Wadhwa	411 411	
		Reviewed by:	ATT OVOUNT OVOUN	
		Int: Arun Wadhwa, Sonal Modak	denrose The H	
		Internal photography permission denied	AND AND OF A	
		Ext: Arun Wadhwa, Sonal Modak	L' L' L'	
	CASHMIR ART PALACE	Photo Ref.: 185(h)_Candy House	The second second	
100	TANK MARKE		White House	
			Location plan	
1.0		Denomination		
1.1	Name of Premises	Candy House		
1.2	Earlier Name	Anglo Indian Association building		
1.2	Built in:	Foundation stone laid on 27 January 1889	Extension Date:	
1.5	Duiit III.		Extension Date: -	
2.0				
2.0	Mar's	Access	lable law and David Ch	
2.1	Main	Shri Boman Kawasji Boman Behram Marg - V	ehicular and Pedestrian	
2.2	Subsidiary	Mandlik Road - Vehicular & Pedestrian		
3.0		Ownership pattern		
3.1	Present	Private - Owner		
3.2	Past	Indeterminable		
3.3	Status	Tenant		
4.0		Use		
4.1	Present	Shops on ground floor, offices and residences	s above	
4.2				
	Past	Shops on ground floor, offices and residences	s above.	
4.3	Usage	Daily.		
5.0		Significance & Value Classification		
5.1	Townscape (manmade)	Corner building with mandatory pedestrian an	cade on street level and uniform height as a	
	,	unifying feature to all the buildings on Shri Boman Kawasji Boman Behram Marg. Main		
		access is from north side road into the stairca	ise lobby.	
5.2	Architectural Description	Planning		
		Corner building rectangular in plan with L-	shaped main building and low height seven-	
		storied servant's quarter in the southwest corner. Main staircase is located off center in the		
			three upper floors. Two apartments flank the	
			on the sides and rear adjacent to servant's	
		wing.	on the slace and rear adjusent to servante	
		Features		
			manad of parias of comisiroular arch aroads	
			posed of series of semicircular arch arcade	
			Distinct cornice bands break down the façade	
			by a pediment feature at the third floor marks	
1				
		, ,	decorative iron railing supported on numerous	
		small corbels.	decorative iron railing supported on numerous	
		small corbels. Style	decorative iron railing supported on numerous	
		small corbels.	decorative iron railing supported on numerous	
5.3	Intrinsic	small corbels. Style		
5.3 5.4	Intrinsic Value Classification	small corbels. Style	decorative iron railing supported on numerous	
		small corbels. Style Colonial style features.		
		small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp),	decorative iron railing supported on numerous	
5.4		small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography	Recommended grade II B	
5.4 6.0	Value Classification	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp),	Recommended grade II B	
5.4 6.0 6.1	Value Classification	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le	Recommended grade II B	
5.4 6.0 6.1 7.0	Value Classification Floors	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction	Recommended grade II B	
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in	Recommended grade II B	
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in Brick masonry load bearing walls.	Recommended grade II B evels in servant's wing. rough grey basalt stone.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	small corbels. Style Colonial style features. - A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra	Recommended grade II B evels in servant's wing. rough grey basalt stone.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4	Value Classification Floors Plinth Walls Floor Stairs	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5	Value Classification Floors Plinth Walls Floor Stairs Openings	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of framed glazed panel door window shutters on	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing	small corbels. Style Colonial style features A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of framed glazed panel door window shutters on Flat stone slab supported on steel members	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood external facades.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5	Value Classification Floors Plinth Walls Floor Stairs Openings	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of framed glazed panel door window shutters on Flat stone slab supported on steel members Decorative keystone over arch openings, floo	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood external facades.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of framed glazed panel door window shutters on Flat stone slab supported on steel members Decorative keystone over arch openings, floo	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood external facades.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6 7.7	Value Classification Value Classification Floors Plinth Walls Floor Stairs Openings Roofing Articulation	small corbels. Style Colonial style features. A(arc), B(per), E, G(grp), Topography G + 3 main building and G + 7 intermediate le Construction Medium plinth height about 0.9 M dressed in 1 Brick masonry load bearing walls. Wooden floorboards supported on wooden ra Regular double flight wooden staircase with w Rectangular door window openings large of framed glazed panel door window shutters on Flat stone slab supported on steel members Decorative keystone over arch openings, floo	Recommended grade II B evels in servant's wing. rough grey basalt stone. fter and beam members. vooden balusters and handrail. enough to have separate ventilators. Wood external facades. r level cornice bands. and plastered/ painted internal wall finishing	

Candy Ho	use	185(h)	
		·	
		Immovable -	
7.10	Compound/ Fence/ Gate	Building itself forms boundary along the two road fronts, a common masonry compound wall to the rear and south sides with the adjoining properties.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	
8.1	Lighting	Inadequate natural light relies on artificial means.	
8.2	Ventilation	Inadequate natural ventilation in the interiors relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM- Underground & overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.'s	
9.0		Condition	
9.1	Plinth	Poor – interventions along the shop fronts and neglected state.	
9.2	Walls	Poor – cracks, plant growth and seepage observed in the rear sides.	
9.3	Floor	Poor – Totally reconstructed verandas with steel members and stone slabs.	
9.4	Stairs	Fair except finishing and minor damage.	
9.5	Openings	Fair except Iron box grill window openings and neglected shutters on the rear and inne sides.	
9.6	Roofing	Fair.	
9.7	Articulation & Finishes	Poor -	
9.8	Services	Poor – leaking and corroding plumbing lines; also poor electrical maintenance.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Poor Maintenance level: Low	
10.0		Transformation	
	Form	-	
	Structure	Reconstructed steel balconies are insensitively done.	
	Articulation & Finishes	Sign boards obscure and damage arch openings and decorative features on ground floor.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: His Excellency the Honorable William Baron Sandhurst, Governor of Bombay laid foundation stone on 27 January 1889 for Anglo Indian Association Building as mentioned in the marble tablet at the building entrance. The Bombay Port Trust reclaimed several acres of land at Colaba and Apollo Bunde during 1873 to 1903 to provide spacious and valuable residential estates. It evolved as a planned residential scheme. As part of the scheme, shops were set up at the lower floors unified by the mandatory requirement of an Arcade along Merewether road. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and managing the area, (2004) Urban Design Research Institute	



Façade with arched openings, pediments and new modifications



Arcade with arched openings, wooden ceiling etc



Marble tablet with foundation details

Florence H	łouse		185(i)
		Common Ref No: 185(i)	TOJU TOJU B. B. E. L.
		Card No: 251	- A A
		Ward (Part): A (Part III)	
		CS No: 406 (Colaba Division)	- A
		Plot Area: Part of 543.95 sq m.	the state of the s
		B U Area: -	
		Date: 18/1/2005	B. BEHRAM ROAD MEREWEATHER ROAL
E		Recorded by: Arun Wadhwa	CHRAM PA
The		Reviewed by:	- TOAD MED
		Int: Arun Wadhwa, Sonal Modak	REWEATHE
CARLTON	HOTEL	Ext: Arun Wadhwa, Sonal Modak	ER ROAL
All second		Photo Ref: 185(i)_Florence House	
F	LORENCE HOUSE		
A SHATTER	and the second s		
1011			
			Location plan
1.0		Denomination	
1.1	Name of Premises	Florence House	
1.2	Earlier Name	Florence House	
1.3	Built in:	Indeterminable	Extension Date: -
1.0			Extension Bate.
2.0		Access	
2.1	Main	Shri Boman Kawasji Boman Behram Mar	n - Vehicular & Pedestrian
2.1	Subsidiary	-	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Mr. Melwani - Private Owner	
3.1	Past	Indeterminable	
-			
3.3	Status	Owner	
4.0			
4.0	Durant	Use	7
4.1	Present	Showroom on ground floor, hotel on first	loor and residences above.
4.2	Past	Shops and residences.	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Corner building accessed through an arca	aded east side road front. Mandatory pedestrian
			s serve as unifying feature to all the buildings on
		the Merewether road.	
5.2	Architectural Description	Planning	
			raight front and two wings around a narrow space
			ocated to the front south end accessing all uppe
			by. Series of rooms in all three wings accessed by
		narrow passages, common tollets are in	ocated at the passage ends. South wing is small
			e has an open veranda on to the road front. Fron
			e the pedestrian arcade, forming the front façade.
		Features	
			s composed of semicircular arch arcade with
			nt opening marks the entrance archway. Distinc ade at floor levels. Rusticated vertical bands flan
			ch segmental arch and rectangular openings are
		The end bays of lipper tioors within whi	ch seomental arch and rectandular obeninds are
		composed also marked by a running mole	
		composed also marked by a running mole Style	
5.2	Intrinsia	composed also marked by a running mole Style Colonial features.	ding band at lintel level.
5.3	Intrinsic	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a	ding band at lintel level.
		composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg.	ding band at lintel level.
5.3 5.4	Intrinsic Value Classification	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a	ding band at lintel level.
5.4		composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F.	ding band at lintel level.
5.4 6.0	Value Classification	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography	ding band at lintel level.
5.4		composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F.	ding band at lintel level.
5.4 6.0 6.1	Value Classification	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor.	ding band at lintel level.
5.4 6.0 6.1 7.0	Value Classification Floors	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction	ting band at lintel level. an intrinsic quality to all buildings along the Shr Recommended grade II B.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dressed	ting band at lintel level. an intrinsic quality to all buildings along the Shr Recommended grade II B.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresse Brick masonry load bearing walls.	an intrinsic quality to all buildings along the Shr Recommended grade II B.
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresss Brick masonry load bearing walls. Wooden floorboards supported on woode	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4	Value Classification Floors Plinth Walls Floor Stairs	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresse Brick masonry load bearing walls.	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5	Value Classification Floors Plinth Walls Floor Stairs Openings	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresse Brick masonry load bearing walls. Wooden floorboards supported on woode Regular double flight wooden staircase w -	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone. In rafter and beam members. ith wooden balusters and handrail.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresss Brick masonry load bearing walls. Wooden floorboards supported on woode	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone. In rafter and beam members. ith wooden balusters and handrail.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6 7.7	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing Articulation	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresse Brick masonry load bearing walls. Wooden floorboards supported on woode Regular double flight wooden staircase w - Sloping Mangalore tile roof with overhang -	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone. In rafter and beam members. ith wooden balusters and handrail.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing	composed also marked by a running mole Style Colonial features. High street level arcade seems to be a Boman Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F. Topography G + 3 and part fourth floor. Construction Medium plinth height about 0.75 M dresse Brick masonry load bearing walls. Wooden floorboards supported on woode Regular double flight wooden staircase w - Sloping Mangalore tile roof with overhang -	an intrinsic quality to all buildings along the Shr Recommended grade II B. ed in rough basalt stone. In rafter and beam members. ith wooden balusters and handrail.

Florence H 7.9		185(i Moyable
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable
7.10	Compound/ Fence/ Gate	Original small stone post and chained fence are now replaced with iron frame and chai link fence.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Large swimming pool in the landscaped open space enclosed in between the wings to th rear side. High G + 21 storied annex connected at ground and first floor stands to th northeast side.
8.0		Services & Utilities
8.1	Lighting	Inadequate natural light relies on artificial means except well-lit verandas.
8.2	Ventilation	Inadequate natural ventilation in the interiors relies on artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM- Underground & overhead water tank
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM
8.6	Fire Precaution	
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.
9.0		Condition
9.1	Plinth	Poor – poor finishing and interventions along the shop fronts in the form of cladding don-
9.1	FIIIUI	over the stone dressed surfaces.
9.2	Walls	Fair except some cracks and plant growth.
9.3	Floor	Fair as observed on first floor, indeterminable on upper floors being privately occupied.
9.4	Stairs	Fair.
9.5	Openings	Fair except on neglected inner side and ground floor.
9.6	Roofing	Indeterminable since inaccessible.
9.7	Articulation & Finishes	Poor – neglected externally and inner chowk side, also decaying wooden verandas and brackets.
9.8	Services	Poor – neglected plumbing lines and internal chowk space.
9.9	Out Buildings	Fair. Single storied structure abutting south side is fair.
9.10	Overall Conditions	Fair Maintenance level: fair except poor external finishes.
10.0		Transformation
	Form	-
	Structure	
	Articulation & Finishes	Advertisement boards on the façade.
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:
		The Bombay Port trust reclaimed several acres of land at Colaba and Apollo Bunder durin 1873 to 1903 to provide spacious and valuable residential estates. It evolved as a planne residential scheme. As part of the scheme, shops were set up at the lower floors unified b the mandatory requirement of an Arcade along Merewether road. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture,</i> Division of International Thomson Publishing Inc.

Florence House



Front façade with arcade, upper level arched openings, corner quoins, blocking of arches by hoardings etc



Balcony with arched openings with prominent keystone, railing, cornice band, corner quoins etc



Side elevation with balcony projection, wooden louvered railing wirk etc



Minton tile flooring



Arcade with arched opening, wooden ceiling etc



Window with incongruous installation of hoarding



Brackets supporting projecting balconies



Wooden trellis work in railing, bracket detail, sloping roof etc

Roosevelt House			185(j)
		Common Ref No: 185(j) Card No: 252 Ward (Part): A (part III) CS No: 471 (Colaba Division) Plot Area: 925.31 sq m B U Area: Indeterminable Date: 18/1/2005 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Sonal Modak Ext: Arun Wadhwa, Sonal Modak Ext: Arun Wadhwa, Sonal Modak Photo Ref.: 185(j)_Roosewelt House Denomination	B. BEHRAM ROAD MERE WEATHER ROAD Location plan
1.1 Na	ame of Premises	Roosevelt House	
	arlier Name	Roosevelt House	
1.3 Bu	uilt in:	Indeterminable	Extension Date: -
		A	
2.0 2.1 Ma	ain	Access	abigular & Dedactrian
	ain ubsidiary	Shri Boman Kawasji Boman Behram Marg - V Nauroji Fardaunji street and Tullock Road to t	
2.2 30	uboluidi y		
3.0		Ownership pattern	
	resent	Private - Owner	
3.2 Pa	ast	Indeterminable	
3.3 St	atus	Tenant	
4.0		Use	
	resent	Restaurants and shops on ground floor, reside	ences above.
	ast	Indeterminable	
4.3 08	sage	Daily.	
5.0		Significance & Value Classification	
5.1 To	ownscape (manmade)	Corner building with mandatory pedestrian arc unifying feature to all the buildings on the Shri access is from east side road through arcade	Boman Kawasji Boman Behram Marg. Main
	rchitectural Description	upper typical layouts from a staircase lobby. S narrow passages, common toilets are located quarters and south side has an open verand additional verandah bay articulated as the commercial shop front on two road fronts. Features Ground floor front facade is composed of seri decorative keystone and triangular pediment bands break down the facade scale into floor upper floors; various arch and rectangular pediment feature. Continuous projecting wo wooden supports mark South facade.	s located to the front north end accessing all Series of rooms in all three wings accessed by I at the passage ends. North wing is servant's dah on to the road front. Front side also has front façade. Entire ground floor serves as les of semicircular arch rusticated arcade with marks the entrance archway. Distinct cornice s. Rusticated vertical bands flank end bays of openings are uniformly arranged some with woden verandas with cast Iron parapet and and louvered trellises. Also some projecting
5.3 Int	trinsic	-	
5.4 Va	alue Classification	A(arc), B(per), E, G(grp), F	Recommended grade II B
1		Topography	
6.0		Topography	
6.0	oors		
	oors	G + 3 and part fourth floor.	
6.1 Flo	oors		n rough basalt stone.
6.1 Flo 7.0 7.1 Pli		G + 3 and part fourth floor. Construction	n rough basalt stone.
6.1 Flo 7.0 7.1 7.2 Wi 7.3 Flo	inth	G + 3 and part fourth floor. Construction Medium plinth height about 0.75 m. dressed ir	fter and beam members.

Roosevelt I 7.5	Openings	185(j Arch and rectangular facade openings with wood framed glazed panel shutters and	
7.5	Openings	Arch and rectangular racade openings with wood tramed glazed panel shutters an separate ventilator panel. External façade doors have upper glazed and lower woo paneled shutters. Also north side verandah openings are supported on wooden member with iron railing parapet.	
7.6	Roofing	Sloping Mangalore tile roof with overhangs. Single side sloping roof over part fourth floo Flat concrete roof over narrow servant's wing.	
7.7	Articulation	Decorative keystone over arch openings, floor level cornice bands, decorative pedimer and console features.	
7.8	Finishes	Plaster stucco finish external wall surfaces and plastered/ painted internal wall finishing Ceramic tile floor finishes.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	Building itself forms boundary along the two road fronts, a common masonry compound wall to the rear and south side with the adjoining properties.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	- -	
0 0		Services & Utilities	
8.0	Lighting		
8.1 8.2	Lighting	Inadequate natural light, relies on artificial means. Inadequate natural ventilation in the interiors, relies on artificial means.	
•••=	Ventilation Electricity	BEST	
8.3			
8.4 8.5	Water Supply Drainage (Plumbing & Sanitation)	MCGM- Underground & overhead water tank	
	Fire Precaution	Drainage connected to municipal sewers of MCGM	
8.6 8.7	Other (HVAC/BMS/Security Systems)	- Window unit A.C.'s	
9.0		Condition	
9.1	Plinth	Poor – interventions along the shop fronts and neglected state.	
9.2	Walls	Poor – cracks, plant growth and seepage observed in the rear sides.	
9.3	Floor	Poor – Totally reconstructed verandas with steel members and stone slabs.	
9.4	Stairs	Fair except finishing and minor damage.	
9.5	Openings	Poor - encroached verandahs, grilled window openings and neglected shutters on the rea and inner sides.	
9.6	Roofing	Fair except some missing Mangalore tiles and decayed eaves board.	
9.7	Articulation & Finishes	Fair front façade whereas poor side, rear and inner wall finishes, negligible maintenance.	
9.8	Services	Poor – leaking and corroding plumbing lines; also poor electrical maintenance.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Poor - except the front façade. Maintenance level: Low	
10.0		Transformation	
10.0		Transformation	
	Form	- Reconstructed verandahs have lost character.	
	Structure Articulation & Finishes	Sign boards obscure and damage arch openings and decorative features on ground floor.	
	Alliculation & Finishes		
11.0		DP Remarks/ Perceived Threats	
1110		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: The Bombay Port trust reclaimed several acres of land at Colaba and Apollo Bunder duri 1873 to 1903 to provide spacious and valuable residential estates. It evolved as a plann residential scheme. As part of the scheme, shops were set up at the lower floors unified the mandatory requirement of an Arcade along Merewether road. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading a managing the area, (2004) Urban Design Research Institute	

Roosevelt House



Entrance with corner rusticated quoins, incongruous installment of hoardings



Arched window opening with glazed paneled shutters, carved railing etc



Bracket detail supporting the projection



Minton tile flooring

Devidas N	lansion		185(k)
		Common Ref No: 185(k) Card No: 253 Ward (Part): A (Part III). CS No: 470 (Colaba Division). Plot Area: 2205.79 sqm. B U Area: - Date: 03/1/2005 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Sonal Modak Ext: Arun Wadhwa, Sonal Modak Photo Ref: 185(k)_Devidas Mansion	PU BULLET CONTRACTOR OF CONTRA
1.0		Denomination	
1.1	Name of Premises	Devidas Mansion	
1.2	Earlier Name Built in:	Thoburn House Indeterminable	Extension Date: -
1.0			LAGUISIUN Dale
2.0		Access	
2.1	Main	Shri Boman Kawasji Boman Behram Marg	- Vehicular & Pedestrian
2.2	Subsidiary	-	
3.0	_	Ownership pattern	
3.1	Present		urdas Thawani and Kalawanti Jotumal Thawani -
2.0	Dest	Private Owners since 1966.	
3.2 3.3	Past Status	Indeterminable Tenants	
5.5	Status		
4.0		Use	
4.1	Present	Shops on ground floor, offices, hospital an	d residences above.
4.2	Past	Shops on ground floor, offices and resider	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	accessed from Shri Boman Kawasji Boma on street level and uniform height serve as Boman Kawasji Boman Behram Marg.	acing the junction the rear of Taj Mahal hotel n Behram Marg. Mandatory pedestrian arcade s unifying feature to all the buildings on the Shri
5.2	Architectural Description	C-shaped overall volume with a narrow in into a passage leading to the staircase lo	attached servant's wing to the south side forming nternal open space. Main access is from arcade cated centrally in the north wing. Narrow internal spaces with long depths arranged side by side. ands of the long passage.
		on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast inc scale of the façade and continue the unif road stretch. Style	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long
5.3		Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast inc scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the un Kawasji Boman Behram Marg.	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman
5.3	Intrinsic Value Classification	Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast in scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the un	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long
5.4		Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast in scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the un Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman
		Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast inc scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the un Kawasji Boman Behram Marg.	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade enings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman Recommended grade II B
5.4 6.0 6.1	Value Classification	Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast irc scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the ur Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F Topography G + 4 main building and G + 8 intermediat	ircular arched openings and decorative keystone ber floors have wide central and side bays formed elieved by floor level comice bands. Front façade enings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman Recommended grade II B
5.4 6.0 6.1 7.0	Value Classification Floors	Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast irc scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the un Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F Topography G + 4 main building and G + 8 intermediat	ircular arched openings and decorative keystone per floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman Recommended grade II B
5.4 6.0 6.1	Value Classification	Long symmetrical front façade with semic on the rusticated ground floor arcade. Upp by rusticated column like projections and r is marked by regular segmental arch op features. Projecting wooden balconies on the fro wooden brackets and decorative cast irc scale of the façade and continue the unif road stretch. Style Colonial style features. High street level arcade continues the ur Kawasji Boman Behram Marg. A(arc), B(per), E, G(grp), F Topography G + 4 main building and G + 8 intermediat	ircular arched openings and decorative keystone per floors have wide central and side bays formed elieved by floor level comice bands. Front façade benings with decorative keystones and spandrel nt and arcade side facades are supported on in railings. Floor level cornice bands relieve the ormity with the adjacent buildings along the long niformity of the street experience of Shri Boman Recommended grade II B

Devidas Mansi	ion	185(k	
		floorboards supported on wooden rafter and beam members.	
7.4	Stairs	C – shaped wooden stair with a central well the accommodating lift shaft.	
7.5	Openings	Rectangular door/ window openings large enough to have separate ventilators. Wood framed glazed panel door/ window shutters on external facades.	
7.6	Roofing	Flat stone slab supported on steel members.	
7.7	Articulation	Decorative keystone over arch openings, floor level cornice bands.	
7.8	Finishes	Plaster stucco finished external wall surfaces and plastered/ painted internal wall finishing Ceramic tiles and altered glazed tile floor finishes.	
7.9	Interiors (Movable & Immovable)	Movable -	
		Immovable	
7.10	Compound/ Fence/ Gate	Building fronts the main road and masonry wall along the rear side enclosing the large compound.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Ancillary structures extensively used as commercial premises on the rear side of the large compound. Also numerous water tanks, pump rooms, etc. located in open spaces.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light except staircase, relies on artificial means.	
8.2	Ventilation	Adequate natural ventilation except some internal areas, relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM- Underground and overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Window and split unit A.C.	
9.0		Condition	
9.1	Plinth	Poor – interventions along the shop fronts and neglected state.	
9.2	Walls	Poor – cracks, plant growth and seepage observed in the rear sides.	
9.3	Floor	Indeterminable due to false ceilings.	
9.4	Stairs	Poor - Fair except finishing and minor damage.	
9.5	Openings	Fair except Iron box grill window openings and neglected shutters on the rear and inne	
0.0	opolinigo	sides.	
9.6	Roofing	Fair.	
9.7	Articulation & Finishes	Poor – varied interventions like cladding, repainting and signage over arcade opening and	
		features. Side and rear facades poorly finished. Also neglected staircase and passage areas. Internal finishes well maintained by occupants.	
9.8	Services	Poor – leaking and corroding plumbing lines; also messy electrical lines in staircase lobby and passages.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Poor Maintenance level: Low	
		÷	
10.0		Transformation	
	Form	-	
	Structure	Reconstructed steel balconies insensitively done.	
	Articulation & Finishes	Sign boards obscure and damage arch openings and decorative features on ground floor Iron brackets supporting A.C. units on the main facade	
44.0		DD Demarke/ Deventual Threats	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes/ References/ Documents available Additional Notes: The Bombay Port trust reclaimed several acres of land at Colaba and Apollo Bunder during 1873 to 1903 to provide spacious and valuable residential estates. It evolved as a planned residential scheme. As part of the scheme, shops were set up at the lower floors unified by the mandatory requirement of an Arcade along Merewether road. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and managing the area, (2004) Urban Design Research Institute	

Devidas Mansion



Fcaade with arched openings, projecting balconies, corner quoins etc



Balcony with stone balustrade, supported on scroll brackets, arched openings with carved keystone and spandrel



Corner detail with wooden trellis work, sloping chajjas on brackets, railing etc



Bracket detail



Balcony projection supported on brackets



Stone staircase with carved railing

Redshield	House		186
		Common Ref No: 186	B.E.S.T. MARG
		Card No: 254	et MARC
		Ward (Part): A (Part III)	
		CS No: 404 (Colaba Division)	464 7
		Plot Area: 546.45 sq m.	Bode House 404 VI N VI
	A LANDA A ANDREAM	B U Area: 8335.1282 sq m.	House V Farnham House
		Date: 11/01/2005	Transformer and the second sec
	of Law Total State	Recorded by: Zankhana Prajapati	
DAL		Reviewed by:	4 That Ad
		Int: Zankhana Prajapati, Arun Wadhwa	House VIII Chamber H
UTTOR	RED SHELD BURFY	Internal photography permission denied	
CONTRACTOR DE		Ext: Zankhana Prajapati, Arun Wadhwa	403 403 ×
INA A		Photo Ref: 186_Redshield House.	403 Churchill Chamber
			ALLANA MARG
			A MARO S
4.0		Denemination	Location Plan
1.0	Name of Premises	Denomination Redshield House	
1.1			
1.2	Earlier Name	Farnham House	Eutonoion Doto:
1.3	Built in:	Indeterminable	Extension Date: -
2.0		A	
2.0 2.1	Main	Access	
2.1	Main Subsidian	Shri Boman Kawasji Boman Behram Marg.	
Z.Z	Subsidiary	BEST Marg.	
2.0		Ownership pattern	
3.0 3.1	Present	Ownership pattern Indeterminable	
-			
3.2 3.3	Past	Bombay Port Trust. Owner/Tenent.	
3.3	Status	Owner/Tenent.	
4.0		Use	
4.0	Present	Ahmed Joo, Simran cleaners, Farm product	ts and Co. and Hostol and Dormitorios
4.1	Past	Indeterminable	ts and Co. and Hoster and Domittones.
4.2	Usage	Daily.	
4.0		Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)		inction of Shri Boman Kawasji Boman Behram
		Marg and BEST Marg.	,
		The main access to the building is from Shr	i Boman Kawasji Boman Behram Marg.
		Building has same height line along the r	oad and represents characteristics of the neo-
		classical style.	
5.2	Architectural Description	Planning	
			orter side along the Shri Boman Kawasji Boman
		Behram Marg.	
		The building is ground plus three storied hig	gh with part fourth floor.
			n Kawasji Boman Behram Marg, which leads to
		the corridor and staircase area rest is indete	
		Entire building is a dormitory except for the	ground floor, which has some shops.
		Features	
		Building has a semicircular arched arcade	e at ground floor and all window opening are
			with decorative scroll key stone, with cornice
			eatures treated as classical fluted columns with
		base and capital intercepted between windo	ow openings.
		Style Building displays characteristics of the Neo	Classical style
5.3	Intrinsic		Olassival style.
		1	[]]
54		$A(arc) B(per) \in G(arp) \in C$	Recommended grade II R
5.4	Value Classification	A(arc), B(per), E, G(grp), F`	Recommended grade II B.
			Recommended grade II B.
5.4 6.0 6.1		Topography	Recommended grade II B.
6.0	Value Classification		Recommended grade II B.
6.0	Value Classification	Topography	Recommended grade II B.
6.0 6.1	Value Classification	Topography G + 3 part fourth floor.	
6.0 6.1 7.0	Value Classification Floors	Topography G + 3 part fourth floor. Construction	e for plinth protection.
6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 3 part fourth floor. Construction Medium height stone plinth with edging don Load bearing brick walls plastered and pain	e for plinth protection.
6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	Topography G + 3 part fourth floor. Construction Medium height stone plinth with edging don Load bearing brick walls plastered and pain	e for plinth protection. ted externally as well as internally.


Redshield	House	186
		It is an open well-doglegged RCC staircase. It has wooden handrail and balusters.
7.5	Openings	All door and window openings are semicircular arched openings. Windows are four shuttered with ventilators above All windows are glazed panels in wooden frame.
7.6	Roofing	Partly terraced and part sloping roof supported on wooden framework with mangalore tiling and AC sheets.
7.7	Articulation	Keystones and comice bands.
7.8	Finishes	External walls are plastered and painted.
		Internal walls are plastered and painted. Flooring is varied.
7.9	Interiors (Movable & Immovable)	Movable
		Immovable
7.10	Compound/ Fence/ Gate	Chain link fencing. Has low compound wall.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Open spaces at rear and side.
	Landscape	Presence of pump room as outbuilding.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric ligh
0.1	2.9.10.19	fixtures.
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No trace.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
0.0		Condition
9.0 9.1	Plinth	Poor - Stone painted, weathering of plinth, changed near shops, dripping of AC, water or
		plinth, drainage pipe leakage.
9.2	Walls	Fair - Exposed brickwork at certain places, dampness, blackening and plant growth.
9.3	Floor	Indeterminable.
9.4	Stairs	Fair
9.5	Openings	Poor - Broken windowpanes, frames transformed, new windows replaced, grills, AC punctuates, railing closed with either brick wall or by wooden planks, dust accumulation and wooden frame deteriorated.
9.6	Roofing	Fair - Wooden members are deteriorating, addition of AC sheets as well as Mangalore tiles seepage is observed.
9.7	Articulation & Finishes	Poor - Comice band broken, blackened, plant growth, paint and plaster peeling off weathered and covered by hoardings.
9.8	Services	Fair - Leaking pipes, pipes blackened and plant growth on pipes.
9.9	Out Buildings	Pump room is not maintained and debris lying in open spaces.
9.10	Overall Conditions	Poor Maintenance level: Poor
10.0		Transformation
	Form	-
	Structure	- A dua dia mante basedin na bida faca da adio dation
	Articulation & Finishes	Advertisement hoardings hide façade articulation
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
		¥ '
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Direct for Compared in the Compared in t
		Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and
		managing the area, (2004) Urban Design Research Institute



Façade Articulation with arched openings, bands, columns etc



Arcade with arched openings, wooden ceiling



Window opening with modifications made to the shutters

Cama Hou	se			18
		Common Ref No: 187	MODI STREET	ož ož ož
		Card No: 255		CHE HE PARTE NO
		Ward (Part): A (Part II)		N-
		CS No: 279 (Fort division)		
A		Plot Area: 543.48 sq m.		
		B U Area: -	M OV 20	St G
		Date: 03/02/05		T T AGA
12			- 17 713	
145-1		Recorded by: Sonal Modak		
	KEYKE YONI RESTARANT	Reviewed by:		
		Int : Zankhana Prajapati, Sonal Modak	and where a	- I - I
16. 2		Ext: Zankhana Prajapati, Sonal Modak	t [*] MINT° I	ROAD
CPS-		Photo Ref: 187_Cama House.	MILL	-
				lo di
			SHAHID BHAGA	×
			i - LAGA	I SING ROAD
			Locat	ion Plan
1.0		Denomination		
1.1	Name of Premises	Cama House		
1.2	Earlier Name	Cama House		
1.3	Built in:	Indeterminable	Extension Date: -	
1.0			Extension Date.	
2.0		Access		
2.0	Main	Access Mint Bood Dodectrian		
2.1	Main	Mint Road – Pedestrian		
2.2	Subsidiary	Agiary Lane - Pedestrian		
3.0		Ownership pattern		
3.1	Present	Private – Trust		
3.2	Past	Private – Bai Hirabai (Wife of Dadiba Nowroj	i Saherdiedon) and oth	ers.
3.3	Status	Tenant		
4.0		Use		
4.1	Present	Residential, Commercial – Shops, offices		
4.2	Past	Residential		
4.3	Usage	Residential, Commercial - Daily		
4.5	Usage	Residential, Commercial - Daily		
5.0		Significance & Value Classification		
5.0	Townscape (Manmade)	It's a corner structure at the junction of Mint F	Pood and a narrow land	on couth of the
5.1	Townscape (Mannade)	structure with central eastern entrance and e		
5.2	Architectural Description	Planning	Apuseu blick laçade.	
J.Z	Architectural Description		acurtuard Main antron	aa diraathu anana inta
		Symmetrical squarish in plan with an internal		ice directly opens into
		courtyard. Central bay of front (eastern) faça		
		Two staircases lead to upper floors along the	northern and southern	i sides of court. All the
		service areas are located on rear (western) s	ide of the building.	
		Features		
		Exposed brick masonry on symmetrical front	façade. Semicircular a	nd segmental arched
		door/window openings.		
		Style		
		No Particular style. It displays the influence of	of the vernacular archite	ecture style.
5.3	Intrinsic	-		
5.4	Value Classification	B(per)	Recommended	Delete
			grade:	
6.0		Topography		
6.1	Floors	G + 2 front wings, G + 3 rear wings		
7.0		Construction		
7.1	Plinth	No plinth as such. Small portion that is visible	e, in grey random rubbl	e masonary.
7.2	Walls	Thick load bearing external walls in brick with		
7.3	Floor	Timber floors with wooden rafters in some ar		
-		original wooden flooring has been replaced.		
7.4	Stairs	Three timber staircases.		
· .7		Main doglegged staircase located in the cent	er of rear wind	
				of court
	Ononingo	Two straight flight staircases along the north	unadas franced siles	UI COUIL.
7 5		All windows are arched openings with glazed	wooden tramed glaze	u paneis. All window
7.5	Openings		-	
		openings are fixed with MS grills.	-	
7.5 7.6 7.7	Roofing Articulation		top.	

Cama Hou		18		
7.8	Finishes	Front façade has exposed bricks while the rest is plastered. Walls are plastered and painted internally. Shahabad tiles and cement coba as flooring material in all areas.		
7.9	Interiors (Movable & Immovable)	Movable		
		Immovable		
		A well in the south-east corner of the plot.		
7.10	Compound/ Fence/ Gate	Building sits on the entire plot.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Internal open court with Shahabad paving.		
	Landscape			
8.0		Services & Utilities		
8.1	Lighting	Adequate daylight is supplemented with artificial lighting equipments wherever necessary.		
8.2	Ventilation	Adequate ventilation through windows and verandahs supplemented with electrical fans as required.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	No Traces		
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed in some areas.		
9.0		Condition		
9.1	Plinth	Its height is reduced to almost nil.		
9.2	Walls	Fair – Minor cracks, dampness in walls. Plant growth.		
9.3	Floor	Fair – Deteriorated wooden members. In many areas original wooden flooring is replaced by ladi coba. Steel sections have been provided as additional supports to the floors.		
9.4	Stairs	Poor - Not maintained at all. Loose, broken treads. It is in dilapidated and dangerous stage		
9.5	Openings	Poor – MS grills fixed to all windows. All window shutters in bad condition. Broken, missing panes etc.		
9.6	Roofing	Poor - Deteriorated wooden members. Leakages through broken Mangalore tile roofing. Missing roof tiles.		
9.7	Articulation & Finishes	Poor – Plaster and paint peeling of due to dampness. Cracks in cement coba and shahabad flooring.		
9.8	Services	Poor – Broken pipes resulting in leakages. Cleanliness not maintained. Plant growth.		
9.9	Out Buildings	Well is kept closed, not in use.		
9.10	Overall Conditions	Poor Maintenance level Poor		
10.0		Transformation		
10.0	F			
	Form	Third floor has been added on the rear (western) side wing.		
	Structure	Floors are strengthened using steel members in many areas.		
	Articulation & Finishes	-		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of R Zone with shopline		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.		



Openings with sill and lintel level frieze bands win geometric pattern, sloping chajjas etc



Bombav	Water Works	188	
		Common Ref No: 188 Card No: 256 Ward (Part): A (Part II) CS No: 1078 (Fort division)	
		Plot Area: 451.51 sqm. B U Area: Date: 29/12/04 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa Ext: Arun Wadhwa Photo Ref.: 188_Bombay Water Works	
		Location Plan	
1.0		Denomination	
1.1	Name of Premises	Bombay Water Works	
1.2	Earlier Name	Bombay Water Works	
1.3	Built in :	Indeterminable Extension Date: -	
2.0		Access	
2.1	Main	Mint Road	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Municipal Corporation of Greater Mumbai	
3.2	Past	Bombay Municipal Corporation	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Office of Water Department, leakage department, pest control	
4.2	Past	Indeterminable	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Natural/ Manmade)		
5.2	Architectural Description	Planning It is a relatively small building that fronts the road. The plan is symmetrical around a regular staircase. The toilets are located to the rear of the staircase. A series of rooms span the depth of the building. There are typical floor spaces on the three floors. Features Semi circular arched openings, stucco details, projecting stone cornices at floor levels, keystone detail, colonnade, Features in stucco with a distinct base and capital.	
5.3	Intrinsic	-	
5.4	Value Classification	B(per), B (des) Recommended grade: III	
6.0		Tonography	
6.0 6.1	Floors	Topography G + 2	
0.1			
7.0		Construction	
7.0 7.1	Plinth	Construction Black basalt dressed stone, ashlar coursed, around one foot high.	
7.1	Walls	Brick Masonry walls.	
7.3	Floor	The first floor is jack arched, the second and third floors have flat concrete slabs. The floor finishes vary from Kotah to mosaic tiles. There is no trace of the original floor finishes.	
7.4	Stairs	The timber staircase is supported on floor beams. A large decorated wooden newel post is at the entrance. The staircase has timber balusters and a timber handrail.	
7.5	Openings	The openings have semi circular arches.	
7.6	Roofing	The building has for a roof, a flat concrete slab. The staircase roof is Mangalore tiled.	
7.7	Articulation	-	
	Finishes	- The ground level is finished in rough black basalt. The upper floors have a brick faced finish. The	
7.8		projecting features are in a light coloured Porbander stone. The internal surfaces are plastered and painted.	

Bombay	Water Works	188
		and furniture are very ordinary.
7.10	Compound/ Fence/ Gate	The entrance to the building has a double shutter door.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The residential quarter is a single storied sloping roof structure to the north of the plot. The attached road has been developed. There is a sloping roof structure to the south. An illegal shanty like structure houses the printing press to the rear west side.
8.0		Services & Utilities
8.1	Lighting	Natural and artificial light is available
8.2	Ventilation	Natural and artificial ventilation is available.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Several alterations and plumbing interventions have been made to the rear and the side of the plinth. Encroachments, plant growth and water logging were observed to the rear.
9.2	Walls	The walls display many cracks. The brickwork is exposed. Plant growth and dampness is seen in many areas.
9.3	Floor	Cracks can be seen in the floors and reinforcement has been exposed. Dampness can be seen in a few places.
9.4	Stairs	Some timber floor boards are broken, the finish is poor, balusters are missing and the handrail is loose.
9.5	Openings	The openings have been altered and are damaged. Ventilator panels are missing and glass panes are broken. The louver shutters are damaged and in a poor state.
9.6	Roofing	The roof level is inaccessible but is of no major concern. The wooden roof over the staircase is neglected and relatively decayed. Damp surfaces can be observed from below.
9.7	Articulation & Finishes	The Porbander stone features like the cornice and the openings have blackened and are damaged. The brick facing is severely damaged and there is excessive plant growth on the rear façade. Pan stains can be observed on the lower portion of the front façade, abutting the road.
9.8	Services	The walls tiles and toilets are in poor condition. The plumbing lines need maintenance.
9.9	Out Buildings	-
9.10	Overall Conditions	Poor Maintenance level: Neglected
10.0		Transformation
	Form	
	Structure	-
	Articulation & Finishes	There is paint application over the dressed basalt stone entrance façade.
11.0		DP Remarks/ Perceived Threats
11.0		Municipal office extension, building forms part of R zone.
12.0		Additional Natas/ Deferences/ Desuments susilable
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

Bombay Water Works



Front façade with arched openings with prominent keystone, balustrade, floor bands etc



Recessed arched opening with louvered paneled shutters, balustrade, double columns, floor bands etc



Brick lined façade with arched openings, louvered shutters



Grey stone clad façade with arched window with modifications made to the shutters and chajja



Balustrade detail



Interior view with high ceiling and arched openings



Arched entrance with modifications made to the opening



Staircase with wooden railing

Urban Design Research Institute

Young Lad	lies High School		189
		Common Ref No: 189	
		Card No: 257	PURSHOTTAN THANUDAS ROAD
		Ward (Part): A (part II)	TTAN THAN
		CS No: 736	R A ROAD AS ROAD
		Plot Area: 801.01 sqm.	and and a second
		B U Area: 6209.7308 sqft.	T. E. The second second
1		Date: 30/12/2004	St 3 - 5 Tot las
		Recorded by: Arun Wadhwa	
13		Reviewed by:	The Phan is the second
		Int: Zankhana Prajapati, Arun Wadhwa	
		Ext: Zankhana Prajapati, Arun Wadhwa	The first of the second
1		Photo Ref.: 189_Young Ladies' High School	
			NAU - 5 - 5
			MAHARISHI DADICHI MARG
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Young Ladies High School	
1.2	Earlier Name	-	
1.3	Built in:	1867	Extension Date: -
2.0		Access	
2.1	Main	Murzban Road	
2.2	Subsidiary	Prescott Road	
2.2	Gubsidiary	1 Tescoll Nodu	
3.0		Ownership pattern	
	Dresent	Private (Abbas Nooroudin Zunkhawala Mariar	m Abbas)
3.1	Present		n Abbas)
3.2	Past	Indeterminable	
3.3	Status	Owner/Tenant	
4.0		Use	
4.1	Present	Girls school, shop – Trafford House and reside	ential.
4.2	Past	Indeterminable	
4.3	Usage	Institutional/commercial/residential – Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	The building is between Murzban and Prescot	tt Road
		The main access to the building is from Murzh	oan Road
5.2	Architectural Description	Planning	
		The building has a rectangular plan with the n	arrow side along the road.
		The building is ground plus three storied high	with sloping roof and part terrace.
		Entrance of the building is from Murzban road	
		to corridor and staircase area, at each floor le	
		different classes. Toilets are in the center of the	
		there is presence of service spiral staircase.	
		Ground floor has a residential flat and Trafford	House shop, rest all floors accommodate the
		girl's school.	
		Features	
		The building is in gray stone ashlar masonry v	vith cornice band on each floor and lintel
		level. It has pointed arch openings and top flo	
		openings. Has ventilators with colored glass a	
		cyclopean masonry surface. Festoon at terrac	
		Style	
		Building represents characteristics of Neo-Got	thic style
5.3	Intrinsic		uno styre.
5.4	Value Classification	A(arc), A(his), A(cul), B (des), B (uu), F, G(grp) Recommended II B
5.4	Value Classification	A(aic), A(iis), A(cui), B (ues), B (uu), F, G(gip	
			grade:
6.0		Tananyanhu	
6.0		Topography	
6 4	Floors	G + 3.	
6.1			
		• • •	
7.0		Construction	
7.0 7.1	Plinth	Grey stone with low plinth with edging done for	
7.0		Grey stone with low plinth with edging done for Thick load bearing rubble masonry with ashlar	
7.0 7.1	Plinth	Grey stone with low plinth with edging done for	r masonry on external fascia, and internal wal

Urban Design Research Institute

MMR- Heritage Conservation Society

	es High School	18
7.4	Stairs	Two staircases are present. The main staircase is L-shaped winding while the second staircase is a spiral service
		staircase. Timber staircase with decorative handrail and baluster and above the existing handrail
		there runs MS hollow pipe as additional handrail. The spiral staircase is of mild steel with MS handrail and balusters.
7.5	Openings	All doors are under pointed arch openings and at third floor semicircular arched openings.
		All doors are double leaf heavy panel wooden doors with ventilator above. All windows are pointed arch windows except for the third floor windows which has
		semicircular arched openings. All windows are double shutter partly glazed windows.
7.6	Roofing	Staircase has conical roof with manglore tile over timber framework, the front and half of the building has sloping roof and rest has terrace.
7.7	Articulation	Cornice bands, terrace parapet motif, corbels.
7.8	Finishes	External walls have exposed stone fascia and Grey ashlar masonry. Internal walls are plastered and painted.
		Flooring in some portion is of Minton and ceramic mosaic tile.
7.9	Interiors (Movable & Immovable)	Movable Old benches and tables.
		Immovable Decorative brackets and wooden partition.
7.10	Compound/ Fence/ Gate	Compound wall is a stone wall- plastered and painted. Has gatepost with crown like
7.10	Compound, Tence, Gale	feature.
7 1 1	Curtilage/ Unbuilt space/ Out Buildings/	Has Iron gate at both front and rear side.
7.11	Landscape	Has open space in front and sides of the building. Has water tank, pump room as out building; some old trees and some planter boxes.
0 0		Camilaan 9 Hitilitian
8.0 8.1	Lighting	Services & Utilities Adequate natural light through door-window openings supplemented by electric light
	Lighting	fixtures.
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Nothing prevalent.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
9.0		Condition
9.1	Plinth	Fair. Blackening of stone, dust accumulation, cement pointing and painted surface.
9.2	Walls	Fair. Blackened wall surfaces, cement pointing, plant growth, seepage and dampness and broken stone.
9.3	Floor	Fair. At certain places paint on wooden members was peeling off, I section have been added to strengthen the flooring.
9.4	Stairs	Good. The main staircase is in good condition lacks only polishing of wooden members. Poor. The spiral staircase is in total dilapidated condition, rusted to the extent where tread
		and member are missing, neglected and not in use.
9.5	Openings	Poor. Windows has wooden awning, many windowpanes were closed with tin sheet, wooden members are painted incongruously, addition of grills, AC, ventilators closed and
		shutter damaged. Many arches are having heavy cracks.
9.6	Roofing	Poor. The entire roof is poured with asphalt and stone parapet damaged at certain portion.
9.7	Articulation & Finishes	Poor. Arches are having cracks, cornice band and corbels are blackened, dust accumulation on festoon.
		Internal Plaster and paint peeling off plant growth and dust accumulation.
		External wall blackened, cement pointing and plant growth Tiling is done in patchwork.
9.8	Services	Poor. Toilets have dampening due to improper service connection.
9.9	Out Buildings	Fair.
9.10	Overall Conditions	Fair Maintenance level: Poor.
10.0		Transformation
	Form	- Addition of Least Constant and Co
	Structure Articulation & Finishes	Addition of I section for strengthening. Painted arches and signboard.
11.0		DP Remarks/ Perceived Threats
		Secondary school, building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
-	Design Research Institute	MMR- Heritage Conservation Society

Young Ladies	High School	189
Toung Ladies		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.
		-



Grey stone clad building with corner projecting bay with sloping roof, arched openings and floor bands



Arched openings with carved balustrade, sloping chajjas, round windows, bands etc



Bracket detail

Urban Design Research Institute



Rear façade with arched openings, carved arched ventilator and sill level frieze bands, floor and lintel level bands



Window opening with modifications made to the chajja



Sloping chajja with wooden fascia detail, stone balustrade at terrace level

MMR- Heritage Conservation Society

Young Ladies High School



Gate with grey stone clad gate posts



Cement tile flooring



Railing detail



Chajja deail with carved brackets, carved fascia, curved soffit profile in wood

First Churc	ch of Christ Scientist and Christian Sc	ience and DBS House	190
	85.	Common Ref No: 190	
P		Card No: 258	PURSHOTTAM THAKURDAS ROAD
-	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ward (Part): A (Part II)	RSHOTTA
		CS No: 735 (Fort)	O AM THAK
		Plot Area: 932.86 sq m.	NURDAS D
Le		B U Area: -	Manual Control of Cont
1	A LOOK AND	Date: 29/12/2004	and the second second
			S Trener War
10.2		Recorded by: Sonal Modak	105 - Til - T
86 - C		Reviewed by:	the start a start
me l		Int: Sonal Modak	
		Internal photography permission denied	The she she of So
		Ext: Sonal Modak	A A A A A A A A A A A A A A A A A A A
		Photo Ref: 190_DBS House.	W Hannah Manan Bran St
1			Contras Non
			Location Plan
- 26	No and No.		
1.0		Denomination	
1.1	Name of Premises	First Church of Christ Scientist and Christian S	
1.2	Earlier Name	First Church of Christ Scientist and Christian S	Science and DBS House
1.3	Built in:	1885	Extension Date: -
			· · · ·
2.0		Access	
2.1	Main	Murzban Road – Vehicular and Pedestrian	
2.1	ividii i	Prescott Road – Vehicular and Pedestrian	
2.2	Subsidiary		
2.2			
3.0		Ownership pattern	
	Dresset		
3.1	Present	Private	
3.2	Past	Diners Club India Pvt. Ltd.	
3.3	Status	Owner and Tenant	
4.0		Use	
4.1	Present	Commercial – Offices	
		Institutional – Library and Reading Room	
4.2	Past	Commercial – Offices	
		Institutional – Library and Reading Room	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	Exposed brick structure, stands out in the neigh	ghboring massive stone structures.
	,	The stretch of plot is from Murzban Road on w	
		There are two main entrance gates from both	the roads.
		The building is located roughly centrally in the	plot.
5.2	Architectural Description	Planning	
		A symmetrical building with central main entra	ance and another from a marginal space on
		northern side.	5 · · · · · · · · · · · · · · · · · · ·
		First Church of Christ Scientist and Christian S	Science occupy western half part on ground
		floor. There is one medium size hall to accom	
		are lectures and seminars and a library with re	
		DBS Company occupies remaining half on gro	
		Central main staircase leads to upper floors.	
		Services and toilet block is located along sout	hern side of the building
		Features	
		Projecting timber balconies supported on deco	orative wooden brackets on western facade
		External walls display exposed red brick masc	
		Corner step out balconies. Bands at each floo	
		Segmental arches above some of the opening	
		the rectangular openings. Floral motifs on faca	
		Octagonal short columns at the corner balcon	
		Style	to mar accordave column capitals.
1		Building displays no particular style.	
1		Dulluling displays no particular style.	
5.2	Intrincio		
5.3	Intrinsic	-	am) Decommonded are de U
5.3 5.4	Intrinsic Value Classification	- A(arc), A(his), A(cul), B (des), B (uu), E, F, G(
		- A(arc), A(his), A(cul), B (des), B (uu), E, F, G(grp) Recommended grade II A
5.4			
		- A(arc), A(his), A(cul), B (des), B (uu), E, F, G(Topography G + 2	

7.0		Construction
7.1	Plinth	Medium plinth about 2 ft. 6 inches high in grey stone shallow courses with projecting plinth protection layer.
7.2	Walls	Thick load bearing brick walls with wooden columns to support upper floors. Internal non- load bearing brick walls.
7.3	Floor	Timber floors with large wooden beams, wooden rafters and planks above as floorboards.
7.4	Stairs	Total two staircases.
	otano	Main open well RCC staircase located centrally.
		Rear side narrow, straight flight steel service staircase.
7.5	Openings	All the doors have wooden panel shutters.
		Arched and rectangular openings have wooden framed glazed double shutters.
		Projecting wooden balconies are enclosed using glazed double shutters. All the window
		openings are provided with wooden sloping chhajja.
		Wooden louvers fixed in the upper part of balconies and verandahs as ventilators.
7.6	Roofing	Timber truss gable roofing with Mangalore roofing tiles.
7.7	Articulation	Decorative columns capitals.
7.8	Finishes	Painted brick masonry externally. Walls plastered and painted internally. Terracotta tiles as flooring finish.
7.9	Interiors (Movable & Immovable)	Movable
		Old wooden partitions, wooden chairs, table.
		Immovable
7.40	0	-
7.10	Compound/ Fence/ Gate	Grey random rubble masonry on all sides. Road facing walls have MS fencing above.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	BEST sub station in eastern side margin.
	Landscape	Water storage tank, servant's room on southern side. Open space paved with Shahabad tiles.
		ules.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through door-window and balconies supplemented by artificial
0.1	Lighting	lighting.
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by forced
0.2	Vondiadon	ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Provision of fire extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	Centrally air-conditioned upper floors with window AC units installed in some parts as per
		requirement.
9.0		Condition
9.1	Plinth	Good – Plant growth.
9.2	Walls	Good – Repainted
9.3	Floor	Fair – Floors invisible due to false ceiling in upper floors.
0.0	11001	Timber floors with large wooden beams seen on ground floor level.
9.4	Stairs	Good – Lift well is installed in the open well of the staircase.
9.5	Openings	Fair – Window panes broken in some places.
9.6	Roofing	Not visible in most areas due to false ceiling.
9.7	Articulation & Finishes	Good – Plant Growth
9.8	Services	Fair – No evident damage or leakage.
9.9	Out Buildings	Fair
9.10	Overall Conditions	Good Maintenance level Good
10.0		Transformation
10.0	Form	-
	Structure	- Addition of lift shaft in open well of main RCC staircase.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture

	190
Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) <i>City Map – Mumbai,</i> Mumbai.	



Red brick building with projecting balconies supported on brackets



Wooden bracket supporting the projecting balconies



Intricate trellis work, fascia bands, paneling etc



Side façade with corner quoins, lintel level bands, frieze band etc



Corner detail of the bay window with carved arches, columns etc



Window detail with arched band with a keystone, sill band etc

PWD Office	S	191
	-	Common Ref No: 191 Wallace Card No: 259 Ward (Part): A (Part II) CS No: 756 (Eort) Street
M. col	Ni 78	Card No: 259
N.	A Allow Stranger	Ward (Part): A (Part II) CS No: 756 (Fort)
	1	CS No: 756 (Fort)
S.C.C.		Plot Area: 3,331.13 sq m.
2		B U Area: 2422.24 sq m
all de la company de la compan		
		Date: 28/12/2004
		Recorded by: Sonal Modak
the first first		Reviewed by:
A second as		Int: Sonal Modak
The second second		Int: Sonal Modak Ext: Sonal Modak Photo Ref: 191_PWD office. CHARANJIT RAI ROAD
		Photo Ref: 191 PWD office.
T		- AIROAD
		12 mg
		Location Plan
1.0		Denomination
1.1	Name of Premises	PWD Offices
1.2		PWD Offices
	Earlier Name	
1.3	Built in:	1875 Extension Date: -
2.0		Access
2.1	Main	Murzban Road – Vehicular and Pedestrian
2.2	Subsidiary	Wallace Street - Pedestrian
		Charanjit Rai Road - Pedestrian
		· · ·
3.0		Ownership pattern
3.1	Present	Owner - State Government
3.2	Past	Owner - The Secretary of State for Indian Council
-	Status	
3.3	Status	Owner
4.0		Use
4.1	Present	Government Services – Offices
4.2	Past	Government Services – Offices
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	The building is located on a corner plot with roads on northern, southern and western side,
-		with the main entrance from Murzban Road on western side.
5.2	Architectural Description	Planning
0.2		Building has an elongated plan with verandahs facing intermediate open spaces along the
		longer side.
		The building consists of three linear, interconnected structures (wing A, B, C) and open
1		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above.
		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style
5.3	Intrinsic	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of
5.3 5.4		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture.
	Intrinsic Value Classification	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of
5.4		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade II B.
5.4 6.0	Value Classification	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade II B.
5.4		spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade
6.0 6.1	Value Classification	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade II B. Topography Wing A: G+1, Wing B: Ground floor structure, Wing C: Ground floor structure
5.4 6.0 6.1 7.0	Value Classification Floors	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade Recommended grade II B. Topography Wing A: G+1, Wing B: Ground floor structure, Wing C: Ground floor structure
6.0 6.1	Value Classification	spaces inbetween. Wing A has part first floor whereas wing B and C are ground floor structures. Main entrance is from Murzban Road on western side. Subsidiary entrances open in the open space between wings B and C. Plot has roads on three sides and MTNL building on one side. Main staircase leading to first floor is on the left side in wing A as one enters from the western main entrance gate. Open spaces house water storage tanks, temporary structure serving as storeroom. All wings cater to different departments of PWD. Main entrance is made prominent with projecting first floor resting on wooden brackets. Features Verandahs along the longer sides from which all the offices are accessed. Building has a wooden structural system with entrance made prominent. Door window openings have pointed and segmental arches with ventilators above. Style The structure displays no particular style. It has influences of vernacular style of architecture. - A(arc), B (des), B (uu), F, G(grp) Recommended grade II B. Topography Wing A: G+1, Wing B: Ground floor structure, Wing C: Ground floor structure

PWD Office	s	191	
7.3	Floor	Timber flooring system with wooden rafters supporting the wooden planks.	
7.4	Stairs	Main timber dog-legged staircase with wooden balustrades and handrail.	
7.5	Openings	A stone segmental arch spans main western entrance. Some of the door/window opening have pointed arches, some have segmental arches and some are rectangular openings. All the door shutters are wooden panel shutters with small glazing at top level and fixed with half height, double swing shutters. Windows are provided with wooden frame glazing panels and fixed MS grills.	
7.6	Roofing	Timber truss sloping roof with Mangalore roofing tiles and dormer windows.	
7.7	Articulation	-	
7.8	Finishes	Stone masonary painted externally. Internally plastered and painted walls.	
		Kotah, ceramic tiles, marble mosaic tiles provided as flooring in various areas.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	External wall of the structure forms boundary on western side. High brick masonary or other three sides. High cast iron gate at main entrance.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Internal open spaces house water storage tank, toilet block, temporary storage shed.	
8.0		Services & Utilities	
8.1	Lighting	Adequate daylight through windows and verandahs and supplemented with artificia lighting.	
8.2	Ventilation	Adequate cross ventilation through windows and verandahs with a provision of force ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No traces.	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed.	
9.0		Condition	
9.1	Plinth	Fair – Painted over without plaster.	
9.2	Walls	Fair - Painted over without plaster externally. Plastered and painted from internally.	
9.2	Floor	Fair – False ceiling makes original flooring system invisible.	
9.3		Good – No evident damages.	
	Stairs		
9.5	Openings	Fair – some of the openings are blocked using ply.	
9.6	Roofing	Fair – False ceiling makes original flooring system invisible.	
9.7	Articulation & Finishes	Fair – Flooring tiles replaced in all the interior spaces.	
9.8	Services	Fair	
9.9	Out Buildings	Fair – Temporary storage shed is used as a dumping yard.	
9.10	Overall Conditions	Fair Maintenance level Fair	
10.0		Transformation	
10.0	Form	-	
	Structure	MS sections are added to support wooden flooring.	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 Zone.	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) <i>City Map – Mumbai</i> , Mumbai.	

PWD Offices



Main entrance side with projecting floor supported on wooden brackets, with sloping roof



Internal courtyard with the verandahs with sloping roof, opening into it



Balcony railing detail



Stone balustrade detail



Projecting balcony with wooden columns and railing with sloping roof, supported on wooden brackets

Central Bank building		192	
	Common Ref No: 192		
	Card No: 260		
	Ward (Part): A (Part II)		
	CS No: 1518 (Fort division)		
	Plot Area: 926.89 sq m.	- CAB	
	B U Area: -		
States & The	Date: 7/01/05		
H Sho letter	Recorded by: Prachi Merchant	e la contraction a	
	Reviewed by:		
	Int: Prachi Merchant, Zankhana Prajapati	F PHOMIMO	
	Ext: Prachi Merchant, Zankhana Prajapati	HOM MODISTREET	
	Photo Ref.: 192_Central Bank building	GA GA	
		Location plan	
1.0	Denomination		
1.1 Name of Premises	Central Bank building		
1.2 Earlier Name	Central Bank building		
1.3 Built in:	Indeterminable	Extension Date: -	
		<u> </u>	
2.0	Access		
2.1 Main	Corner of Nagindas Master Road and Homi N		
2.2 Subsidiary	Homi Modi Street and Nagindas Master Road		
3.0	Ownership pattern		
3.1 Present	Central Bank of India		
3.2 Past	Central Bank of India limited and others		
3.3 Status	Owner		
4.0	Use		
4.1 Present	Commercial – Banks		
4.2 Past	Commercial - Offices		
4.3 Usage	Daily.		
5.0	Significance & value Classification		
5.1 Townscape (Manmade)	Prominent corner building at the junction of N The building form is a response to the site co		
5.2 Architectural Description	Planning		
	The building has 'L' shaped form with its wings extending at the rear to enclose a court The main access to the building is from the northwest corner. The central bay with the dome is the highest level of the building. The portions of the added fifth floor at the corner are higher than the rest of the building. Features The ground floor and the marginally projecting bays in the center and corners have stone rusticated joints.		
	geometric pattern and top fire temple like flan	eystone, floral pattern around the openings, brackets. The dome base has round windows ne feature.	
	The side façade has recessed rectangular wi and geometric pattern friezes in the sill portio	n. The façade has continuous projecting	
	balconies on the first and second floor of eas south façade. Balconies are supported on su bands with stone balustrade.	pported on decorative brackets, and corbel	
	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style	pported on decorative brackets, and corbel in the east and south corner. Chajjas.	
5.3 Intrinsic	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C	pported on decorative brackets, and corbel in the east and south corner. Chajjas.	
5.3 Intrinsic	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style The building derives influence from Neo Class	pported on decorative brackets, and corbel in the east and south corner. Chajjas. sical style of architecture.	
5.3 Intrinsic 5.4 Value Classification	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style	pported on decorative brackets, and corbel in the east and south corner. Chajjas. sical style of architecture.	
5.4 Value Classification	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style The building derives influence from Neo Clas - A(arc), B(per), B (des), B (uu), E, F, G(grp), I	pported on decorative brackets, and corbel in the east and south corner. Chajjas. sical style of architecture.	
5.4 Value Classification 6.0	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style The building derives influence from Neo Clas - A(arc), B(per), B (des), B (uu), E, F, G(grp), I Topography	pported on decorative brackets, and corbel in the east and south corner. Chajjas. sical style of architecture. (sce) Recommended grade II A.	
5.4 Value Classification	south façade. Balconies are supported on su bands with stone balustrade. The side facades have arched door entrance The top floor dormer windows have sloping C Style The building derives influence from Neo Clas - A(arc), B(per), B (des), B (uu), E, F, G(grp), I	pported on decorative brackets, and corbel in the east and south corner. Chajjas. sical style of architecture. (sce) Recommended grade II A.	

	nk building	1
7.1	Plinth	High stone plinth due to basement.
7.2	Walls	Load bearing brick walls. The walls are slanting internally widening the width of the wall to increase the strength.
7.3	Floor	RCC slab and beam structure.
7.4	Stairs	Three staircase structures with two on either ends and one in the center. Open well staircase with stone finished risers and treads and cast iron intricate railing.
7.5	Openings	Main corner entrance door arched opening with wooden paneled door shutters and semicircular arched ventilator.
		Rectangular window openings with glazed paneled shutters. Top floor dormer windows with glazed paneled shutters and sloping wooden <i>chajja</i> . Round openings on the dome wall.
7.6	Desting	Rectangular openings leading to projecting balconies with stone balustrade.
1.0	Roofing	Central wing connecting the two arms with dome. Rest all wings with flat terrace roof. Window openings with sloping wooden <i>chajjas</i> .
7.7	Articulation	Arched openings, façade with rusticated stone joints, projecting balconies with decorative brackets, central dome.
7.8	Finishes	Walls are clad with buff stone on the external side, and plastered and painted from inside. Floor is finished with cement tiles, marble at places.
7.9	Interiors (Movable & Immovable)	Movable
		Immovable
7.10	Compound/ Fence/ Gate	The building is directly accessed from the road. No compound wall, no fence or gate present.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The building abuts the road and occupies the site completely with an enclosed court at the rear.
	Landodpo	Tour.
8.0		Services & Utilities
8.1	Lighting	Inadequate natural light due to hindrance by internal partitions, supplemented by artificial light.
8.2	Ventilation	Inadequate natural ventilation due to hindrance blocking of openings, supplemented by artificial ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	Centrally air conditioned with cooling towers placed on the terrace.
		Manual security, metal detector, surveillance camera.
9.0		Condition
		The interior of the building is completely altered, retaining the main structural system.
9.1 9.2	Plinth Walls	Fair – Internal partitions added to suit the requirements of the bank.
		Externally cladding is deteriorating, organic growth observed.
9.3	Floor	Fair – Major leakages have been observed in the basement floor area.
9.4	Stairs	Fair – Materials have been altered.
9.5	Openings	Poor – The openings have been blocked to house AC's, window shutters have been changed, grills have been added, AC machines have been installed in the projecting balconies. The front and side façade openings have been maintained very insensitively.
9.6	Roofing	Fair – Terrace maintained well, window chajjas have been replaced.
9.7	Articulation & Finishes	Fair – Hoardings been installed insensitively. All internal finishing is altered.
9.8	Services	Fair – Electric wires passing through in a haphazard way. AC outdoor units are installed in the projecting balconies, cooling towers and tanks have been installed on terrace.
9.9	Out Buildings	•
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	The fifth and part sixth portion of the building have been added later.
	Structure	Projecting balconies are enclosed. Tanks, cooling towers have been installed on the terrace.
	Articulation & Finishes	Openings are blocked to house AC's, window shutters have been changed, grills have been added. <i>Chajja</i> coverings have been replaced.
		Hoardings have been installed insensitively in the openings.
11.0		DP Remarks/ Perceived Threats

19
Additional Notes/ References/ Documents available
Additional Notes:
-
References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd.
RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.
SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.
Eicher Goodearth Ltd. (2002) <i>City Map – Mumbai,</i> Mumbai.





Main entrance corner bay with arched and rectangular openings, surmounted with a dome.





Main entrance with arched opening, rusticated stone joints with a keystone emphasized.

Side façade with rusticated joints on the ground floor and vertical columns, projecting balconies supported on stone carved brackets.



Projecting stone balcony with stone balustrade, brackets



Rectangular window openings with scroll bracket keystone and brackets, floral motifs around the window frame.

		Common Ref No: 193(a) Card No: 261 Ward (Part): A (Part II) CS No: 4/1187(Fort Division) Plot Area: 1122.54 sq m
Mar Marker		Ward (Part): A (Part II)
	IN IN IN	
	IN I III I II	
		21/187
		Plot Area: 1122.54 sq m
2		BILArea -
Z STA		B U Area: - Date: 06/04/2005 Recorded by: Sonal Modak Reviewed by: Int: Permission denied
		Recorded by: Sonal Modak
- Park		Reviewed by:
		Int: Permission denied
		Ext: Sonal Modak
		Photo Ref: 193(a)_Scindia House
1.5		
- Internet and		Location Plan
1.0		Denomination
1.1	Name of Premises	Scindia House
1.2	Earlier Name	Scindia House
1.3	Built in:	1938 Extension Date: -
1.0	Duit in.	
2.0		Access
2.1	Main	Narottam Morarji Marg - Pedestrian
2.1	Subsidiary	ivalottalli iviolalji ivialy - Eucotilali
Ζ.Ζ	Subsidiary	-
3.0		Ownership pattern
3.1	Present	Private
3.2	Past	Private
3.3	Status	Owner
4.0		Use
4.1	Present	Commercial – Offices
4.2	Past	Commercial – Offices
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Located on a corner plot at the junction of Walchand Hirachand Marg and Narottam
		Morarji Marg with roads on three sides and tree-lined avenue maintaining similar height &
		features as per urban design regulations laid down for the entire Ballard Estate.
		It is an imposing corner building forming a local landmark.
		Main access is from corner of Narottam Morarji Marg.
5.2	Architectural Description	Planning
		Building is roughly rectangular in plan. Facades are simple symmetrical with verticality
		emphasized. Building is sharing common open spaces with buildings on sides and rear.
		Corner tower rises higher than the rest of the building height.
		Large floor heights without any setback or interception generate an urban scale-volume
		to the building block.
		Features
		Yellow ashlar masonary having massive look and vertical engaged columns having
		rectangular windows in between.
		Rustication is seen at ground floor level in same yellow stone masonary. Simple band at
		first floor level runs continuously forming step out balconies at places.
		Style
		Influence of European Renaissance style of architecture with emphasized verticality.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade: II A
6.0		Topography
6.1	Floors	G + 5 with basement
7.0		Construction
7.1	Plinth	High plinth about 4 ft. high to accommodate ventilators for basement, in yellow ashlar
		masonry.
	Walls	Load bearing yellow ashlar masonry along the entire periphery, open internal space is
7.2		
7.2		
		supported on columns.
7.2 7.3 7.4	Floor Stairs	
7.3	Floor	supported on columns. Indeterminable

Scindia H	ouse	193(a)
7.6	Roofing	Indeterminable
7.7	Articulation	Comice bands.
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted internal finishes.
7.9	Interiors (Movable & Immovable)	Movable - Immovable
7.10	Compound/ Fence/ Gate	No compound wall, only an Iron gate enclosing the common open space along both the sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
0.0 8.6	Fire Precaution	
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.
9.0		Condition
9.1	Plinth	Good except plumbing interventions along the rear side.
9.2	Walls	Good
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Good
	Roofing	Indeterminable
9.6		
9.7	Articulation & Finishes	Good
9.8	Services	Fair – old and neglected plumbing lines to the rear side.
9.9	Out Buildings	
9.10	Overall Conditions	Good Maintenance level: Good
10.0		Transformation
	Form	No visible changes externally
	Structure	No visible changes externally
	Articulation & Finishes	No visible changes externally
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.

Scindia House



Side façade with vertical bands, rectangular columns



Buff stone clad building with rectangular openings, projecting vertical bands, rectangular window openings



Projecting balconies on the first floor

L & T Hous	6e		193 (b)
		Common Ref No: 193 (b)	the strain the life is the strain
		Card No: 262	Hand House
		Ward (Part): A (Part II)	And
ø.		CS No: 20/1187.	the second way to the second s
		Plot Area: 966.00 sq m.	and a stranger and a stranger and a stranger and a stranger a stranger and a stranger a strange
	- ma As	B U Area: -	
	1 1	Date: 10/02/2005	Manchurn of the same the
			MERCANTILE CHAMBERS
All and a second de		Recorded by: Arun Wadhwa	· · · · · · · · · · · · · · · · · · ·
		Reviewed by:	PEITHAM HANN
		Int: Arun Wadhwa	1 L
The same	And Anna Anna Anna Anna Anna Anna Anna A	Ext: Arun Wadhwa	The souther the offer
1. 1. 1. 1.		Photo Ref: 193(b) L&T House.	TO TO TO
in in			THAN WORARINARG
1.0		Denomination	
1.1	Name of Premises	L & T House	
1.2	Earlier Name	ICI building	
1.2	Built in:	1924	Extension Date:
1.0		1324	
2.0		A	
2.0	Maia	Access	
2.1	Main	Narottam Morarji Marg	
2.2	Subsidiary	J. N. Heredia Marg	
3.0		Ownership pattern	
3.1	Present	Larsen & Toubro Ltd.	
3.2	Past	Imperial Chemical industries	
3.3	Status	Owner	
5.5	Status	Owner	
4.0		Use	
4.1	Present	Corporate headquarters of L&T, Danis	sh Consulate office.
4.2	Past	Offices	
4.3	Usage	Commercial	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)		sides with splayed face along the southeast corner.
5.2	Architectural Description	Planning	sides with splayed lace along the southeast comer.
		Long narrow comer building with ar forming wide east side & narrow wes lobby connected to first floor boardre ends of rear side lead to typical colonnaded open office space to the Pantry, toilet and service facilities are floor accommodates recreational facil Features Plain façade seems bold in appearar surfaces. Large semicircular openin balcony on the splayed façade. Larg metal clad fascia over the fourth floor Style Renaissance style influences.	
5.3	Intrinsic	in this building & went on to become a	
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G	G(grp) Recommended grade: II A
6.0		Topography	
6.1	Floors	G + 4 and basement.	
7.0		Construction	
7.1	Plinth	Plinth height of about 0.9 m. with a ba	asement below
7.2	Walls	Non-load bearing brick masonry walls	
7.3	Floor	R.C.C. slab supported on beams and	columns.
7.4	Stairs		n a central lift shaft, wooden constructed from third to the rear side at both ends. Also a wide stair with an n lobby to the first floor boardrooms.

& T Hous		193 (b)	
7.5	Openings	Large rectangular facade openings some of which are double height with recessed meta frame glazed panel windows. Some original retained door shutters carry wood relief work whereas rest of the openings are modified in laminate finish shutters.	
7.6	Roofing	Sloping A.C. sheet supported over hollow steel box sections.	
7.7	Articulation	-	
7.8	Finishes	Fascia clad façade externally resembles stone dressed	
7.9	Interiors (Movable & Immovable)	Movable Antique wooden furniture in the corporate hall at fourth floor. Immovable Sculpture of H. Holck Larsen –founder of L&T at the entrance. Wooden partitions subdividing office spaces. No particular heritage value.	
7.10	Compound/ Fence/ Gate	Building itself forms boundary along its three road fronts, iron gates secure the common space along the North side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Shares paved open space along the North side with adjacent buildings used for services.	
8.0		Services & Utilities	
8.1	Lighting	Relies on artificial lighting.	
-	0 0		
8.2	Ventilation	Central A.C. system	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Underground and overhead water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Smoke detector and fire extinguisher.	
8.7	Other (HVAC/BMS/Security Systems)	Central A.C. plant. Electronic door locking devices.	
9.0		Condition	
9.1	Plinth	Fair except on the rear side due to plumbing interventions	
9.2	Walls	Fair. Well maintained	
9.3	Floor	Fair	
9.4	Stairs	Fair, except some wear and tear observed	
9.5	Openings	Fair. Except rear side with A.C units and weather shades.	
9.6	Roofing	Fair.	
9.7	Articulation & Finishes		
9.8	Services	Good.	
9.0		Fair.	
9.9	Out Buildings Overall Conditions	Fair Maintenance level: Good	
10.0		Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of C1 Zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.	



Buff stone clad building with a corner curved bay, rectangular inset windows, bands.



Internal open well stone staircase



Façade detail with modifications made to the upper part



Railing detail



Arched window opening



Completely modified interior view

Magnet Hous	Se		193(C)
Magnet Hous		Common Ref No: 193(C) Card No: 263 Ward (Part): A (Part II) CS No: 12/1187 (Fort division) Plot Area: Indeterminable B U Area: - Date: 25/11/2004 Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Zankhana Prajapati Internal photography permission denied Ext: Arun Wadhwa, Zankhana Prajapati Photo Ref.: 193(c)_Magnet House	193(C) Name of the state of th
		-	Location plan
1.0		Denomination	
1.1	Name of Premises	Magnet House	
1.2	Earlier Name	Magnet House	
1.3	Built in:	1920's -1930's	Extension Date: -
2.0		Access	
2.1	Main	Narottam Morarji Marg	
2.2	Subsidiary	-	
[
3.0		Ownership pattern	
3.1	Present	Oriental Insurance company	
3.2	Past	Indeterminable	
3.3	Status	Ownership with multi tenanted premises.	
0.0		e uneremp mar mara terrantea premiese.	
4.0		Use	
4.0	Procent	Vacant ground floor, private offices on first an	d accord floor. Oriental Incurance promises
4.1	Present	on third and fourth floor.	a second hoor, Onental insurance premises
4.2	Dest		
	Past	Commercial	
4.3	Usage	Daily	
5.0		Cincificance & Value Classification	
5.0		Significance & Value Classification	and a fair the first of the second of the fair to the factor of the first of the factor of t
5.1	Townscape (Manmade)	Part of well conceived planning layout with co	introl guidelines in sense of retaining similar
5.2	Analaite at unal De a aniatic a	façade character and street profile. Planning	
	Architectural Description	Rectangular plan with long side facing the stra spacious lobby. Typical floor layout with symmetrical office spi and pantry services at the rear southern side. A narrow service stair planned at the rear side Features Continuous semi-circular arches stone dresse Projecting cornice bands on the first and third openings. Projecting balcony with decorative brackets, re Intricate wrought iron railing work as window g Overhanging porch supported on long curvilin Style European Renaissance style.	aces planned on both the sides with toilets e. Receding fourth floor seems later addition. ed at the ground floor. floor slab levels. Stone relief work on façade relief features and parapet balusters. grills.
5.3			
5.4	Intrinsic	-	
	Intrinsic Value Classification	- A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended grade: II A
6.0		- A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography	Recommended grade: II A
			Recommended grade: II A
6.0	Value Classification	Topography	Recommended grade: II A
6.0	Value Classification	Topography	Recommended grade: II A
6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 4 floors Construction Low plinth about a foot in height rough dresse course.	ed in stone masonry topped with a rain-drip
6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	Topography G + 4 floors Construction Low plinth about a foot in height rough dresse course. Non-load bearing brick masonry walls on the	ed in stone masonry topped with a rain-drip upper floors.
6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 4 floors Construction Low plinth about a foot in height rough dresse course.	ed in stone masonry topped with a rain-drip upper floors. ctural grid of concrete columns and beams.

Magnet Ho	use	193(C)	
		Wrought iron decorative railing panel with wooden handrail and large newel post.	
7.5	Openings	Large door openings continuous at the first & fourth floor and projecting balcony like	
		features at some places on second and third level. Window openings with wooden paneled glazed shutters and top hung ventilator.	
7.6	Roofing	Sloping pitched roof with Mangalore tile finish supported on trusses and false ceiling finish.	
7.7	Articulation	Projecting balcony like features in the form of cornice bands.	
7.8	Finishes	External walls are finished in yellow stone ashlars masonry medium course whereas	
		internally the surfaces are plastered. Varied ordinary floor finishes. All door and window openings are emulsion painted. Ornamental detailing and projecting features are painted in white.	
7.9	Interiors (Movable & Immovable)	Movable	
		- Immovable -	
7.10	Compound/ Fence/ Gate	No compound wall as the building shares open space with adjoining buildings except the street front. Collapsible gate at the entrance leading to stair.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Iron gate enclosing open space with adjoining buildings on the two sides.	
8.0		Services & Utilities	
8.1	Lighting	Large door and window openings with louvered panels provide ample daylight supplemented with electric lighting.	
8.2	Ventilation	Large door and window openings provide natural ventilation along with electric fans and air	
0.0	Flootrigity	conditioning devices. BEST	
8.3	Electricity Water Supply	MCGM	
8.4	Water Supply Drainage (Plumbing & Sanitation)	MCGM	
8.5 8.6	Fire Precaution	Absence of integrated fire fighting system, some tenanted offices have fire extinguishers,	
		which seem inadequate incase of major breakout.	
8.7	Other (HVAC/BMS/Security Systems)	Installation of window unit and split air-conditioning in office premises.	
9.0		Condition	
9.1	Plinth	Fair to the front side, sides and rear face seepage problem and plant growth affecting plinth course.	
9.2	Walls	Poor - Damaged plaster, cracks and plant growth observed externally as well as internally. Damp and poorly finished surfaces.	
9.3	Floor	Fair - Floor structure fair, Ceiling plaster and finish in poor condition.	
9.4	Stairs	Fair except in need of maintenance, with pan stains and encroachment of services in a haphazard manner. Also dark and ill ventilated.	
9.5	Openings	Poor - Full height glass doors in place of wooden paneled shutters. Some window openings are damaged with missing panes and broken shutters on the side and rear facades. Box type iron grills fitted to the openings externally. Air-conditioning units installed within the openings altering wooden shutters.	
9.6	Roofing	Fair except waterproofing and maintenance.	
9.7	Articulation & Finishes	Poor – blackening and plant growth observed externally over stone dressed surfaces, also poorly maintained internal wall finishes in some premises and common areas. varied floo finishes by different occupants throughout the building	
9.8	Services	Poor - old plumbing lines cause leakage affecting strength and hygiene. Unplanned additions in plumbing, electrical and telephone lines have damaged the external fabric as well mar the visual congruity of the facades.	
9.9	Out Buildings		
9.10	Overall Conditions	Fair except walls, openings, finishes and services. Maintenance level: Low	
10.0		Transformation	
	Form		
	Structure	Addition of fourth floor, False ceiling and mezzanines in the interiors.	
	Articulation & Finishes	Signboards on the porch and projecting frieze band. Paint finishing on projecting decorative features on the façade.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes: Additional Notes:	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	

Magnet House 19	
	Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.



Side façade with additions made with AC units, pipes etc



Main entrance with arched and rectangular opening, extended porch supported on wooden brackets



Arched opening with decorative band, enclosed opening to take the AC

NTC House			193 (d)
		Common Ref No: 193 (d)	
		Card No: 264	Date O C C C C C C C C C C C C C C C C C C
		Ward (Part): A (Part II)	
		CS No: 15/1187.	
ALL SOM		Plot Area: 1041.62 sq m	
131 竹芋根		B U Area: -	
11 4		Date: 25/11/2004	
S Maler		Recorded by: Arun Wadhwa	NW NW
	The second secon	Reviewed by:	S WINK RUN NARG
		Int: Arun Wadhwa, Zankhana Prajapati	S S S S S S S S S S S S S S S S S S S
C. F. A. W. F. M.		Internal photography permission denied	AROTIAM
Gr W		Ext: Arun Wadhwa, Zankhana Prajapati	NN ST
1.10	The state of the s	Photo Ref.: 193(d)_NTC House	war hor
	HE HE HE HE HE HE HE HE		
			serie interest
			Location plan
1.0		Denomination	· · ·
1.1	Name of Premises	NTC House	
1.2	Earlier Name	S.D. Sassoon Building.	
1.3	Built in:	1920's -1930's	Extension Date: -
2.0		Access	
2.1	Main	Narottam Morarji Marg - vehicular & pedes	trian.
2.2	Subsidiary		es to the east and west side presently not used.
3.0		Ownership pattern	
3.1	Present	National Textile Corporation, a Government	t Undertaking
3.2	Past	Sassoon trust presently occupying first floor	
3.3	Status	Ownership with multi tenanted premises.	
4.0		Use	
4.1	Present		studios on the ground floor, private offices on
		first & second floor, NTC offices on third and	d fourth floor.
4.2	Past	Commercial	
4.3	Usage	Daily	
5.0	-	Significance & Value Classification	
5.1	Townscape (Manmade)		ngs in a well conceived planning layout with
5.0		control guidelines in sense of retaining simi	ar façade character and street profile.
5.2	Architectural Description	Planning	
			he street to the south with central staircase and
			planned on both the sides with toilets and pantry service stair planned centrally at the rear side.
		Features	service stall plained centrally at the real side.
			d relieved by cornice bands and arch openings.
		Continuous semi-circular arch openings at t	
			ative brackets. Projecting cornice and keystone
		in stone relief work. Wooden awnings over	
		Sloping wooden awnings shading door/wing	
		Mansard roof punctuated by wooden windo	
		Intricate wrought iron railings and balusters	including large wooden navel post in the
		staircase.	
	1	Style	
1		Otyle	
		European Renaissance style.	
5.3	Intrinsic	European Renaissance style. Old antique ambience of 'Hamilton studios'	on the ground floor.
5.3 5.4	Intrinsic Value Classification	European Renaissance style.	on the ground floor. Recommended grade: II A
		European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp)	
5.4 6.0	Value Classification	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography	Recommended grade: II A
5.4		European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended grade: II A
5.4 6.0 6.1	Value Classification	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan	Recommended grade: II A
5.4 6.0 6.1 7.0	Value Classification Floors	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan Construction	Recommended grade: II A
5.4 6.0 6.1 7.0 7.1	Value Classification Floors	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan Construction Low plinth about a foot in height dressed in	Recommended grade: II A rge floor heights) rough stone masonry.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan Construction Low plinth about a foot in height dressed in Rubble stone masonry walls on the ground	Recommended grade: II A rge floor heights) rough stone masonry. floor and brick masonry on the upper floors.
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan Construction Low plinth about a foot in height dressed in Rubble stone masonry walls on the ground Reinforced concrete slab supported on a st	Recommended grade: II A rge floor heights) rough stone masonry. floor and brick masonry on the upper floors. ructural grid of concrete columns and beams.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	European Renaissance style. Old antique ambience of 'Hamilton studios' A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G + 4 (additional mezzanines built within lan Construction Low plinth about a foot in height dressed in Rubble stone masonry walls on the ground	Recommended grade: II A rge floor heights) rough stone masonry. floor and brick masonry on the upper floors. ructural grid of concrete columns and beams. e with a central lift shaft.

NTC House		193 (d	
7.5	Openings	Large door openings continuous at the first & fourth floor and projecting balcony like	
		features at some places on second and third level. Window openings with wooden paneled	
		glazed shutters and top hung ventilator.	
7.6	Roofing	Mansard roof.	
7.7	Articulation	Projecting balcony like features in the form of cornice bands	
7.8	Finishes	Exterior walls are finished in yellow stone ashlar masonry medium course whereas	
		internally the surfaces are plastered. All door and window openings are emulsion painted.	
		Varied and ordinary floor finishes. Ornamental detailing and projecting features are painted	
		in white.	
7.9	Interiors (Movable & Immovable)	Movable	
		-	
		Immovable	
		-	
7.10	Compound/ Fence/ Gate	No compound as the building touches the street on two sides whereas the other two sides	
		share open space with adjoining buildings. Collapsible gate at the entrance leading to stair	
		Iron gate enclosing open space with adjoining buildings on the two sides.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	-	
	Landscape		
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through large door and window openings with louvered panels	
		supplemented by artificial lighting.	
8.2	Ventilation	Adequate natural ventilation through large door and window openings also supplemented	
		by fans and air-conditioning devices.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Absence of integrated fire fighting system, some tenanted offices have fire extinguishers,	
		which seem inadequate incase of major breakout.	
8.7	Other (HVAC/BMS/Security Systems)	Installation of window unit and split air-conditioning in office premises.	
9.0		Condition	
9.1	Plinth	Fair to the front side, sides and rear face seepage problem affecting plinth course.	
9.2	Walls	Fair except damaged plaster, cracks and plant growth observed externally as well as	
		internally.	
9.3	Floor	Fair condition of floor structure	
9.4	Stairs	Fair except in need of maintenance, with pan stains and encroachment of services in a	
		haphazard manner. Also dark and ill ventilated.	
9.5	Openings	Poor - Full height glass doors in place of wooden paneled shutters. Some window opening	
		are damaged with missing panes and broken shutters on the side and rear facades.	
		Box type iron grills fitted to the openings externally.	
		Window air-conditioning units installed within the window openings altering shutters and	
		openings.	
9.6	Roofing	Fair – except few damp patches.	
9.7	Articulation & Finishes	Poor - Cracks and exposed steel reinforcement observed in cornice and bracket members.	
		Balcony railing damaged and unmaintained.	
9.8	Services	Poor - Old plumbing lines cause leakage affecting strength and hygiene. Unplanned	
		additions in plumbing, electrical and telephone lines have damaged the external fabric as	
		well mar the visual congruity of the facades.	
9.9	Out Buildings	N.A.	
9.10	Overall Conditions	Fair except openings, finishes and services. Maintenance level: fair	
10.0		Transformation	
	Form	-	
	Structure	False ceiling to the interiors and a few mezzanines.	
	Articulation & Finishes	White paint applied over stone dressed arch openings, decorative features.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
-		Additional Notes:	
		-	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

NTC House	193 (d)
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.
	Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.



Side façade with ached openings, projecting balconies supported on brackets, sloping chajjas, modified openings to take in services



Balcony supported on stone brackets, bands



Main entrance façade with arched openings with bands

New Hind Bu	uilding		193(e)
		Common Ref No: 193(e)	NAROTTAM NORARJI NARG
		Card No: 265	ARJI MA
		Ward (Part): A (Part II)	M MORA
4		CS No: 7/1187	AROTTA
1	A DESTRUCTION OF THE OWNER	Plot Area: 530.10 sqm.	NAROITAN NAROITAN IN SULANS IN SULANS Itopic sunary NAROITAN IN IN Itopic sunary NAROITAN
		B U Area: -	THE BULLOWS I THE LE
Aller		Date: 23/03/05	- They E
Aleset		Recorded by: Prachi Merchant	ttayeni ≋uilkiing 🗭
		Reviewed by:	The second second
		Int: Prachi Merchant, Zankhana Prajapati	6 C
		Internal photography permission denied Ext: Prachi Merchant, Zankhana Prajapati	-
No.		Photo Ref.: 193(e)_New Hind House	Harmilton Mouse
		Photo Rel. 193(e)_New Hind House	
			Location Plan
1.0		Denomination	Eocation Fian
1.1	Name of Premises	New Hind Building	
1.2	Earlier Name	J and K building, Lloyd building	
1.3	Built in:	1920-1930	Extension Date: -
2.0		Access	
2.1	Main	Naorottam Morarji Marg	
2.2	Subsidiary	J. N. Heredia Marg	
		g	
3.0		Ownership pattern	
3.1	Present	Private - Owner	
3.2	Past	Private - Owner	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Commercial	
4.2	Past	Commercial	
4.3	Usage	Daily	
5.0 5.1 5.2	Townscape (Manmade) Architectural Description	Significance & value Classification Prominent corner curved building at the junct Heredia Marg. The building is accessed from the corner and The building forms a part of the Ballard Estate Planning The office building is accessed from the north The staircase and lift block is located in the w The central portion and the two corner bays a The ground, first and fourth floors are occupie and the second and third by CBI. Features The buff stone clad building has curved steps supported on carved brackets above. A projecting cornice band defines the first floor	from the Naorottam Morarji Marg. e precinct. n end and has a curvilinear profile. vest side. are higher than the rest of the wings. ed by offices of the J & K group of company s to the shop entrance with a projection
		The ground floor has semicircular full height a rectangular openings with projecting sill piece	9S.
5.3 5.4	Intrinsic Value Classification	The ground floor has semicircular full height a	es. ave projecting with cast iron railing.
5.4		The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp)	es. ave projecting with cast iron railing. n Renaissance style of Architecture.
5.4 6.0	Value Classification	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from European - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography	es. ave projecting with cast iron railing. n Renaissance style of Architecture.
5.4		The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp)	es. ave projecting with cast iron railing. n Renaissance style of Architecture.
5.4 6.0 6.1	Value Classification	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G+3 with terrace	es. ave projecting with cast iron railing. n Renaissance style of Architecture.
5.4 6.0 6.1 7.0	Value Classification Floors	The ground floor has semicircular full height a rectangular openings with projecting sill piece. The first floor and the recessed fourth floor has Style The building derives influence from Europear	es. ave projecting with cast iron railing. In Renaissance style of Architecture.
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G+3 with terrace Construction Normal height buff stone clad plinth with plint	es. ave projecting with cast iron railing. In Renaissance style of Architecture.
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G+3 with terrace Construction Normal height buff stone clad plinth with plint Load bearing walls	es. ave projecting with cast iron railing. In Renaissance style of Architecture.
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G+3 with terrace Construction Normal height buff stone clad plinth with plint Load bearing walls RCC slab and beam structure	es. ave projecting with cast iron railing. I Renaissance style of Architecture. Recommended grade II A
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	The ground floor has semicircular full height a rectangular openings with projecting sill piece The first floor and the recessed fourth floor ha Style The building derives influence from Europear - A(arc), B(per), B (des), B (uu), E, F, G(grp) Topography G+3 with terrace Construction Normal height buff stone clad plinth with plint Load bearing walls	es. ave projecting with cast iron railing. I Renaissance style of Architecture. Recommended grade II A h protection band.

New Hind	Building	193(e)
		The fourth floor has slanting dormer windows finished with ceramic tile china mosaic.
		Internal doors have paneled shutters.
7.6	Roofing	Flat RCC terrace roof
7.7	Articulation	Projecting cornice bands, stone brackets, dormer windows.
7.8	Finishes	Walls are clad with buff stone.
		The floors are finished with natural stone.
7.9	Interiors (Movable & Immovable)	Movable
		•
		Immovable
7.10	Compound/ Fence/ Gate	Side MS fencing leading to the rear courtyard.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Trees with tree guard on paved footpath area.
	Landscape	
	· ·	
8.0		Services & Utilities
8.1	Lighting	Natural lighting through openings supplemented with artificial lighting.
8.2	Ventilation	Natural ventilation through openings supplemented with artificial ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	MCGM
8.7	Other (HVAC/BMS/Security Systems)	- Individual office analogo have AC's installed according to individual requirement
8./	Other (HVAC/BINS/Security Systems)	Individual office spaces have AC's installed according to individual requirement. Strict manual security.
		Strict manual security.
0.0		Condition
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair – Stone finish of treads and risers have been changed, railing has been changed
9.5	Openings	Poor - Openings have been blocked to occupy AC's, shutters have been changed.
		Front side openings have been blocked by hoardings etc. Grills and jalis have been added
		to the front full height window openings.
9.6	Roofing	Fair
9.7	Articulation & Finishes	Poor – features are blackened, broken bands.
9.8	Services	Poor – the rear side is not maintained and services have been added haphazardly.
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level Poor
10.0		Transformation
	Form	•
	Structure	
	Articulation & Finishes	Openings have been blocked. Front shop entrance shutters have been changed to suit the
		tenant's requirements. Jalis have been added on the front façade openings, hoardings
		have covered the façade features.
		have covered ine laçade leatures.
11.0		DP Remarks/ Perceived Threats
11.0		Building forms part of C1 Zone
		Building forms part of CT 2018
40.0		Additional Natas (Defense and Decomposite and lable
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		Structure's listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd.
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) <i>The Fort Precinct</i>
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) <i>The Fort Precinct</i> <i>in Bombay – Conserving an Image Centre</i> , 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminenc Designs Pvt. Ltd.
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) <i>The Fort Precinct</i> <i>in Bombay – Conserving an Image Centre</i> , 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminenc Designs Pvt. Ltd.
		Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence

New Hind Building



Corner buff stone clad building with a curved wing, rectangular openings



Projecting balconies with floor bands



Side façade view with enclosed openings to take in services



Projecting balcony supported on stone brackets, bands etc

Jony Castle	9		194
1		Z Common Ref No: 194	1 PC 3VA
Elene I		Card No: 266	TIN NO PAR
Weller States		Ward (Part): A (part IV)	1 15 A STAR
19		CS No: 1061	and the state of the
s 11 - 14		Plot Area: 1540.14 sqm.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		B U Area: -	Malau A
		Date: 10/01/2005	Noad A
and the states		Recorded by: Zankhana Prajapati	- 1 Sie A V
		Reviewed by:	I Road I Road
		Int: Zankhana Prajapati, Sonal Modak	Contraction of the second seco
		📑 Ext: Zankhana Prajapati, Sonal Modak	Age to A all all all all all all all all all a
		Photo Ref.: 194_Jony Castle	Inde Road
and the			Location plan
1.0		Denomination	· · ·
1.1	Name of Premises	Jony Castle	
1.2	Earlier Name	Jony Castle	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Nathalal Parekh Road	
2.2	Subsidiary	Khatau Road	
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Indeterminable	
3.3	Status	Owner/Tenant	
4.0		Use	
4.1	Present	Residential and shops	
4.2	Past	Indeterminable	
4.3	Usage	Residential and Commercial – Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Corner building at the junction of Nathalal	Parikh Road and Khatau Road.
		There are two entrances for the building; b	ooth entrances are from Nathalal Parikh Road.
5.2	Architectural Description	while the other is up to second floor, there corridor goes around the court and all the Ground floor has shops and residential, wil Features Islamic arches and window openings, woo verandah, floral motif, turret with <i>Chatri</i> lik	gh with mezzanine. lats, southern end staircase is up to fourth floor is no entrance lobby while at each floor level the service utilities are abutting the central court. hereas rest other floors are residential. and en decorative verandahs, wooden column of e element, small semicircular arch opening in level, corbels, brackets, decorative entrance
5.3	Intrinsic	•	
5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade II A
6.0		Tanaaranhu	
6.0	Eleore	Topography	
6.1	Floors	G + 4 with mezzanine.	
7.0		Construction	
7.1	Plinth	Grey stone with high plinth with edging do	ne for plinth protection
7.1	Walls		external grey stone fascia and internal brick wall.
7.3	Floor	Wooden floor joist over which flooring is la	
7.3	Stairs	· · ·	
7.4	Openings	Two dogleg timber staircases with wooder	ground, first and third, rectangular window at third
		and fourth floor. Windows has ventilator at top and has dou verandah supported on decorative bracket	uble leaf glass shutter; Has decorative wooden ts.
7.6	Roofing	Mangalore tile roofing and AC sheets, sup	
7.7			
7.8	Articulation Finishes	Cornice bands, decorative columns, brack External walls have exposed stone fascia	

Urban Design Research Institute

MMR- Heritage Conservation Society

)	19 Internal walls are plastered and painted.	
		Flooring is of varied materials according to user.	
7.9	Interiors (Movable & Immovable)	Movable	
		-	
		Immovable	
7.10	Compound/ Fence/ Gate	Two cast iron decorative iron gates and has stone compound wall.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Garage in rear open space.	
	Landscape	Some planter boxes toward Khatau Road.	
		Unbuilt space margin at the rear side.	
8.0		Services & Utilities	
8.1	Lighting	Inadequate Natural light through door-window openings supplemented by electric light	
		fixtures.	
8.2	Ventilation	Inadequate Natural ventilation through door-window openings supplemented by electric	
8.3	Electricity	fans. BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Nothing prevalent.	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.	
9.0		Condition	
9.1	Plinth	Poor - Painted stone surface, edging band broken, drainage pipe haphazard, open	
9.2	Walls	downtake pipe and dust accumulation.	
9.2	waiis	Poor - Have cracks at certain places, exposed brickwork; stone weathered, plant growth, seepage and dampness and broken stone.	
9.3	Floor	Fair - In few places wooden members have been replaced by I-section, the flooring is not	
		maintained well.	
9.4	Stairs	Fair - Tread and riser material changed, loosened, sagging of tread and landing, and	
		unclean and not maintained.	
9.5	Openings	Poor - Broken windowpanes, closed ventilators, incongruous addition of grills and <i>jalis</i> , dus accumulation, shutters replaced, painted shutters, balcony and verandah enclosed and	
		window AC units.	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Poor - Plaster and paint peeling off, plant growth, dust accumulation and broken bands.	
		External wall painted, weathered, plant growth	
		Flooring changed according to user and in bad condition.	
9.8	Services	Poor - Leaking drainage pipelines, electrical wiring is haphazard and dangerous and	
0.0	Out Duildings	unhygienic conditions near toilets.	
9.9 9.10	Out Buildings Overall Conditions	Poor - Neglected condition. Poor. Maintenance level: Poor	
5.10			
10.0		Transformation	
	Form	Addition of two floors.	
	Structure	Structural loading must have changed due to addition of two floors and mezzanine.	
	Articulation & Finishes	Painted stone surface of facade.	
44.0		DD Demonte / Demoised Threate	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
-		Additional Notes:	
		-	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.	
		Emerer er international monorn i abioning inc.	

Jony Castle



Arched opening articulation with decorative intrados, columns, floral motif



Central entrance bay with arched openings, bands



Entrance with decorative



Cement tile flooring

Urban Design Research Institute



Projecting balcony and sloping roof supported on brackets





Intricate wooden trellis and railing with sloping roof supported on brackets





194

Rafiya Ma	nzil		195
		Common Ref No: 195	89 C V V V
		Card No: 267	
		Ward (Part): A (part III)	
1. 1		CS No: 20 (Colaba division)	CARDER CARDER
		Plot Area: 1871.25	
2 . 19		B U Area: -	
14 M		Date: 06/04/2005	2010 11 44 10
	A REAL STREET, AND A REAL	Recorded by: Arun Wadhwa	Contraction of the second of t
		Reviewed by:	
11	Vie Mare Comments Vie	Int: Permission denied	
An An		Ext: Arun Wadhwa	
		Photo Ref.: 195_Rafia Manzil	H LE B B
			Location plan
1.0		Denomination	Location plan
1.1	Name of Premises	Rafiya Manzil	
1.2	Earlier Name	Rafiya Manzil	
1.3	Built in:	Indeterminable	Extension Date: -
			<u> </u>
2.0		Access	
2.1	Main	Nathalal Parikh Marg – vehicular and peo	lestrian.
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Government	
3.2	Past	The Trustees of BIT (Lessors & others)	
3.3	Status	Government	
0.0			
4.0		Use	
4.1	Present	Residences of Naval officers.	
4.2	Past	Indeterminable	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Building located on a planned street. Acc	essed from south side front and characterized by ings along the road front in a predominantly
5.2	Architectural Description	Planning Indeterminable. Features Grey stone dressed façade with distinct c carved relief panels within recessed oper spaced and slightly recessed segmental a eaves board. Fine carved tablet feature s bay with large segmental opening and with	cornice bands, segmental arch openings and nings. Long front façade is punctuated by widely arch openings with sloping awning feature and fine et within window panels. Slightly projecting central de cornice forming balcony like feature with slief panels set within parapets of wide recessed
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade: III
6.0		Topography	
6.1	Floors	G + 4 floors.	
7.0		Construction	
7.1	Plinth	Stone dressed plinth about 0.9 m.	
7.2	Walls	Indeterminable	
7.3	Floor	Indeterminable	
7.4	Stairs	Indeterminable	
7.5	Openings	panel shutters also separate ventilator pa have wood louver panels up to sill level.	gs in external facade with wood framed and glazed inel. Few door openings along the external façade
7.6	Roofing	Indeterminable	
7.7	Articulation	Distinct cornice bands at floor levels, fine	carved decorative tablet set within recessed

Rafiya Ma	nzil		19
		opening.	
7.8	Finishes	Grey basalt stone dressed external wall surfa	aces with arch and decorative features in and shutters. Internal finishes indeterminable.
7.9	Interiors (Movable & Immovable)	Movable	
		- Immovable -	
7.10	Compound/ Fence/ Gate	Reconstructed front compound wall about 1. masonry wall along the sides with adjacent b	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
0.7			
9.0		Condition	
9.1	Plinth	Indeterminable	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable	
9.5	Openings	Indeterminable	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Indeterminable	
9.8	Services	Indeterminable	
9.9	Out Buildings	Indeterminable	
9.10	Overall Conditions	Fair externally otherwise indeterminable.	Maintenance level: Fair externally otherwise indeterminable.
40.0		Tanakanakan	
10.0		Transformation	
	Form	-	
	Structure	Indeterminable	
	Articulation & Finishes	Insensitive pointing and painting carried out	over grey stone dressed façade.
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
		¥ :	
12.0		Additional Notes/ References/ Documents	s available
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRANE Division of International Thomson Publishing	D REINHOLD Visual dictionary of Architecture,

Rafiya Manzil



Grey stone ashlar masonry wall with white joints, projecting chajjas, bands etc



Sloping chajjas with wooden decorative supports and barge board



Rectangular window opening with decorative sill panel, bands, sloping chajjas as a later addition covering the arch

Nadia Hou	ISE		19
		Common Ref No: 196	N A CAL
		Card No: 268	1 1 A A
		Ward (Part): A (Part IV)	1. 990 H
		CS No: 47 (Colaba division)	
		Plot Area: part of 1742.30 sqm.	
		B U Area: -	Ashoe Acao Handha Partin Cont
		Date: 03/02/2005	A. A
			Pande Road
4		Recorded by: Sonal Modak	ad the
		Reviewed by:	A A A A A A A A A A A A A A A A A A A
		Int: NA	
	IS IT I DIN I I	Ext: Sonal Modak, Zankhana Prajapati	This Y / X
		Photo Ref: 196_Wadia House	Location Plan
1.0		Denomination	
1.1	Name of Premises	Wadia House	
1.2	Earlier Name	Wadia House	
1.3	Built in:	Currently under construction	Extension Date: -
		-	
2.0		Access	
2.1	Main	Nathalal Parekh Marg – Vehicular and Ped	estrian
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Indeterminable	
3.2	Past	Indeterminable	
3.3	Status	Indeterminable	
4.0	-	Use	
4.1	Present	Under construction	
4.2	Past	Residential	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	-	
5.2	Architectural Description	Planning	
		- Features	
		realures	
		Style	
		-	
5.3	Intrinsic	-	
5.4	Value Classification	Nil	Recommended Delete
			grade:
6.0		Topography	
6.1	Floors	-	
7.0		Construction	
7.1	Plinth	· · · ·	
	Walls		
1.4			
	Floor		
7.3	Floor Stairs	Having gone through major transformations	s the original structure is all but invisible
7.3 7.4	Stairs	Having gone through major transformations	the original structure is all but invisible.
7.3 7.4 7.5	Stairs Openings	Having gone through major transformations	the original structure is all but invisible.
7.3 7.4 7.5 7.6	Stairs Openings Roofing	Having gone through major transformations	the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7	Stairs Openings Roofing Articulation	Having gone through major transformations	the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8	Stairs Openings Roofing Articulation Finishes		the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8	Stairs Openings Roofing Articulation	Having gone through major transformations	the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8	Stairs Openings Roofing Articulation Finishes	Movable -	the original structure is all but invisible.
7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9	Stairs Openings Roofing Articulation Finishes		the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8 7.9	Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable)	Movable -	the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10	Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate	Movable - Immovable - -	the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8 7.9	Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	Movable - Immovable -	s the original structure is all but invisible.
7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10	Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate	Movable - Immovable - -	s the original structure is all but invisible.

Wadia Hou	ISE	196	
8.1	Lighting	Natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	-	
9.0		Condition	
9.1	Plinth	-	
9.2	Walls	-	
9.3	Floor	-	
9.4	Stairs	-	
9.5	Openings	-	
9.6	Roofing	•	
9.7	Articulation & Finishes	-	
9.8	Services	•	
9.9	Out Buildings	-	
9.10	Overall Conditions	Under Construction Maintenance level Under Construction	
10.0		Transformation	
	Form		
	Structure	The original structure has been totally demolished and the construction of new high-rise	
	Articulation & Finishes	building is going on.	
11.0		DP Remarks/ Perceived Threats	
-		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
1210		Additional Notes:	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	



View of new building, under construction after demolishing the original one

Shoen Ho	use		197
		Common Ref No: 197	AN INTERNET
		Card No: 269	
1		Ward (Part): A (Part III)	
		CS No: 440 (Colaba)	
Ser .		Plot Area: 1272.58 sq m.	- I Brown H FR -
1		Rev	
- 6		B U Area: 4747.41 sq m.	
		Date: 02/02/2005	
		Recorded by: Sonal Modak	V. C. S. S. P.
North Cart		Reviewed by:	
1 min		Int: Permission denied	
		Ext: Sonal Modak, Zankhana Prajapati	a start and the start of the
		Photo Ref: 197_Shoen House.	
		-	
10		Denomination	Location Plan
1.0 1.1	Name of Premises	Denomination Shoen House	
1.1	Earlier Name	Shoen House	
1.2	Built in:	Indeterminable	Extension Date: -
1.5	Built III.		Extension Date
2.0		Access	
2.0	Main	Nathalal Parekh Marg – Pedestrian and Ve	ahiqular
2.1	Subsidiary	Convent Street - Pedestrian	
L.L			
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Khushru Manekji and others	
3.3	Status	Tenant	
0.0	Clalus		
4.0		Use	
4.1	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Daily	
1.0			
5.0		Significance & value Classification	
5.1	Townscape (Manmade)	It is one of the several buildings along Nathalal Parekh Marg.	
			northern side, facing Nathalal Parekh Marg with
		separate entrance and exit gates.	
5.2	Architectural Description	Planning	
		No access into the building.	
		Front façade is divided into roughly three bays viz - left hand side, central porch and righ	
		hand side bays.	
			d in four vertical bays; alternate two bays having
		gable ends.	ing having a concrete entrance gate
		There is a garage on rear side of the buildi	ing having a separate entrance gate.
		Features Prominant projecting control porch with la	rge segmental arch with three trefoil arches.
		Porch has floral band at impost level, garg	
			two storeys high rising from second floor level.
			stilted; top floors are segmental, round trefoils.
		Right side has prominently plain pointed a	arches with hood moulding. The bay has a gabl
		end with decorative fascia and finial like fe	atures.
			nicircular arches and plain floor cornice bands.
		Style	
		Neo-Classical and Neo-Gothic features pre-	edominantly observed.
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade II B.
6.0		Topography	
6.1	Floors	G + 2	
7.0		Construction	
7.1	Plinth		stone rough dressed ashlar masonary with stone
7.0	Mar II.	plinth protection layer.	for some statistic
7.2	Walls	Thick load bearing external walls as seen t	from outside.
7.3 7.4	Floor Stairs	Indeterminable Indeterminable	
	STORE	Incereminanie	

Shoen Hou	se	197
7.5	Openings	Arched window openings with ventilators above fixed with stained glass panels and lowe
		part of the window having decorative balustrade.
		Wooden window shutter frames with glazed panels. Some of the windows have lower pa
		fixed with wooden louvers.
		Doors have wooden frames with glazed double panels.
7.6	Roofing	Partly flat and Partly sloping with Mangalore tiles.
7.7	Articulation	Wooden brackets supporting the roof overhang. Decorative column capitals and arc
		springing points. Floral bands at Impost level.
7.8	Finishes	Walls are plastered and painted from externally.
1.0	1 mones	All door/window wooden shutters, louvers and frames are painted.
		No access otherwise into the building.
7.9	Interiors (Movable & Immovable)	Movable
1.5		Indeterminable
		Immovable
7.40		
7.10	Compound/ Fence/ Gate	Grey ashlar masonry about 2 ft. in height with cast iron railing above and pillars with coping
		Plot has separate entry and exit gates marked by pillars on either side. Another entrance to
		the garage from western side, which looks not in use.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	A garage having separate entrance gate from western side.
	Landscape	
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable
		A 10
9.0		Condition
9.1	Plinth	Fair – Plant growth, cracks in stones of plinth protection layer, blackening of stone externally.
9.2	Walls	Indeterminable. Minor cracks seen from outside.
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Poor - Broken glazing. Sloping chajjas installed. All window openings are fixed with
		additional grills. Balconies are enclosed on upper floors in some area.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Poor – Blackening of stone due to weathering. Plant growth. Not maintained.
9.8	Services	Fair – No evident damage or leakage observed.
9.9	Out Buildings	Poor – Not in use.
9.10	Overall Conditions	Poor Maintenance level: Poor
0.10		
10.0		Transformation
10.0	F	
	Form	Additional chhajjas installed from outside above all windows. Balconies are enclosed or
		upper floors in some areas.
	Structure	Indeterminable
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
-		Additional Notes:
		- Beferences
		- <u>References:</u> NITACLI (1990) Decliminary unadited listing of Uppretacted Manumante, Duildings and
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and

Shoen House



Front façade with central projecting porch with semi circular arched openings, side bay with projecting windows, stone balustrade, sloping roof



Garage structure added at the rear side



Oriel Window with decorative floral pattern bands, sill panel



Front arched opening with floral pattern frieze band, cusped arched opening, bands, gargoyles



Side Elevation with decorative elements like arched openings, arch bands, stone jaliwork and balustrade, floor bands



Side bay with continuous pointed arched openings with round ventilator opening



Projecting side verandahs with intricate wooden trellis work, railing and sloping chajjas supported on brackets



Stone gargoyle, floor bands, balustrade

197

Park Hous	e (inclusive of annex building and Kism	at Park)	19
1.0		Common Ref No: 198 Card No: 270 Ward (Part): A (Part III) CS No: 122 (Colaba division) Plot Area: 3782.64 sq m. B U Area: - Date: 7/01/05 Recorded by: Prachi Merchant Reviewed by: Int: Prachi Merchant, Zankhana Ext: Prachi Merchant, Zankhana Ext: Prachi Merchant, Zankhana Photo Ref.: 198_Park House	
1.1	Name of Premises	Park House (inclusive of annex	building and Kismat Park)
1.2	Earlier Name	Park House	
1.3	Built in:	Indeterminable	Extension Date: 1971. Society was formed. Kismat Park building was added later.
2.0 2.1	Main	Access Nathalal Parekh Marg- pedestri	an
2.2	Subsidiary	•	
3.0		Ownership pattern	
3.1	Present	Society	
3.2	Past	Private	
3.3	Status	Society – Shop tenants	
4.0		Use	
4.1	Present	Residential, Commercial - shop	o and offices
4.2	Past	Residential, Commercial - shore	
4.3	Usage	Daily	
5.0		Significance & Value Classifi	cation
5.1	Townscape (Manmade)	The building is located on the N	lathalal Parekh Marg with front access from the south side.
5.2	Architectural Description	building is rectangular in the no the road. The building has higher side an The main building opens into a either side, planned in split-leve the road and a side straight fligi planned between the two buildi The main building has bigger hu wing is located in the rear part. The main building has shops lir above. The annex building is occupied Kismat Park has been added at Features Main Building: The ground floor shops have ar The first and second floor of ce along the sides of long windows swan neck pediment at the sec openings with emphasized keys such as corbel bands, round wi pediment. The middle verandah spaces ha Annex Building:	staircase lobby and leads to two unequal sized flats on I. The annex building has an office accessed directly from ht staircase leading to the first floor. There is a service cour

Park House	e (inclusive of annex building and Kismat	Park) 198	
		Style Colonial style of planning residential flats with influence from Neo Classical style of	
		Architecture.	
5.3 5.4	Intrinsic Value Classification	- A(arc), B(per), B (des), E Recommended grade III	
6.0		Topography	
6.1	Floors	Main building G+3 with part terrace, Annex building G+1, Kismat Park G+5	
7.0		Construction	
7.1	Plinth	Low plinth clad with stone and stone plinth protection band.	
7.2	Walls	Load bearing brick walls Jack-arch method of floor construction.	
7.3 7.4	Floor Stairs	Main open-well wooden staircase with wooden risers, treads and railing.	
7.4	Stans	Cast iron spiral servants at the rear. The annex building has a side single flight stone staircase	
7.5	Openings	Arched main entrance door with emphasized keystone.	
1.0		Arched and rectangular window openings with full height double, glazed paneled, at places louvered shutters with stained glass. Verandah spaces have sash window shutters and at places louvered shutters.	
7.6	Roofing	Sloping roof with wooden supporting members and Mangalore tiles.	
		Flat RCC are on servant block and part main building.	
7.7	Articulation	Bands, motifs, columns, pediments.	
7.8	Finishes	The walls are externally clad with grey stone in the front and plastered and painted at the rear and inside.	
		Floors are finished with cement tiles.	
7.9	Interiors (Movable & Immovable)	Novable	
		Immovable -	
7.10	Compound/ Fence/ Gate	Building directly opening into the footpath. Side and rear brick compound wall. Rear gate connecting main building and Kismat building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Garage occupies the south side setback. Paved pathway.	
8.0		Services & Utilities	
8.1	Lighting	Adequate light through verandah and openings supplemented by artificial light.	
8.2	Ventilation	Adequate light through verandar and openings supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed window and split AC's. Manual security for the society.	
9.0		Condition	
9.1	Plinth	Poor – The level is reduced to one step in some places due to alterations. Finishes have been altered to suit individual requirement.	
9.2	Walls	Poor – the lime mortar plaster is damaged and seepage is observed from the top floor levels.	
9.3	Floor	Cracks and organic growth observed in the rear side. Fair – The floor is repaired and strengthened by individual tenant, according to requiremen I-sections are installed on the top floor, to add extra space, adding load on the building.	
9.4	Stairs	Fair – The main wooden staircase have few wooden parts in a deteriorating condition. The annex building staircase is blocked and is unused.	
9.5	Openings	Poor – The openings are blocked to occupy AC's, shutters are changed, grills are added. Opening sizes are changed, paneled in an insensitive manner.	
9.6	Roofing	Poor – The condition of roof is deteriorating. Top floor beams are exposed and are rusted.	
9.7	Articulation & Finishes	Poor – many features are covered with hoardings, panel. Some features are in a broken condition.	
9.8	Services	Poor – Electrical wires, meter box has been installed haphazardly. Service court is in a bad condition. Leakages observed in the toilet areas.	
0.0	Out Buildings	New building, Kismat Park built on the playground area at the rear.	
9.9			
9.9	Overall Conditions	Poor Maintenance level Poor	
	Overall Conditions	Poor Maintenance level Poor Transformation	

Park House	(inclusive of annex building and Kis	smat Park) 198
	Structure	I-sections are installed on the top floor, to add extra space, adding load on the building. Extensions made on the rear side. The front portion is partially maintained but the rear side of the building is completely changed from its original.
	Articulation & Finishes	Openings are blocked, opening size and shutters have been changed, grills have been added. Wall cladding, hoardings, paneling has completely changed the ground floor façade.
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes: - <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.





Annex building with arched entrance opening, round opening with floral band, projecting balcony with decorative bracket



Façade articulation with columns, decorative lintel in floral pattern



Projecting bay with curved pediment, dentil band, decorative tympanum



Detail of the round opening with decorative frieze band, brackets, columns with rusticated joints



Stained glass window shutters

Archbishop'	's house		199
		Common Ref No: 199	
STATE OF		Card No: 271	
		Ward (Part): A (part III)	A THALL RECURSTIC
		CS No: 438 (Colaba division)	H WAY
		Plot Area: 1308.53 sqm.	A RELL COLLEGITIE OF THE OF TH
a con		B U Area: -	F
10 miles		Date: 06/04/2005	JATHA A
		Recorded by: Arun Wadhwa	T ACCORDED AND C
		Reviewed by:	
when the second second		Int: Permission denied	
		Ext: Arun Wadhwa	
		Photo Ref.: 199_Archbishop's House	
			So the
			the man and the top
			Location plan
1.0		Denomination	
1.1	Name of Premises	Archbishop's house	
1.2	Earlier Name	Archbishop's house	
1.3	Built in:	Indeterminable	Extension Date: -
0.0		A	
2.0	Maia	Access	atrian
2.1	Main	Nathalal Parikh Marg – vehicular and pede	รเกลก.
2.2	Subsidiary	-	
3.0		Ownership nettern	
	Dresset	Ownership pattern	
3.1	Present	Mission His Grace the most Reverend & others	
3.2 3.3	Past	Mission	
3.3	Status	MISSION	
4.0		Use	
-	Dracant		
4.1	Present Past	Residence Residence	
4.2			
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Building located along a well-planned street	at front within a common plot along with Holy
5.1	Townscape (mannade)	Building located along a well-planned street front within a common plot along with Holy Name Cathedral and related buildings. Accessed from north side road fronts. Low scale	
		building with plain façade features set in a predominantly residential and institutional	
		neighborhood with dense tree foliage.	
5.2	Architectural Description	Planning	
		Indeterminable.	
		Features	
			ct cornice bands, continuous chajja features and
			oof form. Projecting high porch with pointed arch
			f features. Decorative tri-foil parapet balusters
		0 1 0	bove porch. Decorative post and railing in the
		compound wall.	
		Style	
		No particular style.	
F 0		-	
5.3	Intrinsic	A(are) D(aer) D (de-) D	Decemmended greater U.D.
5.3 5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade: II B
5.4			Recommended grade: II B
5.4 6.0	Value Classification	Topography	Recommended grade: II B
5.4			Recommended grade: II B
5.4 6.0 6.1	Value Classification	Topography G + 4 floors.	Recommended grade: II B
5.4 6.0 6.1 7.0	Value Classification Floors	Topography G + 4 floors. Construction	Recommended grade: II B
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 4 floors. Construction Plinth height about 0.9 m.	Recommended grade: II B
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	Topography G + 4 floors. Construction Plinth height about 0.9 m. Indeterminable	Recommended grade: II B
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	Topography G + 4 floors. Construction Plinth height about 0.9 m. Indeterminable Indeterminable	Recommended grade: II B
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4	Value Classification Floors Plinth Walls Floor Stairs	Topography G + 4 floors. Construction Plinth height about 0.9 m. Indeterminable Indeterminable Indeterminable Indeterminable	
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	Topography G + 4 floors. Description Plinth height about 0.9 m. Indeterminable Indeterminable Indeterminable Indeterminable Pointed arch openings in porch and entrant	ce, otherwise rectangular door window openings.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5	Value Classification Floors Plinth Walls Floor Stairs Openings	Topography G + 4 floors. Plinth height about 0.9 m. Indeterminable Indeterminable Indeterminable Pointed arch openings in porch and entran Wood framed and glazed panel shutters w	ce, otherwise rectangular door window openings.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5 7.6	Value Classification Floors Plinth Walls Floor Stairs Openings Roofing	Topography G + 4 floors. Description Plinth height about 0.9 m. Indeterminable Indeterminable Indeterminable Pointed arch openings in porch and entrant Wood framed and glazed panel shutters w Indeterminable.	ce, otherwise rectangular door window openings. ith separate ventilator panel.
5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4 7.5	Value Classification Floors Plinth Walls Floor Stairs Openings	Topography G + 4 floors. Description Plinth height about 0.9 m. Indeterminable Indeterminable Indeterminable Pointed arch openings in porch and entrant Wood framed and glazed panel shutters w Indeterminable.	ce, otherwise rectangular door window openings.

Archbishop'	s house		19
		shutters. Internal finishes indeterminable.	
7.9	Interiors (Movable & Immovable)	Movable	
		-	
		Immovable	
		-	
7.10	Compound/ Fence/ Gate	Low grey basalt stone dressed wall and iron	railings above with intermediate decorative
		post	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	-	
	Landscape		
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
0.1			
9.0		Condition	
9.1	Plinth	Indeterminable	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable.	
9.5	Openings	Indeterminable	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Indeterminable	
9.8	Services	Indeterminable	
9.9	Out Buildings	Indeterminable	
9.10	Overall Conditions	Fair externally otherwise indeterminable.	Maintenance level: Fair externally otherwise
			indeterminable.
10.0		Transformation	
	Form	-	
	Structure	Indeterminable.	
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
40.0			9
12.0		Additional Notes/ References/ Document	s available
		Additional Notes:	
		- References:	
		INTACH (1990) Preliminary unedited listing	of I Inprotected Monuments, Buildings and
		Structures listed for Conservation.	or onprototica monuments, buildings and
			D REINHOLD Visual dictionary of Architecture
		Division of International Thomson Publishing	



Extended porch with pointed arched openings, round motifs, horizontal and vertical bands, enclosed first floor



Compound wall detail

Janjira C	hambers		200
		Common Ref No: 200	MADAM CAMA ROAD
		Card No: 272	I ROAD
		Ward (Part): A (Part III)	A REAL BOLZONA
		CS No: Indeterminable	The sale of the
1 5000		Plot Area: Indeterminable	A CONTRACTOR
1		B U Area: -	
		Date: 31/12/04	
The state	Charles and the second s	Recorded by: Prachi Merchant	- BELLENN MANAJES
Service		Reviewed by:	T THURS MORE
2 Cast		Int: Prachi Merchant, Arun Wadhwa	
3 PTS	State of the second sec	Ext: Prachi Merchant, Arun Wadhwa	C. S. Martin Kard
	Water Martine	Photo Ref: 200_Janjira Chambers.	Star Star Star
			the stand and
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Janjira Chambers	
1.2	Earlier Name	Janjira Chambers	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Nathalal Parekh Marg – vehicular and ped	estrian
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Central Railway	
3.2	Past	Central Railway	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Residential – Railway officers residences	
4.2	Past	Residential – Railway officers residences	
4.3	Usage	Daily	
5.0			
5.0	Tanana (Mananada)	Significance & value Classification	and the Manager of the Constant of the second state of the second state of the
5.1 5.2	Townscape (Manmade)		rekh Marg with front access from the west side.
5.Z	Architectural Description	Planning	e plot with offsets on three sides except on the
		north side.	e plot with onsets on three sides except on the
		The building is 'C' shaped, with one of its v	vings facing the road
		The building has the central staircase bloc	
		The building entrance is through a court from the west side through an extended porch, leading to a staircase block. The building has residential flats on either side of the staircase block with its wings extending to the north, enclosing a court.	
		Each flat has verandahs on both sides, with rooms planned in a linear way, accessed from	
		both ends. The servant room block and its access are from the rear east.	
		both ends. The servant room block and its	access are from the rear east.
		Features	
		Features The entrance porch of the building is flam	ked with granite round columns with decorative
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> .	ked with granite round columns with decorative
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham	
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing.	ked with granite round columns with decorative fered parts consist of verandahs with wooden
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open	ked with granite round columns with decorative freed parts consist of verandahs with wooden ings with emphasized keystones, decorative
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl	ked with granite round columns with decorative fered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs.
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor	ked with granite round columns with decorative fered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it.
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decon The building top level has a projecting <i>cha</i>	ked with granite round columns with decorative fered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs.
		Features The entrance porch of the building is flan capitals and extended wooden <i>chaijas</i> . The arms of the wings along with charr columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade.	ked with granite round columns with decorative fered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it.
		Features The entrance porch of the building is flan capitals and extended wooden <i>chaijas</i> . The arms of the wings along with charr columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style	ked with granite round columns with decorative affered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has
5.3	Intrinsic	Features The entrance porch of the building is flan capitals and extended wooden <i>chaijas</i> . The arms of the wings along with charr columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade.	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has
5.3		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style Colonial style of planning residential flats w	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
5.3 5.4	Intrinsic Value Classification	Features The entrance porch of the building is flan capitals and extended wooden <i>chaijas</i> . The arms of the wings along with charr columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
5.4		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style Colonial style of planning residential flats w - A(arc), B(per), B (des), E	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>ija</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
		Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style Colonial style of planning residential flats w	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
5.4 6.0	Value Classification	Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style Colonial style of planning residential flats w - A(arc), B(per), B (des), E Topography	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
5.4 6.0	Value Classification	Features The entrance porch of the building is flan capitals and extended wooden chajjas. The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decord the building top level has a projecting chara a stone balustrade. Style Colonial style of planning residential flats w - A(arc), B(per), B (des), E Topography G + 3 with terrace, Servants block G + 4	ked with granite round columns with decorative infered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>jja</i> on wooden brackets and the terrace level has with influence of The Neo Classical style.
5.4 6.0 6.1	Value Classification	Features The entrance porch of the building is flan capitals and extended wooden <i>chajjas</i> . The arms of the wings along with cham columns, chajjas and cast iron railing. The side windows have arched open tympanum at places, sill bands, bands at fl The staircase block has an arch with decor The building top level has a projecting <i>cha</i> a stone balustrade. Style Colonial style of planning residential flats w - A(arc), B(per), B (des), E Topography	iked with granite round columns with decorative offered parts consist of verandahs with wooden ings with emphasized keystones, decorative loor levels, friezes, and geometric pattern motifs. rative motifs on it. <i>ija</i> on wooden brackets and the terrace level has with influence of The Neo Classical style. Recommended grade: III

Janjira Cr	hambers	200
7.3	Floor	Stone slabs wire mesh and lime mortar, supported on steel sections
7.4	Stairs	Open-well wooden staircase with wooden risers, treads and railing, newel post and a lift in the center. Servant block doglegged staircase at the rear.
7.5	Openings	Entrance door of wooden paneled shutter.
	- p	Arched door openings with ventilator and paneled shutters.
		Arched window openings with glazed paneled shutters.
		Full height staircase block windows with glazed paneled shutters.
		Verandah spaces have rectangular openings with wooden column post.
7.0	Desfer	
7.6	Roofing	RCC slab with a <i>chajja</i> running along the periphery.
7.7	Articulation	Bands, motifs, arches, wooden verandahs.
7.8	Finishes	The walls are externally clad with grey stone and plastered and painted inside.
		Floors are finished with cement tiles.
7.9	Interiors (Movable & Immovable)	Movable
		-
		Immovable
		-
7.10	Compound/ Fence/ Gate	Brick compound wall with fence above, two MS gates on south side.
7.11	Curtilage/ Unbuilt space/ Out	Garage in the front setback area.
	Buildings/ Landscape	Partially paved, shrubs and old trees in the front.
	· ·	Pump room added on the rear north side.
8.0		Services & Utilities
8.1	Lighting	Adequate light through verandah and openings supplemented by artificial light.
8.2	Ventilation	Adequate light through veralidarian and openings supplemented by artificial ventilation.
-		BEST
8.3	Electricity	
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security	Individual tenants have installed window and split AC's.
	Systems)	Manual security to the society.
9.0		Condition
	Diath	
9.1	Plinth	Fair – The band and the stone cladding is deteriorating.
9.2	Walls	Poor – The plaster is damaged and seepage is observed from the top floor levels.
		Cracks and organic growth observed in the rear side.
		Punctures are made through walls for passing electric wires and sanitation pipes
9.3	Floor	Poor - Due to its deteriorating state, the floor and arched openings have been
		strengthened with steel sections.
		Tanks have been installed on the Terrace level.
9.4	Stairs	Fair – The main wooden staircase have few wooden parts in a deteriorating condition.
5.4	Otans	The servant block staircase is in not maintained.
0.5	Oneninge	Poor – The openings have been blocked to house AC's, shutters changed, grills added.
9.5	Openings	
		Opening sizes have been changed, paneled in an insensitive manner.
		Verandah openings are enclosed with grills, panels.
9.6	Roofing	Fair – The condition of roof is deteriorating.
		Top floor beams have been exposed and are rusted.
9.7	Articulation & Finishes	Poor – Some features are in a broken condition.
		Verandah cast iron railing has been replaced.
9.8	Services	Poor – Electrical wires, meter box has been installed haphazardly. Leakages observed in
		the toilet and service areas.
9.9	Out Buildings	New building, Kismat Park built on the playground area at the rear.
9.10	Overall Conditions	Fair Maintenance level: Poor
J.IU		
10.0		Transformation
10.0		Transformation
	Form	
	Structure	I-sections are installed to strengthen the floor. Verandahs are enclosed.
		Extensions to the blocks are made at the rear side.
	Articulation & Finishes	Openings are blocked, opening size and shutters have been changed, grills have been
		added. Outbuildings have been insensitively added in the front and rear portion.
		The north side setback is blocked. Chajjas have been replaced with asbestos sheet.
		"
		DP Remarks/ Perceived Threats
11.0		DF Remarks/ Ferceived Infeats
11.0		
11.0		Building forms part of R zone.
		Building forms part of R zone.
11.0		Building forms part of R zone. Additional Notes/ References/ Documents available
		Building forms part of R zone.
		Building forms part of R zone. Additional Notes/ References/ Documents available

Janjira Chambers	20	0
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings a	nd
	Structures listed for Conservation.	



Street side façade with incongruous modifications



Grey stone ashlar masonry building with arched openings, scroll bracket



Sill level motif detail



Main side entrance façade with central high wing with arched openings, bands, verandah opening



Cement tile flooring



Verandah with wooden rafters supported with columns

Clark Hou	se	2	
		Common Ref No: 201 Card No: 273 Ward (Part): A (Part III) CS No: Indeterminable Plot Area: Indeterminable B U Area: -	
		Card No: 273	
	in the second	Ward (Part): A (Part III)	
		CS No: Indeterminable Plot Area: Indeterminable B U Area: -	
		Plot Area: Indeterminable	
		Date: 23/12/2004	
		Recorded by: Sonal Modak	
		Reviewed by:	
	Hite, Mile	Int: Sonal Modak	
	and the second second		
		Ext: Sonal Modak	
		Photo Ref.: 201_Clark House	
		MAJESTIC MAJESTIC	
		Location Plan	
1.0		Denomination	
1.1	Name of Premises	Clark House	
1.2	Earlier Name	Clark House	
1.2	Built in:	1907 (Tablet) Extension Date: -	
1.3			
2.0		Access	
2.1	Main	Nathalal Parekh Marg – Pedestrian and Vehicular	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	R.D. Satna Trust - Private	
3.2	Past	Indeterminable	
3.3	Status	Tenants	
4.0		Use	
4.1	Present	Residential and Commercial – Offices.	
4.2	Past	Residential	
4.3			
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	It is one of the heritage buildings along Nathalal Parekh Marg.	
		The main access is from southern side, facing Nathalal Parekh Marg.	
5.2	Architectural Description	Planning	
		A C-shaped plan with a rear light and service court having access to the servant's quarter	
		Symmetrical front façade with slightly protruding central bay housing lift and stairwell, whi	
		rises higher and has a decorated pediment atop, the entrance too has a decorative	
		entrance door with a semicircular arch in the center and a tiled slope roof extended porch	
		Features	
		Step-out balustrade balconies resting on decorative stone brackets. Circular columns on	
		either side of central entrance topped with a pediment.	
		Style	
		Neo-Gothic features prominently observed.	
5.3	Intrinsic	- ·	
5.4	Value Classification	A(arc), B(per), B (des), E Recommended grade II B	
v . 1			
6.0		Tanagraphy	
6.0		Topography	
6.1	Floors	G+ 3 front portion.	
		G+ 5 rear side housing servants' quarters.	
7.0		Construction	
7.1	Plinth	Medium plinth about 1ft. 6 inches in height in grey ashlar masonary with stone plinth	
		protection layer.	
7 2	Walls	I block load bearing composite maconany with vollow drossod regular achier mesonany	
7.2	Walls	Thick load bearing composite masonary with yellow dressed regular ashlar masonary	
		facing and brick backing.	
7.3	Floor	facing and brick backing. Hollow concrete block flooring.	
		facing and brick backing.	
7.3	Floor Stairs	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail.	
7.3 7.4	Floor	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail. Arched window openings with ventilators above fixed with stained glass panels in the	
7.3 7.4	Floor Stairs	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail. Arched window openings with ventilators above fixed with stained glass panels in the balcony area. Side bays have two semicircular arches with prominent keystone.	
7.3 7.4	Floor Stairs	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail. Arched window openings with ventilators above fixed with stained glass panels in the balcony area. Side bays have two semicircular arches with prominent keystone. Openings defined by plastered architraves with keystones.	
7.3 7.4 7.5	Floor Stairs Openings	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail. Arched window openings with ventilators above fixed with stained glass panels in the balcony area. Side bays have two semicircular arches with prominent keystone. Openings defined by plastered architraves with keystones. Wooden door/window shutter frames with glazed double panels.	
7.3 7.4	Floor Stairs	facing and brick backing. Hollow concrete block flooring. Wide timber dog-legged staircase with wooden newel post, balustrades and handrail. Arched window openings with ventilators above fixed with stained glass panels in the balcony area. Side bays have two semicircular arches with prominent keystone. Openings defined by plastered architraves with keystones.	

Clark Hous		20
7.8	Finishes	Walls are plastered and painted internally. Externally exposed yellow ashlar masonary. All door/window wooden shutters, louvers and frames are painted.
7.0	Interiors (Mayable & Immeyable)	An door/window wooden shutters, louvers and names are painted.
7.9	Interiors (Movable & Immovable)	Movable:
		- Immovable:
7.10	Compound/ Fence/ Gate	Yellow ashlar masonry about 1ft.6 inches in height with cast iron railing above and pillars
		with coping. Plot has a common central entry and exit gates marked by pillars on either
		side. Another entrance to the garage from western side, which looks not in use.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	A garage and temporary shed for parking on western side. Remaining is a neglected open
	Landscape	space with no paving or soft landscape.
		Consistent 0 114/14/20
8.0	Lichting	Services & Utilities
8.1	Lighting	Adequate daylight is supplemented with artificial lighting equipments wherever necessary.
8.2	Ventilation	Adequate ventilation through windows and verandahs supplemented with electrical fans as
0.2	Flootricity	required. BEST
8.3	Electricity	
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	•
9.0		Condition
9.1	Plinth	Poor – Plant growth. Blackening of stone externally. Dampness due to leakages. Plinth is
9.1	Fillion	partly covered due to planter boxes.
9.2	Walls	Fair – Minor cracks observed from internally. Dampness due to leakage in some parts.
9.3	Floor	Fair – no evident damages seen.
9.4	Stairs	1 all – No evident damages seen.
9.5	Openings	 Fair – with replaced shutters, broken glass panes. Frontal step out balconies are enclosed.
9.6	Roofing	Fair – no evident damages seen.
9.0	Articulation & Finishes	Poor – Blackening of stone due to weathering. Plant growth. Not maintained. Damaged
5.1	Anticulation & Finishes	features.
9.8	Services	Poor – Leakage through broken service pipes. Plant growth.
9.9	Out Buildings	Fair – Not maintained
9.10	Overall Conditions	Poor Maintenance level: Poor
0.10		
10.0		Transformation
	Form	
	Structure	Timber floors have been replaced by hollow concrete blocks.
		Step out balconies are strengthened using steel sections.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		- References
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.




Buff stone clad symmetrical building with projecting side bays, sloping roofscape



Projecting balcony with decorative brackets, balustrade



Side façade



Minton tile flooring



Arched openings with a prominent keystone, sill and floor band

YMCA buil	dina		202
	g	Common Ref No: 202	
		Card No: 274	
		Ward (Part): A (part III)	
		CS No: 21 (Colaba division)	GARDEN
**** (3.5) ***		Plot Area: Indeterminable	
		B U Area: -	
1.1		Date: 06/04/2005	- NRG
			- KHWE
Stor Jacob		Recorded by: Arun Wadhwa	AREI
		Reviewed by:	NA THALA LA RETHINGS
		Int: Permission denied	THAL
- 18		Ext Arun Wadhwa	AA C School House
		Photo Ref.: 202_YMCA	
			The second se
			Location plan
1.0		Denomination	
1.1	Name of Premises	YMCA building	
1.2	Earlier Name	YMCA building	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Nathalal Parekh Marg - vehicular & pedestri	ian.
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	YMCA - Mission	
3.2	Past	YMCA - Mission	
3.3		Mission	
3.3	Status	WISSION	
4.0		Use	
	Durant		
4.1	Present	Hostel	
4.2	Past	Hostel	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Building located along a well planned street predominantly residential and institutional ne	
5.2	Architectural Description	Planning	
		Indeterminable.	
		Features	
		Grey stone dressed façade characterized by	arch openings, bay windows and floor level
		cornice bands.	
		Entrance is marked by an extended porch w	ith segmental arch openings and circular tablet
		feature with YMCA inscribed to east and we	st sides.
		Stone dressed facades are relieved by distir	nct cornice bands at floor levels and projecting
		bay window features.	
			with decoratively treated spandrels with relief
			ked by curved chajja like feature supported on
		decorative brackets.	
		Bay window opening is lined by sloping chaj	ia feature supported on wooden brackets.
			with lower parapet panel in fine relief work and
		upper arch portion in tracery. Also highly de	
		Style	- J
		Colonial influence.	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade: II B
6.0		Topography	
6.1	Floors	G + 3 floors.	
7.0		Construction	
7.1	Plinth	Low plinth about 0.6 m.	
7.1	Walls	Indeterminable	
7.3	Floor	Indeterminable	
7.4	Stairs Openings	Indeterminable	n external facade with wood framed and glazed
7.5			

YMCA buil	dina		20
		panel shutters also separate ventilator panel. Some ground floor openings also have	
		wooden louvered shutters. Few large arch openings have circular tracery panel.	
7.6	Roofing	Indeterminable	
7.7	Articulation	Cornice bands at floor levels, bay window feature, arch openings and decorative relief spandrel.	
7.8	Finishes	Grey basalt stone dressed external wall surfaces with arch and decorative features in lighter stone finish. Wood finish bay window and shutters. Internal finishes indetermin	
7.9	Interiors (Movable & Immovable)	Movable	
		- Immovable	
7.10	Compound/ Fence/ Gate	Low stone dressed wall with iron railing above at the front side and highly decorative post with carved features. Common masonry wall along the sides with adjacent buildi	stone
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape		
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable.	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
9.0		Condition	
9.1	Plinth	Indeterminable	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable	
9.5	Openings	Indeterminable	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Indeterminable	
9.8	Services	Indeterminable	
9.9	Out Buildings	Indeterminable	
9.10	Overall Conditions	Fair externally otherwise indeterminable. Maintenance level: Fair externally othe indeterminable.	erwis
		<u> </u>	
10.0	_	Transformation	
	Form	<u>-</u>	
	Structure	Indeterminable.	
	Articulation & Finishes	Insensitive pointing and painting carried out over grey stone dressed façade.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Archited Division of International Thomson Publishing Inc.	cture



Arched shaped chajja projection with supporting scroll brackets, dentil band



Round medallion at the entrance



Gate post with carvings



Entrance porch with an arch, bands, terrace floor above with balustrade



Arched window with decorative tympanum, decorative sill and lintel level band with floral pattern



Bay windows with sloping chajjas supported on brackets, wooden louvered shutters, decorative frieze bands at the sill, lintel and floor level

Beryl Ho	ISE		203
		Common Ref No: 203	COOPERAGE ROAD
	Bart State	Card No: 275	ANGE ROAD
-	24.	Ward (Part): A (Part III)	
1.		CS No: 19 (Colaba Division)	and some a "
1 1 2		Plot Area: Indeterminable	
		B U Area: -	
. Alter		Date: 29/12/2004	
11122		Recorded by: Zankhana Prajapati	
10-2/-		Reviewed by:	
A DI		Int: Zankhana Prajapati, Sonal Modak	
		Ext: Zankhana Prajapati, Sonal Modak	
		Photo Ref: 203_Beryl House.	
			It was a find
and the second second		1	Location plan
1.0		Denomination	Location plan
1.0	Name of Premises	Beryl House	
1.2	Earlier Name	Beryl House	
1.2		Indeterminable	Extension Date:
1.3	Built in:	Indeterminable	Extension Date: -
		A	
2.0	Math.	Access	
2.1	Main	Nathalal Parekh Marg.	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Central Railway	
3.2	Past	-	
3.3	Status	Owner/Tenant	
4.0		Use	
4.1	Present	Residential Flats	
4.2	Past	Residential Flats	
4.3	Usage	Daily	
		2009	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	The main access to the plot is from Nathalal Parekh Marg.	
0.1	(maninade)		ar height as other buildings along the along the
		streetscape.	a neight as other ballange along the along the
5.2	Architectural Description	Planning	
0.2		0	s centrally located on the plot with open spaces
		all around.	
		The building is ground plus four storied high	h with terrace
			which leads to a staircase and corridor area with
			each flat, there are attached servant's guarters
			Iding by two staircases hence creating a service
			all the toilets and service utilities are provided.
		All floors have residential flats.	
		Features	
			a combination of flat arch and segmental arch
			nent with ancon and floral motif, with projecting
			n, it has several features like arabesque bands,
		medallions, scroll keystones, cartouches ar	
		Style	
		Building displays characteristics of the Neo	-Classical style
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), E	Recommended grade: II B.
у .т		יונמוט, שנאטון, ש נעכטן, ב	
6.0		Topography	
6.1	Floors	G + 4	
0.1	1 10013		
7.0		Construction	
7.0	Dist	Construction	a slight and at a
7.1	Plinth	Low height stone plinth with edging done for	
7.2	Walls		stone fascia, internally plastered and painted.
7.3	Floor		on I-section over which Minton tiles are laid.
		Originally supported with wood columns.	
7.4	Stairs		aircase and other two-service staircases, which
		are connected to servant quarter's wings.	
		Main staircase is a doglegged timber stairc The two-rear staircases are supported on I-	

Beryl Hou	ISE	203	
7.5	Openings	All doors have rectangular openings with single or double leaved wooden shutter. Windows have a combination of flat, segmental and semicircular arched openings with no set pattern observed, and ventilators with stained glass above. All shutters are glazed within a wooden framework.	
7.6	Roofing	Flat terrace with staircase block and water tanks.	
7.7	Articulation	Comice band, pediment, ancon, floral motif, arabesque band, medallion, scroll keystone,	
7.8	Finishes	cartouche and decorative spandrel. External walls - gray stone ashlar masonry. Internal walls are plastered and painted.	
7.9	Interiors (Movable & Immovable)	Minton tiles are present in flooring. Movable - Immovable	
7.10	Compound/ Fence/ Gate	Wooden decorative arched frame partition. Half height stone wall with MS grill - front compound wall. Remaining three sides have a brick wall. Cast iron gates at the sides of the building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Open space around the building. Presence of garages, watchmen's cabin, water tank and pump house. Front portion has planter boxes.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	AC units.	
9.0		Condition	
9.1	Plinth	Poor - has plant growth, dust accumulation, stone surface blackened due to drain pipes, cracks and broken stone.	
9.2	Walls	Fair - blackened stone surface at some areas, seepage, cement pointing, dust accumulation and plant growth.	
9.3	Floor	Poor - water seepage from floor to floor, has heavy cracks and major repair work is going on where replacements of I – sections is being carried out.	
9.4	Stairs	Fair – dust accumulation, broken treads, cracks in railing, missing balusters, unpolished, rear staircase has rusted I-sections, concrete treads have cracks and in a very dangerous and poor condition.	
9.5	Openings	Poor - addition of grills, chajjas, window AC units, window frames changed, closed, pattern changed and broken windowpanes.	
9.6	Roofing	Fair – leakage but building is under restoration.	
9.7	Articulation & Finishes	Fair – broken comice band, dust accumulation and blackening of articulation. Internal Plaster and paint peeling off at certain places. External wall painted in certain areas, dust accumulation, plant growth, cracks and seepage. Tiling is being changed due to reconstruction of floors.	
9.8	Services	Poor – Broken, leaking and corroded iron sewage pipes, open disconnecting chambers with plant growth.	
9.9	Out Buildings	Poor – not maintained.	
9.10	Overall Conditions	Fair. Maintenance level: Poor.	
10.0	Form	Transformation	
	Structure Articulation & Finishes	Reconstruction of the building floor with new I-sections Painted articulation.	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	

Beryl House



Grey ashlar stone clad building with sloping chajjas



Minton tile flooring



Façade articulation with decorative tympanum in floral pattern



Interior View with wooden decorative partition paneling

Wooden staircase with intricately carved newel post, railing



Arch Detail with scroll bracket keystone, round ventilator opening



Cast iron railing detail

Arsiwala bu	uilding		204
	No. 100	Common Ref No: 204	
A NUMBER		Card No: 276	
		Ward (Part): A (Part IV)	
		CS No: 119 (Colaba division)	
all market	and the second second	Plot Area: 1872.92 sqm.	
		B U Area: -	
- I - Contra		Date: 11/01/2005	- Starting Starting
			The second second
		Recorded by: Sonal Modak	
	Weiteren Smith	Reviewed by:	OH HE HE
INE CHOWNER	Land Die Contraction	Int: NA	
10 2		Ext: Sonal Modak, Prachi Merchant	
Min E		Photo Ref.: 204_Arsiwalla building	Ar . Ar and been
			and the second s
4.0		Describerthe	on Plan
1.0		Denomination	
1.1	Name of Premises	Arsiwala building	
1.2	Earlier Name	Arsiwala building	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Nathalal Parekh Marg – Pedestrian	
2.2	Subsidiary	R. Salgaonkar Road – Pedestrian	
L.L	Subsidialy	n. Jaiyaumai Nuau - reuesillali	
2.0		Ownership notten	
3.0		Ownership pattern	
3.1	Present	Indeterminable	
3.2	Past	Indeterminable	
3.3	Status	Tenant	
4.0		Use	
4.1	Present	Residential – flats, Commercial – Offices, s	hons etc
4.2	Past	Residential, Commercial.	
4.2			
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	-	
5.2	Architectural Description	Planning	
		The building is completely transformed. No	special observation.
		Features	
		No special observation.	
		Style	
		No special observation.	
5.3	Intrinsic	-	
5.4	Value Classification	Nil	Recommended grade Delete
5.4			Recommended grade Delete
6.0		Tanagraphy	
6.0	<u> </u>	Topography	
6.1	Floors	G+2	
7.0		Construction	
7.1	Plinth		
7.1			
7.1 7.2	Walls		
7.1 7.2 7.3	Walls Floor		
7.1 7.2 7.3 7.4	Walls Floor Stairs	Having gone through major transformations	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5	Walls Floor Stairs Openings	Having gone through major transformations	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6	Walls Floor Stairs Openings Roofing	Having gone through major transformations	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7	Walls Floor Stairs Openings Roofing Articulation	Having gone through major transformations	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes		s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7	Walls Floor Stairs Openings Roofing Articulation	Having gone through major transformations	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes		s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes	Movable	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8	Walls Floor Stairs Openings Roofing Articulation Finishes		s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable)	Movable - Immovable	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate	Movable - Immovable -	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	Movable - Immovable	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate	Movable - Immovable -	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10 7.11	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	Movable - Immovable - -	s the original structure is all but invisible.
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10 7.11 8.0	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Movable Immovable - - - Services & Utilities	
7.1 7.2 7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10 7.10 7.11	Walls Floor Stairs Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	Movable - Immovable - -	s supplemented by electric light fixtures.

Arsiwala b	uilding	204	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace	
8.7	Other (HVAC/BMS/Security Systems)	No trace	
9.0		Condition	
9.1	Plinth	Poor	
9.2	Walls	Poor	
9.3	Floor	Poor	
9.4	Stairs	Poor	
9.5	Openings	Poor	
9.6	Roofing	Poor	
9.7	Articulation & Finishes	Poor	
9.8	Services	Poor	
9.9	Out Buildings	Poor	
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0		Transformation	
	Form		
	Structure	Completely transformed building.	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	

Buckley Co	ourt		205
		Common Ref No: 205	
200		Card No: 277	COOPERAGE
		Ward (Part): A (part III)	
1		CS No: 436 (Colaba division)	
	and and a second		
and the second second		Plot Area: 1252.51 sqm.	
	W.	B U Area: -	Names
9.5		Date: 06/04/2005	
2		Recorded by: Arun Wadhwa	a the set of the set o
		Reviewed by:	
	the first of the second	Int: Permission denied	
100		Ext: Arun Wadhwa	JATH.
38 B	A STATE INTER COMPANY	Photo Ref.: 205_Buckley Court	
		FIIOLO REI 205_Buckley Coult	
Contraction of the			
			BESS
			BEST WARG
			The second secon
			Location plan
1.0		Denomination	
1.1	Name of Premises	Buckley Court	
1.2	Earlier Name	Buckley Court	
1.3	Built in:	Old portion in 1920's	Extension Date: - high rise constructed in 1998.
2.0		Access	
2.0	Main		r and podoctrian
		Nathalal Parekh Marg – vehicula	
2.2	Subsidiary	BEST marg - vehicular and pede	strian.
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Indeterminable	
3.3	Status	Owner	
5.5	Status	Owner	
4.0		Use	
4.1	Present	Residences – Apartments.	
4.2	Past	Residence – Bungalow.	
4.3	Usage	Daily.	
5.0		Significance & Value Classifica	ation
5.1	Townscape (manmade)		e intersection of Nathalal Parikh marg with cooperage
0.1	Townooupe (maninado)	road. Accessed from north as w	
			the road junction in a predominantly residential and
		institutional neighborhood with de	ense tree follage.
5.2	Architectural Description	Planning	
			 Leaving apart the front portion the building is
		reconstructed into a high rise with	h luxurious apartments.
		Features	
			by continuous wooden verandas, well articulated corners
		bays topped by dome feature.	
		Entrance marked by central proje	ecting porch with semicircular arch openings with keystone
		feature and stone baluster parap	
			with wooden supports, infill ventilator panels with
		decorative stain glass.	
			per have culminate into elongated dome feature. Projecting
		Projecting octagonal shaped corner bays culminate into elongated dome feature. Projecting wooden balcony feature supported on decorative brackets and marked by sloping awning	
			eu on decorative brackets and markeu by stopling awning
		resting on wooden brackets.	energine with depending transferrer and some doubt of
		ũ	openings with decorative keystone and carved relief
		panels.	
		Floor levels are marked by distin	ct cornice bands.
		Style	
		Building displays Neo Classical f	eatures
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), E (Old po	rtion only) Recommended grade: III
			//
6.0		Topography	
	Eleore	G + 4 floors. Reconstructed high	rico is C+ 20 floors
6.1	Floors		1100 10 UT 20 110015.
7.0		O a materia tita a	
7.0		Construction	
7.1	Plinth	Stone dressed plinth about 0.9 m).

Buckley Co	ourt		205
7.2	Walls	Indeterminable	
7.3	Floor	Indeterminable	
7.4	Stairs	Indeterminable	
7.5	Openings	Segmental arch architrave openings with wo	
		separate ventilator panel. Wooden veranda	members and shutters with glazed panels and
		stain glass set within infill ventilator portion.	
7.6	Roofing	Indeterminable since access denied.	
7.7	Articulation	Distinct cornice bands at floor levels, architra	ave segmental arch openings with decorative
		keystone feature, overhanging wooden balc	ony and sloping awning feature supported on
		decorative wooden brackets, octagonal corn	er bays surmounted by elongated dome
		feature.	
7.8	Finishes	Buff basalt stone dressed external wall surfa	ces with arch and decorative features in lighter
		stone finish. Wood finish veranda bays and	door window shutters. Internal finishes
		indeterminable.	
7.9	Interiors (Movable & Immovable)	Movable	
	, , , , , , , , , , , , , , , , , , ,	-	
		Immovable	
		-	
7.10	Compound/ Fence/ Gate	Low stone dressed wall and iron railings abo	ove with intermediate decorative stone post
7.11	Curtilage/ Unbuilt space/ Out Buildings/		•
	Landscape		
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
0.1			
9.0		Condition	
9.1	Plinth	Indeterminable	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable	
9.5	Openings	Indeterminable	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Indeterminable	
9.8	Services	Indeterminable	
9.9	Out Buildings	Indeterminable	
9.10	Overall Conditions	Fair externally otherwise indeterminable.	Maintenance level: Fair externally otherwise
9.10			indeterminable.
40.0		Transformation	
10.0		Transformation	
	Form	Except front portion the villa structure is maj	orly transformed by constructing a high-rise
		above it.	
	Structure	Indeterminable.	
	Articulation & Finishes	Cement pointing observed over buff basalt s	tone dressed façade.
44.0			
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
40.0			
12.0		Additional Notes/ References/ Documents	s available
		Additional Notes:	
		<u> </u>	
		References:	
		INTACH (1990) Preliminary unedited listing	ot Unprotected Monuments, Buildings and
		Structures listed for Conservation.	
			D REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing	j Inc.

Buckley Court



Original structure with projecting porch with arched openings, balustrade, window openings with wooden trellis work



Corner projecting bay with sloping chajjas supported on wooden brackets



Wooden bracket detail supporting the projecting balcony



Window opening with decorative sill panel, decorative keystone, comice band with dentil



Porch with arched openings, prominent keystone, columns with rusticated joints, bands



Projecting balcony with columns supporting sloping chajjas, decorative brackets, railing, trellis work



Side bay with onion shaped dome, sloping chajjas supported on brackets



Newly constructed tower over the original structure

205

Urban Design Research Institute

Holy Name	Cathedral		206 (I
3.5		Common Ref No: 206 (I)	the states of the states
		Card No: 278	
		Ward (Part): A (Part III)	
		CS No: 439 (Colaba division)	A A A A A A A A A A A A A A A A A A A
		Plot Area: Indeterminable	
1		B U Area: -	the standard the
		Date: 10/12/2004	E and the and the
and the second se		Recorded by: Prachi Merchant	
100		Reviewed by:	
1. T.		Int: Sonal Modak, Prachi Merchant	
- Barris			1.1. 1.
		Ext: Sonal Modak, Prachi Merchant Photo Ref.: 206(1)_Holy Name Cathedral	
		Photo Ref. 200(1)_noty Name Cathedral	H H HICHAN
			A BAR AND AND
			SHAHD BHACAT SINGH ROAD
- Sector			HAGAT SINGH S
and the second			Location Plan
1.0		Demensionation	Location Plan
1.0	News of Decision	Denomination	
1.1	Name of Premises	Holy Name Cathedral	
1.2	Earlier Name	Church of Holy Name	
1.3	Built in:	Construction started in 1901, completed in 1904	Extension Date: -
2.0		Access	
2.1	Main	Nathalal Parekh Marg – Pedestrian and vehicular	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Trust - Archbishop	
3.2	Past	Trust - Archbishop	
3.3	Status	Owner	
0.0			
4.0		Use	
4.1	Present	Cathedral - Religious, School - Educational, Archb	hishons house - Residential
	Past	Religious, Educational, Residential	Jishops house - Residential
4.2			
4.3	Usage	Daily	
5.0			
5.0	Teurosene (Menmede)	Significance & Value Classification	a Fart Canvant Cabaal are leasted in and
5.1	Townscape (Manmade)	The Cathedral with the Archbishops House and th	
		complex, forming a part of skyline of the buildings	
		The building is accessed through an extended por	ch from the west side.
5.2	Architectural Description	Planning	
		The building has an oblong plan with an apsidal sa	anctuary of a semi-octagonal form.
		The west side arched entrance porch is extended	out, with a terrace above with stone
		balustrade.	
		The congregational hall comprises of a long nave	
		both sides, a projecting loft for organ and choir on	
		baptistery in the tower-basement. There is a Sacri	
		Overall, a strong influence from Early Gothic style	
		The west side entrance consists of an imposing de	
		containing belfry storey, resolved into an octagona	al form, surmounted by an articulated
		cornice.	
		The side altars and the pulpit are highly ornament	al.
		The nave consists of 5 bays of arches supported of	on square piers amplified by pilasters and
		slender shafts, which carry corbels of statues.	
		Features	
		The main features of the cathedral are the flying b	uttresses and its pinnacles over the nave
		which strengthen the groined vaulted roof built by	arched work supported by stone ribs.
		The walls and the vaulted roof are highly decorate	d with rich paintings and frescos
		representing biblical subjects.	· -
		Building articulation comprises of openings with po	ointed arches, stain glass windows, rose
		windows, flying buttresses, friezes, bands, corner	
		The vaulting is covered with rich and glowing freso	
		Testament subjects, beginning from Gospel side a	
		Style	
		The building derives influence from Neo Gothic st	vle of Architecture
5.3	Intrinsic	-	
5.3 5.4	Intrinsic Value Classification	- A(arc), A(his), B (per), B(des), B(uu), E, F Re	commended grade II A

6.0	Cathedral	206 Topography
6.1	Floors	Cathedral is a ground floor structure with 2 higher towers on either side, consisting of a
0.1	1 10015	belfry storey with a spire and the tower basement. A loft projects over the entrance area.
		being storey with a spire and the tower basement. A fort projects over the entrance area.
7.0		Construction
7.1	Plinth	Plinth is low, with a stone plinth protection band.
7.2	Walls	Stone load bearing walls are clad in grey stone and plastered, supported by stone pilaste
7.3	Floor	RCC. Stone flooring at the entrance and white marble with black stone inlay within the
1.0		cathedral.
7.4	Stairs	Three staircases in all. Wooden narrow spiral staircase with the stepped wooden soffit an
		wooden railing located in the tower to access the loft.
		Wooden dogleg staircase in both towers to access the belfry storey
		Wooden ladders to access the spires.
7.5	Openings	Arched window openings with stained glass fixed in partly openable and partly fixed
		shutters, with rose window above the arch.
		The apse area has a row of highly ornamental pointed arched window openings with dou
		pointed arches. The shutters are of stain glass.
		Window openings at a higher level have shutters are of wooden louvers.
		The main door opening to the cathedral has a grand door with wooden paneled shutters.
		The doors leading to the rooms near the apse consists of wooden paneled shutters.
7.6	Roofing	The nave and the main apse have a barrel vault roof while the side aisles have groined
		vaulted roof.
7.7	Articulation	Column capital in apse is highly ornamental and frieze has floral motifs.
		Marble and wooden sculptures placed in the apse are highly ornamental.
		Cast Iron brackets for fan and light fixture.
		Gallery consists of cast iron brackets and wooden railing for the loft.
		Pulpit is a hexagonal base in marble.
		The ceiling of the main cathedral has elaborate Bible story painting friezes.
7.8	Finishes	The walls are clad with cyclopean and ashlar grey stone masonry externally. Internally, the
		walls are finished in plaster and paint.
		The floor is finished with an inlay of marble and black stone.
7.9	Interiors (Movable & Immovable)	Movable
		Wooden benches with book case and shelf, chairs, cupboards, reading table, wooden
		statue case, high chairs.
		Old fan brackets, light fittings etc.
		Immovable
		Marble pentagonal pedestal, marble statues in apse, wooden paneling for paintings, mar
		plaques etc.
7.10	Compound/ Fence/ Gate	Brick wall 2'-0" ft in height with cast iron fencing above.
		2 decorative cast iron entrance gates on the eastern side.
7.11	Curtilage/ Unbuilt space/ Out	Shrubs, potted plants, the side and front open spaces.
	Buildings/ Landscape	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through long window openings.
		Inadequate lighting in the residential areas
8.2	Ventilation	Natural ventilation is adequate.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No traces.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed.
9.0		Condition
9.1	Plinth	Fair - maintained well.
9.2	Walls	Fair - The stone cladding of the external wall is in a good condition. Wall is plastered and
		painted internally.
9.3	Floor	Fair - maintained well.
9.4	Stairs	Fair
9.5	Openings	Fair - In many places openings of the window are blocked to occupy AC units. Shutters a
5.0	- Poiningo	changed, stained glass has been replaced, grills and <i>jalis</i> added.
9.6	Roofing	Fair – Few members need maintenance.
9.7	Articulation & Finishes	Fair - All the features are painted. The materials cannot be differentiated.
	Services	Fair
	OCIVILES	
9.8	Out Buildings	-
9.9	Out Buildings	- Fair Maintananaa lavali Good
	Out Buildings Overall Conditions	- Fair Maintenance level: Good

athedral	206 (I
Form	-
Structure	-
Articulation & Finishes	All the parts are plastered and painted insensitively. Original materials are difficult to identify.
	DP Remarks/ Perceived Threats
	Building forms part of R zone
	Additional Notes/ References/ Documents available
	Additional Notes:
	•
	References:
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
	SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.
	Form Structure



Front façade with series of pointed arched windows, gable end roof flanked with sides towers with spires



Detail of the flying buttress at the terrace level



Rising tower with random and ashlar stone masonry, corner quoins, pointed arched opening, culminating into a steep Mangalore tile spire



Internal façade articulation with highly decorative panels, bands, frescos, statues

Holy Name Cathedral



Projecting porch with pointed arches



Apsidal end with pointed arched openings with stain glass work, frieze bands



Congregation hall with old benches in aisle



Staircase with carved cast iron railing

Urban Design Research Institute



Projecting balcony with cast iron bracket supports, carved wooden railing



Interior view with groined vault ceiling supported on columns, with detailed frescoes, arched windows etc



Stained glass window panel in the pointed arched windows



Tomb with a marble plaque

MMR- Heritage Conservation Society

206 (I)

	e school		206(ii)
Parent .	ITTRA ITTRA	Common Ref No: 206(ii)	
TO DO		Card No: 279	
	N/A	Ward (Part): A (part III)	
		CS No: 445 (Colaba division)	The fall of the second s
		Plot Area: Indeterminable	CHE 2 TO BE ME STORE
		B U Area: -	
hill		Date: 06/04/2005	
	HALV MARE BILLEY STORED	Recorded by: Arun Wadhwa	
		Reviewed by:	
		Int: Arun Wadhwa	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	NAME OF TAXABLE PARTY.	Ext: Arun Wadhwa	
		Photo Ref.: 206(2)_Holy Name School	
	11111 All All All All All All All All Al	Flioto Rel.: 200(2)_libiy Name School	
and the second se	The second secon		
Se			the state of the state
1.6			Location plan
1			
1.0		Denomination	
1.1	Name of Premises	Holy Name school	
1.2	Earlier Name	Holy Name school	
1.2	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main		strian
	-	Nathalal Parikh Marg – vehicular & peder	Suidii.
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Holy Name school and mission - Owner	
3.2	Past	Holy Name school and mission - Owner	
3.3	Status	Mission	
4.0		Use	
4.1	Present	School – educational institution	
4.2	Past	School – educational institution	
4.3	Usage	Daily.	
4.5	Usage	Dally.	
5.0		Significance & Value Classification	
			side of Llow News astheodyst is the lower
15 4	Taura a sa a (as a sa a da)		side of Holy Name cathedral in the large
5.1	Townscape (manmade)		
5.1	Townscape (manmade)	compound accessed directly along the si	
		compound accessed directly along the si Also accessed through a by lane from the	ide of the cathedral. e east side adjacent to the open playground.
5.1 5.2	Townscape (manmade) Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning	e east side adjacent to the open playground.
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e	e east side adjacent to the open playground. nclosing large open court space serving as
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and	e east side adjacent to the open playground. nclosing large open court space serving as
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court
-		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors.	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing.
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also a Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation.	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
		compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also a Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
5.2	Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also a Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation.	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
5.2	Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also a Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2	Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also a Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the mediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective
5.2 5.3 5.4	Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Nil	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0	Architectural Description Architectural Description Intrinsic Value Classification	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Niil Topography	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0	Architectural Description	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Nil	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0	Architectural Description Architectural Description Intrinsic Value Classification	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Niil Topography	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0	Architectural Description Architectural Description Intrinsic Value Classification	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Niil Topography	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0 6.1	Architectural Description Architectural Description Intrinsic Value Classification	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Nil Topography G + 5 floors.	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No
5.2 5.3 5.4 6.0 6.1 7.0 7.1	Architectural Description Architectural Description Intrinsic Value Classification Floors Plinth	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chaijas</i> and slightly staggered <i>chaija</i> ban ornamentation. Style Modern RCC structure - Nil Topography G + 5 floors. Construction Low plinth about 0.3 M.	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No Recommended grade: III
5.2 5.3 5.4 6.0 6.1 7.0 7.1 7.2	Architectural Description Architectural Description Intrinsic Value Classification Floors Plinth Walls	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Nil Topography G + 5 floors. Construction Low plinth about 0.3 M. Non-load bearing brick masonry walls an	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ids along the court facing passages. No Recommended grade: III aud RCC structural members since reconstructed.
5.2 5.3 5.4 6.0 6.1 7.0 7.1	Architectural Description Architectural Description Intrinsic Value Classification Floors Plinth	compound accessed directly along the si Also accessed through a by lane from the Planning L-shaped building with two long wings, e playground and recreational activities. A side provides access to classrooms and floors. Ground floor west wing serves as large a facing the cathedral also forms a small e intersection of two wings and other intern at the end close to intersection and also Features Simple modern exterior with plain rectang <i>chajjas</i> and slightly staggered <i>chajja</i> ban ornamentation. Style Modern RCC structure - Nil Topography G + 5 floors. Construction Low plinth about 0.3 M. Non-load bearing brick masonry walls an	e east side adjacent to the open playground. nclosing large open court space serving as continuous narrow passage along the inner court other facilities arranged along it on all typical auditorium for social cultural activities. North wing ntrance at ground level. Two staircases, one at the nediate in the longer north wing. Toilets are placed at the end of west wing. gular façade openings marked by protective ds along the court facing passages. No Recommended grade: III

Holy Nam		206(i
7.5	Openings	Plain rectangular window openings with wood framed glazed panel shutters, with separate ventilator panel. Wood paneled double shutter door openings.
7.6	Roofing	Flat RCC slab forming terrace.
7.7	Articulation	-
7.8	Finishes	Plain plaster paint finish to external and internal wall surfaces. Ordinary mosaic and ceramic tiles in floors, except original retained wooden floor finish at first floor.
7.9	Interiors (Movable & Immovable)	Movable
		Immovable
7.10	Compound/ Fence/ Gate	Located within a large plot along with cathedral and residential facilities, secured by high boundary walls. Iron gate to the east side direct entry.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light except stair and common passage also relies on artificial sources.
8.2	Ventilation	Adequate natural ventilation except in staircase and toilets also relies on artificial means.
8.3	Electricity	BEST.
8.4	Water Supply	MCGM. Water storage tank.
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.
8.6	Fire Precaution	Fire extinguishers only – no integrated fire fighting system.
8.7	Other (HVAC/BMS/Security Systems)	Window unit A.C.'s in computer Labs.
0.7		
9.0		Condition
9.1	Plinth	Fair and well maintained.
9.2	Walls	Fair and well maintained.
9.3	Floor	Fair and well maintained.
9.4	Stairs	Fair
9.5	Openings	Fair and well maintained.
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair and well maintained.
9.8	Services	Fair
9.9	Out Buildings	
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	Reconstructed RCC structure.
	Structure	Reconstructed RCC structure.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
11.0		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
-		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.



Newly constructed building with no trace of the old building

Badhwar P	ark		20
		Common Ref No: 207	1 Martin Martin
		Card No: 280	1 his 1/2
		Ward (Part): A (Part III)	BACKBAY
		CS No: - 112 (Colaba Division)	
	EEE .	Plot Area: Indeterminable	
		B U Area: -	
		Date: 16/12/2004	
	T. HILL IN A THINK P. T.	Recorded by: Sonal Modak	-
		Reviewed by:	
THE PARTY AND			
	IL THEFT I SAME THE AVE	Int: Sonal Modak, Prachi Merchant	- II AND AT
		Ext: Sonal Modak, Prachi Merchant	- 1/2 100-1 600 1/142
		Photo Ref: 207_Badhwar Park.	
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Badhwar Park	
1.2	Earlier Name	Badhwar Park	
1.3	Built in:	Indeterminable	Extension Date: -
			<u> </u>
2.0		Access	
2.1	Main	Captain Pethe Marg.	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Central Government	
3.2	Past	Central Government	
3.3	Status	Owner	
0.0			
4.0		Use	
4.1	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Daily	
	000.90		
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)		other buildings of different periods and styles.
5.2	Architectural Description	Planning	
		categories of officers and staff housing in its It also had its own park and sports facilities – Features Horizontal and vertical bands, projecting balo Style Influences from Art Deco style of Architecture	a badminton hall and clubhouse. xonies. e.
5.3	Intrinsic		of the central and western railway were built c t had remained vacant since the last train le
5.4	Value Classification	Nil	Recommended Delete grade
		Tanananaha	
6.0		Topography	
6.1	Floors	Each building of G + 6	
7.0		Construction	
7.0	Dliath	Construction	
7.1	Plinth	RCC	
7.2	Walls	Brick walls	
7.3	Floor	RCC floor	
7.4	Stairs	RCC	
7.5	Openings	Rectangular openings with glazed panels	
7.6	Roofing	Flat RCC roof	
7.7	Articulation	-	
7.8	Finishes	-	
7.9	Interiors (Movable & Immovable)	Movable: - Immovable: -	

Badhwar P	Park	207
7.10	Compound/ Fence/ Gate	Brick compound wall with MS fence.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Front landscaped area, playground, lawns, badminton hall and clubhouse.
8.0		Services & Utilities
8.1	Lighting	
8.2	Ventilation	
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed AC's Strict Manual security.
9.0		Condition
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Out Buildings	Good
9.10	Overall Conditions	Good Maintenance level Good
10.0		Transformation
	Form	There are a failed and the Orlete Orlete and and Darks and and
	Structure	There are no visible remains of the Colaba Station and yard. Badhwar Park was constructed on the site in the 1950's
	Articulation & Finishes	
11.0		DP Remarks/ Perceived Threats
		Part RG, Plot forms part of R zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Six blocks of the scheme named Badhwar Park after chairman of the Railway Board, Faki Chand Badhwar, were completed by July 1955. While using the land sympathetically in response to the residential neighbourhood adjacent to it, Badhwar Park added an important facility to the Railway – a good housing stock for its officers and made a posting in the otherwise overcrowded Bombay an attraction. <u>References:</u> RAHUL MEHROTRA and SHARADA DWIVEDI (2000) Anchoring A City Line, 1899-1999 The History of the Western Suburban Railway and its Headquarters in Bombay : Eminence Designs Pvt. Ltd.



A view of the buildings from across the main road

Reliance E	Building (Forbes House)			208
		Common Ref No: 208		- openty
		Card No: 281	Pa	AR
		Ward (Part): A (Part III)	Jahne in day	TIP
		CS No: 143	IAG	F STO H
		Plot Area: 1729.94	19 500-10	
		B U Area: -	101	1 1. 1
		Date: 17/05/06	Dr. V. B. Gar	dhi Marg
		Recorded by: Prachi Merchant	DI. v	11 the
		Reviewed by:	6	An - TT
		Int: Prachi Merchant	tait.	A A B
		Ext: Prachi Merchant		shrup, and the
		Photo Ref: 208_Forbes House	all the second s	"Bash
		FIIOLO REI. 200_FOIDES HOUSE	-	"arg
			103	01 N
			Loca	ation Plan
1.0		Denomination		
1.1	Name of Premises	Reliance Building		
1.2	Earlier Name	Forbes House		
1.3	Built in:	18 th Century	Extension -	
			Date	
			•	
2.0		Access		
2.1	Main	Dr. V. B. Gandhi Marg		
2.2	Subsidiary	Dr. V. B. Gandhi Marg (Old Rope Walk Lane	e)	
			- /	
3.0		Ownership pattern		
3.1	Present	Private		
3.2	Past	Life Insurance Corporation of India		
3.3	Status	Owner		
5.5	Status	Owner		
4.0		1100		
-	Dresset	Use		
4.1	Present	Commercial		
4.2	Past	Commercial		
4.3	Usage	Daily		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	Corner building at the junction of internal	V. B. Gandhi Marg ju	extaposed in front of the
		buildings lined at Kalaghoda area.		
5.2	Architectural Description	Planning		
		Prominent corner building on V. B. Gandhi	Marg, with corner entra	ance opening. The shape
		of the building is a site response.		
		Internally the space has been modified to su	lit the functions.	
		Features		
		Rectangular openings with triangular and se	micircular pediments, t	floor bands, quoins etc
		Style		
		Derives influence from Neo classical style of	Architecture	
5.3	Intrinsic	-		
5.4	Value Classification	A(arc), D(per), D(bio), A(his)	Recommended	IIA
			grade:	
6.0		Topography		
6.1	Floors	G+2		
7.0		Construction		
7.1	Plinth	2'-0" high plinth finished with new materials		
7.2	Walls	Stone load bearing		
7.3	Floor	Indeterminable		
7.4	Stairs	New staircase has been added		
7.5	Openings	Rectangular openings		
7.6	Roofing	Sloping roof with asbestos sheet covering		
	Articulation	Bands, quoins, triangular and semicircular p	edimente	
7.7			GUIIIGIIIS	
7.8	Finishes	Plaster and paint		
7.9	Interiors (Movable & Immovable)	Movable		
		-		
		Immovable		
7 40		- Ne serve such well after the server of the server	he used	
7.10 7.11	Compound/ Fence/ Gate	No compound wall, directly accessed from t	ne road	
	Curtilage/ Unbuilt space/ Out Building	15/1 -		

	Building (Forbes House) Landscape		
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light supported on artificial lighting	
8.2	Ventilation	Adequate natural ventilation supported on artificial ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	-	
9.0		Condition	
9.1	Plinth	Fair	
9.2	Walls	Fair	
9.3	Floor	Fair	
9.4	Stairs	Changed to suit the new requirements	
9.5	Openings	Openings at places have been blocked to install AC units, grills have been added.	
9.6	Roofing	Fair	
9.7	Articulation & Finishes	Fair	
9.8	Services		
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level: Fair	
10.0		Transformation	
	Form	-	
	Structure	Openings at places have been blocked to install AC units, grills have been added.	
	Articulation & Finishes	•	
11.0		DP Remarks/ Perceived Threats	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: The original structure on the site was the residence of Charles Forbes, a leading Merchar of his time. References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings an Structures listed for Conservation.	



Floor level dentil band, sloping roof with rain water pipes.



Detail of the opening with full height shutters, bands



Opening detail with bands, pediments, corner quoins



Corner view with rectangular and semi circular openings

Devidas Pi	urshottamdas Kothari Kabutarkhana an	d Pyaav 209
The second second		Common Ref No: 209 Card No: 282 Walchand Hirachand Marg
	The second second second	Ward (Part): A (Part II)
11 111		CS No: Indeterminable
T de		Plot Area: Indeterminable
		B U Area: -
P		Date: 29/10/2004 Recorded by: Sonal Modak Reviewed by: Int: Sonal Modak. Arun Wadhwa
		Recorded by: Sonal Modak
		Reviewed by:
		Int: Sonal Modak, Arun Wadhwa
	CAN WARE	Ext: Sonal Modak, Arun Wadhwa
	Juli al	Photo Ref.: 209_Devidas Purushottamdas
		Kothari Kabutarkhana and Pvaav
1.0		Denomination
1.1	Name of Premises	Devidas Purshottamdas Kothari Kabutarkhana and Pyaav
1.1	Earlier Name	Devidas Purshottamdas Kothari Kabutarkhana and Pyaav
1.3	Built in:	1823 Extension Date: Additions made in 19 th and 20 th century
2.0		Access
2.1	Main	Mint Road - Pedestrian
2.2	Subsidiary	Walchand Hirachand Marg - Pedestrian
2.0		Oumorohin nottorn
3.0 3.1	Dresent	Ownership pattern
-	Present	Municipal Corporation of Greater Mumbai
3.2	Past	Private
3.3	Status	Owner
4.0		Use
4.0	Present	Fountain and Kabutarkhana
		Fountain and Kabutarkhana
4.2 4.3	Past	Not in Use
4.3	Usage	Not in Use
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Opposite GPO at the junction of Mint Road and Walchand Hirachand Road.
0.1	rownooapo (marinado)	It is one of the oldest pigeon enclaves in the city.
5.2	Architectural Description	Planning
		A small square shaped structure having dwarf bulbous petal dome minarets on four corners
		with ornamental low parapet, below which is a <i>chhajja</i> on brackets.
		Each side has octagonal engaged columns at the corners with a central blind Saracenic
		arch with ornamentation within.
		South side is fenced as an open space serving as the kabutarkhana with a small pond for
		pigeons. The building is painted in different colours.
		Features
		Bulbous small domes, minarets, pointed blind arches, cornice bands forming chhajja.
		Style
		Visible influence of the Indo-Saracenic and Jain style in architecture.
5.3	Intrinsic	-
5.4	Value Classification	B(des), B(uu), F Recommended grade III
6.0		Topography
6.1	Floors	The fountain is a stand-alone structure having water storage tank within the plinth.
0.1	Floors	The foundain is a stand-alone structure having water storage tank within the plinth.
7.0		Construction
7.1	Plinth	The structure is built on a plinth about 2 ft. 6 inches high, which houses the water tank.
7.2	Walls	-
7.3	Floor	•
7.4	Stairs	-
7.5	Openings	•
7.6	Roofing	-
7.7	Articulation	Cornice bands at top level, petal base of bulbous domes, stone carve parapet.
7.8	Finishes	Original exposed stone structure painted with layers and layers of paint.
7.9	Interiors (Movable & Immovable)	Movable
	, ,	-
		Immovable
		Immovable

Devidas Pu	urshottamdas Kothari Kabutarkhana and I	Pyaav 20	
7.10	Compound/ Fence/ Gate	A compound wall has been constructed around the open space known as kabutarkhana, fixed with MS section fencing.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Additional water tank, small water pond for pigeons to drink water from, bird house or cage. The open space is paved.	
8.0		Services & Utilities	
8.1	Lighting		
8.2	Ventilation	-	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	•	
9.0		Condition	
9.1	Plinth	-	
9.2	Walls	•	
9.3	Floor	-	
9.4	Stairs	•	
9.5	Openings	•	
9.6	Roofing	•	
9.7	Articulation & Finishes	All are painted with multiple coats of paint.	
9.8	Services	-	
9.9	Out Buildings		
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0		Transformation	
	Form	Encroachment of small temple on one of its sides. Writers sit around the main structure in temporary sheds.	
	Structure	-	
	Articulation & Finishes	Original exposed stone structure painted with layers and layers of paint.	
11.0		DP Remarks/ Perceived Threats	
		Public sanitary convenience, forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.	



Detail of the old structure with posts on either side with bulbous top, chajja with decorative band and brackets



Pyyav now used as a temple with new modifications

St. George	Hospital		210
	•	Common Ref No: 210	
		Card No: 283	
	1	Ward (Part): A (Part I)	
		CS No: 1457.	
n North &		Plot Area: 60125.75 sq m.	E HILL
	A A A A A A A A A A A A A A A A A A A	B U Area: 14890 sq m.	T AAR T A AAR T
and a state		Date: 17/01/2005	G I
		Recolueu by. Aluli Wauliwa	
		Reviewed by:	No and the second se
		Int: Arun Wadhwa, Sonal Modak	
		Ext: Arun Wadhwa, Sonal Modak	
		Photo Ref: 210_St George's Hospital.	WALCHARD
		Y. Lat	HIRACHAND WARG
A CONTRACTOR			Location Plan
1.0		Denomination	
1.1	Name of Premises	St. George Hospital	
1.2	Earlier Name	St. George Hospital	
1.3	Built in:	1894 – 1909 (as per Tablet)	Extension Date: annex –1955
			Dental college & hospital-1962 & hostel 1976
2.0		Access	
2.1	Main	P. D'Mello Road- vehicular & pedestrian	
2.2	Subsidiary	St. George Road – vehicular & pedestriar	1
		O markle ff	
3.0	Durant	Ownership pattern	
3.1	Present	State Government of Maharashtra	
3.2	Past	Government of Bombay	
3.3	Status	Owner	
10			
4.0	Decent	Use	
4.1	Present	Hospital	
4.2	Past	Hospital Daily.	
4.3	Usage	Dally.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)		d with substantial distance from the access road.
5.2	Architectural Description	Planning	
0.2		Long building with a central staircase blo	ock flanked by two wings, longer south for male a rough porches to both the male and female ward
			to continuous wide verandas for circulation and
			any projecting wings serving varied functions like
			pres, toilets, etc. Also a single storied kitchen an
		many ancillary structures are placed t	to the east side accessed through connecting
		walkways. An annex building serving as C	OPD abuts the southern side.
		Features	
			arch openings on the ground floor, similar pointe
			e end sloping roof at the end and projecting wings
		Projecting stone cornice band at first and	
			nolding feature at the staircase entrance. Highl
		decorative iron railing as parapet in veran	uas and stairs.
		Style The building displays influences of the Go	athic style
5.3	Intrinsic		אמווט טנאוס.
5.3 5.4	Value Classification	A(arc), A(his), B (per), B(des), B(uu), E, F	(old buildings only) Recommended grade:
0.4		B	
6.0		Topography	
6.1	Floors	Ground + two floors.	
7.0		Construction	
7.1	Plinth		n grey basalt stone ashlar course topped with bu
		basalt projecting course.	
7.2	Walls	Heavy load bearing rubble stone masonry	v walls.
			tions across and larger beam sections resting o
7.3	Floor		
	FIOOI	load bearing walls.	
	Stairs	load bearing walls.	vooden handrail in both symmetrical wings.

St. George	Hospital	210
7.5	Openings	Pointed arch openings in veranda- arch portion composed of wooden louvered panels and
		central fixed glazed panel.
		Door window shutters are partly glazed and partly wood paneled. Some openings have
7.0		shallow lower arches.
7.6	Roofing	Series of gable end sloping Mangalore tile roof over the projecting wings. Double level
		sloping roof, lower to verandahs and high over central wing. Presence of dormer roof within the long roofscape.
7.7	Articulation	High gable end roof, cornice band, alternate stone arch openings,
7.8	Finishes	Black/ gray basalt dressed ashlar course, arch openings and cornice band features dressed
7.0	1 11131163	in buff basalt stone. Internally plaster and paint finish. Original Minton floor tiling in some
		portions whereas varied floor finishes in later modified areas.
7.9	Interiors (Movable & Immovable)	Movable
	, , , , , , , , , , , , , , , , , , ,	-
		Immovable
		•
7.10	Compound/ Fence/ Gate	High compound wall about 1.5 m. high and iron gate at the two entrances from west and
7.44		south side.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Large G+5 dental college and hospital built in 1962 fronting the south side road. Also students hostel added in 1976 to the west side. Numerous small independent structures
	Landscape	scattered along the western and eastern sides of the main building. Old fort remnants close
		to the eastern boundary wall.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light supplemented by artificial means.
8.2	Ventilation	Adequate natural ventilation supplemented by artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM - Underground and overhead water tank.
8.5	Drainage (Plumbing & Sanitation)	MCGM - Drainage connected to municipal sewers.
8.6	Fire Precaution	Fire extinguisher and dry riser arrangement, but no fire detection system.
8.7	Other (HVAC/BMS/Security Systems)	Window unit air conditioners installed.
9.0	Diate	Condition
9.1	Plinth Walls	Poor with blackening & plumbing interventions also damaged plinth protection course.
9.2 9.3	Floor	Fair except some damage, seepage and plant growth observed. Fair except some modifications carried.
9.3	Stairs	Fair except some modifications carned.
9.5	Openings	Poor since decorative iron railings in veranda parapet replaced with brick walls. Insensitive
5.5	opennigs	interventions like box grills and metal <i>chajjas</i> . Altered and poorly maintained door window
		shutters.
9.6	Roofing	Fair except minor damage to wooden rafters and eaves board.
9.7	Articulation & Finishes	Poor due to dust accumulation, blackening and cracks observed on stone dressed façade.
		Also damaged arched & ornamental features.
9.8	Services	Old and poorly maintained plumbing lines. Messy unplanned electric wiring in staircase and
		lobby. Internal leakages due to poor waterproofing.
9.9	Out Buildings	• Matterie la construction de la
9.10	Overall Conditions	Fair internally, poor external facades. Maintenance level: poor
10.0		Transformation
10.0	Form	Annex added to the south side, not coherent with the main building, also a porch added to
		the subsidiary north entrance.
	Structure	-
	Articulation & Finishes	Semi circular arch openings enclosed with brickwork. Plaster finished patchwork over
		damaged stone dressed surfaces. Dado cladding and painting of stone dressed veranda
		surfaces.
11.0		DP Remarks/ Perceived Threats
		Hospital, part of the complex is Telephone exchange, building forms part of C1 zone
42.0		Additional Nation/ Deferences/ Desumentsit-bla
12.0		Additional Notes/ References/ Documents available
		Additional Notes: St. George hospital is built over the ruins of Fort St. George with some remnants still
		existing near western compound wall.
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MERKUTRA (2001) FOIL Walks, Bolhbay . Eminence
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,

St. George Hospital

Division of International Thomson Publishing Inc.



Grey stone clad building with arched openings with buff stone vouissoirs, sloping roof



Railing detail



Grey ashlar stone masonry façade with buff stone pointed arches, round windows, pilasters, bands



210

Newly constructed Dental college



Series of segmental arched opening with curved chajja, louvered paneling



Main building with central extended porch wing



Residential quarters with sloping roof, wooden railing

Urban Design Research Institute

Building	js on P. J. Ramchandani Marg		211(a
		Common Ref No: 211(a)	
		Card No: 284	~ ^
		Ward (Part): A (Part III)	
		CS No: -	
		Plot Area: -	
		B U Area: -	No. Contraction of the second se
	Not applicable	Date: 11/01/2005	
	Not applicable	Recorded by: Sachin Borkar	
		Reviewed by:	
		Int: Arun Wadhwa, Zankhana Prajapa	ti ALANTARA
		Ext: UDRI Committee	
		Photo Ref: -	
			Location plan
1.0		Denomination	
1.1	Name of Premises	Buildings on P. J. Ramchandani Marg	
1.2	Earlier Name	Buildings on P. J. Ramchandani Marg	
1.3	Built in :		nsion Date: -
1.3		Valleu Exter	ISIOII Dale
		<u> </u>	
2.0		Access	
2.1	Main	P. J Ramchandani Marg	
2.2	Subsidiary	Rajkavi Bhushan Marg, BEST Road, H	lenry Road
3.0		Ownership pattern	
3.1	Present	Varied	
3.1		Varied	
	Past		
3.3	Status	Varied	
4.0		Use	
4.1	Present	Mixed - Commercial, Residential areas	3
4.2	Past	Mixed - Commercial, Residential areas	6
4.3	Usage	Daily	
1.0		Bully	
5.0		Significance & value Classification	
5.0	T		Man free the second the second still the Osterney
5.1	Townscape (Natural/ Manmade)		ni Marg face the sea on the west with the Gateway o
		India on the side.	
5.2	Architectural Description	Planning	
		The Residential buildings on this road	have similar plan excluding Taj Mahal Hotel. The
			etbacks with the entrance through an extended
		porch.	the first sead
		The buildings have balconies overlook	ing the front road.
		Features and Style	the first second discussion for the second second
		Most residential buildings have vernad	ular features with wooden projecting with wooden
		columns, trellis, louvers, railing, slopin	g chajjas etc.
		I ne Gateway of India derives influenc	e from Indo Saracenic and Gujrat style of
			g derives influence from Indo Saracenic style of
		Architecture	
F 0	La tel se la	Madad	
5.3		Varied	
5.4	Value Classification	-	Recommended grade: -
6.0		Topography	
6.1	Floors	Varied	
7.0		Construction	
	Dlinth		
7.1	Plinth		
7.2	Walls	-	
7.3	Floor	-	
7.4	Stairs	-	
7.5	Openings	-	
7.6	Roofing	-	
7.7	Articulation	-	
	Finishes	-	
		- Movable	
	Interiore (Massahle Olivers and C		
7.8 7.9	Interiors (Movable & Immovable)	wovable	
	Interiors (Movable & Immovable)	-	
	Interiors (Movable & Immovable)	- Immovable	

Building	s on P. J. Ramchandani Marg	211(a)
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	· ·
8.2	Ventilation	-
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	•
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	-
9.2	Walls	•
9.3	Floor	•
9.4	Stairs	•
9.5	Openings	•
9.6	Roofing	·
9.7	Articulation & Finishes	•
9.8	Services	·
9.9	Out Buildings	
9.10	Overall Conditions	- Maintenance level: -
10.0		Transformation
	Form	-
	Structure	-
	Articulation & Finishes	
11.0		DP Remarks/ Perceived Threats
10.0		
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols. Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.



Taj Mahal Hotel



Gateway of India



Villar Ville

Note: Please refer Card no.: 285, 286, 287, 288.




Evelyn House

Villar Ville			211(b)
		Common Ref No: 211(b)	Alter Sanda
1		Card No: 285	307 The Anchody 304
		Ward (Part): A (Part III)	
1		CS No: 393 (Colaba Division)	June 1
		Plot Area: Indeterminable	Vilar Ville
		B U Area: -	
		Date: 11/01/2005	I I I I I I I I I I I I I I I I I I I
		Recorded by: Arun Wadhwa	II LAN ON S
		Reviewed by:	Cutin ut " T Som
		Int: Arun Wadhwa, Zankhana Prajapati	The second secon
		Ext: Arun Wadhwa, Zankhana Prajapati	- ONH
		Photo Ref: 211(b)_Villar Ville	HEWRY ROAD THE A
			Even H
T			" " "
			Location plan
1.0	News (Deceleration)		
1.1	Name of Premises	Villar Ville	
1.2	Earlier Name	Villar Ville	Future Date:
1.3	Built in:	1905	Extension Date: -
2.0			
2.0	Main	Access	destrian
2.1	Main	P. J. Ramchandani Marg - Vehicular and pe	uesman
2.2	Subsidiary	-	
2.0		Oumership	
3.0	Procent	Ownership pattern Mr. Samant and Mr. Tarun Tahiliani - Owner	~
3.1 3.2	Present		5
-	Past	Purshottam Ramchandra Bhojne	
3.3	Status	Owner, Tenants.	
4.0		llee	
	Present	Use Show room and residences.	
4.1 4.2			
4.2	Past	Residences.	
4.3	Usage	Daily.	
5.0			
5.0	T	Significance & Value Classification	the second Assells Development of features of
5.1	Townscape (manmade)		g the sea at Apollo Bunder accessed from east
5.2	Architectural Departmention	side road. Planning	
J.Z	Architectural Description		oad and central staircase along the longer side
			the front and back. Entrance passage at the
			centre accessing upper floor apartments. Each
		apartment has three rooms occupying the	entire width along with verandah fronts. Large
		floor heights accommodate intermediate le	evels serving as servant's wing in the central
			d kitchen at the main floor. Also a narrow stair is
		provided to access servant's wing independ	ently.
		Features	
		Wooden verandah front with sloping Man	galore tile awnings form the most prominent
		feature. Projecting bay windows along with	sloping awning feature and stone relief parapet
		panel on the long side facades. Also	numerous projecting balconies supported on
			s board and supporting brackets impart villa
			rindow openings with keystone feature at the
		corner bay. Floor level cornice bands scale	down the facades.
		Style	
		Vernacular and Colonial style features.	-
5.3	Intrinsic		Descence ded and a UD
5.4	Value Classification	A(arc), B(per), B (des), B(uu), E, F, G(grp)	Recommended grade II B
6.0		Tananyanhi	
6.0	Flooro	Topography	a in the convention
6.1	Floors	G + 3 floors in main building and G + 6 level	
70		Construction	
7.0	Dlinth	Construction	accelt atoma achlara acuras masana
7.1 7.2	Plinth Walls	Plinth height about 1.0 m. dressed in black t	
7.2	Floor	Load bearing stone masonry external walls	- sections and large beams for large spans.
1.3			
1		shahabad stone slabs supported on wooder wing.	n members form intermediate levels in servant's
		NVII ILI	
74	Stairs	8	tral open well serving as lift shaft. It has a
7.4	Stairs	C- shaped wooden staircase with a cen	tral open well serving as lift shaft. It has a
7.4	Stairs	C- shaped wooden staircase with a cen decorative iron railing and wooden handrai	tral open well serving as lift shaft. It has a I. Narrow wooden double flight stair supported
7.4	Stairs Openings	C- shaped wooden staircase with a cen decorative iron railing and wooden handrai on rafters and load bearing walls.	

/illar Ville		211(b)	
		window shutters. Separate openable ventilator panel above most of the openings.	
7.6	Roofing	Sloping Mangalore tile roof over the part fourth floor supported on wooden truss members and flat jack arch roof over the part third floor.	
7.7	Articulation	Large molded base of bay window projection, long wooden verandas with sloping awnings.	
7.8	Finishes	Plaster painted external and internal wall surfaces, polished wooden members in verandahs and door window shutters.	
7.9	Interiors (Movable & Immovable)	Novable	
		Immovable	
7.10	Compound/ Fence/ Gate	Low stone compound wall with iron railing above. Two gates at both ends of the east side road front. Barbed wire fencing on the sides and rear.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Two garage structures and a dispensary at the rear end of the south side open space Narrow open spaces all around the building including the front side.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light except staircase, lobby and servant's wing. Relies on artificial light.	
8.2	Ventilation	Adequate natural ventilation except in servant's wing. Relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM - Underground & overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	Fire extinguishers present.	
8.7	Other (HVAC/BMS/Security Systems)	Window and split unit A.C.	
9.0		Condition	
9.1	Plinth	Poor – Neglected state.	
9.2	Walls	Poor – under repair.	
9.3	Floor	Poor – under repair.	
9.4	Stairs	Fair condition of main staircase, poor and damaged state of servant's stair.	
9.5	Openings	Poor – decaying wooden veranda members, modified and neglected window shutters.	
9.6	Roofing	Fair. Well maintained and in good state.	
9.7	Articulation & Finishes	Poor – external wall surfaces under repair, internally fair. Corroding Iron brackets and damaged relief features.	
9.8	Services	Poor – old and corroding plumbing lines. Messy and unplanned electrical wiring below staircase at ground floor lobby.	
9.9	Out Buildings	Poor – under repair and neglected open spaces.	
9.10	Overall Conditions	Poor Maintenance level: poor externally, well maintained internally.	
10.0		Transformation	
	Form	-	
	Structure	Repair Board is in the process of reconstructing some damaged slab portions. Cantilevered toilet areas in servant's wing have been reconstructed incongruously with concrete structural supports.	
	Articulation & Finishes	External replastering and repair work in progress is damaging stucco features and floor level cornice bands.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.	

Villar Ville



Front façade with corner projecting bays, main structure with verandahs with wooden trellis work, columns, sloping chajjas



Side bay with arched windows, chajjas supported by decorative brackets



Minton tile flooring



Projecting bay windows with sloping chajjas supported on brackets, decorative panel in the sill level, bands



Detail of the entrance with rusticated joints, arched opening with scroll bracket keystone



Cast iron railing detail

Taj Mahal	Hotel (old wing)		211(c)	
	· · · · · · · · · · · · · · · · · · ·	Common Ref No: 211(c)		
		Card No: 286		
	1 1	Ward (Part): A (Part III)		
		CS No: 405 (Colaba Division)	AVIBHUSHAN APOLLO	
		Plot Area: Indeterminable	BHUSHAN MARG APOLLO BUNDER	
		B U Area: -		
		Date: 18/1/2005	- City	
		Recorded by: Arun Wadhwa		
		Reviewed by:	a a a a a a a a a a a a a a a a a a a	
1	Shanger I is the first state of the state of	Int: Arun Wadhwa, Zankhana Prajapati,		
ATT		Sonal Modak	BEST MARG HARBOUR	
(Florest)		Ext: Arun Wadhwa, Zankhana Prajapati,	- La A	
Rami		Sonal Modak	The second second	
Martin		Photo Ref: 211(c)_Taj Mahal Hotel.	- Honotion plan	
			Location plan	
1.0		Denomination		
1.1	Name of Premises	Taj Mahal Hotel (old wing)		
1.2	Earlier Name	Taj Mahal Hotel	E tracia Data	
1.3	Built in:	1904	Extension Date: -	
2.0		Access		
2.1	Main	P. J. Ramchandani Marg - Vehicular and pe	edestrian.	
2.2	Subsidiary		sji Boman Behram Marg to west - Vehicular and	
		pedestrian.		
3.0		Ownership pattern		
3.1	Present	Tata enterprises - Owner		
3.2	Past	Tata enterprises.		
3.3	Status	Owner.		
4.0		Use		
4.1	Present	Five star hotel and Banquet hall, Restauran	nts Discotheque Shons etc	
4.2	Past	Five star hotel and Banquet hall, Restaurar	nts Discotheque, Shops, etc.	
4.3	Usage	Daily.		
4.5		Daily.		
5.0				
5.0		Significance & value Classification		
5.1	Townscape (manmade)	Landmark corner building facing Gateway of	of India at the seaside promenade of Apollo	
		Bunder.		
			g the eastern sea front. It stands as one of the	
		most important buildings besides the histor	ic Gateway of India.	
5.2	Architectural Description	Planning		
		Large C- shaped building with long frontag	e along the seaside and projecting wings to the	
		rear side enclosing landscaped swimming	0001 area.	
			h side with main access from the eastern arcade	
		into a grand atrium accommodating wide st		
			south and north sides about the central staircase	
		and facilities like discotheque, gymnasium are in the south wing whereas additional shop		
		and services are located in the north wing.		
		First floor serves as ceremonial space with large Banquet halls and the main restauran		
		Along with the kitchen facilities.		
			or onwards in all the three wings on both sides	
		with a central sky lit space and accessed fr		
			on to doubly loaded corridor layout withour	
			tion and generates a soothing awe-inspiring	
			ed toilets located internally sharing service lines	
		Basement floor houses enormous service		
		house keeping and ancillary functions requi		
		house keeping and ancillary functions requi	ired by the five star hotel.	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by	ired by the five star hotel. / a high central dome and marked by projecting	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from	ired by the five star hotel. / a high central dome and marked by projecting	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the comer.	ired by the five star hotel. / a high central dome and marked by projecting Rajasthani style.	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level cornice bands, varied arch open	ired by the five star hotel. y a high central dome and marked by projecting	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level cornice bands, varied arch open relieve stone dressed external facades.	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level cornice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i>	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level cornice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels.	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level comice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels.	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level comice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin long front facade.	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels. g Rajasthani <i>jharokas</i> form important part of the	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the corner. Floor level cornice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin long front facade. Decorative cast iron column capitals in the	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels. g Rajasthani <i>jharokas</i> form important part of the e interior hall space. Very well conceived sky li	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the comer. Floor level comice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin long front facade. Decorative cast iron column capitals in the narrow atrium with passages to access gui	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels. g Rajasthani <i>jharokas</i> form important part of the e interior hall space. Very well conceived sky lif est rooms on upper floors. Ornamentally treated	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the comer. Floor level comice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin long front facade. Decorative cast iron column capitals in the narrow atrium with passages to access gu and richly decorated banquet halls on first f	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels. g Rajasthani <i>jharokas</i> form important part of the e interior hall space. Very well conceived sky lif est rooms on upper floors. Ornamentally treated	
		house keeping and ancillary functions requi Features Long symmetrical front façade crowned by bay windows with features influenced from Onion shaped cupolas mark the comer. Floor level comice bands, varied arch oper relieve stone dressed external facades. Some of the projecting balconies have high work in geometric patterns adores the arch Projecting wooden bay windows resemblin long front facade. Decorative cast iron column capitals in the narrow atrium with passages to access gui	ired by the five star hotel. y a high central dome and marked by projecting Rajasthani style. nings and projecting decorative balcony features nly ornamental base and brackets. Fine stone <i>jal</i> portion and parapet panels. g Rajasthani <i>jharokas</i> form important part of the e interior hall space. Very well conceived sky li est rooms on upper floors. Ornamentally treated	

	lotel (old wing)	Fine wood conved interior of Deinut quite. Cont	el etcircono oron with	211(
5.3	Intrinsic	Fine wood carved interior of Rajput suite. Central staircase area with a high dome se be a well-conceived space with a public character.		
5.4	Value Classification	A(arc), A(his), A(cul), B (per), B(des), B(uu), C(seh), D(bio), E, F, I(sce)	Recommended grade:	II A
			giude.	
6.0		Topography		
6.1	Floors	G + 2 and part third floor.		
7.0		Construction		
7.1	Plinth	Plinth height about 1.0 m. dressed in black bas		
7.2 7.3	Walls Floor	Load bearing stone masonry external walls and cast iron columns within. Shahabad stone slabs supported on I-sections and steel girders as observed in a roo		
	FIOOI	undergoing renovation otherwise the entire floor is covered with false ceilings.		
7.4	Stairs	Three stairs – Central grand C-shaped stone stair with large open atrium under the dome.		
7.5	Openings	Pointed arch pedestrian arcade to the east and south side road, also segmental, pointe and semicircular arch window openings		
7.6	Roofing	Sloping Mangalore tile roof with a central skylight and flat roof over the passages in all the three wings. Large dome structure in the centre and smaller domes at the corners.		
7.7	Articulation	Sculpted in stone and done in plaster.		
7.8	Finishes	Black basalt Khadki stone dressed ashlar cou	irse external wall sur	faces with decorative
		carved features in soft Porbunder stone. Smooth plaster painted internal wall finishes. Ric marble granite floor and dado finishes. Ceramic tile floor finishes. Polished wooden doo window shutters.		
7.9	Interiors (Movable & Immovable)	Movable		
		Large collection of paintings - contemporary an		
		Wood carved furniture in passages - benches,	vase, etc. some of ar	itique value.
		Immovable		
		Interiors done in guest rooms with varied theme		
		settings like Rajasthani. Also the restaurants an		
their individuality like Chinese and Japanese restau				
7.10	Compound/ Fence/ Gate	schemes. Wooden brackets and parapet members in internal atrium passage. Open arcade along the east and south road fronts, rear west side has high jali wall fencir		
-		the landscaped swimming pool area. Large swimming pool in the well-laid landscaped open space between the wings to the rea		
7.11	Curtilage/ Unbuilt space/ Out Buildings/			
	Landscape	side. G + 21 storied annex connected at ground and first floor stands to the no		to the northeast side
8.0		Services & Utilities		
8.1	Lighting	Adequate natural light except basement floor a		ight.
8.2	Ventilation	Centrally A.C. although adequate natural ventil	ation.	
8.3	Electricity	BEST	1-	
8.4 8.5	Water Supply	MCGM - Underground and overhead water tan		
8.6	Drainage (Plumbing & Sanitation) Fire Precaution	Drainage connected to municipal sewers of MC Smoke detector and sprinkler systems.	GIVI.	
8.7	Other (HVAC/BMS/Security Systems)	Central A.C. plant in the basement. Video surv system.	eillance in passages,	electronic door locki
9.0		Condition		
9.1	Plinth	Fair except some interventions along the high r	ise annex.	
9.2	Walls	Fair except some cracks and plant growth.		
9.3	Floor	Indeterminable due to false ceiling.		
9.4	Stairs	Good. Regular maintenance.		
9.5	Openings	Fair except modified window shutters.		
9.6	Roofing	Fair except some missing Mangalore tiles and	decayed eaves board	
9.7	Articulation & Finishes	Fair except plumbing interventions on stone fac	ades	
9.8	Services	Fair - well maintained except plumbing interver	tions on the stone fag	ade.
9.9	Out Buildings	Fair. Well maintained.		
9.10	Overall Conditions	Good. Maintenance level: Good.		
10.0		Transformation		
	Form	-		
	Structure Articulation & Finishes	- Central stone stair painted indiscriminately features also painted.	in bright colors. De	corative stone carv
11.0		DP Remarks/ Perceived Threats		
11.0		Building forms part of R zone		
12.0		Additional Notes/ References/ Documents a	vailable	
		Additional Notes:		
		Taj Mahal Hotel was conceived by the Pars		

Taj Mahal Hotel (old wing)	211(c)
	created by Jamsetji with Raosaheb Sitaram Khanderao Vaidya, who had worked as an overseer during the construction of the Sailor's Home. He was subsequently appointed Resident Engineer for Bombay and was responsible for the construction of the Bombay Municipal Corporation building. After Vaidya's death in 1900, W.A. Chambers of the firm Gosling, Chambers, & Fritchley was appointed as Architect. In his Design Jamsetjee moved away from <i>Gothic</i> style in vogue for public buildings to more <i>Indian</i> features. The building reflects an amalgamation of indigenous local sentiments with an imported western concept – that of a grand hotel. Several elements like staircase, onion shaped cupolas, arches, balconies and the use of a variety of local stones are incorporated from public buildings like Victoria Terminus, Municipal headquarters, Western railway headquarters, and Royal Alfred Sailor's home. References: INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation</i> . FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminence Designs Pvt. Ltd.



Grey stone clad massive stone façade with central dominating dome structure flanked with onion shaped dome towers on sides, with ground floor arched arcade, window openings, projecting balconies, bands



Projecting bay with wooden trellis work, railing, sloping roof



Arcade with arched openings and columns with Corinthian capitals, dentil band, balustrade



Projecting balconies with tapering floral pattern bands, arched openings, jaliwork, balustrade



Corner detail with decorative frieze bands, floral motifs at the springing point



Series of semicircular arched openings with decorative intrados supported on columns with Corinthian capital, floor bands



Window detail with stone ventilator jaliwork, balustrade



Central bay with dome flanked with side bays with smaller domes, arched windows, brackets, bands



Projecting balcony with stone carved balustrade, supported on decorative brackets



Projecting bay windows with sloping chajjas supported on brackets, tapering bands with floral pattern, sill jaliwork etc



Stone decorative jaliwork in floral pattern



Corner detail with curved balcony projection with supporting brackets

gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st jali along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped shikhara as in a Hindu temple. Projecting chajja like slabs supported on stone curvilinear carved brackets influenced from Gujarati architecture form part of the façade. Style Designed in the Indo-Saracenic style and heavily influenced by the Medieval Architecture Gujarat. 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aft Independence.	Gateway o	f India			211(d)
Ward (Part, A. (Part III) Ward (Part, A. (Part III) Observation Date: 0111/12004 Prot Area: Indeterminable Date: 0111/12004 Reviewed by: Interviewed by: Interviewed by: Path Reviewed by: Interviewed by:			Common Ref No: 211(d)	CH CH	han and the second s
CS No: 384 (Colaba division) B U Area: Recorded by: Atom Wadhwa Pacing Denomination 1:1 Name of Premises Gateway of India 1:2 Earlier Name Gateway of India 1:3 Built in: Construction: commenced in May 1920; Completed in 1924. 2:1 Main Chhattspeal Shivaji Marg - Vehicular drop point and pedestrian access. 2:2 Subsidiary 2:3 Subsidiary access by Ferry from the Eastern waterfront. 3:1 Present Municipal Corporation of Greatern Munteil 3:2 Past Bornbay Municipal Corporation 3:3 Sitaus Ownership patter			Card No: 287	A A RANK	
CS No: 384 (Colaba division) B U Area: Recorded by: Atom Wadhwa Pacing Denomination 1:1 Name of Premises Gateway of India 1:2 Earlier Name Gateway of India 1:3 Built in: Construction: commenced in May 1920; Completed in 1924. 2:1 Main Chhattspeal Shivaji Marg - Vehicular drop point and pedestrian access. 2:2 Subsidiary 2:3 Subsidiary access by Ferry from the Eastern waterfront. 3:1 Present Municipal Corporation of Greatern Munteil 3:2 Past Bornbay Municipal Corporation 3:3 Sitaus Ownership patter			Ward (Part): A (Part III)	annan an Anna	X/ C - 3 C - II
Reviewed by: In: Auri Wadhwa, Prach Merchant In: Auri Wadhwa, Prach Merchant Proto Ref. 211(d). Gateway of India 10 Denomination 11 Name of Premises Gateway of India Construction commenced in May 1920, Completed in 1924. 13 Built in: 20 Access 21 Main 22 Subsidiary 23 P A Ranco and a protocol on an approximation of the statemation				A. Sugar	HA CAN STATIS
Reviewed by: In: Ann Wadhwa, Prach Merchant Protected by: In: Ann Wadhwa, Prach Merchant Proto Ref. 211(d). Geleway of India Annover the second				TAL A	ATT AND
Reviewed by: In: Ann Wadhwa, Prach Merchant In: Ann Wadhwa, Prach Merchant Protection Prote Ref. 211(d). Galeway of India Area to ur 10 Denomination 11 Name of Premises Gateway of India 12 Earlier Name Gateway of India 13 Built in: Construction commenced in May 1920, Completed in 1924. 24 Name of Premises Gateway of India 25 Subsidiary F.J. Aranchantal Marg Vahicular drop point and pedestrian access. 22 Subsidiary F.J. Aranchantal Marg Public access and a parking lot. 30 Ownership pattern Subsidiary access by Ferry from the Eastern waterfront. 31 Present Monument (commerrorative) 33 Status Ownership 40 Usa Itsands as the most prominent built form at Apolo Bunder. 41 Present Monument of Cateway of India stands on a protouding piece of reclaimed land overlooking the eastern harbour front. 5.2 Architectural Description The Gateway of India stands on a protouding piece of reclaimed land overlooking the eastern harbour front. 5.2 Architect				- BH	ATT AND A STATE OF A S
Reviewed by: In: Ann Wadhwa, Prach Merchant Protected by: In: Ann Wadhwa, Prach Merchant Proto Ref. 211(d). Geleway of India Annover the second				SH. (and and and
Reviewed by: In: Ann Wadhwa, Prach Merchant Protected by: In: Ann Wadhwa, Prach Merchant Proto Ref. 211(d). Geleway of India Annover the second		A REAL PROPERTY AND A REAL		1 1 1	
Int. Aun Wadnwa, Prach Merchant Probe Ref. 211(d), Cateway of India Ans a u w 10 Denomination Location plan 11. Name of Premises Gateway of India Location plan 12. Earlier Name Gateway of India Location plan 13. Built m: Construction commenced in May 1920, Completed in 1924. Extension Date: - 2.0 Access Chatagati Shivaji Marg - Vehicular drop point and pedestrian access. Extension Date: - 2.1 Main Chatagati Shivaji Marg - Vehicular drop point and pedestrian access. Extension Date: - 2.2 Subsidiary P. J Ranchandani Marg - public access and a parking lot. Extension Date: - 3.0 Construction of Greater Mumbai Bombay Municipal Corporation 3.3 3.1 Present Municipal Corporation 3.3 3.2 Past Bombay Municipal Corporation 4.1 3.3 Status Ownership - 4.1 Present Monument. - 4.2 Past Monument of Cateway of India stands on a protuding piece of reclaimed land overoking the astor as the most prominent features w		AND A DECEMBER OF A DECEMBER O		*PG	St 104
Ext: Anu Wadhwa, Prechi Merchant Busses Proto Ref: 211(d)_Cateway of India Location plan 10 Denomination Location plan 11 Name of Premises Gateway of India Location plan 13 Built in: Construction commenced in May 1920, Completed in 1924. Extension Date: - 20 Access Construction commenced in May 1920, Completed in 1924. Extension Date: - 20 Access Construction commenced in May 1920, Completed in 1924. Extension Date: - 21 Main Construction commenced in May 1920, Completed in 1924. Extension Date: - 22 Subaidiary access by Fenry from the Eastern waterfront. Ownership plattern Maningal Corporation of Greater Mumbai 32 Past Borbay Municipal Corporation Greater Mumbai Borbay Municipal Corporation 33 Status Ownership pale Corporation Townership Townership and Corporation of Greater Mumbai 40 Usage Daily Townscape (Mammade) The Gateway of India marks as a symbolic entry point to the city of Mumbai 5.2 Architectural Description The monument of Gateway of India stands on a					Visit
Photo Ref: 211(d). Gateway of India Image: Construction Commenced India 10 Denomination Location plan 11 Name of Premises Gateway of India Image: Construction Commenced India 12 Earlier Name Gateway of India Image: Construction Commenced India Image: Construction Commenced India 13 Built in: Construction commenced India Image: Construction Commenced India Image: Construction Commenced India 20 Access Chinarapati Shivaji Marg - Vehicular drop point and pedestrian access. Extension Date: - 21 Main Chinarapati Shivaji Marg - Vehicular drop point and pedestrian access. Extension Date: - 20 Access Main Chinarapati Shivaji Marg - Vehicular drop point and pedestrian access. Extension Date: - 30 Subsidiary costs by Ferry from the Eastern waterfront. Omership pattern Image: Costs by Ferry from the Eastern waterfront. 30 Status Ownership Ownership Image: Costs by Ferry from the Eastern Warbait 41 Present Monument. Image: Costs by Ferry from the Eastern Warbait Image: Costs by Ferry from the Eastern Warbait 51	THE PARTY OF			the come	
10 Denomination 11 Name of Premises Gateway of India 12 Eafer Name Gateway of India 13 Built in: Construction commenced in May 1920, Completed in 1924. Extension Date: - 20 Access Access Extension Date: - 21 Main Chatargati Shivaji Marg - Vehicular drop point and pedestrian access. P. J Ramchandnain Marg - public access and a parking lot. 22. Subsidiary P. J Ramchandani Marg - public access and a parking lot. Subsidiary access by Ferry from the Eastern waterfront. 30 Ownership Darbet mining Corporation of Greater Mumbai Bornbay Muningal Corporation of Greater Mumbai 32 Past Bornbay Muningal Corporation of Greater Mumbai 33 Status Ownership 40 Use Significance & Value Classification 5.1 Townscape (Mammade) The Gateway of India stands on a portuding piece of reclaimed land overoloxing the assets mabbolic rof roft. 5.2 Architectural Description Planning The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Projecting radialasis supported on stone curvilnear careed brackets infl	-16				and the second second
1.1 Name of Premises Gateway of India 1.2 Earlier Name Gateway of India 1.3 Bull in: Construction commenced in May 1920, Completed in 1924. Extension Date: - 2.0 Access Access Extension Date: - 2.1 Main Chatarpati Shivaji Marg - Vehicular drop point and pedestrian access. P. J. Ramchandani Marg - public access and a parking lot. 2.2 Subsidiary P. J. Ramchandani Marg - public access and a parking lot. Subsidiary access by Ferry from the Eastern waterfront. 3.0 Demership pattern Municipal Corporation of Greater Mumbai 32 3.1 Present Municipal Corporation 33 3.2 Past Bombay Municipal Corporation 33 4.0 Use Monument. 44 4.1 Present Monument (commemorative) 43 4.3 Usage Daily 50 5.0 Significance & Value Classification 52 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. 11 Itsafda sa the most prominent built form at Apolio Bunder. 5.2 Architectural				1	× .
1.3 Earlier Name Cateway of India Extension Date: - 1.3 Built in: Construction commenced in May 1920, Completed in 1924. Extension Date: - 2.0 Access -	1.0		Denomination	·	
1.3 Built in: Construction commenced in May 1920, Completed in 1924. Extension Date: - 2.0 Access Access 2.1 Main Chhatrapati Shivaji Marg - Vehicular drop point and pedestrian access. 2.1 2.2 Subsidiary P J Ramchandani Marg - public access and a parking lot. 3.0 3.0 Ownership pattern 3.0 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument. 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. 1.1 tstands as the most prominent built from at Apolo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India marks as a symbolic entry point to the city of Mumbai. 1.1 tstands as the most prominent built from at Apolo Bunder. 5.2	1.1	Name of Premises	Gateway of India		
2.0 Access 2.1 Main Chhatrapati Shivaji Marg - Vehicular drop point and pedestrian access. 2.2 Subsidiary P.J. Ramchandani Marg - public access and a parking lot. 3.0 Subsidiary access by Fary from the Eastern waterfront. 3.0 Ownership pattern 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument. 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. 1 It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description The monument of Gateway of India stands on a protruding piece of reclaimed land overtooking the asset marbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four side	1.2	Earlier Name	Gateway of India		
2.0 Access 2.1 Main Chhatrapati Shivaji Marg - Vehicular drop point and pedestrian access. 2.2 Subsidiary P J Ramchandani Marg - public access and a parking lot. 3.0 Subsidiary access by Fary from the Eastern waterfront. 3.0 Ownership pattern 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument. 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. 1 It stands as the most prominent built form at Apollo Bunder. 5.2 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overhooking the asset in about front. The aignument of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a				leted in 1924.	Extension Date: -
2.1 Main Chhatrapati Shivaji Marg - Vehicular drop point and pedestrian access. 2.2 Subsidiary P J Ranchandani Marg - public access and a parking lot. 3.0 Ownership pattern 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use			, , , , , , , , , , , , , , , , , , ,		
2.1 Main Chhatrapati Shivaji Marg - Vehicular drop point and pedestrian access. 2.2 Subsidiary P J Ranchandani Marg - public access and a parking lot. 3.0 Ownership pattern 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use	20		Access		
2.2 Subsidiary P J Ramchandami Marg - public access and a parking lot. 3.0 Subsidiary access by Ferry from the Eastern waterfront. 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation of Greater Mumbai 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with hip base flanking the central arch gradually recede at upper level culminating as stepped shi/hara as in a Hindu temple. Projecting chaji like stabs supported on stone curvilinear carved brackets influenced for Gujarat architecture form part of the fazede. 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of		Main		nt and nedestrian ac	ress
3.0 Subsidiary access by Ferry from the Eastern waterfront. 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bornbay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument. 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Peatures Large openings in the form of archways are the most prominent features with intricate st jail along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped sinkara as in a Hindu temple. Projecting chajia like siabs supported on stone curulinear carved brackets influenced for Guj					
3.0 Ownership pattern 3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apolic Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overdoxing the eastern harbour front. The alignment of harbour was altered to arrange architect George Witte's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st jai along side and above the smaller arched openings. Projecting per like slabs supported on stone curvilinear carved brackets influenced for Gujarati architecture with alph base flanking the central arch gradually recede at upper level culminating as stepped shifkhara as in a Hindu temple. Projecting per like slabs supported on stone curvilinear carved brackets influenced for Gujarati architecture form part like s	L.L				
3.1 Present Municipal Corporation of Greater Mumbai 3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apolio Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument of Gateway and the Plaza. 5.2 Architectural Description The faugo side and above the smaller arched openings. Features Large openings in the form of archways are the most prominent features with intricate st <i>jai'</i> aliong side and above the smaller arched openings. Projecting piar like structure with high base flanking the central arch gradually recede at upper level culminating as stepped shikhara as in a Hindu temple. Projecting chajal kiek slabs supported on stone curvilinear carved brackets influenced for Gujarati architecture form part of the façade. Style 5.3 Intrinsic <td>2.0</td> <td></td> <td></td> <td>watemont.</td> <td></td>	2.0			watemont.	
3.2 Past Bombay Municipal Corporation 3.3 Status Ownership 4.0 Use 4.1 4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Cateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning 7.6 Value Classification 5.7 The monument of Gateway of India stands on a protruding piece of reclaimed land overidoxing the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for thigateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being in the form of archways are the most prominent features with intricate st <i>jali</i> along side and above the smaller arched openings. Projecting pier like statucture with high base flanking the central arch gradually recede at upper level culminating as stepped shithara as in a Hindu temple. Projecting chaja like slabs supported on stone curvilinear carved brackets influenced fro: Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway also witnessed the departure of the last British soldiers from Indian soil at Independence. 5.4		Dresset			
3.3 Status Ownership 4.0 Use 4.1 Present Monument. 4.2 Past Monument (commemoralive) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jail</i> along side and above the smaller arched openings. Projecting <i>chaji</i> like stabs supported on stone curvilinear carved brackets influenced for Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway as integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil af Independence. 5.4 Value Classification A(arc). A(this), B (per), B(des), B(uu). D(bio), E, F, I(sce), J					
4.0 Use 4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour font. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being of the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jai</i> along side and above the smaller arched openings. Projecting chajja like slabs supported on stone curvilinear carved brackets influenced for Gujarati architecture form part of the façade. Style Designed in the Indo-Saracenic style and heavily influenced by the Medieval Architectur Gujarati 5.3 Intrinsic The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil at Independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade:					
4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jail</i> along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped <i>shikhara</i> as in a Hindu temple. Projecting cirili like sidas supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set toot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aft independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommende	3.3	Status	Ownership		
4.1 Present Monument. 4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jail</i> along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped <i>shikhara</i> as in a Hindu temple. Projecting cirili like sidas supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set toot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aft independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommende					
4.2 Past Monument (commemorative) 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument of a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st jail along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped sinkhara as in a Hindu temple. Projecting chajia like slabs supported on stone curvilinear carved brackets influenced frc Gujarati architecture form and to the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway is integrally connected to the landmark event in the political soil affindependence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: 6.0 Top					
4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st jali along side and above the smaller arched openings. Projecting chajia like slabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil aft Independence. 5.4 Value Classification A(arc), A(this), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: 6.0 Topography Single storey monument - Structure surmounted by concrete dome. Topography Single storey monument - Structu		Present	Monument.		
5.0 Significance & Value Classification 5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jail</i> along side and above the smaller arched openings. Projecting <i>pier</i> like structure with high base flanking the central arch gradually recede at upper level culminating as stepped <i>shikhara</i> as in a Hindu temple. Projecting <i>chajia</i> like slabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visi of King George V, the first British Monarch to set foot on India soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aff Independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: Independence. 6.0 Topography Single storey monument - Structure surmounted by concrete dome. 7.0 Construction	4.2	Past	Monument (commemorative)		
5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jali</i> along side and above the smaller arched openings. Projecting <i>chajja</i> like stabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. Th	4.3	Usage	Daily		
5.1 Townscape (Manmade) The Gateway of India marks as a symbolic entry point to the city of Mumbai. It stands as the most prominent built form at Apollo Bunder. 5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jali</i> along side and above the smaller arched openings. Projecting <i>chajja</i> like stabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil. Th					
5.2 Architectural Description Planning The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jali</i> along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level cultiminating as stepped shikhara as in a Hindu temple. Projecting chajja like slabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style Designed in the Indo-Saracenic style and heavily influenced by the Medieval Architectur Gujarat. 5.3 Intrinsic The Gateway is integrally connected to the landmark event in the political history of India the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aft Independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J 6.0 Topography Floors Single storey monument - Structure sumounted by concrete dome. 7.0 Construction	5.0		Significance & Value Classification		
The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The monument of harbour was altered to arrange architect George Wittet's scheme for th gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate st <i>jali</i> along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped <i>shikhara</i> as in a Hindu temple. Projecting chaji like slabs supported on stone curvilinear carved brackets influenced fro Gujarati architecture form part of the façade. Style Designed in the Indo-Saracenic style and heavily influenced by the Medieval Architectur Gujarat. The Gateway also witnessed the departure of the last British Soldiers from Indian soil. 5.3 Intrinsic The Gateway also witnessed the departure of the last British soldiers from Indian soil afti Independence. 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: 6.0 Topography Single storey monument - Structure sumounted by concrete dome. Topography 7.0 Construction Structure sumounted by concrete dome. The Gateway is not sumounted by concrete dome.	-	Townscape (Manmade)			of Mumbai.
the visit of King George V, the first British Monarch to set foot on Indian soil. The Gateway also witnessed the departure of the last British soldiers from Indian soil aft 5.4 Value Classification A(arc), A(his), B (per), B(des), B(uu), D(bio), E, F, I(sce), J Recommended grade: 6.0 Topography 6.1 Floors Single storey monument - Structure surmounted by concrete dome. 7.0 Construction	5.2	Architectural Description	 The monument of Gateway of India stands on a protruding piece of reclaimed land overlooking the eastern harbour front. The alignment of harbour was altered to arrange architect George Wittet's scheme for the gateway and its Plaza. The monument is a singular structure with openings on all four sides, larger ones being on the two longer sides. Features Large openings in the form of archways are the most prominent features with intricate stone <i>jali</i> along side and above the smaller arched openings. Projecting pier like structure with high base flanking the central arch gradually recede at upper level culminating as stepped <i>shikhara</i> as in a Hindu temple. Projecting <i>chaja</i> like slabs supported on stone curvilinear carved brackets influenced from Gujarati architecture form part of the façade. Style Designed in the Indo-Saracenic style and heavily influenced by the Medieval Architecture of the structure of the starter of the structure of the structure of the structure of the structure form part of the factore. 		
6.0 Topography 6.1 Floors 7.0 Construction			the visit of King George V, the first British Mor The Gateway also witnessed the departure of Independence.	narch to set foot on I the last British soldi	ndian soil. ers from Indian soil after
6.1 Floors Single storey monument - Structure surmounted by concrete dome. 7.0 Construction		Value Classification		E, F, I(sce), J	Recommended grade: I
7.0 Construction					
	6.1	Floors	Single storey monument - Structure surmount	ed by concrete dom	е.
7.1 Plinth The monument as such does not rise up on a plinth. The open pavement around the					
monument forms the ground level of the structure.	7.1	Plinth			vement around the

7.3 7.4 7.5 7.6 7.7 7.8 7.9 7.10 7.11		The walls are in yellow basalt load bearing stone masonry from Kharodi quarries in Thane district. The monument does not have any floors, being a single storey structure. A terrace gallery around the domes in RCC construction. There are small staircases in all the four pier-like projections flanking the central archway. The staircases are spiral, constructed in stone leading to the terrace gallery. The monument has a large central archway flanked by relatively smaller arched openings; the narrow sides of the monument also have similar arched openings. The sides and upper portion of these openings are of intricately carved sandstone <i>jalis</i> in geometric patterns typically Islamic influence. The projecting piers have slit openings to perpetuate light and ventilation to the staircase. Small wood paneled door forms the stairway entrance. The roofing is in the form of reinforced concrete domes, the central one being larger and higher than the two adjoining ones. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable - Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellen seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.4 7.5 7.6 7.7 7.8 7.9 7.10 7.11	Stairs Openings Proofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	around the domes in RCC construction. There are small staircases in all the four pier- like projections flanking the central archway. The staircases are spiral, constructed in stone leading to the terrace gallery. The monument has a large central archway flanked by relatively smaller arched openings; the narrow sides of the monument also have similar arched openings. The sides and upper portion of these openings are of intricately carved sandstone <i>jalis</i> in geometric patterns typically Islamic influence. The projecting piers have slit openings to perpetuate light and ventilation to the staircase. Small wood paneled door forms the stairway entrance. The roofing is in the form of reinforced concrete domes, the central one being larger and higher than the two adjoining ones. The circular domes rest on the arched openings, in stone masonry. The stone courses are regular and form a high base with moulding like band atop. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable - Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellent seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.5 7.6 7.7 7.8 7.9 7.10 7.11	Openings Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	The staircases are spiral, constructed in stone leading to the terrace gallery. The monument has a large central archway flanked by relatively smaller arched openings; the narrow sides of the monument also have similar arched openings. The sides and upper portion of these openings are of intricately carved sandstone <i>jalis</i> in geometric patterns typically Islamic influence. The projecting piers have slit openings to perpetuate light and ventilation to the staircase. Small wood paneled door forms the stairway entrance. The roofing is in the form of reinforced concrete domes, the central one being larger and higher than the two adjoining ones. The stone courses are regular and form a high base with moulding like band atop. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable - Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellent seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.6 7.7 7.8 7.9 7.10 7.11	Roofing Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	The monument has a large central archway flanked by relatively smaller arched openings; the narrow sides of the monument also have similar arched openings. The sides and upper portion of these openings are of intricately carved sandstone <i>jalis</i> in geometric patterns typically Islamic influence. The projecting piers have slit openings to perpetuate light and ventilation to the staircase. Small wood paneled door forms the stairway entrance. The roofing is in the form of reinforced concrete domes, the central one being larger and higher than the two adjoining ones. The circular domes rest on the arched openings, in stone masonry. The stone courses are regular and form a high base with moulding like band atop. The stone courses are regular and form a high base with moulding like band atop. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable - Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellent seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.7 7.8 7.9 7.10 7.11	Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	The roofing is in the form of reinforced concrete domes, the central one being larger and higher than the two adjoining ones. The circular domes rest on the arched openings, in stone masonry. The stone courses are regular and form a high base with moulding like band atop. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellent seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.8 7.9 7.10 7.11	Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	The stone courses are regular and form a high base with moulding like band atop. The stone curvilinear brackets supporting the slight sloping chajja like slab form an ornamental detail above the archways all around the monument. The walls in rough yellow basalt stone in large courses form the finishing, both external and internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable - Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellent seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.9 7.10 7.11	Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	internal, relieved by projecting bands in soft porbunder stone with carved patterns, at regular intervals. Movable Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellen seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.10	Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/	- Immovable Presence of a <i>palkhi</i> like structure at the centre beneath the large dome with 'Shivaji' head engraved and inscription in Sanskrit. The thick retaining wall along the sea face forms the compound boundary, also an excellen seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	The thick retaining wall along the sea face forms the compound boundary, also an excellen seating arrangement for visitors. Presently the monument is insensitively enclosed with a stone and iron fencing prohibiting entry, originally being accessible.	
	Landscape	The western front is an open plaza and an enclosed landscaped garden with the statue of Chhatrapati Shivaji Maharaj on horse and behind which is a exquisitely carved marble fountain dating back to the British era. To the north is a statue of Swami Vivekanand in landscaped surrounding.	
8.0		Services & Utilities	
	Lighting	Adequate natural light being an open structure. After sunset large electric halogen fittings illuminate the monument externally. Earlier a chandelier with decorative glass suspended from the central dome.	
8.2	Ventilation	Naturally ventilated. No artificial mechanism provided.	
	Electricity	BEST	
	Water Supply	MCGM	
	Drainage (Plumbing & Sanitation)	MCGM	
	Fire Precaution Other (HVAC/BMS/Security Systems)	Relies on the firefighting department. Police <i>chowky</i> near the western access is responsible for the security of the monument.	
		Opendition	
9.0 9.1	Plinth	Condition	
9.2	Floor	Fair - No evident damage. Presence of plant growth and weathering affect the stone course Fair - Plant growth and weathering action observed at many instances along the external and internal side; affect the strength of the stone courses as well as their surface appearance. Fair - Floor finish within the monument is in the process of being replaced with kotah stone.	
		The original stone pavement around the monument still intact, smooth due to heavy usage, only slight damage in leveling and finishing.	
	Stairs	Indeterminable - The narrow pier enclosed staircases are in a neglected state lacking maintenance.	
	Openings	Fair except sandstone <i>jali</i> at certain places is damaged and replaced with artificial jali.	
	Roofing	Fair except Circular dome has exposed reinforcement steel at some place along with rainwater seepage, and surface deterioration for lack of maintenance.	
	Articulation & Finishes	Poor - The stone finish seems uneven and blackish in appearance as a result of exposure to seawater and ficus growth. The stone jali seems to lose intricacy due to lack of maintenance.	
	Services	Insensitive electrical wiring along the surface of the monument	
9.9	Out Buildings	Meteorological observatory to the northern side is in a fair state, the toilet block towards the western approach resembling the monument is a bad example as well as lacking maintenance.	
		Fair but lacks maintenance. Maintenance level: Poor.	

Gateway o	or incla	211(
10.0		Transformation
	Form	There is no significant transformation to the monument itself, but the fencing around seen unnatural, blocking the monument as such from public access
	Structure	No structural transformation to the monument as observed.
	Articulation & Finishes	Some repair work involving the coating the stone surface with a synthetic resin to render the structure waterproof has led the outermost layer of masonry 'peeling off' being detrimental over a span of time. Also sandstone <i>jali</i> is replaced with artificial <i>jali</i> at few places.
11.0		DP Remarks/ Perceived Threats
		Recreation Ground
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Alternative Designs were prepared and displayed for Public criticism reflecting the Participatory approach towards the Design of a Public monument. The Gateway has RC0 pile foundations, driven almost 36 ft. deep. The reinforced concrete dome construction were proneering in terms of technique at that time. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. RHANDA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House. MARIAM DOSSAL (1996) Imperial designs and Indian Realities - The Planning of Bomba City - 1845-1875, Bombay : Oxford University Press. SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.



Grand gateway with a central rising bay along with corner towers, flanked by side symmetrical bays, arched openings on all sides, projecting bands with highly decorative brackets



Projecting bands with decorative scroll brackets, floral motifs



Central bay with dome structure



Detail of decorative frieze band in floral pattern

Gateway of India



Tower with shikhara on top, bands, jaliwork, frieze bands



Central archway with Gujrati style Architecture with side projecting tower, floral motifs, decorative bands




Detail of the projecting tower base with bands at different levels



Inscription in stone describing the purpose of building the Gateway







Three bays with dome structures



Arch panel with intricately carved arch and horizontal bands, floral motif, jaliwork



Tablet in stone at the rear side

211(d)

Evelyn Ho	use		211 (e
,iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii		Common Ref No: 211 (e)	A TA ISANA
		Card No: 288	- Start I have a start of the s
	* 1	Ward (Part): A (part III)	
		CS No: 390 (Colaba Division)	Se state
S.		Plot Area: - Indeterminable	T E on many the state
'n			
E.		B U Area: -	- Fill Anti The Contraction of t
		Date: 10/02/05	
		Recorded by: Prachi Merchant	Plan I and and the
10	ALL	Reviewed by:	The state of the s
		Int: Prachi Merchant	
	AND BERGERALD	Ext: Prachi Merchant	Peter a transition
		Photo Ref.: 211(e)_Evelyn House	
	Contraction of the second		the second secon
			The matter alar
4.0		Denemination	Location plan
1.0		Denomination	
1.1	Name of Premises	Evelyn House	
1.2	Earlier Name	Evelyn House	
1.3	Built in:	1873	Extension Date: -
2.0		Access	
2.1	Main	P. J. Ramchandani Marg – vehicular and	nedestrian
2.1			peneoman
	Subsidiary	Henry Road - pedestrian	
3.0		Ownership pattern	
3.1	Present	Mumbai Port Trust	
3.2	Past	Bombay Port Trust	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Government Guest House	
4.2	Past	Government Guest House	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (manmade)	nmade) The building forms a part of buildings along the P. J. Ramchandani Marg fa	
	,	The building is located on a corner plot at	the junction of Henry road and P J Ramchandani
		Marg and is accessed from the east side	
5.2	Architectural Description	Planning	
0.2			st west direction with its shorter side facing the
		east side. The building is located in the no	
		The north side end, north and south side	
		building.	center bays are nigher than the rest of the
			la than a han a ta a da da a sa ha ta a far ta a far t
		The building is accessed from the east sid	le through an extended porch, leading to a front
		verandah and the front lobby. The staircas	se lobby, kitchen, servants room and staircase
			ntral portion with the two rooms on west side and
		suites on the east side.	
		All rooms and passages overlook veranda	ahs on the side and rear. The suites overlook the
		verandah space on the east side facing th	ie sea.
		The west side of the building occupies two	o rooms on all floors. The east side houses the
			first and third floor and dining area on the first
		floor.	
		Features	
		The toilet block on the east end has arche	ad openings with emphasized keystones
		geometrical mezes in the sill part and sill i	band. The bay ends into a triangular pediment,
			fined with bands and corners have stone quoins.
			keystone emphasized. The ground floor openings
		have pediments.	
			ooden verandahs with wooden intricate louvered
		ventilators, carved cast iron railing, sloping	g chajjas on wooden brackets and column posts.
		The staircase block and terrace has stone	
		Style	
		Building derives influences from the Verna	acular style of Architecture.
5.3	Intrinsic	-	,
5.4	Value Classification	A(arc), B(per), B (des), B(uu), E, F, G(grp) Recommended grade II B
J.7			
6.0		Tonography	
6.0		Topography	
6.1	Floors	G + 3	

Evelyn Hoι	ISE	211 (
7.0		Construction	
7.1	Plinth	Normal height grey stone plinth with plinth protection band.	
7.2	Walls	Composite load bearing wall.	
7.3	Floor	Wooden flooring.	
7.4	Stairs	Main open well wooden staircase with wooden risers, treads and railing.	
7.5	Openings	RCC servants' staircase. Verandah rectangular openings with glazed paneled shutters, louvered ventilators and	
7.6	Roofing	wooden railing. Arched openings with glazed paneled shutters Mangalore tile sloping roof over verandah spaces.	
-		Flat terrace over rooms. Service staircase block with water tanks.	
7.7	Articulation	Wooden verandahs, arched openings, bands and pediments.	
7.8	Finishes	Walls are externally clad with stone. Externally and internally walls are finished with plaste and paint. The floor is finished with mosaic and cement tiles at places, wooden finish in the suites and verandahs.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	- Brick compound wall with fence above.	
		Two MS gates, one from the east side and other from north side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Front and south side landscaped lawn and paved area with old trees.	
	Landscape	Parking area on the south side.	
		Watchman's cabin, near the entrance and substation at the rear.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through verandah and openings, supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation through verandah and openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
	Drainage (Plumbing & Sanitation)	MCGM	
8.5 8.6	Fire Precaution		
		-	
8.7	Other (HVAC/BMS/Security Systems)	AC units are installed in the room. Manual security at the entrance.	
9.0		Condition	
9.1	Plinth	Fair – South side plinth has been altered for new additions.	
9.2	Walls	Fair – Loose plaster and cracks observed. Stone wall is replaced by brick walls.	
9.3	Floor	Fair	
9.4	Stairs	Fair	
9.5	Openings	Poor – Openings have been blocked to occupy AC's. Grills have been added, window shutters have been changed. <i>Chajjas</i> have been replaced. South side servant's wing openings have been blocked.	
9.6	Roofing	Fair	
9.7	Articulation & Finishes	Fair – verandah woodwork is painted and is in a deteriorating condition. Façade features are in a broken condition at places.	
9.8	Services	Poor - Leakage are observed in the servants block.	
9.9	Out Buildings	Fair	
9.9 9.10	Overall Conditions	Fair. Maintenance level: Poor.	
9.10			
10.0		Transformation	
	Form	-	
	Structure	South side façade have major alterations like wall additions.	
	Articulation & Finishes	Openings are blocked, opening size and shutters have been changed, grills have been added. Verandah openings have been blocked.	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		- <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings an Structures listed for Conservation.	

Evelyn House	211 (e)
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence
	Designs Pvt. Ltd.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,



Front façade with corner projecting bay, side main structure with verandahs with wooden railing, trellis work, sloping chajjas




Arched window with scroll bracket keystone, arched bands, corner quoins





Detail of the louvered ventilator panel

Urban Design Research Institute



South façade with projecting balcony spaces with wooden trellis work, railing, sloping chajjas



Verandah with sloping roof overlooking the main road



Railing detail



Minton tile flooring

MMR- Heritage Conservation Society

Seth Mane	ckjee Navrojee Seth Agiary	212	
		Common Ref No: 212 Card No: 289 Ward (Part): 283 (Part II) CS No: 283 Fort division) Plot Area: 165.55 sq. m B U Area: - Date: 19/05/01 Recorded by: Prachi Merchant Reviewed by: Int: Refer # Photo Ref.: 212_Sett Agiary	
1.0	Name of Dramiago	Denomination	
1.1	Name of Premises	Seth Maneckjee Navrojee Seth Agiary	
1.2 1.3	Earlier Name Built in:	19 th June 1733, fire was consecrated as a Daremeher. Extension Rebuilt in 1891 Date: Date:	
2.0		Access	
2.1	Main	Perin Nariman Street	
2.2	Subsidiary	Mody Lane (Rear access)	
3.0		Ownership pattern	
3.1	Present	Maneckjee Navrojee Sett Charities	
3.2	Past	Indeterminable	
3.3	Status	Trust (Trustees: Burjor Anita, Khordabad Cama, Jeroo Cama, Mehli Cama, Sharukh Sethna, Pheroz Katrak, Rustom Vakil, Aloo Dadiseth)	
4.0		Use	
4.1	Present	Religious	
4.2	Past	Religious	
4.3	Usage	Daily	
5.0 5.1	Townscape (Manmade)	Significance & Value Classification This elaborate two storied structure is located on a corner plot accessed Perin Nariman Street with rear access from Mody Lane. The intricately designed façade of the Agiary falls short of an appreciable space as it directly abuts the narrow Perin Nariman street without the setback or front open space. The Agiary encloses an inward looking court with built from along three sides. Presently the Agiary is surrounded by dense, commercial development of disharmonious scale and character except for the clock tower structure in its vicinity, which compliments the Agiary structure.	
5.2	Architectural Description	Planing and Features The Agiary is two storied, composite structure with gabled Mangalore tiled roof. The front façade is intricately detailed with a composition of Assyrian, Greek and Roman elements in addition to lamuses, Persepolitan column capital, emphasized arched openings cornices entablatures and pediment. The rear facade has a domestic (house like) scale covered by a sloping roof. The structure accommodates an introvert open court, flanked by two storied structures to its left with a small rear open space with rear access. The intricacies of the structure are not only limited to the exteriors but also in the interiors with elaborately designed roof ceiling with unique articulation and detailing. Ablution Pavilion (Kasti enclosure): There is no exclusive kasti pavilion. The provision for the same is made along a partly covered passage along rear open courtyard, accommodating the well. The location of the ablution pavilion is peculiar, as one has to pass the Prayer Hall and Kebla to approach the same. Kebla: The entry to the Kebla from the west is exquisitely detailed marble doorframe, marble shutters and brass hardware. The brass-piped, four shuttered wicket gate to the Kebla is one of its kinds. The Kebla has German silver "afarghanyu" (fire) vessel. In the centre surmounted by a German silver tray holding the fire. The urn rests upon a stone pedestal "idhora", which is exquisitely covered out. The internal walls of Kebla areadomed with swords while large bells hang from the	

Seth Mane	ckjee Navrojee Seth Agiary	212
		ceiling on the two opposite sides. A German silver "chatter" is suspended over the fire. The flooring is finished with marble and is laid with pavis. There are in-built cupboards along the rear wall of the Kebla enclosure. <u>Prayer Hall:</u> It is not formally demarcated as a separate room/ hall, but is about eight feet wide space
		that affronts three sides of Kebla. The Prayer space is well lit and ventilated from rear court. The area is accessed from the ceremony hall as well as from the rear court.
		Ceremony Hall:
		The large Ceremony Hall is grand and detailed measuring about twenty five feet deep and forty five feet long, has marble flooring with elaborate detailing along the walls with arched openings pilasters, heavy cornices, coffered ceiling and intricate wood work. Internal posts with elaborate Persepolitian capitals support the timber trabeated structure. Marble plaques in Persian, Avesta, Gujarati and English languages adorn the walls of the ceremony hall. Baj Room: Two elongated Baj rooms from a part of the rear structure and overlook the courtyard
		thereby drawing light and ventilation from the same. The Baj Room has dressed basalt stone flooring with pavis laid and single stone carved "idhoras" occupy every cubicle. The load bearing walls with paneled window openings along one surface while the ceiling is elaborately carved out and oil-painted. Congregation Hall:
		There are two Congregation halls, one above the entire length of the two Baj Rooms, while the other over the ceremony hall on either side of the courtyard drawing light and cross ventilation. A gable ended, circular chord teakwood trussed, Manglore tiled roof encloses the Congregation halls. Adequate light and ventilation is achieved through the arched openings from all four sides long with the small, open to sky terraces. Residence for Preist's (Boiwala's) in serving:
		Not provided in the premises <u>Curtilege Structures (Wells etc):</u> Small curtilege structures for storage are located on the rear side of the plot. They are poorly maintained. The well is accommodated along the central court and is lined with dressed basalt stone flooring Style No particular style is observed. Adaptations of Assyrian features on façade.
5.3	Intrinsic	External façade detailing by way of emphasized arch openings, extensive stucco work, life size lames, Persepolitan columns, articulate projecting balcconettes, deep cornices at floor roof and openings pediment with pronounced entablature topped with a finial shaped as an afarghanyu. The interiors of the Ceremony Hall are well articulated by means of Persepolitan capital columns, carved coffered ceiling, extensive stucco work along the walls by way of cornices pilasters, motifs and arched openings along interiors with elaborate circular chord timber trussed roof for congregation hall, other than intricate detailing for openings, for openings in built furniture, accessories by way of photo frames, plaques, clocks, etc.
5.4	Value Classification	A(arc),A(his),A(cul),B(des),B(per),B(uu), C(seh),D(bio),E Recommended grade:
6.0		Tanaganhu
6.0 6.1	Floors	Topography G+1
7.0 7.1	Plinth	Construction Eighteen-inch high stone plinth in Khandki stone masonry totally lined in marble along
7.2	Walls	ground floor, showing no signs of settlement. Load bearing walls; external walls are partly in stone masonry, while internally brick walls in
		lime mortar and lime plaster are used.
7.3	Floor	Timber trabeated structure with load bearing walls supports the floor with the help of timber beams, simple timber bridging joists And planking along with the intricately detailed timber false ceiling.
7.4	Stairs	Timber doglegged staircase with double stringer and elaborate handrail, baluster and newel post detail.
7.5	Openings	Elaborate arched openings, partly paneled, partly glazed, partly louvered with glazed ventilators with intricate detailing along the frames and lintels.
7.6	Roofing	Gabled end roof with circular chord timber trusses, timber rafters, boarding, battens and Mangalore tiles.
7.7	Articulation	Exquisite articulation along the front façade by way of emphasized arched openings, extensive stuccowork, life size lamuses, Persepolitian columns, articulate projecting balconnettes, deep cornices at floor, roof and opening pediment with pronounced entablature topped with a finial shaped as an "afarghanyu".

Seth Mane	ckjee Navrojee Seth Agiary	212
		paints.
		Internally, the walls are finished in oil-based emulsion paint are presently in poor condition.
7.9	Interiors (Movable & Immovable)	Movable
		-
		Immovable
7.40		- The second se
7.10	Compound/ Fence/ Gate	There is no compound wall in the front of the Agiary. The rear compound wall is in brick
7.11	Curtilage/ Unbuilt space/ Out Buildings/	masonry, plastered and with a MS gate along rear access. Load bearing ground storied structures for storage.
1.11	Landscape	Load bearing ground stoned structures for storage.
8.0		Services & Utilities
8.1	Lighting	Inadequate in front facing ceremony hall, as the windows are mostly shut due to its public
0.1	Lighting	location and demand for privacy. Adequate in the prayer hall and congregation hall.
8.2	Ventilation	Adequate, except in the front facing ceremony hall.
8.3	Electricity	BEST
8.4	Water Supply	Well water and piped water through the MCGM connected supply.
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	-
0.1		
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Fair Maintenance level Fair - Poor
10.0		Transformation
	Form	No visible changes
	Structure	No visible changes
	Articulation & Finishes	No visible changes
44.0		
11.0		DP Remarks/ Perceived Threats
		Building forms part of R zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		- References:
		# The Study conducted by Pankaj Joshi Consultants with support from Mr Jamshed
		Guzder, Merwanji D M Jeejeebhoy Trust and Mrs Ketie Mehta, Gulestan and Rustom
		Billimoria Charitable Trust through auspices of Mr Cyrus Guzder.
		, , , , ,



Carved column capital detail with carved arche bands, balustrade



Entrance flanked with Lamuses, decorative arched band, prominent keystone, flanked with fluted columns with decorative bands and capital



Projecting balcony with decorative railing, tapering bands



Arched window opening with stain glass ventilator panel, balustrade, lintel band

Bomanii H	Iormusji Wadia Fountain	213			
		Common Ref No: 213			
	4	Card No: 290			
		Ward (Part): A (Part III)			
		CS No: 251 (Fort division)			
		Plot Area: Indeterminable			
	CARLES IN THE SALES	B U Area: -			
		Date: 01/11/2004			
		Recorded by: Sonal Modak			
		Reviewed by:			
		Int: Sonal Modak, Arun Wadhwa			
		Int: Sonal Modak, Arun Wadhwa Ext: Sonal Modak, Arun Wadhwa Photo Ref.: 213_Bomanji Hormasji Wadia			
		Photo Ref.: 213_Bomanji Hormasji Wadia			
	81 - O - 10	Fountain Location Plan			
1.0		Denomination			
1.1	Name of Premises	Bomanji Hormusji Wadia Fountain			
1.2	Earlier Name	Bomanji Hormusji Wadia Fountain			
1.3	Built in:	1880 Extension -			
		Date			
2.0	1	Access			
2.1	Main	Perin Nariman Street – Vehicular and Pedestrian			
2.2	Subsidiary	Pherozshah Mehta Road - Vehicular and Pedestrian and			
	,	Ruston Sidhwa Marg - Vehicular and Pedestrian			
	1				
3.0		Ownership pattern			
3.1	Present	Municipal Corporation of Greater Mumbai			
3.2	Past	Trust – Private			
3.3	Status	Owner			
4.0		Use			
4.1	Present	Not in Use.			
4.2	Past	Drinking water fountain for animals and by passers and Clock Tower.			
4.3	Usage	Not in Use.			
5.0		Significance & Value Classification			
5.1	Townscape (Manmade)	The fountain is located at the junction of Pherozshah Mehta Road and Perin Nariman			
		Street.			
		It serves as a visual marker at the termination of Perin Nariman Street.			
5.2	Architectural Description	Planning			
		The fountain has a cruciform plan. It has entrances from all four arms surmounted by a			
		clock tower and the symbol of fire. The central clock tower rises above the rest of the			
		structure.			
		It has central wooden shaft, which might have served as service shaft for the clock at top.			
		The entrance facing Perin Nariman Road has a marble bust of Bomnji Hormusji Wadia.			
		Features			
		Human headed, two winged lions are traditional Zoroastrian royal religious symbols			
		(Lamassu), which guard all the entrances of the fountain.			
		The fountain features at the top, the symbol of fire, held sacred by followers of the Zoroastrian faith.			
		There are floral cornice bands at various levels resting on dentil bands.			
	1	Openings have projecting rectangular moulding around the periphery. Engaged circular and square columns on all facades.			
	1	Style			
	1	Predominant use of Greek-Persepolis style features.			
5.3	Intrinsic	The fountain stands on the land given by the Municipality in exchange for a well, which			
0.0		stood near the spot and was claimed by Bomanji Hormusji as his property.			
5.4	Value Classification	A(arc), B (per), B(des), B(uu), D(bio), F, Recommended grade II B			
		I(sce)			
6.0		Topography			
6.1	Floors	The fountain is a stand-alone structure having water troughs and spouts at ground level			
		and clock tower at upper level surmounted by the symbol of fire.			
7.^		Or and the officer			
7.0		Construction			
7.1	Plinth	Medium plinth in grey stone about 2 ft. 6 inches.			
7.2 7.3	Walls Floor	Thick load bearing stone masonary with grey basalt ashlar facing.			

7.4 7.5 7.6 7.7 7.8 7.9	Stairs Openings Roofing Articulation	MS ladder to access clock tower. Rectangular openings with projecting square molding on all sides. Main entrances are provided with collapsible shutters. Openings are fixed with grills and jali.	
7.6 7.7 7.8	Roofing	Main entrances are provided with collapsible shutters. Openings are fixed with grills and	
7.7 7.8	Roofing		
7.7 7.8	°	jali.	
7.7 7.8	°		
7.8	Articulation	· .	
	Alticulation	Floral cornice bands at various levels. Engaged circular and square columns.	
7.9	Finishes	Exposed stone masonary internally as well as externally.	
	Interiors (Movable & Immovable)	Movable	
	· · · · · · · · · · · · · · · · · · ·	-	
		Immovable	
		Stone inscription on front side on lower wall.	
		Bust of Bomanji Hormusji in the main entrance.	
7.10	Compound/ Fence/ Gate	Structure sits on entire plot.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	-	
	Landscape		
8.0		Services & Utilities	
8.1	Lighting		
8.2	Ventilation	-	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)	-	
9.0		Condition	
9.1	Plinth	Poor – Stone chipping, decorative parapet defining the access path is totally damaged.	
		Height is reduced due to earth filling around the structure.	
9.2	Walls	Fair except cracks and minor damage observed.	
9.3	Floor		
9.4	Stairs	Poor – Steel ladder in clock tower is not structurally sound. Corroded steel members.	
9.5	Openings	Poor - neglected condition of openings covered with grills and protective jalis. Also poor	
		condition of collapsible shutters at the entrances.	
9.6	Roofing		
9.7	Articulation & Finishes	Poor - neglected state. Blackened stone dressed surfaces, cracks and plant growth	
		observed. Hawkers use the space around damaging the features in stone.	
9.8	Services	Poor – water drinking fountain is abandoned, old and neglected services.	
9.9	Out Buildings	· · · · · · · · · · · · · · · · · · ·	
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0		Transformation	
1010	Form	There is no visible transformation in the form of the building.	
	Structure	There is no visible structural transformation in the building.	
	Articulation & Finishes	Hawkers occupy the space around the structure, as the structure is not in use.	
	Ancolation & Finishes		
11.0		DP Remarks/ Perceived Threats	
11.0		Forms part of R zone	
		Tomis part of R zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes:	
		This unusually designed fountain was erected by public subscription in 1880 to honour a	
		leading Parsi citizen whose marble bust, which can be seen inside. The fountain features at	
		the top, the symbol of fire, held sacred by followers of the Zoroastrian faith. The fountain	
		stands on the land given by the Municipality in exchange for a well, which stood near the	
		spot and was claimed by Bomaniji Hormusiji as his property.	
		References:	
		<u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

Bomanji Hormusji Wadia Fountain



View of the symmetrically planned Pyaav, with central rising clock tower



Entrance detail flanked with 'Lamuses', bands with geometric pattern, brackets



Corner detail of cornice band with floral pattern, dentil band



'Farohar' motif on stone



Clock tower with bands in geometric pattern



Marble bust on a pedestal



Marble plaque with foundation details



Window with opening bands, decorative lintel band

Parsi – Lying		Common Ref No: 214	All of I	TTP/ 11 P I To
5 13		Card No: 291	S- Jost	I Mart III
1.1		Ward (Part): A (Part II)		the the
and the second second		CS No: - 741/742 (Fort Division)	PRES	COTTROAD
		Plot Area: 1866.69 sqm.		OTTRO
The		B U Area: -		AD
Oho.			- 1 //	10
		Date: 17/12/2005	* *	9
		Recorded by: Zankhana Prajapati	and parts	HSH
1º 0 4101		Reviewed by:	6901	I A PAR
		Int: Zankhana Prajapati, Sonal Modak	_ // / J	TAM
HELZ DA	LAND A CONTRACT	Ext: Zankhana Prajapati, Sonal Modak	and I	A Stall I
6		Photo Ref.: 214_Parsi Lying in hospital	A. K. N.	HA
				MIHAKUROAS RO
10		Denemination		Location Plan
1.0	Name of Drawing	Denomination		
1.1	Name of Premises	Parsi – Lying in Hospital		
1.2	Earlier Name	Parsi – Lying in Hospital		
1.3	Built in:	Foundation stone laid in 28th march 1893.	Extension	9th December 1899
		Formally opened on 11th January 1895.	Date:	
		· · · ·		
2.0		Access		
2.1	Main	Prescott Road		
2.1	Subsidiary	A. K. Nayak Road, Purshottamdas Thakurdas	s Road	
L.L		A. N. Mayak Noau, Euronollaniuas makuruas	s ruau.	
2.0		Ownership netters		
3.0	-	Ownership pattern		
3.1	Present	Parsi panchayat (trust)		
3.2	Past	Parsi panchayat (trust)		
3.3	Status	Trust.		
4.0		Use		
4.1	Present	Maternity hospital.		
4.1				
	Past	Maternity hospital.		
4.3	Usage	Daily		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	It is on a corner plot at the junction of Prescot	tt Road, A. K. Nay	yak Road, and
		Purshottamdas Thakurdas Road.	_	
		Main access to the building is through Presco		
		The building is marked with its gray stone fac	ades, intricately o	carved stone screens and
		projecting balconies.		
5.2	Architectural Description	Planning		
		It is rectangular in plan with a central courtyar The building is a ground plus three structure. The entrance to the building was from Presco Nayak Road. There are two main staircases of Purshottamdas Thakurdas road, and other fro Nayak; beside this there is one more staircass Thakurdas Road beside which toilet block is p rear comer. Operation theatre is at the left co And administration office is in the ground floo condition of the building is extremely poor. Features	With a sloping sta out road earlier and one at the corner on the center of t e in the center of placed and another rner from Pursho	aircase block. d is now it is from A. K. of Prescott road and he façade along the A. K. façade along Purshottamdas er toilet block is placed at the ttamdas Thakurdas road.
5.3	Intrinsic	The building has gray ashlar masonry in front pointed arch openings with no definite pattern columns on high pedestal with Corinthian colu Each floor is marked with floral patterned corr it also has slit pointed arch openings. There a decorative brackets, with stone parapet. Ston entire pointed arch openings in front and side main staircase and is marked below by arabe respectively. Has wooden awnings, decorative Style The building displays characteristics of Neo C The founders were leading luminaries of the F	n. The entrance is umns and floral b nice band, impost are projecting bala e jalis with arabe elevation. The ro sque openwork, e wooden bracke Bothic Style.	marked with two short asin like motif attached to it. t is done in arabesque band; conies supported on sque pattern are present in pof is high pitched above dentil band and rose window ts in roof and eaves board.

Parsi – Lyi	ing in Hospital	214 Sorabji Framji Patel, Nusserwanji Jehangir Wadia Jamsetjee Nusserwanji Tata and Dr.		
		Temuljee Nariman.		
5.4	Value Classification	A(arc), B(per), B (des), B(uu), E, F, G(grp) Recommended II B grade		
6.0		Topography		
6.1	Floors	G+3 with sloping roof.		
7.0		Over the effect		
7.0 7.1	Plinth	Construction Medium height gray stone ashlar masonry plinth with edging done for plinth protection.		
7.2	Walls	Load bearing stonewalls in old wing with external fascia in gray stone ashlar masonry; the new wing and internal walls are in brick plastered and painted.		
7.3	Floor	Jack arch flooring in certain areas and rest supported on wooden members and Minton tiles.		
7.4	Stairs	Three staircases are present. Two main staircases are C-shaped and the additional staircase is doglegged. The main staircase in old wing is a stone staircase with wooden handrail and cast iron balusters; the main staircase in new wing is cast iron with ornate carvings and balusters and additional staircase is of cast iron with cast iron baluster and railing.		
7.5	Openings	All doors are within pointed arched openings with ventilators above.		
		All doors are double leaf wooden panel door with ventilators above. All windows are within pointed arched openings. All windows are double leaf-glazed panel with ventilators above and below. Beside this there is also presence of <i>jalis</i> and verandah all around the internal court.		
7.6	Roofing	Has arched braced truss gable end roof, hipped roof and lean to roof for verandah.		
7.7	Articulation	Cornice band, Corinthian column capital, dentil band, arabesque band, rose window, floral motif, balcony projection and <i>jalis</i> .		
7.8	Finishes	External walls are gray ashlars stone masonry. Internal walls are plastered and painted. Flooring is done in minton tiling.		
7.9	Interiors (Movable & Immovable)	Movable Old tables, chairs, racks, beds, cradle and portraits. Immovable		
7.10	Compound/ Fence/ Gate	Statues, plaque, built in safe. Has half height stonewall with cast iron fencing with column post in between as compound wall; has cast iron gates.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Has internal court and open space at three sides. Garage, tea stall, laundry, and water tank and pump room as outbuildings; lots of old trees in compound.		
0.0		Convisoo 9 Hidilitiaa		
8.0 8.1	Lighting	Services & Utilities Adequate Natural light through door-window openings supplemented by electric light fixtures.		
8.2	Ventilation	Adequate Natural ventilation through door-window openings supplemented by electric fans.		
8.3 8.4	Electricity Water Supply	BEST MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	-		
8.7	Other (HVAC/BMS/Security Systems)	-		
9.0		Condition		
9.1	Plinth	Poor – stone blackened, covered with planters, plant growth where service pipes are present and plinth is dilapidated.		
9.2	Walls	Poor -heavy cracks, extensive seepage, moss and plant growth, in dilapidated condition.		
9.3	Floor	Poor – tiles broken, replaced, wood beams deteriorated, jack arch flooring is in total dilapidated with moss growth and leakage.		
9.4	Stairs	Poor – cast iron staircase is rusted, no maintenance; stone staircase is not in use, neglected and is in poor state.		
9.5	Openings	Poor – window panes broken, dust accumulation, paint peeling off; some openings are blocked off by plywood, moss and plant growth.		
9.6	Roofing	Poor – wooden members deteriorated, mangalore tiles missing, seepage.		
9.7	Articulation & Finishes	Poor – blackening of surface, dust accumulation, cornice bands broken, plaster and paint peeling off, has seepage and plant growth, arches painted and badly done cement pointing		
9.8	Services	Poor – leakage and broken pipe, rusted pipes, plant growth, duct not maintained and totally unhygienic condition and haphazard electrical layout.		
9.9	Out Buildings	Poor – neglected, broken shed and not maintained.		
9.10	Overall Conditions	Dilapidated. Maintenance level Poor.		

Parsi – Lyi	214	
10.0		Transformation
	Form	Addition of new wing.
	Structure	Addition of mezzanine may have altered the structural loading system.
	Articulation & Finishes	Painted stonewall and articulation.
11.0		DP Remarks/ Perceived Threats
		Hospital
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Situated on Prescott Road, the grey stone building with intricately carved stone screens, was designed by Muncherjee Cowasjee Murzban and constructed with funds raised by members of the Parsi community. The hospital was opened in 1887 at the initiative of Dr Temuljee Bhiccajee Nariman, in a small, sea-facing house on the Marine Lines. As the accommodation was found to be limited, a plot was acquired in the Hornby-Ballard Estate <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Front façade with arched openings, frieze bands



Internal central courtyard



Marble bust



Arched entrance with decorative column capital and frieze band, wooden paneled shutters

Parsi – Lying in Hospital



Inscription in stone about foundation details



Series of pointed arched windows with highly decorative jaliwork



Verandah with sloping roof, wooden railing and support members



Arched window with sill band with geometric pattern motif



Column detail



Tablet 1



stone stancase with wooden raining



Tablet 2

		215
the second s	Common Ref No: 215	The state of the s
Contraction of the second	Card No: 292	And and and the second
A CARLE STREET	Ward (Part): A (Part III)	CHARANSIT
Party and the second se	CS No: 750.	An A
ALL AND AL	Plot Area: 2508.38 sqm.	
Barry Contraction of the second	B U Area: 5992 sq m	
Alle the second	Date: 20/11/2004	
	Recorded by: Arun Wadhwa	
	Reviewed by:	and the second s
AND I DIE THE REAL PROPERTY OF THE	Int: Arun Wadhwa, Zankhana Praja	pati de la constante de la constant
	Ext: Arun Wadhwa, Zankhana Praja	
	_	
		Location plan
	Denomination	Location plan
as of Dromisso		
i in:		Extension Date: R.C.C. extension in 1970's and recen
	Completed in November 1881.	renovation started in 1995 and completed in 1998
	Access	
n		
sidiary	Amrit Keshav Nayak Marg to the ea	ist.
	Ownership pattern	
sent	Trust	
t	Anglo Scottish Education Society.	
us		
<u>_</u>		
	llse	
sent		
ye	Dally	
	Olarifian and Nation Olareifianti	
inscape (Manmade)		
the characteristic state		tree follage along the entire stretch of street.
litectural Description		We assure that the second s
	wing forms the corresponding L' sh	ape enclosing a central open court serving as the hub
	of activities within the school. The e	extension building designed with veranda to the inner
	•	
		courses of dark grey and light colored stone on the
		ade. Large semi-circular arched openings on the
	• ·	rches on the first floor. Steep sloping roof gable end at
	corners.	
	Style	
	Gothic Revival style.	
	-	
nsic		
nsic Je Classification	A(arc), B(per), B (uu), F, G(grp)	Recommended grade: II A
	A(arc), B(per), B (uu), F, G(grp)	Recommended grade: II A
	A(arc), B(per), B (uu), F, G(grp) Topography	Recommended grade: II A
	Topography	Recommended grade: II A
ue Classification	Topography	h pitched roof in the original stone structure and ground
ue Classification	Topography Ground and three upper storeys wit	h pitched roof in the original stone structure and ground
ue Classification	Topography Ground and three upper storeys wit	h pitched roof in the original stone structure and ground
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extens Construction	h pitched roof in the original stone structure and ground
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extens Construction Low height of about a foot, dressed	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extension Construction Low height of about a foot, dressed serving as stilt seems leveled with t	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around.
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extension Construction Low height of about a foot, dressed serving as stilt seems leveled with t Walls are load bearing stone mason	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around. nry dressed in ashlars courses. The extension wing is
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extension Construction Low height of about a foot, dressed serving as stilt seems leveled with t Walls are load bearing stone mason brick masonry wall and concrete str	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around. ny dressed in ashlars courses. The extension wing is ucture.
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extension Construction Low height of about a foot, dressed serving as stilt seems leveled with t Walls are load bearing stone mason brick masonry wall and concrete str Stone slabs supported on wooden in	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around. nry dressed in ashlars courses. The extension wing is ucture. afters and stone masonry walls and arches. Extension
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extens Construction Low height of about a foot, dressed serving as stilt seems leveled with t Walls are load bearing stone masor brick masonry wall and concrete str Stone slabs supported on wooden n wing has concrete floor supported of	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around. my dressed in ashlars courses. The extension wing is ucture. rafters and stone masonry walls and arches. Extension on columns and beams.
ue Classification	Topography Ground and three upper storeys wit and four upper storeys in the extens Construction Low height of about a foot, dressed serving as stilt seems leveled with t Walls are load bearing stone masor brick masonry wall and concrete str Stone slabs supported on wooden n wing has concrete floor supported of	h pitched roof in the original stone structure and ground sion wing. in regular stone masonry course, the extension wing he paving around. my dressed in ashlars courses. The extension wing is ucture. afters and stone masonry walls and arches. Extension
	sidiary sent t	Photo Ref.: 215_Cathedral and Joh Senior School Denomination te of Premises Cathedral and John Connon Senior Senior Schottar Senior Schottar Trust L Margle Schutz Senior School L Senior School L Seni

Urban Design Research Institute

MMR- Heritage Conservation Society

7.5	and John Connon Senior school Openings	211 Arched portion of veranda openings is louvered in wood with central glazed fixed panel.	
<i>I</i> .5	Openings	Arched portion of veranda openings is louvered in wood with central glazed fixed panel. Semicircular as well pointed arched openings form doorways with ventilators in the arched portion and glazed paneled wooden shutters.	
7.6	Roofing	High sloping roof with mangalore tile finishing supported on wooden trusses, replaced with steel sections recently. Pyramidal sloping roof supported on octagonal wooden trusses like curvilinear members.	
77	Articulation		
7.7	Finishes	Externally dressed in grey stone ashlars course masonry with decorative features in light	
1.0	Fillishes	colored porbunder stone and circular columns in red stone. The inner surfaces facing the Stone <i>jali</i> to veranda parapet wall on the external side whereas wooden jali and handrail to the internal veranda. Internal surfaces in original building and all wall surfaces in the extension wing are plastered and painted.	
7.9	Interiors (Movable & Immovable)	Movable -	
		Immovable	
		Decorative metal feature suspended from the center of staircase ceiling truss.	
7.10	Compound/ Fence/ Gate	Low stonewall with wrought iron railing to the south and subsidiary entry to the east. The west and north sides shared with adjoining property have high wall with chain link fencing.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved space around the building and compound wall. Landscaping in the form of plants and shrubs along the boundary wall. Old trees also line the main street front to the south.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through door and window openings also supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation through door & windows openings in verandas also supplemented by fans and Air-conditioner to some staff rooms.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Window unit air-conditioner in a few rooms.	
0.0		Condition	
9.0 9.1	Plinth	Fair condition of plinth since repair work carried out and high level of maintenance	
		observed.	
9.2	Walls	Fair - Walls seemed in fairly good condition due to renovation work, including stone dressing, cleaned and repaired.	
9.3	Floor	Fair - No evident damage observed, floor finish renovated throughout the building.	
9.4	Stairs	Fair condition and well maintained. Polish work to wooden staircase carried out.	
9.5	Openings	Fair condition.	
9.6	Roofing	Fair - Though renovated and restrenghtened, retains the original form intact and in good condition.	
9.7	Articulation & Finishes	Fair - Stonewall surfaces in fair condition since renovation carried out. Interior surfaces we plastered and periodically painted. Furniture and railings polished, painted and maintained.	
9.8	Services Out Duildings	Fairly maintained and systematic lay-out of electrical, plumbing and fire fighting equipment	
9.9 9.10	Out Buildings Overall Conditions	No out buildings. Good Maintenance level: Good	
10.0		Transformation	
	Form	Original form retained in addition to which extension wing planned. Wooden entrance porc seems to be a later addition.	
	Structure	An additional floor added in the extension building and modification carried out in the top floor of the original stone building. Wooden trusses and roof rebuilt in steel and concrete	
		finished in mangalore tiles.	
	Articulation & Finishes	Stone surface painted in white on alternating courses of arched openings.	
11.0		DP Remarks/ Perceived Threats	
		Secondary school, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available Additional Notes: Designed by John Adams; completed November 1896. Estimate as sanctioned Rs. 162245.	
		Presented 'I I A award for Conservation' in 1998. Named after a prominent citizen, John Connon, chief Presidency Magistrate of Bombay who directed Bombay Gazette and also took keen interest in education for the Anglo-Indian community.	
	Design Research Institute	MMR- Heritage Conservation Society	

Cathedral and John Connon Senior school	215
	References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Internal courtyard with overlooking arched Verandahs dressed in grey stone



Entrance Porch with sloping roof



Marble tablet



Arched openings with alternate black and white voussoirs, louvered ventilator jaliwork, railing



Ceiling above main staircase



Arched Verandah overlooking the back open space

Asian Build	ding		216(c)
		Common Ref No: 216(c)	
		Card No: 295	
27-10		Ward (Part): A (Part II)	- 1) // //
	THE CONTRACT OF A DECK	CS No: 33/1187 (Fort)	II CALL IN IN THACKERSE
			U U U U U U U U U U U U U U U U U U U
	La de tente de la	Plot Area: 872.63 sq m.	J. N. HEREDIA MARG
Service of the		B U Area: -	- MARG
	THE HE SING	Date: 17/02/2005	T I I I I I I I I I I I I I I I I I I I
		Recorded by: Sonal Modak	X A MEY HANNING
		Reviewed by:	I I I I I I I I I I I I I I I I I I I
		Int: Sonal Modak, Arun Wadhwa	Man Win - Min - Man
HEITER		Ext: Sonal Modak, Arun Wadhwa	
		Photo Ref.: 216(c)_Asian building	CC BANABERS
			WILSON
64			WILSON ROAD
			(185)
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Asian Building	
1.2	Earlier Name	Asian Building	
1.3	Built in:	1920's	Extension Date: -
2.0		Access	
2.1	Main	Ramjibhai Kamani Marg – Pedestrian	
			d Dedestrien
2.2	Subsidiary	J.N. Heredia Marg – Pedestrian, Wilson Roa	d - Pedestrian
3.0		Ownership pattern	
3.1	Present	Life Insurance Corporation	
3.2	Past	Asian Insurance Company	
3.3	Status	Owner, Tenant	
0.0	olalao		
4.0		Use	
	Durant		
4.1	Present	Commercial – Offices	
4.2	Past	Commercial – Offices	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	It forms part of the buildings of the Ballard Pi	er along Ramjibhai Kamani Marg maintaining
			gn regulations laid down for the entire Ballard
		Estate. The main access is central from Ram	
5.2	Architectural Description	Planning	J
0.2	7 ioniootara Booonpion	Rectangular in plan and symmetrical about the	ne central axis. Central access from western
			on the front (west) side with pantry and toilet
			aircase is located on rear (eastern) side of the
		building. All floors have almost the same layo	
		Building shares open space with the building	adjacent to it on rear side.
		Features	
		Projecting cornice band at first and third floor	
		Openings have small cornice band acting as	
		Projecting balconies with ornamental cast iro	n railing at first floor level.
		Yellow stone dressed façade, arched or recta	angular architrave openings form prominent
		feature. Slight setback topmost floor.	,
		Style	
		Influence of European Renaissance style fea	tures.
5.3	Intrinsic	-	
5.4		- A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended grade II A.
J. 1	Value (Classification		
	Value Classification		Neconiniendeu grade II A.
6.0	Value Classification		Neconinended grade in A.
6.0		Topography	Recommended grade IrA.
6.0 6.1	Value Classification Floors		
6.1		Topography G + 4 with basement	
		Topography G + 4 with basement Construction	
6.1		Topography G + 4 with basement	
6.1 7.0	Floors	Topography G + 4 with basement Construction	
6.1 7.0 7.1	Floors Plinth	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone.	ators for basement in regular dressed yellow
6.1 7.0	Floors	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone. External walls thick load bearing, Internal non	ators for basement in regular dressed yellow
6.1 7.0 7.1 7.2	Floors Plinth Walls	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone. External walls thick load bearing, Internal nor columns and beams.	ators for basement in regular dressed yellow n load-bearing brick masonry walls with RCC
6.1 7.0 7.1 7.2 7.3	Floors Plinth Walls Floor	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone. External walls thick load bearing, Internal nor columns and beams. Concrete floor slab supported on columns and	ators for basement in regular dressed yellow n load-bearing brick masonry walls with RCC id beams.
6.1 7.0 7.1 7.2 7.3 7.4	Floors Plinth Walls Floor Stairs	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone. External walls thick load bearing, Internal nor columns and beams. Concrete floor slab supported on columns an Open well RCC staircase housing lift shaft in	ators for basement in regular dressed yellow n load-bearing brick masonry walls with RCC nd beams. the central well.
6.1 7.0 7.1 7.2 7.3	Floors Plinth Walls Floor	Topography G + 4 with basement Construction High plinth about 4 ft. to accommodate ventil buff stone. External walls thick load bearing, Internal nor columns and beams. Concrete floor slab supported on columns and	ators for basement in regular dressed yellow n load-bearing brick masonry walls with RCC id beams. the central well. el. Above all are rectangular openings.

Asian Buil	ding	216(c)	
		Windows on first floor are full height to access the step out balconies.	
7.6	Roofing	Timber truss sloping hip roof with AC roofing sheets.	
7.7	Articulation	Floor level Cornice bands, architrave facade openings, console.	
7.8	Finishes	Yellow Kurla stone external stone dressed facades. Internal plaster painted wall surfaces. Varied floor finishes like marble, granite & ceramic tiles observed.	
7.9	Interiors (Movable & Immovable)	- A A A A A A A A A A A A A A A A A A A	
		Immovable	
7.10	Compound/ Fence/ Gate	External walls of the building itself form the boundary, iron gate and fencing with adjoining buildings to secure common open spaces rear side of the building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space on rear side shared with the adjoining building. Trees line the wide road front.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light, supplemented by artificial lighting.	
8.2	Ventilation	Adequate natural ventilation, supplemented by forced ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM - Underground & overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Split and window AC units have been installed.	
9.0		Condition	
9.1	Plinth	Poor – Heavy leakages during high tide in the basement. Plant growth.	
9.2	Walls	Fair – No evident damages observed.	
9.3	Floor	Fair – No evident damages observed.	
9.4	Stairs	Fair – No evident damages observed in main staircase. Service staircase is in totally neglected condition.	
9.5	Openings	Fair – Broken panes. Some of the openings blocked to house window AC units. Mostly all the window shutters have been replaced by aluminum sliding shutters.	
9.6	Roofing	Fair – Corroded steel truss members. Broken AC roofing sheets.	
9.7	Articulation & Finishes	Poor – Plant growth, blackening of stone, dampness, leakages through service pipes.	
9.8	Services	Poor – Cracks in service pipes resulting in leakages and dampness. Haphazard electrical wiring.	
9.9	Out Buildings	Poor – Totally neglected. Unhygienic.	
9.10	Overall Conditions	Fair Maintenance level Poor	
10.0		Transformation	
	Form	-	
	Structure	Addition of mezzanine in some parts of the building.	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 Zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	
		Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.	

Asian Building



Side view with arched and rectangular openings



Buff stone clad front façade with arched and rectangular openings, bands supported on brackets



Projecting balcony with opening band, cast iron railing



Window detail with scroll brackets



Interior view with new modifications

216(c)

Kamani Chan	nbers		216(f)	
		Common Ref No: 216(f)		
and the second se		Card No: 298		
		Ward (Part): A (Part II)	KUNTHASTREET	
- And		CS No: 1186 (Fort Division)		
A ALLAN	BOOM STATE	Plot Area: 2965.09 sq m.	CURRINGHOV ROAD	
		B U Area: -		
		Date: 06/04/2005		
<u></u>	THE SHOOL STORE		MANGALO	
cee it		Recorded by: Sonal Modak	MANGALORE STREET	
		Reviewed by:		
		Int: Permission denied	J.N.HEREDIA MARG	
COFF		Ext: Sonal Modak		
	THE STATE OF STATE	Photo Ref: 216(f)_Kamani Chambers	GALICUTSTREET	
			Location Plan	
1.0		Denomination	Locatori ran	
1.1	Name of Premises	Kamani Chambers		
1.2	Earlier Name	Kamani Chambers		
1.3	Built in:	1900's	Extension Date -	
			· · ·	
2.0		Access		
2.1	Main	R. Kamani Marg – Pedestrian and vehicular		
2.2	Subsidiary	Kumtha Street – Pedestrian, Adi Marzban Pa	th - Pedestrian	
3.0		Ownership pattern		
3.1	Present	Private		
3.2	Past	Private		
3.3	Status	Owner		
3.3	Sidius	Owner		
4.0		Use		
	Dresent			
4.1	Present	Commercial - Offices		
4.2	Past	Commercial - Offices		
4.3	Usage	Daily		
5.0	-	Significance & Value Classification		
5.1	Townscape (Manmade)	Located along a row of buildings on a tree-lined avenue maintaining similar height and features as per urban design regulations laid down for the entire Ballard Estate. The building has central access through a porch with separate entry and exit gates from R. Kamani Marg on eastern side. Part of the first phase of development of this area with the buildings overlooking the eastern waterfront.		
5.2	Architectural Description	Planning The building is rectangular in plan with longer side facing R. Kamani Marg. It is located on a corner plot with roads on three sides and sharing common open spaces with buildings on sides and rear. Large floor heights without any setback or interception generate an urban scale-volume to the building block. All facades being symmetrical in grey undressed regular ashlar masonary with yellow dressed stone accents. Front façade is divided in number of vertical bays with central bay rising higher and side square towers topped with pyramidal sloping roof. Features Front central bay has a projecting porch supported on three lancet arches on columns		
53		with small spires at either corners of the porch. Above a series of distinct arch forms define the bay on upper levels and the top has gable end over three lancet arches. The gable end is crowned by a lion shaped finial. The side elevations have equilateral arched openings in a series. Multi-foil parapets, decorative bands, carved arch springing points, carved spandrels, finials form the important features displayed on the facades. Style Influence of European Renaissance style features.		
5.3	Intrinsic		Decommended mede	
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended grade: II A	
		Tarana		
6.0	<u>Flags</u>	Topography		
6.1	Floors	G + 3, G + 4 partly.		
7.0		Construction		
7.1	Plinth	Medium plinth about 2 ft. 6 inches high in yellow ashlar masonry.		
7.2	Walls	Load bearing ashlar masonry along the periphery, internal space is supported on		

Kamani Cl	hambers	216(f)		
		columns.		
7.3	Floor	Indeterminable		
7.4	Stairs	Indeterminable		
7.5	Openings	Large door/window openings with timber frame and double glazing panels.		
7.6	Roofing	Indeterminable		
7.7	Articulation	Semicircular, pointed lancet and equilateral arched window openings, architrave openings, and pediment atop window opening at first floor.		
7.8	Finishes	Grey stone undressed external wall surfaces and plaster painted internal finishes.		
7.9	Interiors (Movable & Immovable)	Movable -		
		Immovable -		
7.10	Compound/ Fence/ Gate	Separate entry and exit gates defined by decorative stone pillars. Grey ashlar compound wall with MS fencing above.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.		
8.0		Services & Utilities		
8.1	Lighting	Indeterminable		
8.2	Ventilation	Indeterminable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
	Fire Precaution			
8.6		Indeterminable		
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.		
9.0		Condition		
9.1	Plinth	Fair except plumbing interventions along the sides and rear.		
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.		
9.3	Floor	Indeterminable		
9.4	Stairs	Indeterminable		
9.5	Openings	Fair except poor maintenance.		
9.6	Roofing	Indeterminable		
9.7	Articulation & Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wall and floor finishes.		
9.8	Services	Poor – old and neglected plumbing lines to the rear side.		
9.9	Out Buildings	-		
9.10	Overall Conditions	Fair Maintenance Low level		
10.0		Transformation		
	Form	Indeterminable		
	Structure	Indeterminable		
	Articulation & Finishes	Indeterminable		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 zone		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes: - <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.		

Kamani Chambers







Central wing flanked with high gable roof with animal motif at the pinacle



Arched openings with frieze bond



Gate post with decorative frieze band

Nav Bhav	/an	216(g)
		Common Ref No: 216(g)
		Card No: 299
		Ward (Part): A (Part II)
		CS No: 1160 (Fort Division)
		CS No: 1160 (Fort Division)
		B U Area: -
		B U Area: - Date: 06/04/2005 Recorded by: Sonal Modak
		Date: 00/04/2003
	Photography denied	Recorded by: Sonal Modak
		Reviewed by:
		Ext: Sonal Modak Photography permission denied
		Photography permission denied
		MANGALORE STREET
1.0		Denomination
1.1	Name of Premises	Nav Bhavan
1.1	Earlier Name	Nav Bhavan
1.2	Built in:	1920's Extension Date -
1.0	Duilt III.	
2.0		Access
2.0 2.1	Main	Access P. Kamani Mara – Dedactrian and vahiaular
	Main	R. Kamani Marg – Pedestrian and vehicular
2.2	Subsidiary	Kumtha Street - Pedestrian
		Adi Marzban Path - Pedestrian
3.0	-	Ownership pattern
3.1	Present	Central Government of India
3.2	Past	Central Government of India
3.3	Status	Owner
4.0		Use
4.1	Present	Commercial - Offices
4.2	Past	Commercial - Offices
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Located along a row of buildings on a tree-lined avenue maintaining similar height and
		features as per urban design regulations laid down for the entire Ballard Estate.
		The building has central access from R. Kamani Marg on eastern side.
		Part of the first phase of development of this area with the buildings overlooking the
		eastern waterfront.
5.2	Architectural Description	Planning
		The building is rectangular in plan with longer side facing R.Kamani Marg. It is located on
		a corner plot with roads on three sides and sharing common open spaces with buildings
		on sides and rear.
		Large floor heights without any setback or interception generate an urban scale-volume to
		the building block. Symmetrical front façade with rusticated masonary at ground floor
		level.
		Features
		The front façade has plastered and painted two storey high, lonic engaged columns with
		fluting above the ground floor arcade. Upper floors have rectangular window openings
		with plastered architrave bands. Above it is an entablature with cornice band at the top.
		The central bay has a prominent rounded pediment with protruding keystones and
		decorative elements.
		Style
		Influence of European Renaissance style features.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A
6.0		Topography
6.1	Floors	G + 3
7.0		Construction
7.1	Plinth	Medium plinth about 2 ft. 6 inches high in yellow ashlar masonry.
7.2	Walls	Load bearing ashlar masonry along the entire periphery, open internal space is supported
	- Trailo	on columns.
7.3	Floor	Indeterminable

Nav Bhava	1			216(g)	
7.4	Stairs	Indeterminable			
7.5	Openings	Large door/window openings with timber frame and double glazing panels.			
7.6	Roofing	Indeterminable			
7.7	Articulation	Semicircular, pointed lancet and equilateral arched window openings, architrave openings, and pediment atop window opening at first floor.			
7.8	Finishes	Grey stone undressed external wall surfaces	and plaster painted i	internal finishes.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable			
7.10	Compound/ Fence/ Gate	- Separate entry and exit gates defined by dec Grey ashlar compound wall with MS fencing a			
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.			
8.0		Services & Utilities			
8.1	Lighting	Indeterminable			
8.2	Ventilation	Indeterminable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing & Sanitation)	MCGM			
o.ə 8.6	Fire Precaution				
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable Split and window unit air-conditioners.			
9.0		Condition			
9.1	Plinth	Fair except plumbing interventions along the	sides and rear		
9.2	Walls	Fair except planting interventions along the sides and rear. Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.			
9.3	Floor	Indeterminable			
9.4	Stairs	Indeterminable			
9.5	Openings	Fair except poor maintenance.			
9.6	Roofing	Indeterminable			
9.7	Articulation & Finishes	Fair except minor blackening, plant growth a and floor finishes.	and interventions. Po	oor state of internal wall	
9.8	Services	Poor – old and neglected plumbing lines to the	ie rear side.		
9.9	Out Buildings	-			
9.10	Overall Conditions	Fair	Maintenance level	Low	
10.0		Transformation			
	Form	Indeterminable			
	Structure	Indeterminable			
	Articulation & Finishes	Indeterminable			
11.0		DP Remarks/ Perceived Threats			
		Building forms part of C1 zone			
12.0		Additional Notes/ References/ Documents available			
		Additional Notes: - <u>References:</u> NTACH (1990) Preliminary unedited listing of Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND Division of International Thomson Publishing Ballard Estate – A Corporate District (2000) U First.	REINHOLD Visual (Inc.	dictionary of Architecture	

Note: Photography permission denied

Metropoli	itan Magistrate's Court	216(h)		
		Common Ref No: 216(h) Card No: 300 Ward (Part): A (Part II) CS No: 1159 (Fort Division) Plot Area: 2050.74 sq m B U Area: - D u Area: -		
		Ward (Part): A (Part II)		
		CS No: 1159 (Fort Division)		
		Plot Area: 2050.74 sq m		
		B U Area: -		
	Photography denied	Date: 06/04/2005		
	Filotography defiled	Recorded by: Sonal Modak		
		Reviewed by: Int: Permission denied		
		Int: Permission denied		
		Photography permission denied		
		Photo Ref: -		
		Location Plan		
.0		Denomination		
.1	Name of Premises	Metropolitan Magistrate's Court		
.2	Earlier Name	Magistrate Building		
.2	Built in:	1890 Extension -		
.5	Duit III.	Date		
		Date		
0				
.0	Main	Access		
.1	Main	R. Kamani Marg – Pedestrian and vehicular		
2.2	Subsidiary	Goa Street - Pedestrian		
		Vaju Kotak Marg - Pedestrian		
.0		Ownership pattern		
.1	Present	Central Railway		
.2	Past	Indeterminable		
.3	Status	Indeterminable		
.0		Use		
.1	Present	Commercial – Offices, Institutional – Metropolitan Magistrate's Courts		
.2	Past	Commercial - Offices		
.3	Usage	Daily		
-				
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	Located along a row of buildings on a tree-lined avenue maintaining similar height and		
	(maninado)	features as per urban design regulations laid down for the entire Ballard Estate.		
		The building has central access through a porch with separate entry and exit gates from		
		R. Kamani Marg on eastern side.		
		Part of the first phase of development of this area with the buildings overlooking the		
		eastern waterfront.		
5.2	Architectural Description	Planning		
		Building has rectangular plan with central wooden porch and symmetrical front facade		
		Building has four tower like turrets at four corners with a pediment like feature on the from		
		façade. An external staircase on front facade from second floor to the south-east tower.		
		Rectangular openings with prominent keystones seen at the towers.		
		There are cornice bands at all floor levels.		
		Features		
		Building has four tower like turrets at four corners with a pediment like feature on the from		
		façade. A series of semicircular arches in yellow stone with prominent keystones.		
		Corridors run along the length on front façade.		
		Balustrade parapet at terrace level.		
		Style		
		Influence of European Renaissance style features.		
.3	Intrinsic	-		
.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A		
.0		Topography		
.1	Floors	G + 2		
.0		Construction		
.1	Plinth	Medium plinth about 2 ft. 6 inches high in grey ashlar masonry.		
.2	Walls	Indeterminable		
.2	Floor	Indeterminable		
. <u>.</u> .4	Stairs	Indeterminable		
.4 7.5	Openings	Large arched door/window openings with timber frame and double glazing panels.		

Metropolit	tan Magistrate's Court	216(h)			
7.6	Roofing	Indeterminable			
7.7	Articulation	Semicircular arched window openings, arcade along the corridors and pediment atop tower like turrets.			
7.8	Finishes	Grey stone undressed external wall surfaces and plaster painted internal finishes.			
7.9	Interiors (Movable & Immovable)	Novable - Immovable			
		-			
7.10	Compound/ Fence/ Gate	Presence of front open space. Separate entry and exit gates defined by decorative stone pillars. Grey ashlar compound wall with MS fencing above.			
7.11	Curtilage/ Unbuilt space/ Out Buildings/Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.			
8.0		Services & Utilities			
8.1	Lighting	Indeterminable			
8.2	Ventilation	Indeterminable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing & Sanitation)	MCGM			
8.6	Fire Precaution	Indeterminable			
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.			
9.0		Condition			
9.1	Plinth	Fair except plumbing interventions along the sides and rear.			
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.			
9.3	Floor	Indeterminable			
9.4	Stairs	Indeterminable			
9.5	Openings	Fair except poor maintenance.			
9.6	Roofing	Indeterminable			
9.7	Articulation & Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wall and floor finishes.			
9.8	Services	Poor – old and neglected plumbing lines to the rear side.			
9.9	Out Buildings	-			
9.10	Overall Conditions	Fair Maintenance Low level			
10.0		Transformation			
	Form	Indeterminable			
	Structure	Indeterminable			
	Articulation & Finishes	Indeterminable			
11.0		DP Remarks/ Perceived Threats			
		Building forms part of C1 zone			
12.0		Additional Notes/ References/ Documents available Additional Notes:			
		- <u>References:</u> NTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.			

Note: Photography permission denied

Contractor	Building	216 (a)		
	Sector Sector	Common Ref No: 216 (a)		
le l		Card No: 293 Ward (Part): A (Part II) CS No: 41/1187 (Fort Division) Plot Area: - 892.86 sq m. B U Area: - Date: 23/03/05. Recorded by: Zankhana Prajapati Reviewed by: Int: Zankhana Prajapati, Prachi Merchant		
		Plot Area: - 892.86 sq m.		
		BUArea: -		
		Date: 23/03/05.		
		Recorded by: Zankhana Prajapati Reviewed by:		
		Reviewed by:		
		Ext: Zankhana Prajapati, Prachi Merchant		
1		Ext: Zankhana Prajapati, Prachi Merchant Photo Ref: 216(a)_Contractor Building		
5h	Interconversion statistics aver			
1	1 . The	Location Plan.		
1.0		Denomination		
1.1	Name of Premises	Contractor Building		
1.2	Earlier Name	Contractor Building		
1.3	Built in:	1922 (from tablet on front elevation) Extension Date: -		
2.0		A		
2.0 2.1	Main	Access Ramjibhai Kamani Marg.		
2.1	Subsidiary	Currimbhoy Road.		
L.L				
3.0		Ownership pattern		
3.1	Present	Private.		
3.2	Past	Indeterminable		
3.3	Status	Owner/Tenant		
4.0		Use		
4.1	Present	J.L. Morrison Ltd., Lionel Edwards Ltd., Ameer Trading Co. Ltd., District special Auditors		
		and Prudential ICICI Asst. Management Co.		
4.2	Past	Offices		
4.3	Usage	Daily.		
5.0		Significance & Value Classification		
5.0 5.1	Townscape (manmade)	It is a corner building at the junction of Ramjibhai Kamani Marg and Currimbhoy Road.		
0.1	(maninade)	The main access to the building is from center.		
		It is marked by pediment on top and has common features as of other buildings in Ballard		
		Estate.		
5.2	Architectural Description	Planning		
		The building has a rectangular plan.		
		The building is ground plus three storied high with basement and terrace.		
		Entrance of the building is from Ramjibhai Kamani Marg, from the center, which leads to staircase and lift block. Front has verandahs on both sides behind which offices are		
		located. The toilet block is located in rear.		
		All floors have offices. Basement -J.L. Morrison Ltd., ground - Lionel Edwards Ltd., first -		
		Ameer Trading Co. Ltd., second - District special Auditors and third - Prudential ICICI Asst.		
		Management Co.		
		Features		
		It is a symmetrical building with nine bays with the central one being the staircase shaft.		
		Entry is marked by semicircular arched opening with heavy panel wooden door and colored		
		glass ventilator above. Has continuous balcony at first and third floor levels; part projecting balcony on second floor. They are supported on decorative brackets; terrace is defined by		
		cornice band and parapet wall with pediment, which has festoon and pilasters, over central		
		bay. All the openings in front and side are segmental opening while the rear have		
		rectangular opening.		
		Style		
F 0	1.1.2	Building displays characteristics of Neo-Classical style.		
5.3	Intrinsic Value Classification	- (arc) P(par) P(das) P(juj) E E C(arc) Decomposided stadel II A		
5.4		A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A		
6.0		Topography		
6.1	Floors	G + 3, terrace and basement.		
7.0		Construction		
7.1	Plinth	Medium height stone plinth with edging for plinth protection, which has ventilators for		
		basement.		

Contractor	Building	216 (a)	
7.2	Walls	Composite wall with external stone fascia and internal plastered and painted. Internally	
		floor is supported by cast iron columns.	
7.3	Floor	Jack arch flooring.	
7.4	Stairs	The main staircase is wooden C-shaped with lift block in well. It has wooden decorative balusters with wooden handrail.	
7.5	Openings	All doors are in segmental arch openings with single or double leaf wooden shutter. All windows are segmental arch openings in front and side elevations, while rectangular opening in rear. They are four leaf-glazed shuttered. It has a continuous balcony projection on first and third floor and part projection on second floor.	
7.6	Roofing	Flat terrace.	
7.7	Articulation	Pediment with festoon and pilasters, cornice and decorative brackets.	
7.8	Finishes	External walls stone ashlar masonry.	
1.0		Internal walls are plastered and painted. Tiling is varied but largely of cement tiles.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	- Heavy panel wooden entrance door.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Have rear and side open space.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric ligh fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	AC units.	
9.0		Condition	
9.1	Plinth	Poor – leakage, extensive seepage, covered with earth and broken edging.	
9.2	Walls	Fair - plant growth and rear façade plastered and painted.	
9.3	Floor	Fair - Good condition and most of the places covered with false ceiling.	
9.4	Stairs	Fair – dust accumulation, new decorative dado wall, rusting of grill around lift block.	
9.5	Openings	Poor - grills added, opening are closed, frames painted, transformed, addition of window AC units.	
9.6	Roofing	Indeterminable.	
9.7	Articulation & Finishes	Fair - Arches of ground floor are covered. Internal Plaster and paint peeling off at certain places. External cement pointing is done and rear is plastered and painted. Tiling is maintained.	
9.8	Services	Poor - Broken sewage pipes, leakage, unhygienic and has plant growth.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair. Maintenance level: Poor.	
10.0	Form	Transformation	
	Form	-	
	Structure	Indeterminable.	
	Articulation & Finishes	Arches blocked by hoardings, addition of grills and painted wall surface.	
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone	
		•	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.	

Contractor Building



Front façade with projecting balconies supported on brackets



View of building with modifications made to the arched window opening shutters



Wooden staircase with wooden railing, ceramic tile dado



Side view with arched window openings, bands, modified shutters to take in services



Entrance arched opening with receding arched bands, coloured glass ventilator panel wooden paneled shutters

216 (a)

		Common Ref No: 216(b)	1 // / / / / / / / / / / / / / / / / /
		Card No: 294	
		Ward (Part): A (Part II)	CONTRACTOR BUILDING
		CS No: 38/1187 (Fort Division)	T 1.0 C
1	MILL THE THE AND	Plot Area: 1373.10 sq m.	
44 NUTE	A AND A AND AND AND AND AND AND AND AND	B U Area: -	CURRIMBHOY MARG
Stored a		Date: 06/04/2005	NA MARA
ALL		Recorded by: Sonal Modak	
40.00		Reviewed by:	Colone
		Int: Permission denied	Here House
1. 1. 1. 1.		Ext: Sonal Modak	RAM.
	- 245 - 10 AL - AL - AL - AL	Photo Ref: 216(b)_Neville House	1 CC
			J. N. HEREDIA MARG
1.0		Denomination	
1.1	Name of Premises	Neville House	
1.2	Earlier Name	Neville House	
1.3	Built in:	1920	Extension Date: -
2.0		Access	
2.1	Main	Currimbhoy Marg and J. N. Heredia Marg	
2.2	Subsidiary	R. Kamani Marg	
-			
3.0		Ownership pattern	
3.1	Present	Indeterminable	
3.2	Past	Indeterminable	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Commercial - Offices	
4.2	Past	Commercial - Offices	
4.3			
1.0	Usage	Daily	
5.0		Significance & Value Classification	
5.0 5.1	Townscape (Manmade)	Significance & Value Classification Located along a row of buildings on a tree-lin	and avenue maintaining similar baight and
-		features as per urban design regulations laid d It is accessed through semicircular arch openin Main access is from Currimbhoy Marg on so triangular canopy in stone.	lown for the entire Ballard Estate. ngs from the three sides facing roads.
5.2	Architectural Description	Planning Rectangular corner building with three sides common open spaces with buildings on sides setback or interception generate an urban scal All facades being symmetrical in yellowish regi Features Central Entrance defined by Tuscan pilaster canopy in stone. Semicircular arched opening ground floor level and rectangular openings or Side bays of all façades have rectangular win triangular pediment. Rectangular openings having projecting sills al Continuous cornice bands at first and third floor Style Influence of European Renaissance style features	s and rear. Large floor heights without any le-volume to the building block. ular stone dressed rusticated masonary. rs and a projecting cantilevered triangula gs with prominent decorative keystones on a upper floors. dow openings at first floor level with simple nd lintels on first and second floors. or level.
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended II A grade:
6.0		Topography	
6.0	Flooro	Topography	
	Floors	G + 4 with basement	
6.1			
		a <i>i i</i>	
7.0		Construction	
	Plinth	Construction High plinth about 4 ft high to accommodate masonry.	ventilators for basement in yellow ashla

Neville Ho	use	216(b)		
		supported on columns.		
7.3	Floor	Indeterminable		
7.4	Stairs	Indeterminable		
7.5	Openings	Large door/window openings with timber frame and double glazing panels.		
7.6	Roofing	Indeterminable		
7.7	Articulation	Semicircular and flat arch window openings, architrave openings, and pediment atop window opening at first floor.		
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted internal finishes.		
7.9	Interiors (Movable & Immovable)	Novable		
		- Immovable -		
7.10	Compound/ Fence/ Gate	No compound wall, only an Iron gate enclosing the common open space along both the sides.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.		
8.0		Services & Utilities		
8.1	Lighting	Indeterminable		
8.2	Ventilation	Indeterminable		
8.3	Electricity	BEST		
	Water Supply	MCGM		
8.4 8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution			
8.7	Other (HVAC/BMS/Security Systems)	Split and window unit air-conditioners.		
9.0		Condition		
9.1	Plinth	Fair except plumbing interventions along the sides and rear.		
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.		
9.3	Floor	Indeterminable		
9.4	Stairs	Indeterminable		
9.5	Openings	Fair except poor maintenance.		
9.6	Roofing	Indeterminable		
9.7	Articulation & Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wal and floor finishes.		
9.8	Services	Poor – old and neglected plumbing lines to the rear side.		
9.9	Out Buildings	-		
9.10	Overall Conditions	Fair Maintenance Low level		
10.0		Transformation		
10.0	Form	Indeterminable		
	Structure	Indeterminable		
	Articulation & Finishes	Indeterminable		
44.0		DD Damaster / Damaster of There she		
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes: - <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.		



Front façade with arched and rectangular window openings, bands




Projecting stone canopy with sloping roof



Arched openings with scroll bracket keystone, sill and floor level bands



Entrance on longer façade with rusticated joints, pilasters, bands



Buff stone clad side façade with rectangular openings



Window with sill band, pediment

	eamen's Society and Bombay Seamen's	s Club 216 (d)	
		Common Ref No: 216 (d)	
		Card No: 296	
		Ward (Part): A (Part II)	
Marcine Con		CS No: 1/1095 (Fort Division) Plot Area: Indeterminable B U Area: - Date: 17/02/05 Recorded by: Prachi Merchant Reviewed by: Int: Prachi Merchant, Zankhana Prajapati Ext: Prachi Merchant, Zankhana Prajapati	
Ser.		Plot Area: Indeterminable	
10 M		B U Area: -	
		Date: 17/02/05	
1.	AL BOWBAY SEAMEN'S SOCIETY	Recorded by: Prachi Merchant	
1		Reviewed by:	
and a		Int: Prachi Merchant, Zankhana Prajapati	
Ser.	CAULT CONTRACTOR	Ext: Prachi Merchant, Zankhana Prajapati	
		Photo Ref.: 216(d)_Bombay Seamen's	
		Society and Bombay Seamen's Club	
1.0		Denomination	
1.1	Name of Premises	Bombay Seamen's Society and Bombay Seamen's Club	
1.2	Earlier Name	Prince of Wales Seamen's society	
1.3	Built in:	1921 Extension Date: -	
2.0		Access	
2.1	Main	R. Kamani Marg - pedestrian	
2.2	Subsidiary		
L.L			
3.0		Ownership pattern	
3.1	Present	Royal Bombay Seamen's Society	
3.2	Past	The Bombay Diocesan Trust Association Ltd. As custodian Trustee and Others	
3.3	Status	Owner	
0.0			
4.0		Use	
4.1	Present	Guest and clubhouse for Merchant Navy Officers.	
4.2	Past	Guest and clubhouse for Merchant Navy Officers.	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (Manmade)	The plot is located on R. Kamani Marg along with other buildings of different styles of	
		architecture. The building forms a part of the Ballard estate precinct.	
		The plot is accessed from the east side through a porch formed by a projecting balcony of	
		the first fleer	
E 0	Architectural Description	the first floor.	
5.2	Architectural Description	Planning	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with arched openings.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric pattern. The arche	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric pattern. The arche opening above the porch is adorned with semicircular pediment. The opening have floral	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with acched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric patterm. The arche opening above the porch is adorned with semicircular pediment. The openings have floral pattern architrave.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The ground floor of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric patterm. The arche opening above the porch is adorned with semicircular pediment. The openings have floral pattern architrave.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The central part of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric pattern. The arche opening above the porch is adorned with semicircular pediment. The openings have floral pattern architrave. The side structures have a mansard roof supported on wooden supporting members. The structure façade has floral pattern.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The central part of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric pattern. The arche opening above the porch is adorned with semicircular pediment. The opening have floral pattern architrave. The side structures have a mansard roof supported on wooden supporting members. The structure façade has floral pattern.	
		Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The central part of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric patterm. The arche opening above the porch is adorned with semicircular pediment. The openings have floral pattern architrave. The side structures have a mansard roof supported on wooden supporting members. The structure façade has floral pattern. Style Building derives influence from Vernacular style of Architecture.	
5.2	Architectural Description	Planning The building is rectangular in shape enclosing a rear courtyard with its shorter side facing the east side. The building is accessed through a rectangular opening, leading to a lobby with a staircase area, with rooms lined on either side of the central bay. The east side wing has balconies overlooking the main road. The main building is taller than the two single storey structures on either side. The servant wing and the service staircase are located at the west corner. The ground floor houses the office, club shop, canteen and kitchen area and bar area, opening into an outdoor seating area. Rooms consisting of dormitories, single and double rooms and family rooms, can be found on the upper floors. The topmost floor has a terrace space on the west side. The side single storey structures have a church and library on the east side. West side structure houses a multipurpose hall. Features The central part of the main and side structures are clad with buff basalt rusticated masonry with arched openings. The central part of the main building is emphasized with circular steps and a circular projecting balcony with decorative stepped bands above and geometric pattern. The arche opening above the porch is adorned with semicircular pediment. The opening have floral pattern architrave. The side structures have a mansard roof supported on wooden supporting members. The structure façade has floral pattern.	

	eamen's Society and Bombay Seamen's C Value Classification			
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended II A arade		
6.0		Topography		
6.1	Floors	G + 3 (4th floor added later), Side ground structures.		
7.0		Construction		
7.1	Plinth	Low height buff stone plinth with curved steps leading to the building.		
7.2	Walls	Load bearing brick wall.		
7.3	Floor	RCC slab and beam structure.		
7.4	Stairs	Main and rear doglegged RCC staircase.		
		Cast iron spiral fire escape staircase on the south side.		
7.5	Openings	Ground floor arched openings with ventilators.		
	- F - 5-	Rectangular openings with glazed paneled shutter.		
		Side structures with louvered paneled shutters.		
7.6	Roofing	Rear portion with sloping roof on sides over rooms with central flat portion.		
		Front sloping roof over family rooms.		
		Mansard roof with sheet coverings, supported on wooden supporting members.		
7.7	Articulation	Projecting balconies, arched openings, bands, floral pattern motifs and pediments.		
7.8	Finishes	Walls are externally clad with buff stone. Internally walls are finished with plaster and pa		
1.0		The floor has kotah and IPS floor finish and wooden floor finish at places.		
7.9	Interiors (Movable & Immovable)	Movable		
1.5		Wooden benches, chairs, billiards room high chair.		
		Immovable		
		-		
7.10	Compound/ Fence/ Gate	Low stone fence on sides. The building directly opens into the road with an approach		
1.10	Compound/ Fence/ Gale			
7 1 1	Custilage / Uphuilt appage / Out Duildinge /	footpath. Main gate is not present.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Front has landscaped lawn with few old trees.		
	Landscape			
8.0		Services & Utilities		
8.1	Lighting	Adequate natural light through openings, supplemented by electric light fixtures.		
8.2	Ventilation	Adequate natural ventilation through openings supplemented by electric fans, AC's.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution			
8.7	Other (HVAC/BMS/Security Systems)	Air conditioning units have been installed in the rooms.		
		Manual security at the entrance.		
9.0		Condition		
9.1	Plinth	Fair – Water seepage marks are observed on the front side.		
9.2	Walls	Fair – Loose plaster and cracks observed.		
9.3	Floor	Fair		
9.4	Stairs	Fair – some parts are in a deteriorating state.		
9.5	Openings	Poor – Openings have been blocked to accommodate air conditioners. Grills have been		
0.0	openinge	added to the windows and shutters have been changed. <i>Chajjas</i> have been replaced.		
		South side servants' wing openings have been blocked.		
9.6	Roofing	Fair		
9.7	Articulation & Finishes	Fair		
9.7	Services	Poor - Pipes are added in a haphazard manner.		
9.9	Out Buildings	Fair		
9.10	Overall Conditions	Fair Maintenance level Fair		
40.0		Transformation		
10.0		Transformation		
	Form			
	Structure	South side façade has major alterations like wall additions.		
	Articulation & Finishes	Openings are blocked; opening size and shutters have been changed; grills have been		
		added.		
		Verandah openings have been blocked.		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 Zone		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		The St Nicholas Church and Seamen's Recreation Rooms were originally situated oppo		

Nombay Seamen's Society and Bombay Seamen's Club 216 (
	James Fergusson laid the foundation stone for the church in 1883. It was opened for service in the following year and consecrated in 1885. The Seamen's Recreation Rooms comprising a spacious building adjoining the Church was opened in 1886. In earlier times, each Saturday concerts were held in the Rooms, which were also equipped with a Library and Reading Room. <u>References</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) <i>City Map – Mumbai</i> , Mumbai. <i>Ballard Estate – A corporate District</i> (2000) Urban Design Research Institute and Bombay First.			



Façade of ball room portion with ground floor with rusticated joints, sloping roof, arched openings, pediment, floral motifs



Arched windows with rusticated joints



Tablet 2



Interior of chapel with wooden sloping roof along with dormer windows



Entrance with curved projecting balcony with decorative opening band



Side view with dormer windows





Old wooden furniture in the chapel

Common Ref No. 216(a) Ward (Part, A (Part, II) Vex of (Part, A (Part, II) Pick Area: 167, 28 sgm. Date: 230303 Pick Area: 167, 28 sgm. Date: 230303 Date: 230303 Pick Area: 167, 28 sgm. Date: 230303 Pick Area: 167, 28 sgm. Date: 230304 Pick Area: 160, Ondon Mechant Reviewed by: Pick Mechant, Zankhana Praggat Date: 230304 Pick Mechant, Zankhana Praggat Date: 200 Demonination Date: 1600, Indon Mecanile Chambers Date: 17000 Date: 17000 Date: 17000 Date: 17000 Date: 170000 Date: 1700000 Date: 170000000 Date: 17000000000000000000000000000000000000	Indian Mercar	ntile Chambers		216(e)	
Ward (Parth, I) (Part II) Project (Parth, Parth) Project (Parth, Parth) Project (Parth, Parth, Parth, Parth) Project (Parth, Parth, Part			Common Ref No: 216(e)		
G No. 113 Figure 103 Segme B U Area: 167 39 sgm. B U Area: 167 39 sgm. B U Area: 162 30305 Recorded by Prachi Merchant. B U Area: 167 20 sgme Decomination L E Larder Name Indian Mecantile Chambers 1.3 Butin n: 1900's 2.4 Main R. Kameni Marg 2.2 Subsidiary - 3.3 Desent Private Owner 3.4 Present Private Owner 3.5 Present Commercial 4.1 Present Commercial 4.2 Past Commercial 5.1 Townscape (Manmade) Morriship pattern 5.1 Townscape (Manmade) Morriship address reservers 5.2 Architectural Description Significance & Value Classification 5.1 Townscape (Manmade) Morrimetoial 5.2					
Piol Area: 147:39 sgm. Date: 230306 Date: 230306 Date: 230306 Point Area: 147:39 sgm. Date: 230:3036 Point Area: 147:39 sgm. Date: 230:3036 Point Area: 147:39 sgm. Date: 230:3036 Point Area: 147:59 sgm. Date: 11: Name: Area: 147:59 sgm. Date: 11: Date: 12: Date: 12: Date: 12: Date: 12: Date: 12: Date: 12:<				Manual And	
B U Aces. Dere 230305 Recorded by: Prach Merchant. Present Present. Present. Ownership pattern Status Ownership attern Status Ownership		Annual Ban and Bank Annual Annual Annual Annual Annual			
Detr. 230305 Excorded by, Prach Merchant, Zankhana Prajapati In: Peach Merchant, Zankhana Prajapati The Pach Merchant, Zankhana Prajapati Charles Denomination 10 Name of Premises Indian Mecanitic Chambers 12 Eafrer Name Indian Mecanitic Chambers 13 Built in: 13 Built in: 14 Access 21 Statistic Chambers 13 Built in: 14 Present 15 Built in: 16 Ownership pattern 17 Present 18 Private Owner 19 Owner 10 Use 11 Present 12 Past 14 Use 15.1 Townscape (Mammade) 16 Significance & Value Classification 17.1 Townscape (Mammade) 18.2 Past 19.3 Significance & Value Classification 1.1 Townscape (Mammade)				MANGALORE OF	
Chambers Chambers Location Plan 10 Denomination Location Plan 11 Name of Premises Indem Mercantile Chambers Location Plan 12 Earlier Name Indem Mercantile Chambers Extension Date - 13 Butt In: 1900's Extension Date - 20 Access - - - 21 Main R. Kamani Marg - - - 22 Subsidiary - - - - - 30 Ownership pattern -					
Chambers Chambers Location Plan 10 Denomination Location Plan 11 Name of Premises Indem Mercantile Chambers Location Plan 12 Earlier Name Indem Mercantile Chambers Extension Date - 13 Butt In: 1900's Extension Date - 20 Access - - - 21 Main R. Kamani Marg - - - 22 Subsidiary - - - - - 30 Ownership pattern -				J.N.HEN	
Chambers Chambers Location Plan 10 Denomination Location Plan 11 Name of Premises Indem Mercantile Chambers Location Plan 12 Earlier Name Indem Mercantile Chambers Extension Date - 13 Butt In: 1900's Extension Date - 20 Access - - - 21 Main R. Kamani Marg - - - 22 Subsidiary - - - - - 30 Ownership pattern -					
Chambers Chambers Location Plan 10 Denomination Location Plan 11 Name of Premises Indem Mercantile Chambers Location Plan 12 Earlier Name Indem Mercantile Chambers Extension Date - 13 Butt In: 1900's Extension Date - 20 Access - - - 21 Main R. Kamani Marg - - - 22 Subsidiary - - - - - 30 Ownership pattern -				CALICUTET	
Chambers Chambers Location Plan 10 Denomination Location Plan 11 Name of Premises Indem Mercantile Chambers Location Plan 12 Earlier Name Indem Mercantile Chambers Extension Date - 13 Butt In: 1900's Extension Date - 20 Access - - - 21 Main R. Kamani Marg - - - 22 Subsidiary - - - - - 30 Ownership pattern -					
10 Denomination 1.1 Name of Premises Indem Mercartile Chambers 1.2 Earlier Name Indem Mercartile Chambers 1.3 Built in: 1900's Extension Date] - 2.0 Access - 2.1 Main R. Kamani Marg - 2.2 Subdiary - - 3.0 Ownership pattern - 3.1 Present Private Owner - 3.3 Situls Owner - 4.0 Use - - 4.1 Present Commercial - 4.2 Past Commercial - 5.1 Townscape (Manmade) Prominent comer building at the junction of R Kamani Marg, Calicul Street and Adi Murchan Pahi. 5.2 Architectural Description Floring is accessed from the south side leading into the entrance lobby and staircase. 5.2 Architectural Description Planning The building is accessed rectangular openings. 5.2 Architectural Description The building is accessed from the south side lead			Photo Ref.: 216(e)_Indian Mecantile	WILSON ROAD	
10 Denomination 11 Name of Premises Indian Mercantile Chambers 12 Earlier Name Indian Mercantile Chambers 13 Bulti n: 1900's Extension Date. 20 Access Extension Date. - 21 Main R. Kamani Marg - - 22 Subsidiary - - - 31 Present Private Owner - - 32 Past Ownership pattern - - - 33 Status Owner - <td< td=""><th></th><td></td><td>Chambers</td><td></td></td<>			Chambers		
10 Denomination 11 Name of Premises Indian Mercantile Chambers 12 Earlier Name Indian Mercantile Chambers 13 Bulti n: 1900's Extension Date. 20 Access Extension Date. - 21 Main R. Kamani Marg - - 22 Subsidiary - - - 31 Present Private Owner - - 32 Past Ownership pattern - - - 33 Status Owner - <td< td=""><th></th><td></td><td></td><td>COCHINSTREET</td></td<>				COCHINSTREET	
10 Denomination 11 Name of Premises Indian Mercantile Chambers 12 Earlier Name Indian Mercantile Chambers 13 Bulti n: 1900's Extension Date. 20 Access Extension Date. - 21 Main R. Kamani Marg - - 22 Subsidiary - - - 31 Present Private Owner - - 32 Past Ownership pattern - - - 33 Status Owner - <td< td=""><th></th><td></td><td></td><td></td></td<>					
1.1 Name of Premises Indian Mercantile Chambers 1.2 Earlier Name Indian Mercantile Chambers 1.3 Buil in: 1900's Extension Date - 2.0 Access - 2.1 Main R. Kamani Marg - 2.2 Subsidiary - - 3.0 Ownership pattern - - 3.1 Present Private Owner - 3.2 Past Owner - 3.3 Status Owner - 4.0 Use - - 4.1 Present Commercial - 4.2 Past Commercial - 4.3 Usage Daily - 5.0 Significance & Value Classification - - 5.1 Townscape (Mammade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Murzban Path. - 5.2 Architectural Descripton The building is accessed from the south side leading into the entrance lobby and staircase. 5.4 Architectural Descripton The tous thave been occipited	1.0		Denomination	Location Plan	
1.2 Earlier Name Indian Mercantile Chambers 1.3 Built in: 1900's Extension Date] - 2.0 Access . 2.1 Main R. Kamani Marg . 2.2 Subsidiary - . 3.0 Ownership patem . . 3.1 Present Private Owner . 3.3 Status Owner . 4.0 Use . . 4.1 Present Commercial . 4.2 Past Commercial . 4.3 Usage Daily . 5.0 Significance & Value Classification . 5.1 Townscape (Manmade) Prominent comer building at the junction of R Kamani Marg. Calcut Street and Adi Murzban Path. 5.2 Architectural Description Planning The building is accessed from the R Kamani Marg. Calcut Street and Adi Murzban Path. All the floors have been occupied for office purposes. Features The building is accessed from the south side leading into the entance lobby and staircase. 5.2 Architectural Description The transin Ada the side bays margina		Name of Premises			
1.3 Built in: 1900's Extension Date: - 2.0 Access 2.1 Main R. Kamani Marg 2.2 Subsidiary - 3.0 Ownership pattern 3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both side so the cornel anys have double height Doit columns with high square base and descorative certain anys have double height Doit columns with high square base and descorative capinage. The building is accessed from the spenings have and proceing architrave band. The string projecting bands and cornice bands. Style 5.3 Intrins					
2.1 Main R. Kamani Marg 2.2 Subsidiary - 3.0 Ownership pattern 3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Muzzban Path. 5.2 Architectural Description Planning 5.2 Architectural Description Planning 7 The building is accessed from the R Kamani Marg. The building portic out with geometric motifs on the parapet. All the floors have been occupied for floe purposes. Features The building of coms ap and of the Ballard Estate precinct. 5.2 Architectural Description Planning The building of coms ap and of the ballard project out with geometric motifs on the parapet. All the floors have been occupied for floe purposes. Features The building openings. The openings have a projecting anchitrav				Extension Date: -	
2.1 Main R. Kamani Marg 2.2 Subsidiary - 3.0 Ownership pattern 3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Muzzban Path. 5.2 Architectural Description Planning 5.2 Architectural Description Planning 7 The building is accessed from the R Kamani Marg. The building portic out with geometric motifs on the parapet. All the floors have been occupied for floe purposes. Features The building of coms ap and of the Ballard Estate precinct. 5.2 Architectural Description Planning The building of coms ap and of the ballard project out with geometric motifs on the parapet. All the floors have been occupied for floe purposes. Features The building openings. The openings have a projecting anchitrav				· · ·	
2.2 Subsidiary - 3.0 Ownership pattern 3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Ourmercial 4.1 Present Commercial 4.2 Past Ommercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Murzban Path. The building is accessed from the south side leading into the entrance lobby and staircase. The building is accessed from the south side leading into the entrance lobby and staircase. 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on bots sides of the entral lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the folors have been occupied for office purposes. Features The building is accessed inside. The openings have a projecting architrave band. The third foor has rectangular openings. The third foor hase scaland becorative calins.					
3.0 Ownership pattern 3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use		-	R. Kamani Marg		
3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Image: Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. 5.2 Architectural Description Planning 7.1 Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. 5.2 Architectural Description Planning 7 The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. 8 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building is accessed from the south side leading into the entrance lobby and staircase. 7 The contral bay has an elaborate entrance with the openings have a projecting statuante ano	2.2	Subsidiary	-		
3.1 Present Private Owner 3.2 Past Private Owner 3.3 Status Owner 4.0 Use Image: Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg. Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. 5.2 Architectural Description Planning 7.1 Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. 5.2 Architectural Description Planning 7 The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. 8 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building is accessed from the south side leading into the entrance lobby and staircase. 7 The contral bay has an elaborate entrance with the openings have a projecting statuante ano			O		
3.2 Past Private Owner 3.3 Status Owner 4.0 Use Commercial 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. The building is accessed from the R Kamani Marg. The building forms a part of the Balard Estate precinct. 5.2 Architectural Description Planning The building forms a part of the galard Estate precinct. 5.2 Architectural Description The offices are located on both sides of the central loby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The build for oral bays have double height Doric columns with high square base and decorative capitals. The arched openings have a projecting balconies supported on decorative raylard penings. The third floor has projecting balconies supported on decorative bands. Style 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade [II A 6.0 Topography 6.		Dresent			
3.3 Status Owner 4.0 Use 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. 5.2 Architectural Description Planning 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building in a cecased rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The preliment has a medalion motif inside the tympanum. The first and second floor central bays have a projecting activities variant with some base and decorative capitals. The arched openings have a projecting activities variant with some balastrade. 5.3 Intrinsic - 5.4 Value Classification 4(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography <t< td=""><th></th><td></td><td></td><td></td></t<>					
4.0 Use 4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. 5.1 Townscape (Manmade) Prominent corner building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning The building forms a part of the Ballard Estate precinct. The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The building is accessed rectangular openings. The building more and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building corner building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medalion motif inside the tympanum. The first and second floor central bays have a oloble height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are to eased inside. The openings have a projecting architrave band. The third floor has projecting bands and cornice bands.					
4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. 5.2 Architectural Description Planning 7 The obliding is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features 7 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features 7 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The contral bay has an elaborate entrance with the top ending in a pediment. The pediment has a medalion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capilatis. The arched openings have a projecting rachitrave band. The third floor has rectangular openings and geometric motifs within. The third floor has rectangular openings and geometric motifs within. The third floor has rectangular openings and geometric motifs within. T	0.0	otatus	Owner		
4.1 Present Commercial 4.2 Past Commercial 4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. 5.2 Architectural Description Planning 7 The obliding is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features 7 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features 7 The contral and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The contral bay has an elaborate entrance with the top ending in a pediment. The pediment has a medalion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capilatis. The arched openings have a projecting rachitrave band. The third floor has rectangular openings and geometric motifs within. The third floor has rectangular openings and geometric motifs within. The third floor has rectangular openings and geometric motifs within. T	4.0		Use		
4.3 Usage Daily 5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent corner building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. The building is accessed from the Ballard Estate precinct. 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The central and the side bays marginally project out with geometric motifs or with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative bands. Style 5.3 Intrinsic -		Present			
5.0 Significance & Value Classification 5.1 Townscape (Manmade) Prominent comer building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features Features The building former bays and elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the typenings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the typenings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the typenings. The third floor has rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade III A 6.0 Topography Grastruction 7.4 7.0 Construction Architecture 7.4 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.	4.2	Past	Commercial		
5.1 Townscape (Manmade) Prominent comer building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building the central lobby and staircase. The building has nusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography E - - - 6.1 Floors G+4 - - 7.0 Construction<	4.3	Usage	Daily		
5.1 Townscape (Manmade) Prominent comer building at the junction of R Kamani Marg, Calicut Street and Adi Murzban Path. The building is accessed from the R Kamani Marg. The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building the central lobby and staircase. The building has nusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography E - - - 6.1 Floors G+4 - - 7.0 Construction<					
Murzban Path. The building is accessed from the R Kamani Marg. The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Flanning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The buff stone clad corner building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medalion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band. <th></th> <td>To serve (Masses da)</td> <td></td> <td>Kenned Marco Oalia (Oliver) and Adi</td>		To serve (Masses da)		Kenned Marco Oalia (Oliver) and Adi	
5.2 Architectural Description Planning 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The building to the entrance with the top ending in a pediment. The pediment floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The third floor has projecting balconies supported on decorative brackets with stone balaustrade. The third floor has rectangular openings and geometric motifs with. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style 5.3 Intrinsic 5.4 Value Classification 6.0 Topography 6.1 Floors 6.2 G+4 7.0 Construction 7.1 Plinth Normal heig	5.1	Townscape (Manmade)		Kamani Marg, Calicut Street and Adi	
The building forms a part of the Ballard Estate precinct. 5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The building is accessed rectangular openings. The build in side the tympanum. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style 5.3 Intrinsic - 5.4 Value Classification - 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.					
5.2 Architectural Description Planning The building is accessed from the south side leading into the entrance lobby and staircase. The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The build floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography - - - - 6.1 Floors G+4 - - - 7.0 Construction Normal height buff stone clad plinth with plinth protection band. -					
Figure 1 The offices are located on both sides of the central lobby. The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The buff stone clad comer building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The buff stone clad comer building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A Construction Construction <th>5.2</th> <td>Architectural Description</td> <td>Planning</td> <td></td>	5.2	Architectural Description	Planning		
Figure 1 The central and the side bays marginally project out with geometric motifs on the parapet. All the floors have been occupied for office purposes. Features The builf stone clad corner building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative backets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor lave form European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography G+4 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.			The building is accessed from the south side I	eading into the entrance lobby and staircase.	
All the floors have been occupied for office purposes. Features The buff stone clad corner building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative backets with stone balustrade. The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade 6.0 Topography 6.1 Floors 7.0 Construction 7.1 Plinth			The offices are located on both sides of the ce	entral lobby.	
Features The buff stone clad corner building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative brackets. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors 7.0 Construction 7.1 Plinth			I he central and the side bays marginally proje	ect out with geometric motifs on the parapet.	
Fine buff stone clad comer building has rusticated joints with curved edges in the ground floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative bands. Style The building derives influence from European Renaissance style of Architecture. - 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography - - - 6.1 Floors G+4 - - 7.0 Construction Normal height buff stone clad plinth with plinth protection band. -				rposes.	
floor with recessed rectangular openings. The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative brackets. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade 11 A Plinth 7.0 Construction 7.1 Plinth				ated joints with curved edges in the ground	
Figure 1 The central bay has an elaborate entrance with the top ending in a pediment. The pediment has a medallion motif inside the tympanum. The first and second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors 7.0 Construction 7.1 Plinth					
Find the second floor central bays have double height Doric columns with high square base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth				th the top ending in a pediment. The pediment	
base and decorative capitals. The arched openings with prominent keystone and rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth					
Final State rectangular openings are recessed inside. The openings have a projecting architrave band. The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth					
The third floor has projecting balconies supported on decorative brackets with stone balustrade. The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth					
balustrade. The third floor has rectangular openings and geometric motifs within. The third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth					
The third floor has rectangular openings and geometric motifs within. The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth					
The first and third floor levels are defined by projecting bands and cornice bands. Style The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.				geometric motifs within.	
The building derives influence from European Renaissance style of Architecture. 5.3 Intrinsic 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 7.0 Construction 7.1 Plinth			The first and third floor levels are defined by p		
5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 Construction 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.					
5.4 Value Classification A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended grade II A 6.0 Topography 6.1 Floors G+4 Construction 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.	5.0	1.1.2	The building derives influence from European	Renaissance style of Architecture.	
6.0 Topography 6.1 Floors 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.			$- \frac{1}{2} \left(\frac{1}{2} - \frac{1}{2} \right) \left(\frac{1}{2} - \frac{1}{$	Decommonded credel II A	
6.1 Floors G+4 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.	5.4		A(a(c), D(per), D (ues), B (uu), E, F, G(grp)	Recommended grade II A	
6.1 Floors G+4 7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.	6.0		Topography		
7.0 Construction 7.1 Plinth Normal height buff stone clad plinth with plinth protection band.		Floors			
7.1 Plinth Normal height buff stone clad plinth with plinth protection band.	-				
	7.0		Construction		
	7.1	Plinth	Normal height buff stone clad plinth with plinth	protection band.	
7.2 Walls Load bearing thick walls	7.2	Walls	Load bearing thick walls		

	cantile Chambers	216(
7.3	Floor	RCC slab and beam structure
7.4	Stairs	Main open well wooden staircase with lift in the center, with a wooden newel post, wooden
7.5		steps, soffit, railing and lift paneling.
7.5	Openings	Ground floor full height rectangular openings with glazed paneled shutter.
		First floor semi circular arched opening with keystone emphasized and upper floor
		rectangular openings with glazed paneled shutters.
7.0	Desfer	Internal doors with high double paneled shutters.
7.6	Roofing	Flat RCC terrace roof
7.7	Articulation	Projecting cornice bands, stone brackets, arched openings with prominent keystone, dorid
7.0		columns with elaborate capital.
7.8	Finishes	Walls are clad with buff stone.
		The floors are finished with natural stone.
7.9	Interiors (Movable & Immovable)	Movable
		-
		Immovable
7 10	Compound/Fonce/Cate	- Front MC forging on the either eide of the control how
7.10	Compound/ Fence/ Gate	Front MS fencing on the either side of the central bay.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Trees with tree guard on paved footpath area.
	Landscape	
		Complete 0 H4H41a
8.0		Services & Utilities
8.1	Lighting	Natural lighting through openings supplemented with artificial lighting.
8.2	Ventilation	Natural ventilation through openings supplemented with artificial ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire Hydrants have been installed in the lobby area.
8.7	Other (HVAC/BMS/Security Systems)	Individual office spaces have AC's installed according to individual requirement.
		Strict manual security.
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair – Wood treads and risers have been changed.
9.5	Openings	Poor - Openings have been blocked to house AC's, shutters have been changed.
		Front side openings have been blocked by hoardings. Grills and <i>jalis</i> have been added.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Poor – features are blackened, broken bands.
9.8	Services	Poor - the rear side is not maintained and services have been added haphazardly.
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level Poor
0.10		
10.0		Transformation
	Form	Fourth floor has been added later.
	Structure	Indeterminable
	Articulation & Finishes	Openings have been blocked. Front shop entrance shutters have been changed to suit th tenant's requirements. Jalis have been added on the front facade openings; hoardings
		have covered the features.
		וומיט שיטוכע נווכ וכמנעוכס.
11.0		DP Remarks/ Perceived Threats
11.0		
		Building forms part of C1 zone
12.0		Additional Natao/ Deferences/ Decuments available
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
	1	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture
		Division of International Thomson Publishing Inc.



Front façade with ground floor with rusticated joints, first and second floor double height columns with bands



Window with decorative sill band



Side view with arched and rectangular openings



Cornice with dentil band with decorative column capital



Projecting balconies with decorative stone brackets



Entrance to the building

Dautaram N	lansion		217	
Dudululul		Common Ref No: 217	MATHALAL PARING	
		Card No: 301		
		Ward (Part): 114 (Part IV)		
	A BILLER DE CONTRACTOR	CS No: 114 (Colaba division)	- * /	
		Plot Area: Indeterminable	-) - / / / X	
		B U Area: -	- A A	
	Grand Street		- IN A	
	In the second second second	Date: 11/01/2005		
The second second		Recorded by: Sonal Modak		
and here		Reviewed by:		
मेल प्यान बीख	Corporation Bank	Int: NA	17 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
There are	A Design of the local division of the local	Ext: Sonal Modak, Prachi Merchant	The second second	
1.		Photo Ref.: 217_Dautaram Mansion	A A A A A A A A A A A A A A A A A A A	
183			Ta Shenkon	
TTTTTTTT			BHACA	
			SHAMUD SHAMUD	
			Location Plan	
1.0		Denomination		
1.1	Name of Premises	Dautaram Mansion		
1.2	Earlier Name	Dautaram Mansion		
1.3	Built in:	Indeterminable	Extension Date: -	
2.0		Access		
2.1	Main	R. Salgaonkar Road – Pedestrian		
2.2	Subsidiary	Shahid Bhagat Singh Road - Pedestrian		
2.2		Shania bhagar Singh Noau - I Eucsthall		
3.0		Ownership pattern		
	Dresset			
3.1	Present	Indeterminable		
3.2	Past	Indeterminable		
3.3	Status	Tenant		
4.0		Use		
4.1	Present	Residential - flats, Commercial - Offices, sho	ops etc.	
4.2	Past	Residential, Commercial.		
4.3	Usage	Daily		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	-		
5.2	Architectural Description	Planning		
		The building has been extensively transformed.		
		Features		
		-		
		Style		
		-		
5.3	Intrinsic	-		
5.4	Value Classification	Nil	Recommended Delete	
			grade:	
6.0		Topography		
6.1	Floors	G+2		
0.1		012		
7.0		Construction		
7.0	Diate	Construction		
7.1	Plinth			
7.2	Walls			
7.3	Floor			
7.4	Stairs	Having gone through major transformations the	he original structure is all but invisible	
7.5	Openings		no onginal subclure is all but invisible.	
7.6	Roofing			
7.7	Articulation			
7.8	Finishes			
7.9	Interiors (Movable & Immovable)	Movable		
-		-		
		Immovable		
		-		
7.10	Compound/ Fence/ Gate	-		
7.10	Curtilage/ Unbuilt space/ Out Buildings/	-		
1.11	Landscape			
	Landoodpo	Services & Utilities		
8.0		Services & Litilities		

Dautaram	Mansion		217
8.1	Lighting	Natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace	
8.7	Other (HVAC/BMS/Security Systems)	No trace	
9.0		Condition	
9.1	Plinth	Poor	
9.2	Walls	Poor	
9.3	Floor	Poor	
9.4	Stairs	Poor	
9.5	Openings	Poor	
9.6	Roofing	Poor	
9.7	Articulation & Finishes	Poor	
9.8	Services	Poor	
9.9	Out Buildings	Poor	
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0		Transformation	
	Form		
	Structure	Completely transformed building.	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone with shop line.	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Archited Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	



Newly constructed building with no trace of the old building

The Kene	seth Eliyahoo Synagogue		218
		Common Ref No: 218	
		Card No: 302	A A A A
		Ward (Part): A (Part III)	Y. My / Ly Fire
and a		CS No: 142 (Fort division)	
1		Plot Area: 1006.50 sqm.	MIS & - V W II-
D		B U Area: -	15 per per per per
T		Date: 03/11/2004	Boy 1 dates www. see
100		Recorded by: Sonal Modak	A ARTICLE
		Reviewed by:	State And
0		Int: Sonal Modak, Arun Wadhwa, Prachi	A State of the sta
31		Merchant, Zankhana Prajapati	
		Ext: Sonal Modak, Arun Wadhwa, Prachi	
		Merchant, Zankhana Prajapati	T THE STORES
		Photo Ref.: 218_Kenneseth Eliyahoo	
		Synagogue	
			Location Plan
1.0		Denomination	Loouton Fluit
1.1	Name of Premises	The Keneseth Eliyahoo Synagogue	
1.1	Earlier Name	The Keneseth Eliyahoo Synagogue	
1.3	Built in:	Construction of building completed in 1884	Extension Date: -
1.0			
2.0		Access	
2.1	Main	Sai Baba Marg	
2.2	Subsidiary	Dr. V. B. Gandhi Marg (Old Forbes Street)	
3.0		Ownership pattern	
3.1	Present	Trust	
3.2	Past	Trust	
3.3	Status	Ownership	
4.0		Use	
4.1	Present	Religious	
4.2	Past	Religious	
4.3	Usage	Place of worship	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	Prominent building with vibrant blue colour faça	
		The building abuts the road and accessed from	Sai Baba Marg and Dr. V. B. Gandhi Marg.
5.2	Architectural Description	Planning	
		The prayer hall is located on first floor with a ga	
		The administrative offices of the synagogue are	
		A wide staircase in one corner leads to prayer h	
		The prayer hall has double height and the galler The Heckhal or the western wall has magnificer	
		The raised platform for the priest is located cent	
		Ground floor caters to the administrative offices	
		having women's gallery on three sides.	. This noor has the high coming prayer han
		Features	
		The western façade has a Roman semicircular	arch surmounted by a pediment and forms
		an important feature.	, ,
		The inside of the western hall is recessed and h	has fluted double columns with ornamental
		capitals on either side.	
		A beautiful stained-glass window on western wa	all above the Heckhal houses the scroll or
		the Books of Law.	
		There is intricate jali work in marble on each sid	
		The facade is characterized using grooves, dec	orative bands various motifs, freezes,
		cornices and corbels.	
		Windows with semicircular arches punctuate the	
		Ornate cast-iron columns with Corinthian floral	patterns and balustrades adorn the interiors.
		Style	f Oathia Davinal at da so d Olassiant
		The building façade has significant influences o	i Gotnic Revival style and Classical
5.2		(Roman) style of architecture.	The prover hall been a double bairsht
5.3	Intrinsic	One of the oldest Baghdadi Jewish synagogues	s. The prayer half has a double height
5.4	Value Classification	space.	Recommonded grade: U.A.
5.4	Value Classification	A(arc), A(his), A(cul), B(per), B(des), B(uu), E, F	F Recommended grade: II A

The Kene:	seth Eliyahoo Synagogue	218	
6.0		Topography	
6.0 6.1	Floors	Topography G+1	
7.0	110013	Construction	
7.1	Plinth	Buff basalt stone plinth marginally varies in height, but overall it's a low plinth approximately of two stone courses.	
7.2	Walls	Walls are thick load bearing brick walls, plastered and painted.	
7.3	Floor	Clay based mosaic tiles have been used for flooring on ground floor and corridors. Wooden planks supported on timber joists support women's gallery.	
7.4	Stairs	The main staircase leading to the prayer hall is a wide single flight wooden staircase with wooden handrail fixed on the wall. A subsidiary wooden doglegged staircase with cast-iron railing and handrail is built to access the women's gallery above.	
7.5	Openings	The synagogue has five external entrance doors. The main entrance door has decorative pediment defining it. The prayer hall has wooden double leaf double shutter folding entrance door. The windows are partly glazed and louvered with hinged ventilators fixed inside the semicircular arches above. The western wall has an exquisite stained glass paneling.	
7.6	Roofing	The Synagogue has gable roof with Mangalore tiles supported on wooden rafters. The ceiling is finished with wooden planks from inside with floral motifs.	
7.7	Articulation	West wall facing west having a full height window fixed with decorative stained glass panels with pediment at the topmost floor. Plain bands are present at each floor level.	
		Window openings having semicircular arches with ventilators and defined by mouldings. Features like decorative brackets, pediment above door openings, ornamental column capitals, cusped arch patterns etc. impart an ornate character to the interior. Intricate <i>jali</i> work in marble is present on either side of the Heckhal. The facade is characterized using grooves, decorative bands various motifs, freezes, corries and cortels.	
7.8	Finishes	cornices and corbels. Externally walls are painted in bright blue and white colour. Internally, the walls are plastered and painted. The prayer hall has Minton tile floor finish and the raised platform for the priest done in marble	
7.9	Interiors (Movable & Immovable)	Movable Special wooden benches in the prayer hall. Original chairs, writing tables, round tables, and cupboards form the loose furniture. Wooden donation boxes are located at entrance to the prayer hall. Immovable Original gas-lights. Original oil lamp in front of Heckal. Two majestic chairs and a wooden alter table form part of the fixed furniture. Mouldings forming an arched pattern on walls on all sides. The fans seem to be old and part of the original furniture. There is a plaque in <i>Hebrew</i> script above Heckal and one on either side in addition to marble plaques fixed on sidewalls of the staircase.	
7.10	Compound/ Fence/ Gate	Since the building abuts the surrounding roads there is no side open space around the building.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	
8.0 8.1	Lighting	Adequate natural light through large windows on northern and southern walls, supplemented by artificial lighting	
8.2	Ventilation	Adequate natural ventilation, supplemented by artificial ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Manual security	
9.0		Condition	
9.1	Plinth	Fair - plinth height has diminished probably due to laying and relaying the road over the years.	
9.2	Walls	Fair - plaster peeling off from places due to dampness.	
9.3	Floor	Fair - there is an addition of waterproofing layer above it.	
9.4	Stairs	Fair - Wooden planks subjected to wear and tear due to friction over the years.	
9.5	Openings	Fair - grills have been added to eastern side ventilators.	
9.6	Roofing	Fair - peeling of paint due to water seepage. Open terrace in a deteriorating condition.	
9.7	Articulation & Finishes	Fair - original tiles have been replaced by ceramic tiles. Wooden flooring on first floor is deteriorating.	

The Keneseth Eliyahoo Synagogue			
9.8	Services	-	
9.9	Out Buildings	-	
9.10	Overall Conditions	Good	Maintenance level Good
10.0		Transformation	
	Form	-	
	Structure	-	
	Articulation & Finishes	Repair work involving the re-pair	ting the external surface undertaken.
11.0		DP Remarks/ Perceived Threa	ts
		Building forms part of C1 zone	
12.0		Additional Notes/ References/	Documents available
		the Sassoon family. It was de completed in 1884. The synage Israeli Jewish community. <u>References:</u> INTACH (1990) Preliminary une Structures listed for Conservatio FRANCIS D.K.CHING and VAN Division of International Thomso Eicher Goodearth Ltd. (2002) Ci	NOSTRAND REINHOLD Visual dictionary of Architecture, n Publishing Inc.



Sitting area with projecting gallery space above supported on cast iron columns and brackets



Women's Gallery Space with highly decorative arched openings, roof panels, brackets, railing, furniture





The Keneseth Eliyahoo Synagogue Detail of the scroll bracket



Column detail with carved capital



Ceiling with cross braced wooden sloping roof



Entrance canopy with decorative scroll brackets, keystone, pediment with dentil band

Stain glass window panel in the window arched opening with frieze band



Detail of the floral motif



Main Prayer hall with arched double height opening, platform for the priest to sit, overlooking galleries




Column with decorative capital, brackets

218



Arched opening detail with decorative bands, keystone



Main staircase with decorative cast iron railing



Old wooden intricately carved chair



Cast iron staircase railing detail



Tablet at Entrance

Wellingto	n Fountain			219
		Common Ref No: 219	MADAM CANNA CI	De Inn
		Card No: 303	L RO	
		Ward (Part): A (Part III)	Han	
		CS No: -	A G A	sumerican succession
		Plot Area: -	MTA	NGH RO.
		B U Area: -	WAH AND	CATSIN .
	N N	Date: 10/02/05	Map C1	D BHAD
			MADAM CAMA ROAD	SHAH
		Recorded by: Prachi Merchant	The second second	RG
		Reviewed by:	Sale -	THE REAL
		Int: NA	They are	CAATI R. C.
-		Ext: Prachi Merchant, Arun Wadhwa		122
1000		Photo Ref.: 219_Wellington fountain	elwin al	71.0
S AS P			ALAL PA MAJESTIC	A A BAR AND A
			WATH T LE A	ON AL MENT
			Loca	tion Plan
1.0		Denomination	Lood	
1.1	Name of Premises	Wellington Fountain		
1.1	Earlier Name	Wellington Fountain		
1.2	Built in:	1865	Extension -	
1.5	Built In.	6001	Date:	
			Dale.	
2.0				
2.0		Access		
2.1	Main	Shyamaprasad P. Mukherjee Chowk (Juncti		li Marg, Shahid Bhagat
		Singh Marg, Madam Cama Road, Nathalal F	arekh Road)	
2.2	Subsidiary	-		
3.0		Ownership pattern		
3.1	Present	Municipal Corporation of Greater Mumbai		
3.2	Past	Municipal Corporation of Greater Mumbai		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Fountain		
4.2	Past	Fountain		
4.3	Usage	Daily		
т. Ј		Dally		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	The Fountain is located in an important urb	an nodo at Shvamanr	acad Mukhariaa Chawk
J.1	Townscape (Maninade)	bound by an array of buildings of varied a		
		building, Majestic Hostel, Maharashtra He	adquartera Drinea Of	Wales Museum Metro
			adquarters, Prince Of	wales museum, metro
- 0		Cinema and Cowasji Jehangir Hall.		
5.2	Architectural Description	Planning & Features		
		Octagonal water basin with stone parapet w		ly and drainage system.
		The fountain is placed at the center of this b		
		The base is octagonal capped with two tie		spouting water. On the
		base is a wide trough with geometric pattern		
		The cylindrical final level of the fountain has		
		Bas-reliefs at the bottom level, depicting Du		
		The levels are demarcated by bands, floral f	riezes and inscriptions	in geometric pattern.
		Style		
		-		
5.3	Intrinsic	The fountain was erected in commemoration		of Wellington.
5.4	Value Classification	A(his), B(per), B(des), B(uu), E, I(sce)	Recommended	1
			grade	
6.0		Topography		
6.1	Floors	-		
7.0		Construction		
7.1	Plinth	-		
7.2	Walls	-		
7.2	Floor			
		-		
7.4	Stairs	-		
7.5	Openings	-		
7.6	Roofing	-		
7.7 7.8	Articulation Finishes	Bands, Bas- reliefs, floral pattern inscription. All parts of the fountain have been painted.		

Wellingto	n Fountain	219
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable
7.10	Compound/ Fence/ Gate	- Two successive rows of MS railing around the fountain.
7.11	Curtilage/ Unbuilt space/ Out	Concrete guard post located at the Pay and Park area to the south of the Fountain.
1.11	Buildings/ Landscape	Area around the fountain is paved.
	Dululigs/ Lanuscape	Lawn, shrubs are planned in the island.
		Lamp posts are installed at intervals.
0 0		Services & Utilities
8.0 8.1	Lighting	-
8.2	Ventilation	•
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	
	Other (HVAC/BMS/Security Systems)	- -
8.7		-
9.0		Condition
9.1	Plinth	All the parts of the fountain are insensitively finished with oil paint. There are numerous layers of oil paint of different colors, resulting in clogging of pores. Growth of plants and algae is visible at many sections.
9.2	Walls	•
9.3	Floor	-
9.4	Stairs	
9.5	Openings	-
9.6	Roofing	-
9.7	Articulation & Finishes	Multiple layers of paint are applied on the fountain. The original material and finish cannot be identified.
9.8	Services	•
9.9	Out Buildings	•
9.10	Overall Conditions	Fair Maintenance level Low
10.0		Transformation
1010	Form	-
	Structure	Fencing around the fountain, surrounding area is occupied by parking lot. Signage board obstructs the vision of the fountain from the Gateway of India end.
	Articulation & Finishes	All the features are insensitively painted. The original material and finish cannot be identified.
11.0		DP Remarks/ Perceived Threats
11.0		Recreational Ground.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: The fountain was erected by public subscription around 1865 to commemorate the visits of the Duke of Wellington to Bombay in 1801 and 1804. There are eight bas-reliefs on the pedestal, illustrating the Duke's many victories in battle. Sadly, this fountain, which was one of the earliest to be installed in Bombay, has been painted like other fountains in the city – a 'beautifying' effort that actually damages porous stone with the permeation of synthetic paint through its natural crevices. The parking around the fountain and the double layer of enclosing fencing have also significantly altered the pivotal quality that such monuments exert on traffic intersections. <u>References:</u> INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House.



Octagonal base with eight Bas reliefs on the pedestal, illustrating the Duke's victories in war.



Fountain with octagonal base with bas reliefs, horizontal projection of water spout, top level tapering smaller projection with decorative motifs



Spout detail with floral motifs