ARCHITECTURAL GRANDEUR OF WILSON COLLEGE

A PRESENTATION BY


VIKAS DILAWARI

CONSERVATION ARCHITECT


THE ORIGINAL BUILDING AS DESIGNED IN 1863



EXTENSION IN 1922




SITE PLAN SHOWING THE GROWTH OF COLLEGE




Note: retraced from Gregson Batley & King layout plan dt. 7th June 1960.

WEST VIEW



ENTRANCE PORCH



SOUTH FACADE



VERANDAHS





MAGNIFICENT HALL










MAGNIFICENT HALL



CHAPEL ON THE NORTH SIDE



STAINED GLASS



MOSAIC FLOORING





ENTRANCE STAIRCASE



DEFECTS

ROOF CONDITIONS



ROOF CONDITIONS










LIME MORTAR REPOINTING REQUIRED







STRUCTURAL DEFECTS






LIME MORTAR REPOINTING REQUIRED





CARPENTARY DETAILS





FLOORING DETAILS







PAINTING AND POLISHING



SMALL BUT RELEVANT DETAILS NEED TO BE

